



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
5 Benoi Place Singapore 629926
Tel: 6861 0908 Fax: 6515 2948

Date: 16.04.2018

AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01/02
AXA Tower
Singapore 068811

Attn: Motor Claims Dept

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanfer 97495749
WP
6/4/18 @ 1640
Resurvey after repair
Sur @ lkkauto.com
4 days

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2178S TOYOTA VELLFIRE (2017)

To Supply

1)	1pc	rear bumper	\$	1,780.57 car
2)	1set	rear bumper clip	\$	30.00 nei
6)	1pc	rear end panel	\$	804.10 Ry
8)	1pc	tail gate	\$	1,935.00 Ry
10)	1set	tail gate glass moulding	\$	245.10 x
11)	1pc	tail gate "Vellfire"	\$	70.40 nei
12)	1pc	tail gate "E-Four"	\$	77.50 nei
13)	1pc	tail gate "Hybrid Synergy Drive"	\$	82.10 nei
20)	1pc	rear bumper center left parking sensor (Genuine)	\$	569.10 ?
21)	1pc	rear bumper center left parking sensor cover (Genuine)	\$	44.50 Ry

Sub total parts	\$	5,638.37
Less: 25% discount	\$	(1,409.59)
	\$	4,228.78

To Supply S.Nett Parts

1)	1tube	rear glass sealant	\$	40.00x
2)	1pc	rear bumper top anti slip mat	\$	60.00 anti
3)	1pc	"Prime" taxi sticker	\$	55.00 nei

Sub total S.Nett Parts \$ 155.00

L/charges

- | | | |
|---|----|--------------|
| 1) To remove & refit rear glass | \$ | 100.00 X |
| 2) To tuff kote rear portion | \$ | 150.00 30 |
| 3) To transfer tail gate trim board, handle, mechanism parts | \$ | 100.00 X |
| 4) To remove & replace rear reverse sensor, reset reverse sensor light | \$ | 50.00 30 |
| 5) To knock /welding rear end panel, remove rear bumper, rear boot lid, replace the above mentioned part | \$ | 900.00 600 |
| 6) To putty, respray painting tail gate inlet & outer, end panel, rear bumper in pearl white | \$ | 1,000.00 700 |

Sub total L/charges	\$	2,300.00
Estimated Total	\$	6,683.78