

KIM CHWEE AUTO PTE LTD
1 KAKI BUKIT AVENUE 6
#01-48 AUTOBAY
SINGAPORE 417883

not Authorized
bkk
4/5 & 5500
427.

VEHICLE NO:SKV 3399J

QTY	PARTICULAR	AMOUNT
1 PCS	BONNET	\$2,415.12 X
1 PCS	BONNET LOGO 45	per \$65.00 ✓
1 PCS	FRONT GRILLE	one \$695.00 ✓
1 PCS	FRONT GRILLE LOGO	per \$80.00 ✓
1 PCS	FRONT BUMPER 1325	no/bon \$1,815.00 ✓
1 PCS	FRONT BUMPER TOW COVER	11 \$30.00 X
1 PCS	FRONT BUMPER SPONGE	7on \$121.00 ✓
1 PCS	FRONT BUMPER REINFORCEMENT 495.15	no \$695.00 ✓
1 PCS	FRONT BUMPER LICENSE PLATE GARNISH	per \$82.00 ✓
2 PCS	FRONT BUMPER FOG LAMPS @\$498.00	11 \$996.00 X
1 PCS	FRONT TOP PANEL CENTRE	no \$188.00 ✓
1 PCS	FRONT TOP PANEL CENTRE GARNISH	one \$172.00 ✓
2 PCS	HEADLAMPS @\$2100 1615 x 2 = 3230	one \$4,200.00 ✓
1 PCS	AIR CON CONDENSER	11 \$1,475.00 X
1 PCS	FRONT LICENSE PLATE W/HOLDER	no \$45.00 ✓
LABOUR CHARGES:		
	TO CHECK WIRING	\$50.00 20
	TO REFILL AIR CON GAS	11 \$120.00 X
	TO SPRAY RUST PROOFING	11 \$50.00 X
	LABOUR FOR PANELBEATING & REPLACING PARTS	\$800.00 450
	TO PUTTY & SPRAY PAINTING	\$1,080.00 600
TOTAL		\$15,174.12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

6478.15
6900.33