

振明摩托 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40/63 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmrmotors@singnet.com.sg

Our Ref: EST112/18/TP
Your Ref: TP claim against SKP6838X

13-Apr-18

AXA Insurance Singapore Pte Ltd
#01-01 GB Building
Singapore 069542

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Estimated cost of repair to Nissan NV350 no: GBD9536S

Date of accident: 12-04-2018

Parts supply (NETT):

- 1 pc Front windscreen moulding
- 1 pc Front panel
- 1 pc Front panel wiper garnish
- 2 pcs Front panel wiper garnish side @\$35.20
- 1 pc Front L/h panel
- 1 pc Front L/h windscreen pillar - Outer
- 1 pc Front L/h windscreen pillar - inner
- 1 pc Front L/h door
- 1 pc front L/h door moulding
- 2 pcs Front L/h door hinges @\$86.10
- 1 pc Front L/h side mirror
- 1 pc Front L/h side mirror cover
- 1 pc Front L/h door board
- 1 pc Front L/h door weatherstrip
- 1 pc Front L/h door wire cover
- 1 pc Front L/h door regulator
- 1 pc Front L/h door motor
- 1 pc Front L/h door sticker - Address
- 1 pc Front L/h door cheek
- 1 pc Front L/h door switch
- 1 pc Front L/h door lock pocket
- 1 pc Front L/h door lock
- 1 pc Front L/h door pillar weatherstrip
- 1 pc Front L/h wheel arch garnish
- 1 pc Front L/h wheel arch inner shield
- 4 pcs Front L/h wheel arch inner shield clips @\$3.50
- 1 pc Front floor panel
- 1 pc Front floor mat
- 1 pc Headlamp L/h
- 1 pc Headlamp socket L/h

ESTIMATE

*Not Affected
Line
2/5/18 \$800?
6 day
16/4/18
The plate has rep*

SS/Re	75.80	—
re	1,096.90	X
re	184.50	X
re	70.40	X
re	477.10	—
re	1,033.20	—
re	380.50	X
re	1,015.00	—
re	149.00	—
re	172.20	—
re	520.30	X
re	105.70	X
re	481.70	—
re	133.50	—
re	45.80	X
re	147.90	—
re	524.40	—
re	15.00	—
re	49.50	—
re	55.30	X
re	33.50	X
re	223.50	—
re	105.60	—
re	186.50	—
re	66.30	—
re	14.00	—
re	865.50	X
re	358.50	X
re	403.20	—
re	12.00	—
	9,002.30	

5469.9

振明摩托 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40/63 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

Re: Estimated cost of repair to Nissan NV350 no: GBD9536S

Date of accident: 12-04-2018

Parts supply (NETT):

Balance b/f:

- 1 pc Front grille
- 4 pcs Front grille clips @\$3.50
- 1 pc Front bumper 514.70
- 2 pcs Front bumper retainers @\$147.00
- 2 pcs Front bumper brackets @\$104.70
- 8 pcs Front bumper clips @\$3.50
- 1 pc Front bumper tow cover
- 1 pc Front bumper reinforcement
- 2 pcs Front bumper fog lamps @\$311.80
- 2 pcs Front bumper fog lamp cover @\$65.80
- 1 pc Front bumper lower grille
- 1 pc ATF cooler
- 1 pc ATF cooler outer cover
- 1 pc ATF cooler holder bracket
- 2 pcs ATF cooler hose @\$28.00
- 1 pc Front L/h step garnish
- 1 pc Front L/h step panel
- 1 pc Front L/h knuckle arm
- 1 pc Front L/h knuckle bearing
- 1 pc Front L/h shock absorber
- 1 pc Front L/h lower arm

	9,002.30	
ONE	455.00	X
11	14.00	X
0.5	517.70	
NISSAN	294.00	4C
NISSAN	209.40	10C
122	28.00	
11	23.50	X
10	630.10	
NISSAN	623.60	12C
NISSAN	131.60	10C
11	89.50	X
10/100	672.30	
100	83.80	
3.4	75.30	
11	56.00	X
10	133.50	
11	145.80	X
11	652.50	X
11	388.50	X
11	204.50	X
11	388.50	X
	14,819.40	
Less 10%:	1,481.94	

8691-9

S/Nett Items

- 1 pc Front windscreen gum (S/Nett)
- 1 pc Front L/h door sticker - CALL 67479707 (S/Nett)
- 1 pc Front L/h tyre (S/Nett)
- 1 pc Front panel sticker - GRADECOOL

11	40.00	✓
11	50.00	30
11	160.00	X
11	100.00	

Labour charges:

- To panel beating, welding, removing damaged parts and replacement of the new parts as mentioned above etc.
- To respray affected part.
- To remove and refit front windscreen
- To remove and refit dashboard
- To remove and refit front L/h door glass
- To apply underseal
- To check wirings.

1,800.00	1080
1,200.00	1000
120.00	
350.00	160
40.00	✓
100.00	60
30.00	✓
SS 20,291.34	

LKK Auto Consultants hence notify the Insurer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

68800

P-9179.40
less 10%
8261.46
S.N - 300
1200 - 2490
11051.46

振明摩托 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40/63 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

Our Ref: EST112/18/TP
Your Ref: TP claim against SKP6838X

19-Apr-18

AXA Insurance Singapore Pte Ltd
#01-01 GB Building
Singapore 069542

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Supplementary cost of repair to Nissan NV350 no: GBD9536S

Date of accident: 12-04-2018

Parts supply (NETT):

1 pc Front L/h arch panel

S/Nett Items

1 pc Front L/h door sound insulation

ESTIMATE

sub/suc
S\$ 487.50 ✓
Less 10%: (48.75)
438.75

na
S\$ 250.00 30
688.75