

15/5/2018

INS. CASE OWNER:

Franchman

CC 4/AXA1800

6992, F6632

LKK:
IDAC:

Surveyor:

Kenneth

DOI:

ASSIGNMENT

16/4/18

Date / Time:

16/4/18

Registered in Merimen:

Pre-assign / CCU / FTE

GRB 5060J



Insured Vehicle No.:

Name of Insured:

AL ARSAR FOOD PRODUCTS PVT

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A:

11/4/18

Is driver the owner?

(YES / ☒ NO)

Nature of Accident:

If NO, Driver Name / Age: MUHAMMAD HAFIM SAMIB MURKIAN

OI GIA REPORT: ☒ YES / NO ; TP GIA REPORT: ☒ YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SHB 9790M

INSRS:
WSP:
Tel:
Liability:
RMKS:Trans
cabINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

16/4/18
TH

SHB 9790M - x

GRB 5060J - x

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OE:

After call ltr to OE:

> THIN By Email
2514

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OE:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

18/4/18

Sent By:

TH

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$ 11,250.00 (7 days) Reduction: 69.75 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with Jasmine Tan

Email ☒ Call ☐

Final Liability:

% 100. (Agreed / Assessed) BOLA S/N No.: 15

If NO or B 28, Ass. Lia:

Repair Cost:

S\$ 11,425.46 (\$10,678.00 + 7% GST) (AXA instruction)

OID change lane

Loss of Rental (LOR):

S\$ 893.88 (9 days) x \$99.32

Loss of Use (LOU):

S\$ - (S x days)

Loss of Income (LOI):

S\$ 450.00 (\$50.00 x 9 days)

LOR only ☐LOU only ☐LOR + LOU ☐ LOR + LOI ☒ (Tick only one)

GIA/LTA Search

S\$ 7.49

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/Independent)

Legal Cost

S\$ -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$350.00

Total:

S\$ 12,776.83

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Payee 1:

S\$ 12,776.83

Name 1:

Trans-cab Auto Services pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18006992/Kub3		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 16-04-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 5060J	Veh. Inspected	SHB 9790M	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	16/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	11/04/2018	Inspection Date	16/04/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Transcab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9790M

AAD1804-122

*Not Authored
L Bny & 11, 2501*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 9790M

VF1ABL15AUC273324

RENAULT

LATITUDE

11.4.2018

AXA**PART****LIST**

1	HEADLAMP LH	\$	SH 1,184.43 X
1	HEADLAMP PANEL FRT LH	\$	R 152.15 X
1	FENDER PANEL FRT LH	\$	R 783.83 X
1	WHEELARCH FRT LH	\$	SH 278.84 X
1	FENDER BRACKET LOWER LH	\$	SH 15.79 X
1	FENDER INSULATOR LH	\$	SH 130.84 X
1	DOOR PANEL FRT LH	\$	R 2,844.66 X
1	DOOR HINGE UPPER LH L70Y	\$	R 261.28 X
1	DOOR HINGE LOWER LH	\$	R 300.55 X
1	DOOR CHECK FRT LH	\$	SH 194.77 X
1	DOOR CHECK BOLT	\$	SH 22.69 X
1	DOOR LOCK FRT LH	\$	R 908.75 X
1	DOOR CATCH FRT LH	\$	R 131.23 X
1	DOOR HANDLE OUTER FRT LH	\$	CM 477.76 X
1	DOOR HANDLE COVER FRT LH	\$	SH 13.22 X
1	DOOR HANDLE MODULE FRT LH	\$	SH 133.60 X
1	DOOR REGULATOR FRT LH	\$	R 505.19 X
1	DOOR REGULATOR MOTOR FRT LH	\$	SH 796.46 X
1	DOOR REGULATOR GUIDE FRT LH	\$	SH 120.97 X
1	DOOR PANEL REAR LH L70Y	\$	R 2,844.66 X
1	DOOR GUIDE REAR LH L70Y	\$	SH 176.82 X
1	DOOR GUIDE SCREW	\$	SH 10.85 X
1	DOOR HINGE UPPER LH L70Y	\$	R 274.50 X
1	DOOR HINGE LOWER L70Y	\$	R 300.55 X
1	DOOR HINGE BOLT	\$	SH 10.85 X
1	DOOR HINGE NUT L70Y	\$	SH 14.60 X
1	DOOR CHECK REAR LH/RH L70Y	\$	SH 203.06 X
1	DOOR CHECK BOLT	\$	SH 22.69 X
1	DOOR CHECK NUT	\$	SH 3.75 X
1	DOOR LOCK REAR LH L70Y	\$	R 908.75 X

Trans-cab Auto Services Pte Ltd**AAD1804-122**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9790M

1	DOOR LOCK SCREW L70Y	\$	Sh	6.12	}
1	DOOR CATCH SCREW L70Y	\$	Sh	10.06	
1	DOOR HANDLE OUTER REAR LH L70Y	\$	Sh	126.49	
1	DOOR HANDLE CAP REAR LH L70Y	\$	Sh	35.52	
1	DOOR HANDLE SEAL REAR LH L70Y	\$	Sh	7.89	
1	DOOR HANDLE COVER REAR LH L70Y	\$	Sh	13.22	
1	DOOR HANDLE MODULE REAR LH L70Y	\$	Sh	133.60	
1	DOOR REGULATOR REAR LH L70Y	\$	Sh	1,135.10	
1	DOOR REGULATOR MOTOR REAR LH L70Y	\$	Sh	893.75	
1	DOOR REGULATOR NUT REAR L70Y	\$	Sh	12.43	
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	Sh	6.31	
1	DOOR FINISHER REAR LH L70Y	\$	Sh	423.10	
1	DOOR MOULDING REAR LH L70Y	\$	Sh	176.82	
1	DOOR MOULDING CLIP L70Y	\$	Sh	5.92	
1	DOOR MOULDING SCREW L70Y	\$	Sh	6.91	
1	DOOR CASING REAR LH L70Y	\$	Sh	1,509.06	
1	DOOR WATER SHIELD REAR LH L70Y	\$	Sh	30.39	
1	DOOR CASING CLIP	\$	Sh	12.63	
1	DOOR CASING LIGHT L70Y	\$	Sh	48.74	
1	DOOR FINISHER INNER REAR LH L70Y	\$	Sh	323.44	
1	DOOR FINISHER BRACKET INNER REAR LH L70Y	\$	Sh	46.97	
1	DOOR FINISHER BRACKET INNER REAR LH L70Y	\$	Sh	20.33	
1	DOOR FINISHER BRACKET INNER REAR LH L70Y	\$	Sh	20.33	
1	DOOR FINISHER BRACKET INNER REAR LH L70Y	\$	Sh	20.33	
1	DOOR GRAB HANDLE REAR LH L70Y	\$	Sh	210.96	
1	DOOR BLIND REAR LH L70Y	\$	Sh	741.80	
1	DOOR WHEATHESTRIIP REAR LH L70Y	\$	Sh	410.66	
1	DOOR SEAL REAR LH L70Y	\$	Sh	162.02	
1	DOOR GLASS RUNNER SEAL REAR LH L70Y	\$	Sh	229.31	
1	DOOR WAIST SEAL OUTER REAR LH L70Y	\$	Sh	334.69	
1	DOOR WAIST SEAL INNER REAR LH L70Y	\$	Sh	115.64	
1	FENDER PANEL REAR LH	\$	Sh	3,299.13	✓
1	FENDER PANEL INNER TRIM REAR	\$	Sh	671.45	X
1	WHEELARCH REAR LH	\$	Sh	543.47	X
1	BUMPER COVER REAR	\$	Sh	1,108.46	✓
1	BUMPER LOWER REAR	\$	Sh	768.84	X
1	BUMPER BRACKET CTR REAR	\$	Sh	113.47	X
1	BUMPER RETAINER LH REAR	\$	Sh	44.99	X
1	BUMPER BEAM REAR	\$	Sh	777.52	X

Trans-cab Auto Services Pte Ltd

AAD1804-122

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9790M

- | | |
|---|-----------------------------|
| 1 | BUMPER BEAM BRACKET LH REAR |
| 1 | DOOR MIRROR ASSY LH |
| 1 | TAILLAMP LH |

\$	<i>Sm</i> 225.95 <i>X</i>
\$	<i>Ad/Sm</i> 1,483.40 ✓
\$	<i>Sm</i> 552.55 <i>X</i>

\$	30,847.89
10% \$	3,084.79
\$	27,763.10

Special Nett

- | | |
|------|--------------------------------|
| 1SET | BUMPER CLIP FRT |
| 1 | BUMPER BRACKET CLIP FRT LH |
| 1 | BUMPER SUPPORT CLIP FRT LH |
| 1SET | BUMPER GRILLE LOWER CLIP |
| 1SET | FRAME FULL SUPPORT PANEL CLIP |
| 2 | FRAME FULL SUPPORT PANEL NUT |
| 2 | FRAME FULL SUPPORT PANEL STUD |
| 1SET | WHEELARCH CLIP FRT LH |
| 1 | FRONT DOOR STICKER 'Trans-cab' |
| 1 | FRONT DOOR STICKER 'Chassis' |
| 1 | REAR DOOR STICKER '6555 3333' |

\$	<i>nn</i> 66.00	} <i>X</i>
\$	<i>nn</i> 12.00	
\$	<i>nn</i> 10.50	
\$	<i>nn</i> 69.00	
\$	<i>nn</i> 70.00	
\$	<i>nn</i> 20.00	
\$	<i>nn</i> 30.00	}
\$	<i>nn</i> 30.50	
\$	<i>nn</i> 80.00 <i>60sm</i>	
\$	<i>nn</i> 50.00 <i>15sm</i>	
\$	<i>nn</i> 80.00 <i>80sm</i>	

TOTAL	\$	518.00
--------------	----	---------------

TOTAL PARTS	\$	28,281.10
--------------------	----	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	<i>100cl</i> 3,500.00
----	-----------------------

Putty and spray painting of the affected portion.

\$	<i>110cl</i> 3,200.00
----	-----------------------

To rust-proofing of the affected areas.

\$	170.00 <i>12cl</i>
----	--------------------

Trans-cab Auto Services Pte Ltd

AAD1804-122

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9790M

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	100/
To check steering geometry and computer wheel alignment	\$	220.00	~ X
To transfer of tire, rim and on wheel balancing.	\$	170.00	~ X
To Check Electrical Lighting Concerned.	\$	170.00	20/
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00	~ X
To vacuum, replace, refix and recharge air condenser	\$	380.00	~ X
To replace, refix and top up coolant for radiator	\$	170.00	~ X
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	~ X

TOTAL	\$	8,910.00
--------------	-----------	-----------------

Over All Total	\$	37,191.10	07.
-----------------------	-----------	------------------	-----

LUMP SUM (REPAIR DAY)**10 DAYS**
7 day

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date:

Catherine Chong (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Friday, 13 April, 2018 4:06 PM
To: assignments
Subject: FW: ARRANGE FOR SURVEY SHB9790M
Attachments: img-413094806-0001.pdf

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Candy Kong [mailto:candy.kong@transcab.com.sg]

Sent: Friday, 13 April, 2018 11:04 AM

To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>

Subject: ARRANGE FOR SURVEY SHB9790M

Kenneth

Dear all,

Please arrange for survey as below :

GBB5060J -11.04.2018 AT 2015Hrs - SHB9790M

Lunch time : 12pm - 1pm.

Kindly pls dun arrange survey during lunch time.

"We Agree to let your In-house surveyor assess/ survey our vehicle with estimate."

Thks & Rdgs

Candy Kong

Claims Service Assistant

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

Poh Kin (LKKAUTO)

From: Jasmine Tan <jasminetan@transcab.com.sg>
Sent: Tuesday, 12 February 2019 5:10 PM
To: Poh Kin (LKKAUTO); 'claims'
Cc: 'Ng Wai Yin'
Subject: RE: Our Ref: CC4/ASM18006992/Kfb3; Your Ref: AAD1804-122

Without Prejudice

Dear Poh Kin

Please proceed to send us the DV.

Thank you
Best Regards
Jasmine Tan



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line : (65) 6287 6666 Fax Line: (65) 6257 1330
Direct Line : (65) 6603 1250
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

From: Poh Kin (LKKAUTO) [mailto:pohkin@lkkauto.com]
Sent: Saturday, 15 December 2018 5:37 PM
To: Jasmine Tan <jasminetan@transcab.com.sg>; claims <claims@transcab.com.sg>
Cc: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Subject: Our Ref: CC4/ASM18006992/Kfb3; Your Ref: AAD1804-122
Importance: High

WITHOUT PREJUDICE SAVE AS TO COSTS

Our Ref: CC4/ASM18006992/Kfb3
Your Ref: AAD1804-122

Dear Sir/Madam,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. GBB 5060J AND SHB 9790M ON 11.04.2018

We refer to the above matter.

Towards an amicable settlement and without admission of liability to our Insured's part, we have instruction from **our Principal** to offer settlement as below:

1. Cost of Repair (\$10,678.00 +7%GST)	S\$11,425.46
--	--------------

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Saturday, 15 December 2018 5:37 PM
To: 'Jasmine Tan'; 'claims'
Cc: 'Ng Wai Yin'
Subject: Our Ref: CC4/ASM18006992/Kfb3; Your Ref: AAD1804-122
Importance: High

WITHOUT PREJUDICE
SAVE AS TO COSTS

Our Ref: CC4/ASM18006992/Kfb3
Your Ref: AAD1804-122

Dear Sir/Madam,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. GBB 5060J AND SHB 9790M ON 11.04.2018

We refer to the above matter.

Towards an amicable settlement and without admission of liability to our Insured's part, we have instruction from **our Principal** to offer settlement as below:

1. Cost of Repair (\$10,678.00 +7%GST)	S\$11,425.46
2. Loss of Rental (\$99.32 x 9days)	S\$ 893.88
3. Loss of income (\$50.00 x 9days)	S\$ 450.00
4. LTA search fee	<u>S\$ 7.49</u>
	<u>S\$12,776.83</u>

Kindly confirm acceptance.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."


Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



AUTO
CONSULTANTS
PTE LTD

Save the Earth. Print only when necessary.



Re:< S8M00DU3> SEEK MANDATE APPROVAL

Type

🔗 Question

Message

COR \$11,425.46 (W/GST) LOR \$893.88 LOI \$450 LTA \$7.49 TOTAL \$12,776.83

10678

Reply



< S8M00DU3> SEEK MANDATE APPROVAL

Type

🔔 Question

Message

Dear Kian Chuan, Liability: Insured Driver collided into the third party vehicle while changing lane. Liability is down against our insured. send letter to OI to notify TP claim and NCD issue on 25th April 2018. Immediate Advice (with mandate) have been uploaded in SMART CLAIM. We hereby seek your approval to offer Third Party repairer M/s "Trans-Cab Auto Services Pte Ltd" is as follows: - 1)COR(w/gst): \$12,037.50 + 2) Loss of Rental (11daysx\$99.32): \$1,092.52 + 3) Loss of Income (11daysx\$50.00): \$550.00 +4) LTA: 7.45 =Total: \$13,687.47. **07days recommendation for repair. **All the relevant documents had been uploaded in SMART CLAIM. For your approval/instruction please. PohKin - 04/12/2018

Reply

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBB 5060J (Insd veh)	Model:	RENAULT LATITUDE (A)
	SHB 9790M (TP veh)		
Date of Accident:	11/04/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	39,794.44
Final Repair Cost	:	\$	11,425.46
Loss of Token Sum	:	\$	450.00
Rental (if any)	:	\$	893.88
LTA / GIA Search Fee	:	\$	7.49

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	12,776.83

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks PLEASE SEND THE CHEQUE PAYMENT TO TRANS-CAB AUTO SERVICES PTE LTD
NO.2 ANG MO KIO ST 63 SINGAPORE 569111

Payment Instruction: Payee's Breakdown			
1)	TRANS-CAB AUTO SERVICES PTE LTD	:	\$ 12,776.83

NUR SHAQILAH BTE ABDOL
WAHAB

25/02/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18006992/Kfb3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 25-02-2019



ATTN: KIAN CHUAN

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 5060J	Veh. Inspected	SHB 9790M
Policy No.	VCA/P1770448	Coverage (\$)	0.00
Claim No.	S8M00DU3	Excess (\$)	0.00
Assign From	KIAN CHUAN	Assign Date	16/04/2018

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	VF1ABL15AUC273324	Colour	WHITE / RED
Odometer	473093	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60R16	GITI	8 mm
L/H Front Tyre	215/60R16	GITI	8 mm
R/H Rear Tyre	215/60R16	GITI	8 mm
L/H Rear Tyre	215/60R16	GITI	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	11/04/2018	Inspection Date	16/04/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 9790M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	HEADLAMP LH (CONSISTENT)	SERVICEABLE	1,184.43	-
1	HEADLAMP PANEL FRT LH (CONSISTENT)	TO REPAIR SEE LABOUR	152.15	-
1	FENDER PANEL FRT LH (CONSISTENT)	BENT	783.83	783.83
1	WHEELARCH FRT LH (CONSISTENT)	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER LH (CONSISTENT)	SERVICEABLE	15.79	-
1	FENDER INSULATOR LH (CONSISTENT)	SERVICEABLE	130.84	-
1	DOOR PANEL FRT LH (CONSISTENT)	BENT	2,844.66	2,844.66
1	DOOR HINGE UPPER LH L70Y (CONSISTENT)	TO REPAIR SEE LABOUR	261.28	-
1	DOOR HINGE LOWER LH (CONSISTENT)	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK FRT LH (CONSISTENT)	SERVICEABLE	194.77	-
1	DOOR CHECK BOLT (CONSISTENT)	SERVICEABLE	22.69	-
1	DOOR LOCK FRT LH (CONSISTENT)	TO REPAIR SEE LABOUR	908.75	-
1	DOOR CATCH FRT LH (CONSISTENT)	TO REPAIR SEE LABOUR	131.23	-
1	DOOR HANDLE OUTER FRT LH (CONSISTENT)	CRACKED	477.76	477.76
1	DOOR HANDLE COVER FRT LH (CONSISTENT)	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE FRT LH (CONSISTENT)	SERVICEABLE	133.60	-
1	DOOR REGULATOR FRT LH (CONSISTENT)	TO REPAIR SEE LABOUR	505.19	-
1	DOOR REGULATOR MOTOR FRT LH (CONSISTENT)	SERVICEABLE	796.46	-
1	DOOR REGULATOR GUIDE FRT LH (CONSISTENT)	SERVICEABLE	120.97	-
1	DOOR PANEL REAR LH L70Y (CONSISTENT)	BENT	2,844.66	2,844.66
1	DOOR GUIDE REAR LH L70Y (CONSISTENT)	SERVICEABLE	176.82	-
1	DOOR GUIDE SCREW (CONSISTENT)	SERVICEABLE	10.85	-
1	DOOR HINGE UPPER LH L70Y (CONSISTENT)	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER L70Y (CONSISTENT)	TO REPAIR SEE LABOUR	300.55	-
1	DOOR HINGE BOLT (CONSISTENT)	SERVICEABLE	10.85	-

Report Ref No. CC4/ASM18006992/Kfb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR HINGE NUT L70Y (CONSISTENT)	SERVICEABLE	14.60	-
1	DOOR CHECK REAR LH/RH L70Y (CONSISTENT)	SERVICEABLE	203.06	-
1	DOOR CHECK BOLT (CONSISTENT)	SERVICEABLE	22.69	-
1	DOOR CHECK NUT (CONSISTENT)	SERVICEABLE	3.75	-
1	DOOR LOCK REAR LH L70Y (CONSISTENT)	TO REPAIR SEE LABOUR	908.75	-
1	DOOR LOCK SCREW L70Y (CONSISTENT)	SERVICEABLE	6.12	-
1	DOOR CATCH SCREW L70Y (CONSISTENT)	SERVICEABLE	10.06	-
1	DOOR HANDLE OUTER REAR LH L70Y (CONSISTENT)	TO REPAIR SEE LABOUR	126.49	-
1	DOOR HANDLE CAP REAR LH L70Y (CONSISTENT)	TO REPAIR SEE LABOUR	35.52	-
1	DOOR HANDLE SEAL REAR LH L70Y (CONSISTENT)	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR LH L70Y (CONSISTENT)	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR LH L70Y (CONSISTENT)	SERVICEABLE	133.60	-
1	DOOR REGULATOR REAR LH L70Y (CONSISTENT)	TO REPAIR SEE LABOUR	1,135.10	-
1	DOOR REGULATOR MOTOR REAR LH L70Y (CONSISTENT)	SERVICEABLE	893.75	-
1	DOOR REGULATOR NUT REAR L70Y (CONSISTENT)	SERVICEABLE	12.43	-
1	DOOR REGULATOR MOTOR SCREW REAR L70Y (CONSISTENT)	SERVICEABLE	6.31	-
1	DOOR FINISHER REAR LH L70Y (CONSISTENT)	SERVICEABLE	423.10	-
1	DOOR MOULDING REAT LH L70Y (CONSISTENT)	SERVICEABLE	176.82	-
1	DOOR MOULDING CLIP L70Y (CONSISTENT)	NOT NECESSARY	5.92	-
1	DOOR MOULDING SCREW L70Y (CONSISTENT)	NOT NECESSARY	6.91	-
1	DOOR CASING REAR LH L70Y (CONSISTENT)	SERVICEABLE	1,509.06	-
1	DOOR WATER SHIELD REAR LH L70Y (CONSISTENT)	SERVICEABLE	30.39	-
1	DOOR CASING CLIP (CONSISTENT)	NOT NECESSARY	12.63	-
1	DOOR CASING LIGHT L70Y (CONSISTENT)	SERVICEABLE	48.74	-
1	DOOR FINISHER INNER REAR LH L70Y (CONSISTENT)	SERVICEABLE	323.44	-
1	DOOR FINISHER BRACKET INNER REAR LH L70Y (CONSISTENT)	TO REPAIR SEE LABOUR	46.97	-
1	DOOR FINISHER BRACKET INNER REAR LH L70Y (CONSISTENT)	TO REPAIR SEE LABOUR	20.33	-

Report Ref No. CC4/ASM18006992/Kfb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR FINISHER BRACKET INNER REAR LH L70Y (CONSISTENT)	TO REPAIR SEE LABOUR	20.33	-
1	DOOR FINISHER BRACKET INNER REAR LH L70Y (CONSISTENT)	TO REPAIR SEE LABOUR	20.33	-
1	DOOR GRAB HANDLE REAR LH L70Y (CONSISTENT)	SERVICEABLE	210.96	-
1	DOOR BLIND REAR LH L70Y (CONSISTENT)	SERVICEABLE	741.80	-
1	DOOR WEATHERSTRIP REAR LH L70Y (CONSISTENT)	SERVICEABLE	410.66	-
1	DOOR SEAL REAR LH L70Y (CONSISTENT)	SERVICEABLE	162.02	-
1	DOOR GLASS RUNNER SEAL REAR LH L70Y (CONSISTENT)	SERVICEABLE	229.31	-
1	DOOR WAIST SEAL OUTER REAR LH L70Y (CONSISTENT)	SERVICEABLE	334.69	-
1	DOOR WAIST SEAL INNER REAR LH L70Y (CONSISTENT)	SERVICEABLE	115.64	-
1	FENDER PANEL REAR LH (CONSISTENT)	BENT	3,299.13	3,299.13
1	FENDER PANEL INNER TRIM REAR (CONSISTENT)	SERVICEABLE	671.45	-
1	WHEELARCH REAR LH (CONSISTENT)	SERVICEABLE	543.47	-
1	BUMPER COVER REAR (CONSISTENT)	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR (CONSISTENT)	SERVICEABLE	768.84	-
1	BUMPER BRACKET CTR REAR (CONSISTENT)	SERVICEABLE	113.47	-
1	BUMPER RETAINER LH REAR (CONSISTENT)	SERVICEABLE	44.99	-
1	BUMPER BEAM REAR (CONSISTENT)	TO REPAIR SEE LABOUR	777.52	-
1	BUMPER BEAM BRACKET LH REAR (CONSISTENT)	SERVICEABLE	225.95	-
1	DOOR MIRROR ASSY LH (CONSISTENT)	DENTED / CUT	1,483.40	1,483.40
1	TAILLAMP LH (CONSISTENT)	SERVICEABLE	552.55	-
	LESS 10% DISCOUNT		-3,084.79	-1,284.19
			27,763.07	11,557.71
	SPECIAL NETT ITEMS			
1	SET BUMPER CLIP FRT (SN) (CONSISTENT)	NOT NECESSARY	66.00	-
1	BUMPER BRACKET CLIP FRT LH (SN) (CONSISTENT)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN) (CONSISTENT)	NOT NECESSARY	10.50	-
1	SET BUMPER GRILLE LOWER CLIP (SN) (CONSISTENT)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN) (CONSISTENT)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN) (CONSISTENT)	NOT NECESSARY	20.00	-

Report Ref No. CC4/ASM18006992/Kfb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRAME FULL SUPPORT PANEL STUD (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	SET WHEELARCH CLIP FRT LH (SN) (CONSISTENT)	NOT NECESSARY	30.50	-
1	FRONT DOOR STICKER 'TRANS-CAB' (SN) (CONSISTENT)	NECESSARY	80.00	80.00
1	FRONT DOOR STICKER 'CHASSIS' (SN) (CONSISTENT)	NECESSARY	50.00	15.00
1	REAR DOOR STICKER '6555 3333' (SN) (CONSISTENT)	NECESSARY	80.00	60.00
			518.00	155.00
	LABOUR			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF HEADLAMP PANEL FRT LH, DOOR HINGE UPPER LH L70Y, DOOR HINGE LOWER LH, DOOR LOCK FRT LH, DOOR CATCH FRT LH, DOOR REGULATOR FRT LH, DOOR HINGE UPPER LH L70Y, DOOR HINGE LOWER L70Y, DOOR LOCK REAR LH L70Y, DOOR HANDLE OUTER REAR LH L70Y, DOOR HANDLE CAP REAR LH L70Y, DOOR REGULATOR REAR LH L70Y, DOOR FINISHER BRACKET INNER REAR LH L70Y AND BUMPER BEAM		3,500.00	1,000.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,200.00	1,100.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	120.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.		380.00	100.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF FRONT FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO VACUUM, REPLACE, REFILL AND RECHARGE AIR CONDENSER.	NOT NECESSARY	380.00	-
	TO REPLACE, REFILL AND TOP UP COOLANT FOR RADIATOR.	NOT NECESSARY	170.00	-
	TO VACUUM, REPLACE, REFILL AND RECHARGE AIR INTERCOOLER.	NOT NECESSARY	170.00	-
			8,910.00	2,340.00

Report Ref No. CC4/ASM18006992/Kfb3s2



GRAND TOTAL		37,191.07	14,052.71
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			10,678.00

Report Ref No. CC4/ASM18006992/Kfb3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.