

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9790M

AAD1804-122

Not Authored
18 May 8 11, 2501

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHB 9790M
VF1ABL15AUC273324
RENAULT
LATITUDE
11.4.2018
AXA

PART**LIST**

1	HEADLAMP LH	\$	<i>Sh</i> 1,184.43 <i>X</i>
1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15 <i>✓</i>
1	FENDER PANEL FRT LH	\$	<i>R</i> 783.83 <i>✓</i>
1	WHEELARCH FRT LH	\$	<i>Sh</i> 278.84 <i>X</i>
1	FENDER BRACKET LOWER LH	\$	<i>Sh</i> 15.79 <i>X</i>
1	FENDER INSULATOR LH	\$	<i>Sh</i> 130.84 <i>X</i>
1	DOOR PANEL FRT LH	\$	<i>R</i> 2,844.66 <i>✓</i>
1	DOOR HINGE UPPER LH L70Y	\$	<i>R</i> 261.28 <i>X</i>
1	DOOR HINGE LOWER LH	\$	<i>R</i> 300.55 <i>X</i>
1	DOOR CHECK FRT LH	\$	<i>Sh</i> 194.77 <i>X</i>
1	DOOR CHECK BOLT	\$	<i>Sh</i> 22.69 <i>X</i>
1	DOOR LOCK FRT LH	\$	<i>R</i> 908.75 <i>✓</i>
1	DOOR CATCH FRT LH	\$	<i>R</i> 131.23 <i>X</i>
1	DOOR HANDLE OUTER FRT LH	\$	<i>CM</i> 477.76 <i>✓</i>
1	DOOR HANDLE COVER FRT LH	\$	<i>Sh</i> 13.22 <i>X</i>
1	DOOR HANDLE MODULE FRT LH	\$	<i>Sh</i> 133.60 <i>X</i>
1	DOOR REGULATOR FRT LH	\$	<i>R</i> 505.19 <i>X</i>
1	DOOR REGULATOR MOTOR FRT LH	\$	<i>Sh</i> 796.46 <i>X</i>
1	DOOR REGULATOR GUIDE FRT LH	\$	<i>Sh</i> 120.97 <i>X</i>
1	DOOR PANEL REAR LH L70Y	\$	<i>R</i> 2,844.66 <i>✓</i>
1	DOOR GUIDE REAR LH L70Y	\$	<i>Sh</i> 176.82 <i>✓</i>
1	DOOR GUIDE SCREW	\$	<i>Sh</i> 10.85 <i>✓</i>
1	DOOR HINGE UPPER LH L70Y	\$	<i>R</i> 274.50 <i>✓</i>
1	DOOR HINGE LOWER L70Y	\$	<i>R</i> 300.55 <i>✓</i>
1	DOOR HINGE BOLT	\$	<i>Sh</i> 10.85 <i>✓</i>
1	DOOR HINGE NUT L70Y	\$	<i>Sh</i> 14.60 <i>✓</i>
1	DOOR CHECK REAR LH/RH L70Y	\$	<i>Sh</i> 203.06 <i>✓</i>
1	DOOR CHECK BOLT	\$	<i>Sh</i> 22.69 <i>✓</i>
1	DOOR CHECK NUT	\$	<i>Sh</i> 3.75 <i>✓</i>
1	DOOR LOCK REAR LH L70Y	\$	<i>R</i> 908.75 <i>✓</i>

Trans-cab Auto Services Pte Ltd

AAD1804-122

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9790M

1	DOOR LOCK SCREW L70Y	\$	Sh	6.12	}
1	DOOR CATCH SCREW L70Y	\$	Sh	10.06	
1	DOOR HANDLE OUTER REAR LH L70Y	\$	N	126.49	
1	DOOR HANDLE CAP REAR LH L70Y	\$	N	35.52	
1	DOOR HANDLE SEAL REAR LH L70Y	\$	Sh	7.89	
1	DOOR HANDLE COVER REAR LH L70Y	\$	Sh	13.22	
1	DOOR HANDLE MODULE REAR LH L70Y	\$	Sh	133.60	
1	DOOR REGULATOR REAR LH L70Y	\$	N	1,135.10	
1	DOOR REGULATOR MOTOR REAR LH L70Y	\$	Sh	893.75	
1	DOOR REGULATOR NUT REAR L70Y	\$	Sh	12.43	
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	Sh	6.31	
1	DOOR FINISHER REAR LH L70Y	\$	Sh	423.10	
1	DOOR MOULDING REAR LH L70Y	\$	Sh	176.82	
1	DOOR MOULDING CLIP L70Y	\$	N	5.92	
1	DOOR MOULDING SCREW L70Y	\$	N	6.91	
1	DOOR CASING REAR LH L70Y	\$	Sh	1,509.06	
1	DOOR WATER SHIELD REAR LH L70Y	\$	Sh	30.39	
1	DOOR CASING CLIP	\$	N	12.63	
1	DOOR CASING LIGHT L70Y	\$	Sh	48.74	
1	DOOR FINISHER INNER REAR LH L70Y	\$	Sh	323.44	
1	DOOR FINISHER BRACKET INNER REAR LH L70Y	\$	N	46.97	
1	DOOR FINISHER BRACKET INNER REAR LH L70Y	\$	N	20.33	
1	DOOR FINISHER BRACKET INNER REAR LH L70Y	\$	N	20.33	
1	DOOR FINISHER BRACKET INNER REAR LH L70Y	\$	N	20.33	
1	DOOR GRAB HANDLE REAR LH L70Y	\$	Sh	210.96	
1	DOOR BLIND REAR LH L70Y	\$	Sh	741.80	
1	DOOR WHEATHESTRIIP REAR LH L70Y	\$	Sh	410.66	
1	DOOR SEAL REAR LH L70Y	\$	Sh	162.02	
1	DOOR GLASS RUNNER SEAL REAR LH L70Y	\$	Sh	229.31	
1	DOOR WAIST SEAL OUTER REAR LH L70Y	\$	Sh	334.69	
1	DOOR WAIST SEAL INNER REAR LH L70Y	\$	Sh	115.64	
1	FENDER PANEL REAR LH	\$	B	3,299.13	✓
1	FENDER PANEL INNER TRIM REAR	\$	Sh	671.45	X
1	WHEELARCH REAR LH	\$	Sh	543.47	X
1	BUMPER COVER REAR	\$	Bu	1,108.46	✓
1	BUMPER LOWER REAR	\$	Sh	768.84	X
1	BUMPER BRACKET CTR REAR	\$	Sh	113.47	X
1	BUMEP R RETAINER LH REAR	\$	Sh	44.99	X
1	BUMPER BEAM REAR	\$	N	777.52	X

Trans-cab Auto Services Pte Ltd

AAD1804-122

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9790M

1	BUMPER BEAM BRACKET LH REAR
1	DOOR MIRROR ASSY LH
1	TAILLAMP LH

\$	225.95	X
\$	1,483.40	✓
\$	552.55	X

\$	30,847.89
10% \$	3,084.79
\$	27,763.10

Special Nett

1SET	BUMPER CLIP FRT
1	BUMPER BRACKET CLIP FRT LH
1	BUMPER SUPPORT CLIP FRT LH
1SET	BUMPER GRILLE LOWER CLIP
1SET	FRAME FULL SUPPORT PANEL CLIP
2	FRAME FULL SUPPORT PANEL NUT
2	FRAME FULL SUPPORT PANEL STUD
1SET	WHEELARCH CLIP FRT LH
1	FRONT DOOR STICKER 'Trans-cab'
1	FRONT DOOR STICKER 'Chassis'
1	REAR DOOR STICKER '6555 3333'

\$	nn	66.00	}	X
\$	nn	12.00		
\$	nn	10.50		
\$	nn	69.00		
\$	nn	70.00		
\$	nn	20.00		
\$	nn	30.00		
\$	nn	30.50		
\$	nn	80.00	605A	
\$	nn	50.00	155A	
\$	nn	80.00	805A	

TOTAL	\$	518.00
--------------	----	---------------

TOTAL PARTS	\$	28,281.10
--------------------	----	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	3,500.00	1000
----	----------	------

Putty and spray painting of the affected portion.

\$	3,200.00	1100
----	----------	------

To rust-proofing of the affected areas.

\$	170.00	1200
----	--------	------

Trans-cab Auto Services Pte Ltd

AAD1804-122

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9790M

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	100/
To check steering geometry and computer wheel alignment	\$	220.00	nn X
To transfer of tire, rim and on wheel balancing.	\$	170.00	nn X
To Check Electrical Lighting Concerned.	\$	170.00	20/
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00	nn X
To vacuum, replace, refix and recharge air condenser	\$	380.00	nn X
To replace, refix and top up coolant for radiator	\$	170.00	nn X
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	nn X

TOTAL	\$	8,910.00
--------------	-----------	-----------------

Over All Total	\$	37,191.10
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)

10 DAYS

7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: