



PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

Tel.: 6741 5336 (6 Lines) Fax: 6741 7208

E-mail: progauto@progauto.com.sg

Reg. No.: 201006949C

u

We specialise in repairing, panel beating, spray painting of all kinds of Vehicles and also insurance claims. All enquiries are welcome.

TP INSURER: India International Insurance Pte Ltd (HQ)

PIARA

Singapore

Claimant Insurer: AXA Insurance Pte Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP 0418-5023
Policy No:		Date of Loss:	12/04/2018
Vehicle Reg. No.:	SGB7855K	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	SIM SIOW LIN MABLE		
Make/Model:	NISSAN SUNNY, 1.6 EX (A)	Vehicle Reg. Date:	03/01/2006
Vehicle Colour:	WHITE	Chassis No:	JN1CFAN16Z0517252
Engine No:	QG16393595		
Odometer:	228831 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Description of Accident/Loss	STATEMENT RECORDED BY SOO - PROGRESSIVE AUTOMOTIVE PTE LTD (6741 5336)		
Remarks:	VEHICLE IS NOT IN WORKSHOP		
Present Location:	PROGRESSIVE AUTOMOTIVE PTE LTD (HQ)		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

Acknowledged by Repairer

Signature:

Date:

COST OF CLAIMS

	Amount
Parts	1,296.00
Miscellaneous Items	10.00
Labour	880.00
Paintwork Labour	650.00
Towing	0.00
Gross Total (S\$)	2,836.00
+ GST 7.00% (S\$)	198.52
Nett Amount (S\$)	3,034.52

This claim is handled by: NG PEI WEN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 14 Apr 2018)**Parts:** 143 NISSAN SUNNY 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Progressive Automotive Pte Ltd/SGB7855K/14/04/2018 09:19**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*REAR BUMPER	22/70.1	0.00	0.00
2	10	NA	*REAR BUMPER CLIPS	22	0.00	0.00
3	1	NA	*REAR BUMPER SIDE HOLDER - LH	22	0.00	0.00
4	1	NA	*REAR BUMPER SIDE HOLDER - RH	22	0.00	0.00
5	1	NA	*REAR BUMPER CHROME MOULDING	22	0.00	0.00
6	1	NA	*REAR BUMPER FOAM - NO STOCK	70.1	0.00	0.00
7	1	NA	*REAR BUMPER BRACKET - LH	22	0.00	0.00
8	1	NA	*REAR BUMPER BRACKET - RH	1A	0.00	0.00
9	1	NA	*REAR PANEL	2	0.00	0.00
10	1	NA	*REAR PANEL TOP GARNISH	17	0.00	0.00
Sub Total (S\$)						1,440.00
- Add. Disc. on L,N Items 10.00% (S\$)						144.00
Total Parts (S\$)						1,296.00

F=Franchise part.

Progressive Automotive Pte Ltd/SGB7855K/14/04/2018 09:19. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

451.3
856.17
1686.17
1348

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	<i>AM</i> 10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	<i>400</i> 650.00
<u>Labour Items</u>			
2	TO KNOCK OUT DENTS; CUT/WELD REAR PANEL; REAR BUMPER; REMOVE; REPLACE ACCIDENT PARTS	New	<i>300</i> 700.00
3	TO CHECK WIRING	New	<i>✓</i> 20.00
4	TO TUFF-KOTE	New	<i>11x</i> 50.00
5	TO REMOVE; REFIX REAR GARNISH	New	60.00
6	TO TRANSFER REAR BUMPER SENSOR	New	<i>40</i> 50.00
Gross Labour Cost (S\$)			1,530.00

Progressive Automotive Pte Ltd/SGB7855K/14/04/2018 09:19. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.