

REF: CSI / LAW 18007013 / S1b52

Special Instruction:

Part by Part : \$ 13328.20

Third Parties:

Claimant:

Surveyor: PAL'S APPRAISER

Workshop: SL Automotive

From (Person): Jolene of Gomez & Vasu Date/Time: 7/20/2018
Estimated Cost: _____ Bill to: _____

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SLM 457E Insured: SWW 775H
 at Workshop m/s SL Automotive Tel: 6365 4741
 of 184 Woodlands Ind Park #01-02
 Policy No: _____ Claim No: GV/673/11/17
 Sum Insured: _____ Excess: _____
 Make of Veh: _____ D.O.A. 13-05-2017
 (Client's Record)

H.O.D. Enforce/ment/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: _____ Person Contacted: _____ Vehicle: 247-555-
Date/Time: _____ Confirmed with _____ Final Fig _____, _____ days (Red \$ _____ / _____ %; Original 18 days)
Date/Time: 24/4/18 Submit Final Fig \$ 9951.58, 13 days (Red \$ 3376.62, 25%; Original 18 days)

Date/Time	Action/Instruction
-----------	--------------------

2M 457E - X

STW 754 - X

16042018	Lawfirm informed no more photograph
----------	-------------------------------------

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

\$ 350.00 (before GST)

RECEIVED 24 APR 2018

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date: _____

1) Date/Time 24/4/19 File Pass to typist

3) Date/Time _____ File Pass to _____

5) Date/Time _____ File Pass to _____

2) Date/Time _____ File Return to _____

4) Date/Time _____ File Return to _____

6) Date/Time _____ File Return to _____

Catherine Chong (LKK Auto)

From: Gomez & Vasu <gomezvasu@alchambers.com>
Sent: Thursday, 22 March, 2018 4:14 PM
To: 'Catherine Chong (LKK Auto)'
Cc: assignments@lkkauto.com
Subject: RE: Assessment of damages to car based on photographs (PAPER SURVEY)

Dear Catherine,

Please go ahead.

Thanks

Regards
Jolene

Gomez & Vasu LLC
Advocates & Solicitors
Commissioner for Oaths
A member firm of *Advocates Legal Chambers Group Law Practice*

133 Cecil Street
#13-01A Keck Seng Tower
Singapore 069535
Tel: +65-67336229
Fax: +65-67339661

Website : www.alchambers.com

Gomez & Vasu LLC (UEN 201213031G) is registered in Singapore with limited liability.

CONFIDENTIALITY NOTE: This message contains information which may be confidential and privileged. Unless you are the intended addressee (or authorised to receive for the addressee), any distribution, copying or disclosure of the message or any information contained in the message is strictly prohibited. If you have received the message in error, please do advise us immediately by telephone or fax. Thank you.

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 22 March, 2018 1:36 PM
To: 'Gomez & Vasu'
Cc: assignments@lkkauto.com
Subject: RE: Assessment of damages to car based on photographs (PAPER SURVEY)

Dear Jolene,

Thank you for your email.

We are pleased to submit our Professional Fee Charges is \$350.00 (before GST).

Our surveyor needs approximately two weeks to complete the report.

Best Regards,
Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Gomez & Vasu [mailto:gomezvasu@alchambers.com]

Sent: Wednesday, 21 March, 2018 1:15 PM

To: 'Catherine Chong (LKK Auto)' <admin-d@lkkauto.com>

Subject: Assessment of damages to car based on photographs (PAPER SURVEY)

Dear Catherine,

1. We refer to the above matter.
2. The claimant is claiming against our client for property damage to the car caused in an accident.
3. We attach herewith the relevant documents for your assessment.
4. Kindly advise on the costs and duration to do the paper survey.

Regards
Jolene

Gomez & Vasu LLC
Advocates & Solicitors
Commissioner for Oaths
A member firm of *Advocates Legal Chambers Group Law Practice*

133 Cecil Street
#13-01A Keck Seng Tower
Singapore 069535
Tel: +65-67336229
Fax: +65-67339661
Website : www.alchambers.com

Gomez & Vasu LLC (UEN 201213031G) is registered in Singapore with limited liability.

CONFIDENTIALITY NOTE: This message contains information which may be confidential and privileged. Unless you are the intended addressee (or authorised to receive for the addressee), any distribution, copying or disclosure of the message or any information contained in the message is strictly prohibited. If you have received the message in error, please do advise us immediately by telephone or fax. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/05/2017 11:32
Date Of Accident	13/05/2017 00:10
Exact Location Of Accident	LENTOR AVE TWO YISHUN AVE 2 B4 JUNCTN OF YISHUN A1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM457E
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	ENQUIRIES.SG@GRABCAR.COM
Mobile Phone No	(LOCAL) +65-90977736
Alternative Phone No	OFFICE-65703925
Vehicle Particulars	
Manufacturer	TOYOTA
Model	VIOS 1.5(A)
Exact Purpose for which vehicle was being used at time of accident	HIRING JOB
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	
Cover Note Number	
Driver	
Name of Driver	SAHIR BIN SALIM
NRIC No	S1611791I
Date Of Birth	17/04/1963
Occupation	OUTDOOR
Date Of Driving Pass	07/07/1986
Driving Experience	30 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90683655
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	APT BLK 175 YISHUN AVENUE 7 #09-853 SINGAPORE 760175
Postcode	760175
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION- CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	YISHUN NORTH N.P.C.
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT: T/20170513/2016.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO & AUDIO WITH OWNER.
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJW775H
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	
Details of Witness	
Name	
Phone Number	
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLG5827U
Vehicle Make/Model/Colour	HONDA / VEZEL / WHITE
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	
Details of Witness	
Name	
Phone Number	
Email Address	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICES

1. Please report accurately the details of the accident to your insurer.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the consent of the GIC Records Management Centre established by the General Insurance Association of Singapore (GIAS) for processing and that copies of this report will be made available upon application by interested parties.
7. By the submission of this report to the insurers, you hereby agree to the disclosure of the report to the insurer and to release of the report being made and sole authorized.
8. Consent under the Personal Data Protection Act (PDPA)
 - (a) I understand, acknowledge, agree and consent that
 - (i) My insurer, my workshop and the General Insurance Association of Singapore (GIAS) may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or consented by my insurer (collectively the "Personal Information"), not disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers", and the said insurers shall have the necessary Authority of Singapore and any relevant government agency/authority issued as the police, for the purposes of:
 - (a) investigating, handling and/or dealing with my claim involving the settlement of the claim and any related investigations relating to the claim;
 - (b) investigating the accident and/or my claims;
 - (c) carrying out and/or dealing with my insurances or responding to any enquiries by me;
 - (d) administering my claim (including the making of claims payments, statements, expenses reports or notices to me) which could involve disclosure of certain personal data solely for the purpose of delivery of the same as stated on the external cover of envelopes/other packaging; and/or
 - (e) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) All insurers (who have insured vehicle(s) involved in this accident and the insurers) may have the right to be permitted to collect, use, disclose and/or process my Personal Information for the purpose of the above Purposes; and
 - (c) my Personal Information may also be disclosed by any of the insurers and/or GIAS to their third party who are permitted to assist (including their government agents) which may be based outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature: Date & Time	Driver's Signature & Date & Time (if not the policyholder)	Witnessed by: Reporting Centre Person
---------------------------------------	--	---------------------------------------

Sketch Plan

A: SLH 4516
B: SJW 737H
C: SLG 5827 11

Sketch Plan #2

Describe Circumstances of the Accident:

REFER TO POLICE REPORT T/20170513/2016

Declaration

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature / Date &
Time

Driver's Signature (if driver is not the Policyholder)
Signature / Date & Time

Witnessed by Reporting Centre
Personnel

POLICE REPORT 1



SINGAPORE
POLICE FORCE



T00173513/2016

Police Station Of Origin
Yishun North N.P.C
31 Yishun Central SINGAPORE 765827
Tel No: 1800-8525955

Report No: T00173513/2016

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/05/2017 02:00		Video Report No		Station Diary No 12	
Informant's Particulars					
Name of Informant SAHIR BIN SALIM		Address APT BLK 175 YISHUN AVENUE 7 #05-853 SINGAPORE 760175			
ID Type / ID No. NRIC NO: S16117911		Contact No Home/Office:		Mobile: 90683855	
Nationality SINGAPORE CITIZEN		Email			
Sex: Male	Age 54	Date of Birth 17/04/1963	Type of Informant Driver		
Race Malay	Language English		Institution / School Name		
Occupation GRABCAR DRIVER	Driving Licence Information Class 3		Date of Expiry		

General Information of the Accident

Type of Accident	Injury Hit and Run	Drunk Drive No	Date/Time of Accident 13/05/2017 09:00	Type of Location Straight Road
Location Along Road 1 Traveling Toward Road 2 LENTOR AVENUE YISHUN AVENUE 1 LENTOR TOWARDS THE DIRECTION OF YISHUN				
Weather Clear	Road Surface Dry	Road Speed Limit		
Traffic Flow Dual Carriage Way	Traffic Control Traffic Light - Working	Traffic Volume Moderate		
Type of Collision Between Moving Vehicles - Rear To Rear	Anyone conveyed by ambulance No			

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJW775H	Car				Seriously Damaged	0
SLG8827U	Car	HONDA	VEZEL	White	Seriously Damaged	1
SLM457E	Car	TOYOTA	VIOS	Silver	Seriously Damaged	1

POLICE REPORT 2



SINGAPORE
POLICE FORCE



T/20170513/2016

Police Station Of Origin:
Yishun North N.P.C.
31 Yishun Central SINGAPORE 756827
Tel No. 1800-8529999

2 of 3

Report No. T/20170513/2016

CONTINUATION OF REPORT

Brief Details.

On 13/05/2017 at 0010hrs, I was driving my GrabCar (SLM457E) along Lentor Ave and I have 3 passengers, a couple and one toddler with me. I had stopped at the traffic light junction of Lentor Ave and Yishun Ave 1 as it had indicated red and there is another car (SLG5827U) in front of mine which had also stopped due to the same condition.

While awaiting for the traffic lights to turn green, my vehicle had suddenly jolted forward due to a very strong impact which my vehicle had received from the rear. Due to the force of the impact, my vehicle had also collided onto the vehicle in front of mine.

The driver of the vehicle in front of mine had came out and started to take pictures while the driver of the rear vehicle had stayed in his car (SJW776H) and did not stepped out to exchange particulars with us. The said rear driver whom had caused the 'chain' accident had instead drove off and left the accident scene.

I wish to state that my passengers had alighted and informed me that the ambulance was called. I also wish to state that I do not know which hospital they had gone to but I have the name and contact number of my passenger (Aida) Hp 83833881 who was with his wife and toddler when the accident took place.

POLICE REPORT 3



SINGAPORE
POLICE FORCE



7201705132016

Police Station Of Origin
Yishun North N.P.C
31 Yishun Central SINGAPORE 758621
Tel No. 1800-8579999

Report No. 7201705132016

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan.

IMPORTANT: Please attach a copy of your vehicle's insurance certificate to this report. If you don't have the certificate with you now, please fax a copy to 85474665 stating the report number as reference.

Signature Of Officer Recording The Report
F /

Staff Sgt KENNETH KOH CHIN HAO

Signature Of Informant

Signature Of Interpreter

Not applicable

Date/Time

13/05/2017 02:00

Officer In Charge Of Case

TP / HR1

S/ ABDUL KAREEM BIN ABDUL HAGUE

Contact No. 65476079

Classification Of Case

Authentication Stamp
10162

SL Automotive Pte Ltd

184 Woodlands Industrial Park E5 #01-02 Singapore 757514
Tel : 63654741 / 6365 4742 Fax : 63684750

170543

Vehicle No : SLM 457 E
Make/Model : Toyota Vios
Name : Grab Rentals Pte Ltd
Address : c/o 184 Woodlands Industrial Park E5
#01-02
Singapore 757514
Accident Date : 13-May-2017

Date : 16-Aug-2017

Part By Part repair of SLM 457 E

QTY	ITEM	AMOUNT (\$)
<u>List Items</u>		
1 pc	Bonnet ✓ DT	\$ 892.80
2 pcs	Front headlamps ✓ CRK	\$ 1,184.00
1 pc	Front headlamp top panel X No Photo	\$ 85.00
1 pc	Front bumper ✓ Defor	\$ 479.90
1 pc	Front bumper centre grille ✓ Defor	\$ 270.75
1 pc	Front bumper reinforcement X No Photo	\$ 386.60
1 pc	Front bumper logo ✓ NEC	\$ 128.25
1 pc	Front bumper chrome moulding ✓ NEC	\$ 128.50
2 pcs	Front fenders R	\$ 1,130.00
1 pc	Front top panel X No Photo	\$ 449.39
1 pc	Front support panel garnish X No Photo	\$ 48.55
1 pc	Air cleaner box X No Photo	\$ 375.26
1 pc	Boot lid	\$ 772.50
1 pc	Boot lid lock	\$ 156.80
1 pc	Boot lid logo	\$ 99.70
1 pc	Boot lid outer handle	\$ 240.00
1 pc	Boot lid 'VIOS' emblem	\$ 105.00
1 pc	Boot lid 'E' emblem	\$ 45.00
2 pcs	Rear taillamps	\$ 618.80
1 pc	Rear end panel	\$ 694.70
1 pc	Rear end panel inner garnish	\$ 370.50
1 pc	Rear bumper	\$ 504.90
1 pc	Rear bumper reinforcement	\$ 330.70
		\$ 9,497.60
	Less 25.0%	\$ 2,374.40
		\$ 7,123.20

3084.20
- 25%

1) 2313.15

No Photo.

Special Nett Items

1 pc	Front number plate ✓ DT	\$ 45.00
1 pc	Rear number plate X No Photo	\$ 50.00
1 pc	Rear reverse sensor (1 set) X No Photo	\$ 280.00
		\$ 375.00

2) 45

<u>S/N</u>	<u>Labour</u>		
1	Towing.	\$	80.00 ✓
2	To remove and refit headlamps.	\$	40.00 30
3	To check wiring.	\$	40.00 30
4	To remove and refit inner garnishes.	\$	140.00 30
5	To remove and refit reverse sensor.	\$	80.00 X No Photo
6	To remove and replace air-con system.	\$	120.00 X No Photo
7	To remove and refit radiator system.	\$	60.00 X No Photo
8	Panel beating	\$	2,640.00 600
9	Spray painting	\$	2,420.00 800
10	To underseal	\$	210.00 40
		\$	5,830.00

Total \$ 13,328.20
GST 7% \$ 932.97
Grand-total \$ 14,261.17

3/16/0

Dollar : Fourteen Thousand Two Hundred Sixty One And Cents Seventeen Only

1) Part : \$ 2313.15
2) S/Nett : \$ 45.00
3) Labour : \$ 1610.00

\$ 3968.15 @ 4 days

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Avenue 6 #01-53 AeroBay @ Kaki Bukit Singapore 417883 Tel: 8181 8802 Fax: 6747 1017
Registration No.: 201000268D

Billing Name & Address
Grab Rentals Pte Ltd
c/o 184 Woodlands Industrial Park E5
#01-02
Singapore 757514

Invoice No 05-17043/DY

Date 16 Aug 2017

Vehicle No : SLM 457 E

Model : Toyota Vios

Item	Descriptions	Amount S\$
1	Date of inspection : <u>16 May 2017</u> A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Purchase of films, develop negatives - Storage of negatives - Submission of photographs <u>277</u> copies	
3	Transportation Charges	
4	2nd Inspection & Final Inspection	
	Total	<u>\$ 1102.00</u>
	SDLS : ONE THOUSAND ONE HUNDRED AND TWO ONLY	

Notes :

1. All cheque payment should be "Crossed" and made payable to "Pal's Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



Official Stamp

E & O. E

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Avenue 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883 Tel: 8181 8302 Fax: 6747 0017
Registration No.: 201000268D

Report Reference : TP / 05-17043/DY / 2017
Date of Report : 16 Aug 2017

Grab Rentals Pte Ltd
c/o 184 Woodlands Industrial Park E5
#01-02
Singapore 757514

THIRD PARTY SURVEY ACCIDENT HAPPENED ON 13 May 2017

As per your instruction dated 16 May 2017 with regard to the above matter. We have carried out a physical inspection on the said vehicle SLM 457 E. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SLM 457 E
Model : Toyota Vios
Year / Capacity : 2017/1496
Chassis No : MHFB29F3102007668
Engine No : 2NRX131601
Mileage : -
Colour : Silver

2. TYRES CONDITION

			Size	Made	Balance		Rim
FRONT	O/S	:	195/50 R16	Bridgestone	6.00	mm	Sport
REAR	O/S	:	195/50 R16	Bridgestone	6.00	mm	Sport
FRONT	N/S	:	195/50 R16	Bridgestone	6.00	mm	Sport
REAR	N/S	:	195/50 R16	Bridgestone	6.00	mm	Sport

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Avenue 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883 Tel: 8181 8802 Fax: 6747 1017
Registration No.: 201000268D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear n/s and front n/s portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : SL Automotive Pte Ltd
184 Woodlands Industrial Park E5
#01-02
Singapore 757514

5. Estimated normal period of repair : 18 working days to complete.
6. Enclosed number of photograph : 277 copies.
7. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey was done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.
8. Should you discover any discrepancy in the report, please kindly notify us within 2 weeks, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: SLM 457 E
Report No: TP/ 05-17043/DY / 2017

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Bonnet ✓ DT	Damage	\$ 892.80	\$ 892.80
2	Bonnet hinges X NN	Intact	\$ 106.00	\$
2	Front headlamps ✓ LRV	Damage	\$ 1184.00	\$ 1184.00
1	Front headlamp top panel ✓ Deform.	Damage	\$ 85.00	\$ 85.00
1	Front bumper ✓ Deform	Damage	\$ 479.90	\$ 479.90
1	Front bumper centre grille ✓ Deform	Damage	\$ 270.75	\$ 270.75
1	Front bumper reinforcement ✓ OT	Damage	\$ 386.60	\$ 386.60
1	Front bumper logo ✓ N.F.C	Damage	\$ 128.25	\$ 128.25
1	Front bumper chrome moulding ✓ NEC	Damage	\$ 128.50	\$ 128.50
2	Front fenders R	Damage	\$ 1130.00	\$ 1130.00
1	Front top panel ✓ DT	Damage	\$ 449.39	\$ 449.39
1	Front support panel garnish ✓ Deform.	Damage	\$ 48.55	\$ 48.55
1	Air con condenser X NN	Intact	\$ 962.80	\$
1	Radiator X NN	Intact	\$ 805.00	\$
1	Radiator fan X NN	Intact	\$ 425.60	\$
1	Air cleaner box ✓ DMG	Damage	\$ 375.26	\$ 375.26
1	Boot lid ✓ DT	Damage	\$ 772.50	\$ 772.50
1	Boot lid lock ✓ JM	Damage	\$ 156.80	\$ 156.80
1	Boot lid logo ✓ NEC	Necessary	\$ 99.70	\$ 99.70
1	Boot lid outer handle X NN	Damage	\$ 240.00	\$ 240.00
1	Boot lid 'VIOS' emblem ✓ NEC	Necessary	\$ 105.00	\$ 105.00 80
1	Boot lid 'E' emblem ✓ NEC	Necessary	\$ 45.00	\$ 45.00
2	Rear taillamps ✓ DT	Damage	\$ 618.80	\$ 618.80
1	Rear end panel ✓ DT	Damage	\$ 694.70	\$ 694.70
1	Rear end panel inner garnish ✓ Deform	Damage	\$ 370.50	\$ 370.50 250
1	Rear bumper ✓ Deform	Damage	\$ 504.90	\$ 504.90
2	Rear bumper lamps X NN	Intact	\$ 363.40	\$
1	Rear bumper reinforcement ✓ AT	Damage	\$ 330.70	\$ 330.70
1	Rear spare tyre panel R	Repair	\$ 675.00	\$
1	Rear spare tyre board X NN	Intact	\$ 351.00	\$
2	Rear fenders R	Repair	\$ 1716.80	\$
			\$ 14903.20	\$ 9497.60
	Discount 25.0%		\$ 3725.80	\$ 2374.40
			\$ 11177.40	\$ 7123.20
<u>Special Nett Items</u>				
1	Front number plate ✓ DT	Damage	\$ 50.00	\$ 45.00
1	Rear number plate ✓ DT	Damage	\$ 50.00	\$ 50.00
1	Rear reverse sensor (1 set) ✓ DMG	Damage	\$ 280.00	\$ 280.00 200
			\$ 380.00	\$ 375.00
	Spare Parts Total		\$ 11557.40	\$ 7498.20

Vehicle No: SLM 457 E
Report No: TP/ 05-17043/DY / 2017

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 11557.40	\$ 7498.20
1	To provide towing service charge. ✓	\$ 80.00	\$ 80.00
2	To remove and refit damage parts, test for proper functioning and focus of headlamps. 30	\$ 50.00	\$ 40.00
3	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning. 30	\$ 50.00	\$ 40.00
4	To remove and refit inner trims, inner garnishes, to facilitate the repairs. 100	\$ 150.00	\$ 140.00
5	To remove and refit rear bumper sensor. 30	\$ 150.00	\$ 80.00
6	To remove and replace air-con system, refill gas and test for leakages. 80	\$ 200.00	\$ 120.00
7	To remove and refit radiator system. ✓	\$ 150.00	\$ 60.00
8	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools. 1600	\$ 3000.00	\$ 2640.00
9	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available. 1600	\$ 3000.00	\$ 2420.00
10	To apply undercoating on the repaired and replaced panels for rust protection. 80	\$ 400.00	\$ 210.00
Total		\$ 18787.40	\$ 13328.20

13 days.


Vehicle No: SLM 457 E
Report No: TP/ 05-17043/DY / 2017

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
Total c/f		\$ 18787.40	\$ 13328.20

Recommended PART BY PART Repair Amount of: \$ 13328.20

SDLS: THIRTEEN THOUSAND THREE HUNDRED
TWENTY EIGHT AND CENTS TWENTY ONLY


Qualified Appraiser



Your Ref: GV/673/11/17

Date: 25th April 2018

Our Ref: CS1/LAW18007013/Srbs2

M/s Gomez & Vasu LLC

133 Cecil Street
#13-01A Keck Seng Tower
Singapore 069535
(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SLM 457E
INSURED VEHICLE: SJW 775H
ACCIDENT DATE: 13/05/2017**

We thank you for your instruction on 22/03/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLM 457E from M/s PAL'S Appraiser Pte Ltd.
- b) Singapore Accident Statement of Vehicles SLM 457E.
- c) Colour damaged vehicle photographs of SLM 457E.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLM 457E
Make & Model	: Toyota Vios
Year of Registration	: 2017
Chassis Number	: MHFB29F3102007668
Engine Capacity	: 1496 cc

2. We recommend that the repairs of the entire damage require about 13 (Thirteen) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 457E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	DENTED	892.80	892.80
2	BONNET HINGES	NOT NECESSARY	106.00	-
2	FRONT HEADLAMPS	CRACKED	1,184.00	1,184.00
1	FRONT HEADLAMP TOP PANEL	DEFORMED	85.00	85.00
1	FRONT BUMPER	DEFORMED	479.90	479.90
1	FRONT BUMPER CENTRE GRILLE	DEFORMED	270.75	270.75
1	FRONT BUMPER REINFORCEMENT	BENT	386.60	386.60
1	FRONT BUMPER LOGO	NECESSARY	128.25	128.25
1	FRONT BUMPER CHROME MOULDING	NECESSARY	128.50	128.50
2	FRONT FENDERS	TO REPAIR SEE LABOUR	1,130.00	-
1	FRONT TOP PANEL	BENT	449.39	449.39
1	FRONT SUPPORT PANEL GARNISH	DEFORMED	48.55	48.55
1	AIR CON CONDENSER	NOT NECESSARY	962.80	-
1	RADIATOR	NOT NECESSARY	805.00	-
1	RADIATOR FAN	NOT NECESSARY	425.60	-
1	AIR CLEANER BOX	DAMAGED	375.26	375.26
1	BOOT LID	DENTED	772.50	772.50
1	BOOT LID LOCK	JAMMED	156.80	156.80
1	BOOT LID LOGO	NECESSARY	99.70	99.70
1	BOOT LID OUTER HANDLE	NOT NECESSARY	240.00	-
1	BOOT LID "VIOS" EMBLEM	NECESSARY	105.00	80.00
1	BOOT LID "E" EMBLEM	NECESSARY	45.00	45.00
2	REAR TAILLAMPS	BENT	618.80	618.80
1	REAR END PANEL	DENTED	694.70	694.70
1	REAR END PANEL INNER GARNISH	DEFORMED	370.50	250.00
1	REAR BUMPER	DEFORMED	504.90	504.90
2	REAR BUMPER LAMPS	NOT NECESSARY	363.40	-
1	REAR BUMPER REINFORCEMENT	BENT	330.70	330.70
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	675.00	-

Report Ref No. CS1/LAW18007013/Srbs2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR SPARE TYRE BOARD	NOT NECESSARY	351.00	-
2	REAR FENDERS	TO REPAIR SEE LABOUR	1,716.80	-
	LESS 25% DISCOUNT		-3,725.80	-1,995.52
			11,177.40	5,986.58
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	DENTED	50.00	45.00
1	REAR NUMBER PLATE (SN)	DENTED	50.00	50.00
1	SET REAR REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
			380.00	295.00
	<u>LABOUR</u>			
	TO PROVIDE TOWING SERVICE CHARGE.		80.00	80.00
	TO REMOVE AND REFIT DAMAGE PARTS,TEST FOR PROPER FUNCTIONING AND FOCUS OF HEADLAMPS.		50.00	30.00
	TO REMOVE AND REFIT REAR ELECTRICAL WIRING,REPLACED DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING.		50.00	30.00
	TO REMOVE AND REFIT INNER TRIMS,INNER GARNISHES,TO FACILITATE THE REPAIRS.		150.00	100.00
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		150.00	30.00
	TO REMOVE AND REPLACE AIR-CON SYSTEM,REFILL GAS AND TEST FOR LEAKAGES.		200.00	80.00
	TO REMOVE AND REFIT RADIATOR SYSTEM.		150.00	60.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.INCLUSIVE OF THE REPAIR OF FRONT FENDERS,REAR SPARE TYRE PANEL AND REAR FENDERS.		3,000.00	1,600.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER,CLEANING AND SANDING OF SURFACES,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		3,000.00	1,600.00
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		400.00	60.00
			7,230.00	3,670.00

Report Ref No. CS1/LAW18007013/Srbs2



GRAND TOTAL		18,787.40	9,951.58
RECOMMENDED COST OF REPAIRS			9,951.58

Report Ref No. CS1/LAW18007013/Srbs2

YEANG WAI KEEN
Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.