

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. 7695 04321 756
 Sum Insured: _____ Excess: 400
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 28 days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SCL1570R Yr Regn: 2015 Sept
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Audi Q7 c.c. 2995
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 34824 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WAUZZ24M56D008075
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 285/40 R20
 R: 285/40 R20
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front Rear
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 16/04/8
 Survey held at Premium
 Des. of Damages: Frt / Rear K/O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>OD ALG</u>
<u>17/4</u>	<u>Revert via merimen.</u>
	<u>17/4 - 16:57pm authorize repair by victor</u>
	<u>18/4 - 8:30am - inform premium authorize repair</u>
	<u>mv: 245K</u>
	<u>RV: 120.6K</u>
	<u>Nett: 124.4K</u>
	<u>RECEIVED 25 JAN 2010</u>
	<u>SCL 1570R - C03 / A1618007017 / Atber</u>
	<u>DD: 06/11/6</u>
	<u>Pending Repair days, Part by Part \$43,135.52</u>

Date/Time, File Pass to? ☐ : Preli. Report1) 25/1 Typist ☒ : Final Report

Date/Time, File Return to?

2)

Report Format: OD
 Lump Sum / (B): \$ 43,135.52

Days Of Repair: 28Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL:

20010210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18007017/Atb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 16-04-2018



Code : AIG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SCL 1570R
Policy No.	2100428877	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	16/04/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	12/04/2018	Inspection Date	16/04/2018
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 SINGAPORE 408699		

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

Denise Tay (LKKAUTO)

From: Koh, Victor-CK <Victor-CK.Koh@aig.com>
Sent: Monday, 30 April 2018 2:35 PM
To: SUR
Cc: Fong, Andy-SY
Subject: SCL1570R/ OD / 7675043217SG

Hi LKK,

Kindly advise on how does replacement of LH/RH front fender, LH A pillar, LH rear door, repair LH front door require 12 days of labour (500/day)?

Thanks & Regards

Victor Koh
AIG
Claims Technical Controller
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120
Tel +65 6419 1785 | Fax +65 68357416
Victor-ck.koh@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

View Received Message

This mail is associated with :

***SCL1570R (76750432175G)**

OD

Apr 12 2018 11:00AM

[NG WEI PING, ELEANOR]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 17/04/2018 16:57 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$29373.00) - SCL1570R - Claim Handler: Tr, Tinesh

Approved:29373.00:What is Rear wheel cover LH, Rear side door wheel LH/RH? Kindly reinspect and indicate photos. Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

Rear wheel covers : Rear Fenders wheel Arc Protector
(photos 20-22)
Rear Side Door Wheel : Rear Door wheel Arc Protector
(photo 19)

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 18 April 2018 8:20 AM
To: Claims; SUR
Subject: RE: SCL 1570 R Own Damage Claims

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SCL 1570R (Excess \$400/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [mailto:claims@premiumauto.com.sg]
Sent: Monday, 16 April 2018 4:27 PM
To: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: RE: SCL 1570 R Own Damage Claims

FYI

Thank you.

Best Regards,

Tony Foong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	Q294E
Vehicle Details	
Vehicle No.:	SCL1570R
Vehicle to be Exported:	Yes
Intended De-registration Date:	16 Apr 2018
Vehicle Make:	AUDI
Vehicle Model:	Q7 3.0 TFSI QU (333 BHP)
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	CRE048791
Chassis No.:	WAUZZZ4M5GD008075
Maximum Power Output:	245.0 kW (328 bhp)
Open Market Value:	\$70,642.00
Original Registration Date:	29 Sep 2015
First Registration Date:	29 Sep 2015
Transfer Count:	0
Actual ARF Paid:	\$99,156.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Sep 2025
PARF Rebate Amount:	\$74,367.00
Intended COE Rebate Details	
COE Expiry Date:	28 Sep 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$62,101.00
COE Rebate Amount:	\$46,265.00
Total Rebate Amount:	\$120,632.00

The information contained herein is correct as at 16 Apr 2018

OK

- [Liverpool 2017/18: YNWA with Klopp](#)
- [GrabHitch/RIDE-car pooling services](#)
- [What Did You Makan Today Part 3!](#)

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)

New 5 Years Coe Renewal Toyota Altis 1.8A



\$2880 Downpayment Monthly
From \$688 Onwards. Lowest
Interest @ 3.58% By Go Finance.
GV Credit Pte Ltd [Search](#)

KA-HUP

**VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND**

HOTLINE: 6741 9997 [view our cars](#)

Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

2 vehicles

Audi Q7

Advanced Search

	Make	Model	Price	Deprecation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Audi Q7		Any	Any	2016	Any	Any	Any	Available
	Audi Q7 3.0A TFSI Quattro		\$265,000	\$26,870 /yr	21-Apr-2016	2,995 cc	12,900 km	SUV	Available
Audi Q7 3.0 Litre, Elegant Black, Powerful Drive With 7 Seater SUV, Agent Unit, 328 Bhp, With High Specifications, One Owner Only, Low Mileage Done, Very Well Maintained.									
Prime Motor & Leasing									
Posted: 06-Apr-2018 Tags: 2016 Audi Q7, Audi Q7, Audi, Q7, Used Audi									
	Audi Q7 2.0A TFSI Quattro		\$228,888	\$23,410 /yr	24-May-2016	1,984 cc	42,000 km	SUV	Available
Modern Graphite Grey Exterior And Black Interior, 5 Years Warranty! Flexible Finance Package And Trade In, Please SMS/Call Now For Viewing Appointment Or More Details. Consignment Unit.									
Posted: 10-Apr-2018 Tags: 2016 Audi Q7, Audi Q7, Audi, Q7, Used Audi									

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Deprecation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	-------------	----------	---------	---------	----------	--------

For old advertisements, view [Expired ads](#)

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Audi Q7, Audi Q7 Singapore, used Audi Q7 Singapore, used Audi Q7, used vehicles Singapore or even buy used Audi Q7 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com
[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.

[Compare](#)

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tr, Tinesh

Date: 17 Apr 2018

Preliminary Advice

Vehicle No	: SCL1570R	Accident Date	: 12/04/2018
Make	: AUDI Q7	Policy No.	: 2100428877-02
Assignment Date	: 16/04/2018	Excess	: S\$400.00
Date of Inspection	: 16/04/2018	Est. Duration of Repair	: 16.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s, n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	56,695.00
Revised Amount	:S\$	29,373.00
Check Items (Estimated)	:S\$	1,615.00
Total	:S\$	30,988.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	245,000.00
COE / PARF Rebate	:S\$	120,614.00
Salvage Value	:S\$	
Margin for Repair	:S\$	124,386.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0294E
Vehicle Details	
Vehicle No.:	SCL1570R
Vehicle to be Exported:	No
Intended De-registration Date:	17 Apr 2018
Vehicle Make:	AUDI
Vehicle Model:	Q7 3.0 TFSI QU (333 BHP)
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	CRE048791
Chassis No.:	WAUZZZ4M5GD008075
Maximum Power Output:	245.0 kW (328 bhp)
Open Market Value:	\$70,642.00
Original Registration Date:	29 Sep 2015
First Registration Date:	29 Sep 2015
Transfer Count:	0
Actual ARF Paid:	\$99,156.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Sep 2025
PARF Rebate Amount:	\$74,367.00
Intended COE Rebate Details	
COE Expiry Date:	28 Sep 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$62,101.00
COE Rebate Amount:	\$46,247.00
Total Rebate Amount:	\$120,614.00

The information contained herein is correct as at 17 Apr 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/04/2018 18:51
Date Of Accident	12/04/2018 11:00
Exact Location Of Accident	IN BETWEEN BLOCK 37 & 39 KEPPEL ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCL1570R
Insured/Policyholder	
Name Of Registered Owner	NG WEI PING, ELEANOR
NRIC No	S7540294E
Email Address	ELEANOR_NWP@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-96461237
Alternative Phone No	HOME-96461237

Vehicle Particulars

Manufacturer	AUDI
Model	Q7 3.0 TFSI QU
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100428877-02
Cover Note Number	-

Driver

Name of Driver	NG WEI PING, ELEANOR
NRIC No	S7540294E
Date Of Birth	11/11/1975
Occupation	INDOOR
Date Of Driving Pass	28/05/1994
Driving Experience	23 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96461237
Fax Number	
Contact Number	HOME-96461237
E-Mail Address	ELEANOR_NWP@HOTMAIL.COM

Address	7 JALAN USAHA
Postcode	537147
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO THE ATTACHED STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YL1675L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKT7665A
Vehicle Make/Model/Colour	VOLVO

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SKJ4197G

Vehicle Make/Model/Colour

TOYOTA

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number

SJM1748H

Vehicle Make/Model/Colour

HONDA

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 01/11/18

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: Tony Fong
NRIC/IN No: G2046978

Sketch Plan #2

SKETCH PLAN



A: YL 1675L

B: SKT 766SA

C: SKJ 4197G

D: SCL 1570R

E: SJM 1748H

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 12th April 2018, around 11 am, my staff called the office from the carpark to inform me that my car had been hit by a lorry. Upon reaching the carpark, I saw that a lorry had collided into a white Volvo, which then hit a Toyota Estima which had hit my car. My car also shifted upon impact and hit the Honda on my right side.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
Policyholder's Signature
Date & Time: 12/4/18

Driver's Signature
(if driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: Tony Fong
NRIC/FIN No: G244167X

Accident Photo



14-00516 OF SINGAPORE 001150245K

License Number: **S7540294E**

Name: **NG WAI PING ELEANOR
(WU HUIBING ELEANOR)**

Birth Date: **11 Nov 1975**

Issue Date: **04 Mar 2004**

001150245K

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S7540294E**



Name

**NG WAI PING ELEANOR
(WU HUIBING ELEANOR)**

吴慧冰

Race

CHINESE

Date of birth

11-11-1975

Country of birth

SINGAPORE

Sex

F

S7540294E

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

**Class 2 Motor Cars and Motor Tractors the weight of
which unladen does not exceed 2500 kilograms**

20 May 1994

NP 428A



License No: **S7540294E**



NRIC No. S7540294E



Date of issue

25-08-2006

**7 JALAN USAHA
SINGAPORE 537147**

NRIC No: S7540294E

Date: 13/07/2010

No: 0597931

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : NG WAI PING ELEANOR (WU HUIBING ELEANOR)
 Period of Insurance : 29 Sep 2017 To 28 Sep 2018
 Engine No. : CRE048791
 Chassis No. : WAUZZZ4M5GD008075

Vehicle No. : SCL1570R
 Policy No. : 2100428577-02
 Endorsement No. :
 Issued Date : 25 Aug 2017

ABOUT THE COVER

Make/Model : AUDI Q7 3.0 TFSI QU (272BHP&333BHP)
 Engine Capacity/Tonnage : 2.995.00 CC Sum Insured : Market Value
 Driver Restriction : NA Off Peak Car : No
 First Year of Registration : 2015
 Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.
 You have to pay an additional sum of \$2,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered inoperative by Section 6 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 185) and Section 90 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$1400 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

NG WAI PING ELEANOR (WU HUIBING ELEANOR) - \$1400 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408698 63062323

For other Approved Reporting Centres/Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 5200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 185), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125210

PREMIUM LEASING - VI

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159936

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

M. J. J. J.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

500/GUH

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- 24-hour assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and witnesses.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and witnesses, if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not speak or discuss fault or blame with the other parties.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Valid Summons/Correspondence from the party(ies) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within 3 working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the original insurance policy and schedule issued by AIG, a copy of the Accident Report from Audi Customer Service Centre must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Premium Automobiles Pte. Ltd.

Activation Hotline: 64741223

55 Ubi Road 1 Singapore 408699

Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 1pm

*The Rental Car Company's Terms & Conditions apply (i.e. refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is IMPORTANT and MUST be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0450/2018/GW
Date : 14-Apr-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Ng Wei Ping, Eleanor
Address : 7 Jalan Usaha
Singapore 537147
Telephone : (HP) 96461237
Type of Claim : Own Damage Claims
Policy No. : 2100428877-02
Vehicle No : **SCL 1570 R**
Model Code : Audi Q7 3.0 TFSI Qu
Model / Year : Sep-15
Engine No : CRE 048791
Chassis No : WAUZZZ4M5GD008075
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 12-Apr-18
Place of Accident : In between Block 37&39 Keppel Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SCL 1570 R.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	✓
2	To remove and transfer both lhs front and rear door's, and rhs front door's multi lock system and power window devices.	S/N \$ 1,080.00 ✓	720 ✓
3	To dismantle front bumper, both front fenders, lhs front and rear doors, and rhs front door. Inspect lhs A-pillar for damage. Renew damaged panels, align to position. Reinstall all parts removed.	\$ 6,400.00 ✓	3600 ✓ $6 \times 600 = 3600$
4	To respray front bumper, both front fenders, all four doors, handles, door covers, wheel arch trims, and both rear fenders.	\$ 10,800.00 ✓	5400 ✓
5	To renew all rims with tyres. Carry out wheel alignment.	S/N \$ 400.00 ✓	✓
6	To carry out diagnostic check.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 19,352.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCL 1570 R.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Repair</i>	S	2,252.00 X
2	FRONT BUMPER AIR GUIDE <i>Green</i>	2 S	114.00 X
3	FRONT BUMPER AIR GUIDE GRILLE-LH/RH	2 S	520.00 X
4	FRONT BUMPER END CAP-RH <i>new</i>	S	29.00 X
5	FRONT WHEEL COVER-LH/RH <i>new</i>	2 S	1,004.00 ✓ 902.40
6	FRONT FENDER-LH/RH <i>Dented.</i>	2 S	2,844.00 ✓ 2275.20
7	FRONT FENDER BRACKET-LH/RH <i>LH Bent</i>	2 S	112.00 56 42.32
8	FRONT FENDER CENTRE BRACKET-LH/RH <i>LH Bent</i>	2 S	112.00 56 49.64
9	FRONT FENDER BRACE-LH/RH <i>Not All</i>	2 S	179.00 ?
10	FRONT FENDER CLOSING ELEMENT-LH/RH <i>new</i>	2 S	58.00 X
11	INSCRIPTION "S-LINE" <i>new</i>	2 S	215.00 ✓ 172
12	FRONT DOOR-LH <i>Dented.</i>	S	3,274.00 ✓ 269.20
13	FRONT DOOR OUTER DOOR SEAL-LH <i>new</i>	S	218.00 ✓ 174
14	BONDING AGENT <i>Not All</i>	S	43.00 ? 34.6
15	CLEANING SOLUTION <i>Not All</i>	S	64.00 ?
16	GROMMET <i>Not All</i>	8 S	18.00 ? } X
17	FRONT DOOR CATCH-LH <i>Not All</i>	S	112.00 X
18	FRONT DOOR HANDLE-LH <i>Repair</i>	S	325.00 X
19	FRONT WINDOW REGULATOR WITHOUT MOTOR-LH <i>new</i>	S	249.00 X
20	FRONT DOOR COVER-LH <i>new</i>	S	608.00 ✓ 486
SUB-TOTAL SPARE PARTS			\$ 12,350.00

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCL 1570 R.

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
21	FRONT EXTERIOR MIRROR MOUNTIN-LH <i>RH LH NOT ALL</i>	S	1,608.00 <i>1286 70</i>
22	FRONT MIRROR CAP-LH <i>2 new</i>	S	159.00 <i>+</i>
23	TURN SIGNAL INDICATOR-LH	S	143.00 <i>+</i>
24	FRONT DOOR-RH	S	3,274.00 <i>+</i>
25	FRONT DOOR OUTER DOOR SEAL-RH	S	218.00 <i>+</i>
26	BONDING AGENT	S	43.00 <i>+</i>
27	CLEANING SOLUTION	S	64.00 <i>+</i>
28	GROMMET	S	18.00 <i>+</i>
29	FRONT DOOR CATCH-RH	S	112.00 <i>+</i>
30	FRONT DOOR COVER-RH	S	608.00 <i>+</i>
31	REAR DOOR-LH <i>Dented</i>	S	3,274.00 <i>✓ 3619 20</i>
32	REAR DOOR OUTER DOOR SEAL-LH <i>new</i>	S	218.00 <i>✓ 179</i>
33	BONDING AGENT <i>new</i>	S	43.00 <i>?</i>
34	CLEANING SOLUTION <i>new</i>	S	64.00 <i>?</i>
35	GROMMET <i>new</i>	8 S	16.00 <i>?</i>
36	REAR DOOR CATCH-LH <i>new</i>	S	92.00 <i>+</i>
37	SILL PANEL SEAL <i>new</i>	S	223.00 <i>?</i>
38	REAR DOOR OUTER SEAL-LH <i>new</i>	S	165.00 <i>?</i>
39	REAR DOOR HANDLE-LH <i>new</i>	S	325.00 <i>+</i>
SUB-TOTAL SPARE PARTS			\$ 10,667.00

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCL 1570 R.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
40	REAR DOOR COVER <i>new</i>	\$ 514.00 ✓	411.70
41	REAR WHEEL COVE-LH <i>new</i>	\$ 172.00 ✓	137.60
42	REAR SIDE DOOR WHEEL-LH <i>cut</i>	\$ 331.00 ✓	264.40
43	FRONT EXTERIOR MIRROR-RH <i>cut in</i>	\$ 1,608.00 ✓	1286.40
44	FRONT MIRROR CAP-RH	\$ 159.00 +	
45	FRONT TURN SIGNAL-RH <i>new</i>	\$ 143.00 X	
46	REAR WHEEL COVER-RH	\$ 172.00 +	
47	REAR SIDE DOOR WHEEL-RH <i>cut</i>	\$ 331.00 ✓	264.40
48	ALUMINIUM RIM <i>3 piece cut</i>	1286 IPC 4 \$ 5,144.00	3858 (3 piece) 3086.4
49	RADIAL TYRE <i>new</i>	4 \$ 4,952.00 +	
50	SUNDIRES <i>new</i>	\$ 800.00 ?	170.96
TOTAL SPARE PARTS		:	\$ 37,343.00
TOTAL LABOUR CHARGES		:	\$ 19,352.00
GRANDTOTAL		:	\$ 56,695.00

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

74578.06

17603

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian Lim

Surveyed Date

: 16/04/18

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: not Authorised, 14-16 days

LKK Auto Consultants hereby notify the Repaired of the following:

- To resurvey before/after spray painting
- To display damaged parts/doors/hood
- Parts prices are subject to contents
- Third party survey is not without Evidence basis
- No illegal modifications are allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Rasul
PA
25/04/18

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0450/2018/GW 25-Apr-18 CHANG 1 of 1 SCL 1570 R Audi Q7 3.0 TFSI QU
Quantity	Description	Unit Price	Amount
Labours			
1	To dislodge and reinstall lhs A-pillar and lhs front door harness. S/N	\$ 1,200.00	✓
2	To remove and reinstall lhs front seat assy, ABCD pillar trims, sill trims, carpets, electrical components and fuse trays. S/N	\$ 1,800.00	✓
3	To remove and reinstall center console and dashboard assy for A-pillar renewal. S/N	\$ 2,800.00	✓
4	To cut out and weld lhs A-pillar, repair inner A-pillar. Renew door hinges. Reinstall all parts removed.	\$ 4,800.00	2400.
5	To respray lhs A-pillar, door entrance and lhs sill panel.	\$ 1,900.00	1200
TOTAL LABOURS :		\$ 12,500.00	
Parts			
1	A-PILLAR PANEL - LH <i>checked</i>	\$ 4,002.00	✓ 3201.60
2	A-PILLAR PLATE - LH INNER <i>Agree with</i>	\$ 7.00	* 5.20
3	FRONT DOOR HINGE - LH UPPER <i>3 bent</i>	\$ 80.00	✓ 63.12
4	FRONT DOOR HINGE - LH LOWER	\$ 80.00	✓ 64.00
5	2 PK FILL FOAM	\$ 118.00	✓ 94.00
6	WELD SCREW	\$ 35.00	✓ 28.00
7	ALUMINIUM POWDER	\$ 507.00	✓ 405.60
8	HARDENER	\$ 186.00	✓ 148.80
9	ACRYLIC SEALER	\$ 180.00	✓ 180
10	CAVITY WAX	\$ 140.00	✓ 140
11	STONE CHIP	\$ 180.00	✓ 180
TOTAL PARTS :		\$ 5,515.00	
GRAND TOTAL :		\$ 18,015.00	

For Premium Automobiles Pte Ltd

Adrian Ling
AS

[Signature]

 Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0450/2018/GW 7-May-18 CHANG 1 of 1 SCL 1570 R Audi Q7 3.0 TFSI QU	
Quantity	Description		Unit Price	Amount
<u>Labours</u>				
1	To remove and renew front windscreen glass	s/n	\$ 500.00	\$ 500.00
2	To place vehicle on Car O Liner for replacement of A pillar	s/n	\$ 1,200.00	\$ 1,200.00
TOTAL LABOURS :			\$ 1,700.00	\$ 1,700.00
<u>Parts</u>				
1	Front windscreen	s/n	\$ 1,492.00	\$ 1,193.60
2	Front windscreen sealant		\$ 200.00	\$ 200.00
3	Front windscreen primer		\$ 18.20	\$ 14.56
4	Front windscreen gel - foil		\$ 126.50	\$ 101.20
5	Aluminium 2k adhesive		\$ 199.20	\$ 159.36
Total Parts			\$ 2,035.90	\$ 1,668.72
Total Labour			\$ 1,700.00	\$ 1,700.00
Grand Total			\$ 3,735.90	\$ 3,368.72



For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0450/2018/GW
Date : 14-Apr-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

Your recommended Max 16 days

**We took 36 days exclude 2 PH
and 6 Sundays - jb - 27 Aug 18**

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Ng Wei Ping, Eleanor
Address : 7 Jalan Usaha
Singapore 537147
Telephone : (HP) 96461237
Type of Claim : Own Damage Claims
Policy No. : 2100428877-02
Vehicle No : **SCL 1570 R**
Model Code : Audi Q7 3.0 TFSI Qu
Model / Year : Sep-15
Engine No : CRE 048791
Chassis No : WAUZZZ4M5GD008075
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 12-Apr-18
Place of Accident : In between Block 37&39 Keppel Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SCL 1570 R.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$	480.00	\$ 480.00
2	To remove and transfer both lhs front and rear door's, and rhs front door's multi lock system and power window devices.	S/N \$	1,080.00	\$ 720.00
3	To dismantle front bumper, both front fenders, lhs front and rear doors, and rhs front door. Inspect lhs A-pillar for damage. Renew damaged panels, align to position. Reinstall all parts removed.	\$	6,400.00	\$ 3,600.00
4	To respray front bumper, both front fenders, all four doors, handles, door covers, wheel arch trims, and both rear fenders.	\$	10,800.00	\$ 5,400.00
5	To renew all rims with tyres. Carry out wheel alignment.	S/N \$	400.00	\$ 400.00
6	Added labour charges - see attached Dtd 25 Apr 18	\$	12,500.00	\$ 9,400.00
6a	Added labour charges - see attached Dtd 7 May 18	\$	1,700.00	\$ 1,700.00
7	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 33,552.00</u>	<u>\$ 21,892.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCL 1570 R.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 2,252.00	
2	FRONT BUMPER AIR GUIDE	2 \$ 114.00	
3	FRONT BUMPER AIR GUIDE GRILLE-LH/RH	2 \$ 520.00	
4	FRONT BUMPER END CAP-RH	\$ 29.00	
5	FRONT WHEEL COVER-LH/RH	2 \$ 1,004.00	\$ 802.40
6	FRONT FENDER-LH/RH	2 \$ 2,844.00	\$ 2,275.20
7	FRONT FENDER BRACKET-LH/RH	2 \$ 112.00	\$ 42.32
8	FRONT FENDER CENTRE BRACKET-LH/RH	2 \$ 112.00	\$ 44.64
9	FRONT FENDER BRACE -LH/RH	2 \$ 179.00	
10	FRONT FENDER CLOSING ELEMENT-LH/RH	2 \$ 58.00	
11	INSCRIPTION " S-LINE "	2 \$ 215.00	\$ 172.00
12	FRONT DOOR-LH	\$ 3,274.00	\$ 2,619.20
13	FRONT DOOR OUTER DOOR SEAL-LH	\$ 218.00	\$ 174.00
14	BONDING AGENT	\$ 43.00	\$ 34.16
15	CLEANING SOLUTION	\$ 64.00	
16	GROMMET	8 \$ 18.00	
17	FRONT DOOR CATCH-LH	\$ 112.00	
18	FRONT DOOR HANDLE-LH	\$ 325.00	
19	FRONT WINDOW REGULATOR WITHOUT MOTOR-LH	\$ 249.00	
20	FRONT DOOR COVER-LH	\$ 608.00	\$ 486.00
SUB-TOTAL SPARE PARTS		\$ 12,350.00	\$ 6,649.92

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCL 1570 R.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
			\$ 6,649.92
21	FRONT EXTERIOR MIRROR MOUNTIN-LH	\$ 1,608.00	\$ 1,286.40
22	FRONT MIRROR CAP-LH	\$ 159.00	
23	TURN SIGNAL INDICATOR-LH	\$ 143.00	
24	FRONT DOOR-RH	\$ 3,274.00	
25	FRONT DOOR OUTER DOOR SEAL-RH	\$ 218.00	
26	BONDING AGENT	\$ 43.00	
27	CLEANING SOLUTION	\$ 64.00	
28	GROMMET	\$ 18.00	
29	FRONT DOOR CATCH-RH	\$ 112.00	
30	FRONT DOOR COVER-RH	\$ 608.00	
31	REAR DOOR-LH	\$ 3,274.00	\$ 2,619.20
32	REAR DOOR OUTER DOOR SEAL-LH	\$ 218.00	\$ 174.00
33	BONDING AGENT	\$ 43.00	
34	CLEANING SOLUTION	\$ 64.00	
35	GROMMET	8 \$ 16.00	
36	REAR DOOR CATCH-LH	\$ 92.00	
37	SILL PANEL SEAL	\$ 223.00	
38	REAR DOOR OUTER SEAL-LH	\$ 165.00	
39	REAR DIIR HANDLE-LH	\$ 325.00	
SUB-TOTAL SPARE PARTS		\$ 10,667.00	\$ 10,729.52

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Material List for Accident Vehicle Regn No. SCL 1570 R.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0450/2018/GW 25-Apr-18 CHANG 1 of 1 SCL 1570 R Audi Q7 3.0 TFSI QU	
Quantity	Description		Unit Price	Amount
Labours				
1	To dislodge and reinstall lhs A-pillar and lhs front door harness.	S/N	\$ 1,200.00	\$ 1,200.00
2	To remove and reinstall lhs front seat assy, ABCD pillar trims, sill trims, carpets, electrical components and fuse trays.	S/N	\$ 1,800.00	\$ 1,800.00
3	To remove and reinstall center console and dashboard assy for A-pillar renewal.	S/N	\$ 2,800.00	\$ 2,800.00
4	To cut out and weld lhs A-pillar, repair inner A-pillar. Renew door hinges. Reinstall all parts removed.		\$ 4,800.00	\$ 2,400.00
5	To respray lhs A-pillar, door entrance and lhs sill panel.		\$ 1,900.00	\$ 1,200.00
TOTAL LABOURS :			\$ 12,500.00	\$ 9,400.00
Parts				
1	A-PILLAR PANEL - LH		\$ 4,002.00	\$ 3,201.60
2	A-PILLAR PLATE - LH INNER		\$ 7.00	\$ 5.20
3	FRONT DOOR HINGE - LH UPPER		\$ 80.00	\$ 63.12
4	FRONT DOOR HINGE - LH LOWER		\$ 80.00	\$ 64.00
5	2 PK FILL FOAM		\$ 118.00	\$ 94.00
6	WELD SCREW		\$ 35.00	\$ 28.00
7	ALUMINIUM POWDER		\$ 507.00	\$ 405.60
8	HARDENER		\$ 186.00	\$ 148.80
9	ACRYLIC SEALER	S/N	\$ 180.00	\$ 180.00
10	CAVITY WAX	S/N	\$ 140.00	\$ 140.00
11	STONE CHIP	S/N	\$ 180.00	\$ 180.00
TOTAL PARTS :			\$ 5,515.00	\$ 4,510.32
GRAND TOTAL :			\$ 18,015.00	\$ 13,910.32

For Premium Automobiles Pte Ltd

 Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SCL 1570 R

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0450/2018/MAS

18 Jan 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SCL 1570 R, Audi Q7 3.0 TFSI Qu

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SCL 1570 R**, claimant, **Ms. Ng Wai Ping Eleanor**, please find the related document per attached.

1. A copy of the Original invoice no. 85013361 – S\$46,155.01
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SCL 1570 R



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6346 2223
Main Telefax: 6471 3723

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6346 2223
Telefax: 6475 1033

Ubi Service Centre
95 Ubi Road 1
Singapore 408629
Telephone: 6346 2223

Customer Service
Service Appointment
24-hour breakdown service
Email: customer.care@premiumauto.com.sg
6346 2223
9828 1212

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 1 11:32

RIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT RIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013361 Date: 08/01/2019 Order: SCL1570R Term: 30	Account: 00006 (T 0) RIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT RIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No.: SCL1570R (V 27429) Regn Date: 29/09/2015 Mileage: 41252 WIP No.: 62162
Model: 07 3.0 TFSI QU (333 bhp) 4MB0A Chassis: WAUZZZ4MS60000075 Engine: CRE 048791 Dept: U
VSB No.:
You have been assisted by :- UA-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	480.00	1.00	480.00
S	BODYWORK	M: TO REMOVE AND TRANSFER BOTH LHS FRONT AND REAR DOOR'S, MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES	720.00	1.00	720.00
S	BODYWORK	M: TO DISMANTLE FRONT BUMPER, BOTH FRONT FENDERS, RHS FRONT DOOR, LHS FRONT DOOR AND REAR DOOR. INSPECT LHS A-PILLAR FOR DAMAGE. RENEW DAMAGED PANELS, ALIGN TO POSITION. REINSTALL ALL PARTS REMOVED	3600.00	1.00	3,600.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, ALL FOUR DOORS, WHEEL ARCH TRIMS AND BOTH	5400.00	1.00	5,400.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6386 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6386 2223
Telefax: 6471 3733

UBI Service Centre
55 Ubi Road 1
Singapore 408722
Telephone: 6386 2223

Customer Service
Service Appointment
Hour Breakdown Service
Email: customer.care@premiumauto.com.sg

6386 2223
9628 1233

Page 2 11:32

INS TAX INVOICE
Company Reg. No.: 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013361 Date : 08/01/2019 Order : SCL1570R Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SCL1570R (V 27429) Regn Date: 29/09/2015 Mileage: 41252 WIP No.: 62162
Model: Q7 3.0 TFSI QU (333 bhp) 4MBA Chassis: WAUZZZ4MS6D000075 Engine: CRE 048791 Dept: U
VSB No.:
You have been assisted by :- UA-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	REAR FENDERS. M:	400.00	1.00	400.00
S	BODYWORK	TO RENEW RIMS AND CARRY OUT WHEEL ALIGNMENT M:	192.00	1.00	192.00
S	BODYWORK	TO CARRY OUT DIAGNOSTIC CHECK M:	1200.00	1.00	1,200.00
S	BODYWORK	TO DISLODGE AND REINSTALL LHS A-PILLAR AND LHS FRONT DOOR HARNES M:	1800.00	1.00	1,800.00
S	BODYWORK	TO REMOVE AND REINSTALL LHS FRONT SEAT ASSY, ABCD PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRICAL COMPONENTS AND FUSE TRAYS. M:	2800.00	1.00	2,800.00
S	BODYWORK	TO REMOVE AND REINSTALL CENTRE CONSOLE AND DASHBOARD ASSY FOR A-PILLAR RENEWAL M:	2400.00	1.00	2,400.00
S	BODYWORK	TO CUT OUT AND WELD LHS A-PILLAR, REPAIR INNER A-PILLAR, RENEW DOOR HINGES, REINSTALL			
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6346 2323
Main Telefax: 6471 7733

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6346 2323
Telefax: 6471 7733

Ubi Service Centre
55 Ubi Road 1
Singapore 408861
Telephone: 6387 7333

Customer Service
Service Appointment: 6346 2323
Hour Breakdown Service: 6426 1233
Email: customer.care@premiumaudis.com.sg

INS TAX INVOICE

Company Reg. No.: 199902271W

GST Reg. No. 199902271W

Page 3 11:32

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013361 Date: 08/01/2019 Order: SCL1570R Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No.: SCL1570R (U 27429) Regn Date: 29/09/2015 Mileage: 41252 WIP No.: 62162

Model: 07 3.0 TFSI QU (333 bhp) 4MB0A Chassis: WAUZZZ4M5G000075 Engine: CRE 048791 Dept: U

USB No.:

You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	ALL PARTS REMOVED M: TO RESPRAY LHS A-PILLAR, DOOR ENTRANCE AND LHS SILL PANEL	1200.00	1.00	1,200.00
S	BODYWORK	M: TO REMOVE AND RENEW FRONT WINDSCREEN GLASS	500.00	1.00	500.00
S	BODYWORK	M: TO PLACE VEHICLE ON CAR D LINER FOR REPLACEMENT OF A PILLAR	1200.00	1.00	1,200.00
S	BODYWORK	M: TO SUPPLY ACRYLIC SEALER, CAVITY WAX AND STONE CHIP	500.00	1.00	500.00
S	BODYWORK	M: TO SUPPLY FRONT WINDSCREEN SEALANT	200.00	1.00	200.00
X	A4M2857410L 989	MOUNTING (A) Less 820%	1.00	1600.00	1,286.40
X	A4M0821167A	BRACKET Less 820%	1.00	52.90	42.32
X	A4M0809839	SECTION(V) (G) Less 820%	1.00	4002.00	3,201.60
X	A4M0806197A	DEADENER(V) Less 820%	1.00	6.50	5.20

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6836 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6888 2223
Telefax: 6475 1023

Ubi Service Centre
35 Ubi Road 1
Singapore 408620
Telephone: 6384 7327

Customer Service
Service Appointment
24-hour Breakdown Service
Email: customer.care@premiumaudi.com.sg
6366 2323
9626 1233

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 4 11:32

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013361 Date: 08/01/2019 Order: SCL1570R Term: 30	Account: 00006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No.: SCL1570R (V 27423) Regn Date: 29/09/2015 Mileage: 41252 WIP No.: 62162

Model: 97 3.0 TFSI QU (333 bhp) 4M00A Chassis: WAUZZZ4M56D000075 Engine: CRE 048791 Dept: U

USB No.:

You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
X	A4M0899181	PLUG(V)	1.00	7.70	6.16
X	A8S0833407A	HINGE (V)	1.00	39.60	31.68
X	A4M0831403A	HINGE (V)	1.00	39.30	31.44
X	A8S0833405A	HINGE (V)	1.00	39.60	31.68
X	A8S0833403E	HINGE (V)	1.00	40.40	32.32
X	A4M2947355	LED MODULE(V) (G)	1.00	44.30	35.44
X	A4M0821105D	FENDER LH	1.00	1422.00	1,137.60
X	A4M0839911C	SEAL (A)	1.00	217.50	174.00
X	A4M0853717A GRU	COVER	1.00	501.50	401.20
X	A4M0853718A GRU	COVER	1.00	501.50	401.20
X	A4M0821106D	FENDER RH	1.00	1422.00	1,137.60
X	A4M0831051F	DOOR (A)	1.00	3274.00	2,619.20
X	A4M0833051E	DOOR (A)	1.00	3274.00	2,619.20
X	A4M0845099A NVB	WINDSHIELD	1.00	1452.00	1,193.60
X	A4M0601025H	RIM 20" F08 (A)	3.00	1286.00	3,856.40
X	AD 00700002	SILICSPRAY (DG)	1.00	29.30	23.44
X	AD 0010001	MIXING JET	2.00	8.10	12.96
X	A8M0853601A	INSCRIPTION 'S-LINE'	2.00	107.50	172.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6346 2223
Main Telefax: 6471 2723

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6346 2223
Telefax: 6471 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408662
Telephone: 6346 7223

Customer Service
Service Appointment:
Hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6346 2223
6471 1223

INS TAX INVOICE

Company Reg. No.: 199902271W

GST Reg. No. 199902271W

Page 5 11:32

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013361 Date : 08/01/2019 Order : SCL1570R Term : 30	Account: 00006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SCL1570R (V 27429) Regn Date: 29/09/2015 Mileage: 41252 WIP No.: 62162

Model: Q7 3.0 TFSI QU (333 bhp) 4MBA Chassis: WAUZZZ4M5G000075 Engine: CRE 040791 Dept: U

VSB No.:

You have been assisted by :- UB-Jiayee (33)

		Details		Qty	Unit Price	Amount
X	A4M0837199	CLIP (A)	Less 020%	22.00	1.00	17.60
X	A4M0821431	BRACKET	Less 020%	1.00	55.60	44.64
X	A4M0854819A GRU	COVER (A)	Less 020%	1.00	172.00	137.60
X	A4M0854451	CLIP	Less 020%	10.00	2.10	16.80
X	ABU0955609	FILM	Less 020%	1.00	126.50	101.20
X	ADA 00173002	2K-ADHESIV	Less 020%	2.00	99.60	159.36
X	AD 35520502	BONAGENT	Less 020%	1.00	42.70	34.16
X	AD 00920002	PRIMER (DG)	Less 020%	1.00	18.20	14.56
X	ADA 00420002	ALU POWDER	Less 020%	1.00	507.00	405.60
X	ADA 004211A1	HARDENER	Less 020%	1.00	186.00	148.80
X	AD 506K01A3	2K FOAM	Less 020%	1.00	117.50	94.00
X	A4M0837911C	SEAL(A)	Less 020%	1.00	217.50	174.00
X	AN 01713113	FUSE(20A)	Less 020%	2.00	1.80	2.88
X	AN 10324001	RIVET NOYE	Less 020%	12.00	3.30	31.68
X	AN 50626303	POP-RIVET	Less 020%	10.00	1.40	11.20
X	AHHT006547	BOLT	Less 020%	10.00	1.60	12.80
X	AN 50632602	BOLT (V)	Less 020%	50.00	0.70	28.00
X	A4M0853959B GRU	COVER (A)	Less 020%	1.00	607.50	486.00
					Sub-Total	
					7% GST	
					Grand Total	



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159558
Main Telephone: 6334 2223
Main Telefax: 6471 2723

Alexandra Service Centre
281 Alexandra Road
Singapore 159558
Telephone: 6334 2223
Telefax: 6471 1033

UBI Service Centre
55 Ubi Road 1
Singapore 408722
Telephone: 6384 2223

Customer Service
Service Appointment
24-hour Breakdown Service
Email: customerservice@premiumauto.com.sg
6366 2121
9828 1233

INS TAX INVOICE

Company Reg. No: 199902271W

GST Reg. No. 199902271W

Page 6 11:32

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013361 Date : 08/01/2019 Order : SCL1570R Term : 30	Accounts: 00006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	---

Regn No.: SCL1570R (V 27429) Regn Date: 29/09/2015 Mileage: 41252 WIP No.: 62162

Model: Q7 3.0 TFSI QU (333 bhp) 4MB0A Chassis: WAUZZZ4MSGD000075 Engine: CRE 048791 Dept: U

VSB No.:

You have been assisted by :- UA-Jiayee (33)

		Details	Qty	Unit Price	Amount
X	A4M0853818A GRU	COVER	1.00	330.50	264.40
X	A4M0853817A GRU	COVER	1.00	330.50	264.40
X	A4M0853969G GRU	COVER (A)	1.00	514.00	411.20

Parts 20,543.52
Labour 0.00
Sublet 22,592.00
Menus 0.00
Lubricant 0.00

Sub-Total 43,135.52
7% GST 3,019.49
Grand Total 46,155.01



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SCL 1570 R

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0450/2018/TF
1 Jun 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

1

total pages

Make & Model : Audi Q7 3.0 TFSI QU
Vehicle Chassis No. : WAUZZZ4M5GD008075
Vehicle Regn No. : **SCL1570R**
Vehicle Mileage : 34824 KM
Vehicle Owner : Ms. Ng Wai Ping Eleanor
Certificate No : 2100428877-02
Policy Excess : NIL
Accident Date : 12 April 2018
Place : In Between Blk 37 & 39 Keppel Rd
Repair Cost : \$ 46,155.01
WIP No. : 62162
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time :
Date : 2/6/18

REPUBLIC OF SINGAPORE
 NATIONAL IDENTITY CARD

Expiry Month Year **S7540294E**

Name
NG WAI PING ELEANOR
(WU HUIBING ELEANOR)

Birth Date: **11 Nov 1975**
 Issue Date: **04 Mar 2004**

001156245K

REPUBLIC OF SINGAPORE
 IDENTITY CARD NO. **S7540294E**



Name
NG WAI PING ELEANOR
(WU HUIBING ELEANOR)
吴慧冰

Race
CHINESE

Date of Birth
11-11-1975

Country of Birth
SINGAPORE

Sex
F

S7540294E

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES):

Class	Description	Valid Until
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 3500 kilograms	25 May 1994

NP 425A



38229

NRIC No: **S7540294E**



Date of Issue:
25-08-2006

7 JALAN USAHA
SINGAPORE 537147
 NRIC No: **S7540294E**

Date: **13/07/2010** No: **0507931**



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : NG WAI PING ELEANOR (WU HUIBING ELEANOR)
 Period of Insurance : 29 Sep 2017 To 28 Sep 2018
 Engine No. : CRE048791
 Chassis No. : WAUZZZ4M5GD008075

Vehicle No. : SCL1570R
 Policy No. : 2100428877-02
 Endorsement No. :
 Issued Date : 25 Aug 2017

ABOUT THE COVER

Make/Model : AUDI Q7 3.0 TFSI QLI (272BHP&333BHP)
 Engine Capacity/Tonnage : 2,995.00 CC
 Driver Restriction : NA
 Sum Insured : Market Value
 Off Peak Car : No
 First Year of Registration : 2015
 Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

as The Policyholder
 to Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$1,000 as "Young and/or Inexperienced Driver Excess" ("YIDR"), if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered inoperative by Section 5 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0; Own Damage - \$1400; Theft - \$0; Flood Cover - \$0.

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

NG WAI PING ELEANOR (WU HUIBING ELEANOR) - \$1400 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center: Add 55 Ubi Road 1 Singapore 408601 (065) 6222

For other Approved Reporting Centres/Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1955 (Malaysia).

0504125210

PREMIUM LEASING - VL

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

SAC00X

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (subject to pre-approval needed)
- Repairs on Motor Claims (provided)
- Medical Referral Assistance

If my one is injured in the accident:

- You are not required to make any police report
- Provide vehicle number, make and address, insurance company and policy number of the other driver(s) and witnesses
- Collect details (name, address and contact number) of witnesses and try to take photographs of the scene of the accident
- Report the accident to us with your sustains vehicle (whether damaged or not) via our approved reporting centres or authorised roadblock within 24 hours or the next working day of the accident

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run cases:

- Report the accident to the police, providing all details of the circumstances of the accident
- Provide vehicle number, make and address, insurance company and policy number of the other driver(s) and witnesses, if applicable
- Collect details (name, address and contact number) of witnesses and try to take photographs of the scene of the accident
- Report the accident to us with your sustains vehicle (whether damaged or not) via our approved reporting centres or authorised roadblock within 24 hours or the next working day of the accident

What should I do in the event of an accident?

- Stop your car and return your car to a safe place
- Do not admit or discuss fault or blame with the other party(ies)
- Report the accident to us with your sustains vehicle (whether damaged or not) via our approved reporting centres or authorised roadblock within 24 hours or the next working day of the accident
- Submit your Sustains/Compensation Claim Form (provided) to AIG immediately

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within 3 working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the original insurance policy and schedule issued by AIG, a copy of the Accident Report from Audi Customer Service Centre must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Premium Automobiles Pte. Ltd.

Activation Hotline: 64741223

55 Ubi Road 1 Singapore 408699

Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 1pm

*The Rental Car Company's Terms & Conditions apply i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc.

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is IMPORTANT and MUST be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Apr 2018 11:19		16 Apr 2018 18:55 Edit Adj Rpt	S\$43,135.52 Edit Estimates	S\$43,135.52 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: NG WEI PING, ELEANOR , ID: S7540294E, Tel: +6596461237, Email: ELEANOR_NWP@HOTMAIL.COM									
Vehicle Reg. No.: SCL1570R		Date of Loss: 12/04/2018 11:00 - :59 [30 Months and 14 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 7675043217SG		Policy/Cover Note No.: 2100428877-02 (Comprehensive)							
		Excess: S\$0.00							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Tr, Tinesh] Tinesh.Tr@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 25/04/2018]									
Driver/Custodian: NG WEI PING, ELEANOR (42 / Female), NRIC: S7540294E, Tel: +6596461237									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (30/04/2018): Alert - Adj Mandate Approved (S\$44281.00) - SCL1570R - Claim Handler: Tr, Tinesh - AIG_SG (18/04/2018): SCL1570R / OD / 12/04/2018 / Coverage & Excess update - AIG_SG (17/04/2018): Alert - Adj Mandate Approved (S\$29373.00) - SCL1570R - Claim Handler: Tr, Tinesh - AIG_SG (17/04/2018): SCL1570R / OD / 12/04/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SCL1570R (7675043217SG)

OD

Apr 12 2018 11:00AM

[NG WEI PING, ELEANOR]

Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser	
Video														1 per page		☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)											Thumbnail		Print	
1	12/04/18 19:20	Video - Accident [Linked Accident Report Documents]												Load MP4		
Assessment Reports														1 per page		☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print	
1	17/04/18 11:32	Adjuster Immediate Advice												Load HTM		
2	27/04/18 17:32	Adjuster Immediate Advice												Load HTM		
Photos/Images														3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print	
1	17/04/18 11:21	General View												Load JPG	☒	
2	17/04/18 11:21	General View												Load JPG	☒	
3	17/04/18 11:21	General View												Load JPG	☒	
4	17/04/18 11:21	General View												Load JPG	☒	
5	17/04/18 11:21	General View												Load JPG	☒	
6	17/04/18 11:21	General View												Load JPG	☒	
7	17/04/18 11:21	General View												Load JPG	☒	
8	17/04/18 11:21	General View												Load JPG	☒	
9	17/04/18 11:21	General View												Load JPG	☒	
10	17/04/18 11:21	General View												Load JPG	☒	
11	17/04/18 11:21	General View												Load JPG	☒	
12	17/04/18 11:21	General View												Load JPG	☒	
13	17/04/18 11:21	General View												Load JPG	☒	
14	17/04/18 11:21	General View												Load JPG	☒	
15	17/04/18 11:21	General View												Load JPG	☒	
16	17/04/18 11:21	General View												Load JPG	☒	
17	17/04/18 11:21	General View												Load JPG	☒	
18	17/04/18 11:21	General View												Load JPG	☒	
19	17/04/18 11:21	General View												Load JPG	☒	
20	17/04/18 11:21	General View												Load JPG	☒	
21	17/04/18 11:21	General View												Load JPG	☒	
22	17/04/18 11:21	General View												Load JPG	☒	
23	17/04/18 11:21	General View												Load JPG	☒	
24	17/04/18 11:21	General View												Load JPG	☒	
25	17/04/18 11:21	General View												Load JPG	☒	
26	17/04/18 11:21	General View												Load JPG	☒	
27	17/04/18 11:21	General View												Load JPG	☒	
28	17/04/18 11:21	General View												Load JPG	☒	
29	17/04/18 11:21	General View												Load JPG	☒	
30	17/04/18 11:21	General View												Load JPG	☒	

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
31	17/04/18 11:21	General View	 Load JPG	☒
32	17/04/18 11:21	General View	 Load JPG	☒
33	17/04/18 11:21	General View	 Load JPG	☒
34	17/04/18 11:21	General View	 Load JPG	☒
35	17/04/18 11:21	General View	 Load JPG	☒
36	17/04/18 11:21	General View	 Load JPG	☒
37	17/04/18 11:21	General View	 Load JPG	☒
38	17/04/18 11:21	General View	 Load JPG	☒
39	17/04/18 11:21	General View	 Load JPG	☒
40	17/04/18 11:21	General View	 Load JPG	☒
41	17/04/18 11:21	General View	 Load JPG	☒
42	17/04/18 11:21	General View	 Load JPG	☒
43	17/04/18 11:21	General View	 Load JPG	☒
44	17/04/18 11:21	General View	 Load JPG	☒
45	17/04/18 11:21	General View	 Load JPG	☒
46	17/04/18 11:21	General View	 Load JPG	☒
47	17/04/18 11:21	General View	 Load JPG	☒
48	17/04/18 11:21	General View	 Load JPG	☒
49	17/04/18 11:21	General View	 Load JPG	☒
50	17/04/18 11:21	General View	 Load JPG	☒
51	17/04/18 11:21	General View	 Load JPG	☒
52	17/04/18 11:21	General View	 Load JPG	☒
53	17/04/18 11:21	General View	 Load JPG	☒
54	17/04/18 11:21	General View	 Load JPG	☒
55	17/04/18 11:21	General View	 Load JPG	☒
56	17/04/18 11:21	General View	 Load JPG	☒
57	17/04/18 11:21	General View	 Load JPG	☒
58	17/04/18 11:21	General View	 Load JPG	☒
59	17/04/18 11:21	General View	 Load JPG	☒
60	17/04/18 11:21	General View	 Load JPG	☒
61	17/04/18 11:21	General View	 Load JPG	☒
62	17/04/18 11:21	General View	 Load JPG	☒
63	17/04/18 11:21	General View	 Load JPG	☒
64	17/04/18 11:21	General View	 Load JPG	☒
65	17/04/18 11:21	General View	 Load JPG	☒
66	17/04/18 11:21	General View	 Load JPG	☒
67	27/04/18 17:33	Reinspection Photo	 Load JPG	☒
68	27/04/18 17:33	Reinspection Photo	 Load JPG	☒
69	27/04/18 17:33	Reinspection Photo	 Load JPG	☒
70	27/04/18 17:33	Reinspection Photo	 Load JPG	☒
71	27/04/18 17:33	Reinspection Photo	 Load JPG	☒
72	27/04/18 17:33	Reinspection Photo	 Load JPG	☒
73	27/04/18 17:33	Reinspection Photo	 Load JPG	☒
74	27/04/18 17:33	Reinspection Photo	 Load JPG	☒
75	27/04/18 17:33	Reinspection Photo	 Load JPG	☒
76	27/04/18 17:33	Reinspection Photo	 Load JPG	☒
77	27/04/18 17:33	Reinspection Photo	 Load JPG	☒
78	27/04/18 17:33	Reinspection Photo	 Load JPG	☒
79	27/04/18 17:33	Reinspection Photo	 Load JPG	☒
80	27/04/18 17:33	Reinspection Photo	 Load JPG	☒

Video				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
81	27/04/18 17:33	Reinspection Photo	 Load JPG	☒	
82	27/04/18 17:33	Reinspection Photo	 Load JPG	☒	
83	27/04/18 17:33	Reinspection Photo	 Load JPG	☒	
84	27/04/18 17:33	Reinspection Photo	 Load JPG	☒	
85	27/04/18 17:33	Reinspection Photo	 Load JPG	☒	
86	27/04/18 17:33	Reinspection Photo	 Load JPG	☒	
87	27/04/18 17:33	Reinspection Photo	 Load JPG	☒	
88	27/04/18 17:33	Reinspection Photo	 Load JPG	☒	
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	17/04/18 11:20	Certificate of Insurance	 Load PDF		
2	17/04/18 11:20	Driver's Driving License	 Load PDF		
3	17/04/18 11:20	ESTIMATE	 Load PDF		
4	17/04/18 11:20	Singapore Accident Statement	 Load PDF		
5	27/04/18 17:27	Supplementary	 Load PDF		
6	25/01/19 12:02	Workshop Invoice	 Load PDF		
7	25/01/19 12:02	Discharge Voucher	 Load PDF		
8	25/01/19 12:14	Supplementary	 Load PDF		

Linked Accident Report Documents

Video				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	12/04/18 19:20	Video - Accident	 Load MP4		
Assessment Reports				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	12/04/18 19:27	Accident Statement	 Load HTM		
Photos/Images				3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	12/04/18 19:23	Accident Photo	 Load JPG	☒	
2	12/04/18 19:23	Accident Photo	 Load JPG	☒	
3	12/04/18 19:23	Accident Photo	 Load JPG	☒	
4	12/04/18 19:23	Accident Photo	 Load JPG	☒	
5	12/04/18 19:23	Accident Photo	 Load JPG	☒	
6	12/04/18 19:23	Accident Photo	 Load JPG	☒	
7	12/04/18 19:23	Accident Photo	 Load JPG	☒	
8	12/04/18 19:23	Accident Photo	 Load JPG	☒	
9	12/04/18 19:23	Accident Photo	 Load JPG	☒	
10	12/04/18 19:23	Accident Photo	 Load JPG	☒	
11	12/04/18 19:23	Accident Photo	 Load JPG	☒	
12	12/04/18 19:23	Accident Photo	 Load JPG	☒	
13	12/04/18 19:23	Accident Photo	 Load JPG	☒	
14	12/04/18 19:23	Accident Photo	 Load JPG	☒	
15	12/04/18 19:23	Accident Photo	 Load JPG	☒	
16	12/04/18 19:23	Accident Photo	 Load JPG	☒	
17	12/04/18 19:23	Accident Photo	 Load JPG	☒	
18	12/04/18 19:23	Accident Photo	 Load JPG	☒	
19	12/04/18 19:23	Accident Photo	 Load JPG	☒	
20	12/04/18 19:23	Accident Photo	 Load JPG	☒	

Video			1 per page	☒
No.	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
21	12/04/18 19:23	Accident Photo	 Load JPG	☒
22	12/04/18 19:23	Accident Photo	 Load JPG	☒
23	12/04/18 19:23	Accident Photo	 Load JPG	☒
24	12/04/18 19:23	Accident Photo	 Load JPG	☒
25	12/04/18 19:23	Accident Photo	 Load JPG	☒
26	12/04/18 19:23	Accident Photo	 Load JPG	☒
27	12/04/18 19:23	Accident Photo	 Load JPG	☒
28	12/04/18 19:23	Accident Photo	 Load JPG	☒
29	12/04/18 19:23	Accident Photo	 Load JPG	☒
30	12/04/18 19:23	Accident Photo	 Load JPG	☒
31	12/04/18 19:23	Accident Photo	 Load JPG	☒
32	12/04/18 19:23	Accident Photo	 Load JPG	☒
33	12/04/18 19:23	Accident Photo	 Load JPG	☒
34	12/04/18 19:23	Accident Photo	 Load JPG	☒
35	12/04/18 19:23	Accident Photo	 Load JPG	☒
36	12/04/18 19:23	Accident Photo	 Load JPG	☒
37	12/04/18 19:23	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No.	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	12/04/18 19:25	Sketch Plan	 Load JPG	☒
2	12/04/18 19:25	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18007017/ATBE2

Date: 25/01/2019

REFERENCE

Insured/Claimant: NG WEI PING, ELEANOR Policy No: 2100428877-02
Date of Loss: 12/04/2018 Nature of Claim: OD Claim No: 7675043217SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCL1570R**
Make & Model: AUDI Q7, 3.0 TDI QUATTRO (A) Engine No: CRE048791
Reg. Date: 29/09/2015 (Man. Year: 2015) Chassis No: WAUZZZ4M5GD008075
Colour: Black Odometer: 34824 km
Engine Capacity: 2995 cc
Market Value/New Car Price: S\$245,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 285/40 R20 Rear Tyre Size: 285/40 R20
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	43,522.04	21,243.52	22,278.52	51.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	33,552.00	21,892.00	11,660.00	34.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	77,074.04	43,135.52	33,938.52	44.03
+ GST 7.00/7.00% (S\$)	5,395.18	3,019.49	2,375.69	44.03
Nett Amount (S\$)	82,469.22	46,155.01	36,314.21	44.03

INSPECTION

Date of Assignment: 16/04/2018
Date Inspected: 16/04/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 28.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Repair	2,252.00 FS	*- FS
2	2	*FRONT BUMPER AIR GUIDE	Not Necessary	114.00 FS	*- FS
3	2	*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	520.00 FS	*- FS
4	1	*FRONT BUMPER END CAP - RH	Not Necessary	29.00 FS	*- FS
5	2	*FRONT WHEEL COVER - LH / RH	Necessary	1,004.00 FS	*802.40 FS
6	2	*FRONT FENDER - LH / RH	Dented	2,844.00 FS	*2,275.20 FS
7	1	*FRONT FENDER BRACKET - LH / RH	N/S Bent	112.00 FS	*42.32 FS
8	1	*FRONT FENDER CENTRE BRACKET - LH / RH	N/S Bent	112.00 FS	*44.64 FS
9	2	*FRONT FENDER BRACE - LH / RH	Not Necessary	179.00 FS	*- FS
10	2	*FRONT FENDER CLOSING ELEMENT - LH / RH	Not Necessary	58.00 FS	*- FS
11	2	*INSCRIPTION S-LINE	Necessary	215.00 FS	*172.00 FS
12	1	*FRONT DOOR - LH	Dented	3,274.00 FS	*2,619.20 FS
13	1	*FRONT DOOR OUTER DOOR SEAL - LH	Necessary	218.00 FS	*174.00 FS
14	1	*BONDING AGENT	Necessary	43.00 FS	*34.16 FS
15	1	*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
16	8	*GROMMET	Not Necessary	18.00 FS	*- FS
17	1	*FRONT DOOR CATCH - LH	Not Necessary	112.00 FS	*- FS
18	1	*FRONT DOOR HANDLE - LH	Repair	325.00 FS	*- FS
19	1	*FRONT WINDOW REGULATOR WITHOUT MOTOR - LH	Not Necessary	249.00 FS	*- FS
20	1	*FRONT DOOR COVER - LH	Necessary	608.00 FS	*486.00 FS
21	1	*FRONT EXTERIOR MIRROR MOUNTIN - LH	Damaged	1,608.00 FS	*1,286.40 FS
22	1	*FRONT MIRROR CAP - LH	Not Necessary	159.00 FS	*- FS
23	1	*TURN SIGNAL INDICATOR - LH	Not Necessary	143.00 FS	*- FS
24	1	*FRONT DOOR - RH	Not Necessary	3,274.00 FS	*- FS
25	1	*FRONT DOOR OUTER DOOR SEAL - RH	Not Necessary	218.00 FS	*- FS
26	1	*BONDING AGENT	Not Necessary	43.00 FS	*- FS
27	1	*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
28	1	*GROMMET	Not Necessary	18.00 FS	*- FS
29	1	*FRONT DOOR CATCH - RH	Not Necessary	112.00 FS	*- FS
30	1	*FRONT DOOR COVER - RH	Not Necessary	608.00 FS	*- FS
31	1	*REAR DOOR - LH	Dented	3,274.00 FS	*2,619.20 FS
32	1	*REAR DOOR OUTER DOOR SEAL - LH	Necessary	218.00 FS	*174.00 FS
33	1	*BONDING AGENT	Not Necessary	43.00 FS	*- FS
34	1	*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
35	8	*GROMMET	Not Necessary	16.00 FS	*- FS
36	1	*REAR DOOR CATCH - LH	Not Necessary	92.00 FS	*- FS
37	1	*SILL PANEL SEAL	Not Necessary	223.00 FS	*- FS
38	1	*REAR DOOR OUTER SEAL - LH	Not Necessary	165.00 FS	*- FS
39	1	*REAR DOOR HANDLE - LH	Not Necessary	325.00 FS	*- FS
40	1	*REAR DOOR COVER	Necessary	514.00 FS	*411.20 FS
41	1	*REAR WHEEL COVE - LH	Necessary	172.00 FS	*137.60 FS
42	1	*REAR SIDE DOOR WHEEL - LH	Cut	331.00 FS	*264.40 FS
43	1	*FRONT EXTERIOR MIRROR - RH	Not Necessary	1,608.00 FS	*- FS
44	1	*FRONT MIRROR CAP - RH	Not Necessary	159.00 FS	*- FS
45	1	*FRONT TURN SIGNAL - RH	Not Necessary	143.00 FS	*- FS
46	1	*REAR WHEEL COVER - RH	Not Necessary	172.00 FS	*- FS
47	1	*REAR SIDE DOOR WHEEL - RH	Cut	331.00 FS	*264.40 FS
48	1	*ALUMINIUM RIM (4PCS)	Cut-3PCS ONLY	5,144.00 FS	*3,086.40 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
49	4		*RADIAL TYRE	Not Necessary	4,952.00 FS	*- FS
50	1		*SUNDRIES	Necessary	800.00 FS	*170.96 FS
51	1		*A-PILLAR PANEL - LH	Buckled	3,201.60 FS	*3,201.60 FS
52	1		*A-PILLAR PLATE - LH INNER	Necessary	5.20 FS	*5.20 FS
53	1		*FRONT DOOR HINGE - LH UPPER	Bent	63.12 FS	*63.12 FS
54	1		*FRONT DOOR HINGE - LH LOWER	Bent	64.00 FS	*64.00 FS
55	1		*2 PK FILL FOAM	Necessary	94.00 FS	*94.00 FS
56	1		*WELD SCREW	Necessary	28.00 FS	*28.00 FS
57	1		*ALUMINIUM POWDER	Necessary	405.60 FS	*405.60 FS
58	1		*HARDENER	Necessary	148.80 FS	*148.80 FS
59	1		*ACRYLIC SEALER	Necessary	180.00 FS	*180.00 FS
60	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
61	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
62	1		*FRONT WINDSCREEN	Necessary	1,193.60 FS	*1,193.60 FS
63	1		*FRONT WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
64	1		*FRONT WINDSCREEN PRIMER	Necessary	14.56 FS	*14.56 FS
65	1		*FRONT WINDSCREEN GEL - FOIL	Necessary	101.20 FS	*101.20 FS
66	1		*ALUMINIUM 2K ADHESIVE	Necessary	159.36 FS	*159.36 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	43,522.04	21,243.52
-------------------	-----------	-----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH LHS FRONT AND REAR DOORS, AND RHS FRONT DOORS MULTI LOCK SYSTEM AND POWER WINDOW DEVICES	New	1,080.00	720.00
3	TO DISMANTLE FRONT BUMPER, BOTH FRONT FENDERS, LHS FRONT AND REAR DOORS, AND RHS FRONT DOOR. INSPECT LHS A-PILLAR FOR DAMAGE. RENEW DAMAGED PANELS, ALIGN TO POSITION. REINSTALL ALL PARTS REMOVED	New	6,400.00	3,600.00
4	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, ALL FOUR DOORS, HANDLES, DOOR COVERS, WHEEL ARCH TRIMS AND BOTH REAR FENDERS	New	10,800.00	5,400.00
5	TO RENEW ALL RIMS WITH TYRES. CARRY OUT WHEEL ALIGNMENT	New	400.00	400.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
7	TO DISLodge AND REINSTALL LHS A-PILLAR AND LHS FRONT DOOR HARNESS	New	1,200.00	1,200.00
8	TO REMOVE AND REINSTALL LHS FRONT SEAT ASSY, ABCD PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRICAL COMPONENTS AND FUSE TRAYS	New	1,800.00	1,800.00
9	TO REMOVE AND REINSTALL CENTER CONSOLE AND DASHBOARD ASSY FOR A-PILLAR RENEWAL	New	2,800.00	2,800.00
10	TO CUT OUT AND WELD LHS A-PILLAR, REPAIR INNER A-PILLAR. RENEW DOOR HINGES. REINSTALL ALL PARTS REMOVED	New	4,800.00	2,400.00
11	TO RESPRAY LHS A-PILLAR, DOOR ENTRANCE AND LHS SILL PANEL	New	1,900.00	1,200.00
12	TO REMOVE AND RENEW FRONT WINDSCREEN GLASS	New	500.00	500.00
13	TO PLACE VEHICLE ON CAR O LINER FOR REPLACEMENT OF A PILLAR	New	1,200.00	1,200.00
Gross Labour Cost (S\$)			33,552.00	21,892.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >