

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

18/4/2018

M/S AIG

ESTIMATE REPAIR COST FOR SJU5159P

S/N	QTY	DESCRIPTION		
1	1 PC	FRONT BUMPER	\$	769.45
2	1 PC	FRONT BUMPER CLIPS	\$	12.30
3	1 PC	FRONT LH BUMPER RETAINER	\$	110.25
4	1 PC	FRONT LH HEADLAMP	\$	654.10
5	1 PC	FRONT LH FENDER	\$	943.10
6	1 PC	FRONT LH FENDER SHIELD	\$	202.45
			\$	2,691.65
		LESS 25%	\$	(672.91)
			\$	2,018.74
7		SPRAY PAINT	\$	880.00
8		WHEEL ALIGNMENT	\$	80.00
9		TUFF KOTE	\$	80.00
10		LABOUR CHARGE	\$	580.00
11		WIRING CHECK	\$	25.00
			\$	3,663.74

Not Actual
 2/3 \$2600/-
 4/4/18
 19/4/18
 to be photo after repair

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: