


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SG1035G
 Ref. No : BUS/03/18/1042
 Reg. Date : 02/04/2018
 Vehicle Type : BUS -12M
 Make : MB CITARO MERCEDES
 Model : MB CITARO O530
 Name of Driver : Yuhazam Bin Zamaludin
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 29/03/2018 07:44:00 AM
 Accident Reported Date / Time : 29/03/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : AIG
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No :
 Special Instruction to ARC, if any :
 SG1035G - RIGHT REAR PORTION
 SGB1295R (TP) - INSURED WITH AIG
 Prepared Date : 02/04/2018 03:45:29 PM



Chassis No : Mileage : 0

Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,060.00	0.00
Total Spray Painting Charges	: 432.00	0.00
Total Material Charges	: 85.05	85.05
Other Charges	: 0.00	0.00
TOTAL	: 1,577.05	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 2.00	0.00 1 day - r/p
Prepared / Adjusted By		
Arc / Surveyor Sing Off Date	: 12/04/2018 06:55:35 PM	01/01/1900 12:00:00 AM




13/04/18 @ 1020

Prepared / Adjusted Date

Remarks :

Prepared Date : 12/04/2018 06:55:35 PM

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :

Quotation Date : Invoice Date :

Invoice Amount : Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	1,060.00	0.00 800
Total Labour	1,060.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	432.00	0.00 300
Total Spray Painting & Panel Beating	432.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
0005446911	VE	6010012	SIDE MARKER LAMP	1	94.50	10.00	85.05	Replace	Replace MS ✓	No
TOTAL MATERIALS										
TOTAL MATERIALS(Discounted)								85.05	85.05	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									