

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

12-Apr-18

Our ref: TP/4491/18

Yee Yoke Fong

TP A19

Xiao Tony

RE: estimate cost for vehicle no : SJH 6031K

1 pc	tailgate <i>Dented</i>	\$	628.15	✓
1 pc	logo emblem <i>3m</i>		19.75	✓
1 pc	Swift emblem		25.55	✓
1 pc	tailgate outer handle <i>Deland</i>		69.65	✓
1 pc	tailgate lock <i>Damaged</i>		180.10	✓
1 pc	tailgate w/strip <i>cut</i>		92.95	✓
1 pc	tailgate trimboard <i>Cracked</i>		123.55	✓
2 pcs	taillamp <i>Hit cracked</i>		451.30	✓
1 pc	rear bumper <i>Deland</i>		549.65	✓
2 pcs	rear bumper bracket <i>3M</i>	2462.5	454.40	X
2 pcs	rear bumper retainer <i>new</i>		34.00	✓
2 pcs	rear bumper holders <i>new</i>	2093.12	24.90	✓
1 pc	end panel <i>Dented</i>		374.25	✓
1 pc	end panel inner garnish <i>Deland</i>		82.75	✓
2 pcs	rear no plate lamp <i>new</i>		41.50	✓
8 pcs	rear bumper clips <i>new</i>		31.60	✓
			3,184.05	
less 15%			477.61	
			2,706.44	

1 pc	rear w/screen gum <i>new</i>	50.00	snett	✓
1 pc	reverse sensor <i>Damaged</i>	250.00	2nd	✓
Panel beating.		1000.00	2nd	✓
Spray painting.		1000.00	2nd	✓
Wiring.		30.00	✓	
Remove & refit rear w/screen.		120.00	1st	✓
Transfer tailgate fitting.		80.00	✓	
Upholstery.		120.00	6th	✓
Rust proofing.		80.00	4th	✓
		5436.44		
Plus 7% GST		380.55		
		5816.99		

SD : Five thousand eight hundred sixteen & cents ninety-nine only.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

plate

405V

cracked

total: 4293.12

Adrian King

1/5 13/04/18

06 Apr.

1/5: 31C
(Nett Value)