

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 07 April 2018

Third Party Insurer: AXA

Vehicle No: SGR8801A

Third Party Veh No: SLN8203M

Model: HONDA JAZZ 1.4A

Date of Accident: 31/03/2018

Chassis: JHMGD17507S212029

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	FRONT FENDER LH		<i>An</i> \$450.80 ✓
1	FRONT FENDER INNER SHIELD LH		<i>D.I</i> \$98.10 —
10	FRONT FENDER INNER SHIELD CLIP LH	\$3.00	<i>m</i> \$30.00 —
2	FRONT HEADLAMP LH + RH	<i>MSB</i> \$524.30	\$1,048.60 ✓
1	FRONT BUMPER		<i>Bu</i> \$530.50 ✓
2	FRONT BUMPER SIDE RETAINER LH + RH	\$20.50	<i>MSB</i> \$41.00 ✓
14	FRONT BUMPER CLIP	\$3.00	<i>m</i> \$42.00 ✓
SUB TOTAL			\$2,241.00
Less 20%			-\$448.20
PARTS TOTAL			\$1,792.80

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION

\$600.00 *400*

TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION

\$800.00 *400*

TO CHECK WIRING, REPLACED WITH FOCUS HEADLAMP & WATER LEAKAGE TEST

\$80.00 *20*

TO TUFF KOTE / ANTI-RUST

\$60.00 *30*

TO SEND VEHICLE FOR 3D COMPUTERISED CHECK & ADJUSTED
WHEEL ALIGNMENT

\$60.00 ✓

LABOUR TOTAL \$1,600.00

WINSON

TOTAL \$3,392.80

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: