

Tampon 17/11/18

18/4/18 @ 1145

5 days

Lumpswe

flouring at the park.

FP 521 H

R7Z

Front wheel ?

— axle ?

Front wheel bearing x2 ?

Rust cover x2 ✓

Front brake disc b1 ✓

Front brake caliper d1 ✓

Front fork R&L b1 ✓

Stem steering w ✓

cone bearing set w ✓

Front fender w ✓

Front cowling w ✓

Windshield w ✓

Front licence plate w ✓

Headlamp b w ✓

Front signal R&L w ✓

Front cowling stay. b1 ✓

Handlebar RH b1 ✓

Brake lever

In bracket

~~Speedometer~~

Exhaust assy d1 ✓

Gasket exhaust w ✓

Brake pedal ?

Front footrest b1 ✓

Footrest bracket R b1 ✓

Rear fairing RH w ✓

Rear licence plate stay. ?

Rear fairing LH w ✓

Battery mis ✓

Fusebox mis ✓

Rear footrest bracket b1 ✓

Mainstand b1 ✓

Fuel tank d1 ✓

Handgrip m ✓

switch LH w ✓

clutch lever b w ✓

Lever holder

~~Speedometer~~ Handlebar LH

Speedometer dis ✓

Gear pedal b1 ✓

side mirrors x2 b w ✓

Transportation TP - Idac - Shop 100

workmanship 250 350

Transportation 2 way 80 100

Body chassis repair 350 180

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: