

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

Your ref : GV5663E

Date: 10.04.2018

M/S QBE INSURANCE (SINGAPORE) PTE LTD

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR GV5663E(NISSAN CABSTAR)

DATE OF ACCIDENT :07.04.2018

TO SUPPLY :

NETT ITEMS

- | | | |
|-----|------|--------------------------------|
| 01) | 1 PC | REAR TAILGATE |
| 02) | 1 PC | REAR TAILGATE "NISSAN" STICKER |
| 03) | 1 PC | REAR PANEL "NISSAN " STICKER |
| 04) | 1 PC | REAR PANEL "CABSTAR" STICKER |
| 05) | 1 PC | REAR PANEL (REPAIR) |
| 06) | 1 PC | REAR LH LAMP |

not Admitted
2hr
13/4/18
4/5 \$2200
3hr.
Whiplash After repair

DD/rel	\$	1,399.70	—
rel	\$	74.00	—
rel	\$	24.00	—
rel	\$	24.00	—
			X
4no	\$	148.70	✓
	\$	1,670.40	
LESS 10%	\$	(167.04)	
	\$	1,440.36	

SPECIAL NETT ITEMS

- | | | |
|-----|------|------------------|
| 07) | 1 PC | "70km/h" STICKER |
| 08) | 1 PC | "6 pax" STICKER |
| 09) | 1 PC | REVERSE SENSOR |

rel	\$	15.00	10
rel	\$	10.00	—
Shed	\$	280.00	200
	\$	305.00	

Labour Cost

- | | |
|-----|---------------|
| 10) | SPRAY PAINT |
| 11) | LABOUR CHARGE |
| 12) | TUFF COAT |
| 13) | WIRING |

\$	880.00	500
\$	780.00	500
\$	80.00	30
\$	25.00	✓

TOTAL LABOUR COST \$ 1,765.00

TOTAL \$ 3,510.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Page 1 of 1

Signature:

Date:

277836