



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

DA/III(SJX5046R)

DOA: 11/04/2018@1850

INDIA INTERNATIONAL INSURANCE PTE LTD

16/04/2018

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:
SKM 7421 Z - TOYOTA YARIS E AUTO
CHASSIS NO: MR054HY9104020679 (2007)

Alignment

\$ 60.00

Labour to repair and respray rear rim RH

\$ 100.00 ~~60~~

Labour to jacking, panel beating, repair and straighten
rear bumper, rear bumper spoiler, rear fender RH, rear
door and RH rocker panel garnish.

\$ ~~500.00~~ 400

Putty and respray rear bumper, rear bumper spoiler, rear
fender RH, rear door and RH rocker panel garnish.

\$ ~~1,000.00~~ 800

\$ 1,660.00

ADD 7% GST

\$ 116.20

\$ 1,776.20

Note: The above is an estimate only. IF other parts requested
during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068
5 days
p/p

19/04/18 @ 1150

Resurvey after
repair