Accident Claim Repair, Corrosion Welding, Body Dent Repairs, Spray-Painting, Mechanical Repair And Customizing of Cars BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724 BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723 TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg Bus. Reg. No. 251513/00M

DA/III(SJX5046R)

DOA: 11/04/2018@1850

INDIA INTERNATIONAL INSURANCE PTE LTD

16/04/2018

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM
ESTIMATE COST OF REPAIR FOR VEIHCLE NO:
SKM 7421 Z - TOYOTA YARIS E AUTO
CHASSIS NO: MR054HY9104020679 (2007)

Alignment	\$ 60.00
Labour to repair and respray rear rim RH	\$ 100.00
Labour to jacking, panel beating, repair and straighten rear bumper, rear bumper spoiler, rear fender RH, rear door and RH rocker panel garnish.	\$ 500.00
Putty and respray rear bumper, rear bumper spoiler, rear	
fender RH, rear door and RH rocker panel garnish.	\$ 1,000.00
	\$ 1,660.00
ADD 7% GST	\$ 116.20
	\$ 1,776.20

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT