

INS. CASE OWNER:

Nann

CC 6 / AIG1800 7059, Kua3sz

LKK:

IDAC:

Surveyor:

Kenneth

DOI:

16-4-18

Date / Time:

17/04/18

Registered in Merimen:

17/04/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLW 56952

Name of Insured:

Samyati Chandhuri

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

10-04-18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Chnika Chandhuri

Driver Tel No.:

91268667

(V/L: YES / NO)

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLG 235C



INSRS:

WSP:

Tel:

Liability:

RMKS:

Optima Work 2.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:


Date / Time

19/4/18

SLG 235C - X

SLW 56952 - X

while turning TP encroaching into OI lane.



RECEIVED 05 JUN 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. 1:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$320.00

REF: ALH

ASSIGNMENT

From: Date: 16/04/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLG 2135C
at Workshop n/s: Optima Werkz
of: 9A Strongdon North Ave 5

Insured:

Policy No.:

Claims No.:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

10am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 07 days Res.: Yes or No

Lum Sum: 1.3.1 % 3 Val.: Yes or No

CA / REV / REP. / 24HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLG 2135C Yr Regn: 09 16

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Prius cc 1797

Colour: M. Black A/C: Insured / Std / NI / NA

Sp. Reading: 135104 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: 8UV50 6008397

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: In order / ☒ Jammed / Leaked / Burnt orBrake: In order / ☒ Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD / ☒ R/Rim or

Tyre Size: F: B.S 195/65R15

R: GY

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 7 mm

R/Bal: 8 mm

L/Bal: 7 mm

L/Bal: 8 mm

D.O.A: 10/4/18

D.O.I: 16/4/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17/4 File pass to Catherine

P/P. \$ 4971.35 (Red: \$ 3956.39 / 44%.)
check item - \$ 146.71

Date/Time: File Pass to?

☐

Preli. Report

Is

☐

Final Report

Date/Time: File Return to?

Is

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1. 3 x P.S. \$

2. Phone

3. Other

4. TOTAL

Report Format:

Lump Sum / L.B.I. (\$)

Add Fee:

☐

Site Insp. (\$)

☐

Interview (\$)

☐

Tech. Insp. (\$)

☐

Weekend (\$)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD			Ref : CC6/AIG18007059/Kua3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120			Date : 17-04-2018	
			Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLW 5695Z	Veh. Inspected	SLG 2135C	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	17/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	10/04/2018	Inspection Date	16/04/2018	
Survey held at	OPTIMA WERKZ PTE LTD 6, KUNG CHONG ROAD SINGAPORE 159143			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

1. B. 1. 6 / Page 8?

7 days

Chassis: ZVW50-6008397

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 12 April 2018

Third Party Insurer: AIG

Vehicle No: SLG2135C

Third Party Veh No: SLW5695Z

Model: TOYOTA PRIUS HYBRID 1.8 CVT

Date of Accident: 10 APRIL 2018

Chassis: ZVW50-6008397

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	\$1,200.00	1000
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$1,400.00	900
TO TUFF KOTE / ANTI-RUST	\$60.00	✓
TO CHECK WIRING WITH WATER LEAKAGE TEST	\$60.00	20
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	\$60.00	50
TO DISMANTLE AND REINSTALL REAR LH SPORT RIMS CHECK UNDER CARRIAGE	\$150.00	nn x
TO SEND VEHICLE FOR 3D COMPUTERISED CHECK & ADJUSTED WHEEL ALIGNMENT	\$60.00	✓
TO DISMANTLE & REINSTALL FRONT LH DOOR INNER COMPONENT MECHANISM TO FACILITATE REPAIR WITH CHECK FOR FUNCTION	\$150.00	60
TO DISMANTLE & REINSTALL REAR LH DOOR INNER COMPONENT MECHANISM TO FACILITATE REPAIR WITH CHECK FOR FUNCTION	\$150.00	60
LABOUR TOTAL	\$3,290.00	

WINSON

TOTAL

\$8,927.74

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Apr 2018 Edit Reg		16 Apr 2018 00:00 Edit Adj Rpt	S\$4,971.35 Edit Estimates	S\$4,971.35 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	SAMYAJIT CHAUDHURI , ID: S2722512H, Tel: +6596220724		
Main Claimant:	STAR DEALS LEASING PTE LTD , Co. Reg. No.: 201612322G		
Vehicle Reg. No.:	SLG2135C	Date of Loss:	10/04/2018 20:00 - :59 [18 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 5746610406SG	Policy/Cover Note No.:	1800017469 (Comprehensive)
Vehicle Reg. No. (Insured):	SLW5695Z	Policy No. (Claimant):	17-MH001278
		Excess:	
Repairer:	Optima Werkz Pte Ltd (HQ) 6 Kung Chong Road, 159143 Leng Kee - Tel: 64721313		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaijye.Wui@aig.com		
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 26/04/2018]		
Driver/Custodian (Insured):	KANIKA CHAUDHURI (), NRIC: S2722513F		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLG2135C (5746610406SG)**
[SLW5695Z]

TP

STAR DEALS LEASING PTE LTD

Apr 10 2018 8:00PM

[SAMYAJIT CHAUDHURI]

Optima Werkz Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser ▾		
Video															1 per page ▾			☒		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)													Thumbnail	Print				
1	19/04/18 14:46	Video - Accident From:SC - Reg. No: SLW5695Z, Claimant: SAMYAJIT CHAUDHURI													Load AVI					
Assessment Reports															1 per page ▾			☒		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)													Thumbnail	Print				
1	18/04/18 16:17	Accident Statement From:SC - Reg. No: SLW5695Z, Claimant: SAMYAJIT CHAUDHURI													Load HTM					
Photos/Images															3 per page ▾			☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	06/06/18 13:03	General View													Load JPG	☒				
2	06/06/18 13:03	General View													Load JPG	☒				
3	06/06/18 13:03	General View													Load JPG	☒				
4	06/06/18 13:03	General View													Load JPG	☒				
5	06/06/18 13:03	General View													Load JPG	☒				
6	06/06/18 13:03	General View													Load JPG	☒				
7	06/06/18 13:03	General View													Load JPG	☒				
8	06/06/18 13:03	General View													Load JPG	☒				
9	06/06/18 13:03	General View													Load JPG	☒				
10	06/06/18 13:03	General View													Load JPG	☒				
11	06/06/18 13:03	General View													Load JPG	☒				
12	06/06/18 13:03	General View													Load JPG	☒				
13	06/06/18 13:03	General View													Load JPG	☒				
14	06/06/18 13:03	General View													Load JPG	☒				
15	06/06/18 13:03	General View													Load JPG	☒				
16	06/06/18 13:03	General View													Load JPG	☒				
Documentation															1 per page ▾			☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	17/04/18 11:00	TP ESTIMATE													Load PDF					
2	17/04/18 11:00	TP GIA REPORT													Load PDF					
3	19/04/18 00:32	TP ESTIMATE - MARKED													Load PDF					
4	06/06/18 13:05	EMAIL													Load PDF					

Documents Checklist

DOCUMENTS CHECKLIST																		Reset	Save	Print
There are no document checklists configured.																				

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:**  Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18007059/KUA3S2

Date: 06/06/2018

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800017469
Claimant Vehicle No :	SLG2135C	Insured Vehicle No :	SLW5695Z
Date of Loss:	10/04/2018	Nature of Claim:	TP
		Claim No:	5746610406SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG2135C	Engine No:	2ZR6668572
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 S (A)	Chassis No:	ZVW506008397
Reg. Date:	23/09/2016 (Man. Year: 2016)	Odometer:	155104 km
Colour:	Metallic Black		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Goodyear 8 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,637.73	2,761.35	2,876.38	51.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,290.00	2,210.00	1,080.00	32.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,927.73	4,971.35	3,956.38	44.32
+ GST 7.00/7.00% (S\$)	624.94	347.99	276.95	44.32
Nett Amount (S\$)	9,552.67	5,319.34	4,233.33	44.32

INSPECTION

Date of Assignment:	16/04/2018		
Date Inspected:	16/04/2018	Inspected At:	Optima Werkz Pte Ltd (HQ) 6 Kung Chong Road Singapore 159143
Estimated Period of Repair:	7.0 days		

Adjuster: KENNETH KONG

Manager: THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

6/6/2018

Adjuster Report

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$146.71 NETT)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Dented	395.60 FL	*395.60 FL
2	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	112.76 FL	*- FL
3	10		*REAR BUMPER CLIP	Necessary	57.10 FL	*57.10 FL
4	1		*REAR FENDER LH	Bent	852.40 FL	*852.40 FL
5	1		*ROCKER SIDE SKIRTING LH	Repair	379.60 FL	*- FL
6	12		*ROCKER SIDE SKIRTING CLIP LH	Not Necessary	87.72 FL	*- FL
7	1		*REAR DOOR LH	Bent	1,121.40 FL	*1,121.40 FL
8	1		*REAR DOOR WEATHERSTRIP LH	Serviceable	221.80 FL	*- FL
9	1		*REAR DOOR RUBBER SEAL LH	Serviceable	249.80 FL	*- FL
10	1		*REAR DOOR POWER WINDOW REGULATOR LH	Repair	230.80 FL	*- FL
11	1		*REAR DOOR POWER WINDOW MOTOR LH	Serviceable	768.90 FL	*- FL
12	1		*REAR DOOR POWER WINDOW CHANNEL LH	*Check	146.71 FL	*- FL
13	1		*REAR DOOR INNER TRIM BOARD LH	Serviceable	1,357.61 FL	*- FL
14	8		*REAR DOOR INNER TRIM BOARD CLIP	Not Necessary	57.68 FL	*- FL
15	1		*FRONT DOOR LH	Dented / Bent	1,126.60 FL	*1,126.60 FL
16	1		*FRONT DOOR WEATHERSTRIP LH	Serviceable	221.80 FL	*- FL
17	1		*REAR 15 WHEEL CAP LH	Dented / Scratched	128.70 FL	*128.70 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	7,516.98	3,681.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,879.25	920.45
Total Parts (\$\$)	5,637.73	2,761.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION.	New	1,200.00	1,000.00
2	TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION.	New	1,400.00	900.00
3	TO TUFF KOTE / ANTI-RUST.	New	60.00	60.00
4	TO CHECK WIRING WITH WATER LEAKAGE TEST.	New	60.00	20.00
5	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR.	New	60.00	50.00
6	TO DISMANTLE AND REINSTALL REAR LH SPORT RIMS CHECK UNDER CARRIAGE.	New	150.00	0.00
7	TO SEND VEHICLE FOR 3D COMPUTERISED CHECK & ADJUSTED WHEEL ALIGNMENT.	New	60.00	60.00
8	TO DISMANTLE & REINSTALL FRONT LH DOOR INNER COMPARTMENT MECHANISM TO FACILITATE REPAIR WITH CHECK FOR FUNCTION.	New	150.00	60.00
9	TO DISMANTLE & REINSTALL REAR LH DOOR INNER COMPONENT MECHANISM TO FACILITATE REPAIR WITH CHECK FOR FUNCTION.	New	150.00	60.00
Gross Labour Cost (\$\$)			3,290.00	2,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >