Not Nothern 8?

1.B.I. Ulling 8?

Fday,

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel: +65 6472 1313 Fax: +65 6472 2112

Branch office: 9A Serangoon North Ave 5 Singapore 554500 Tel: +65 6484 9919 Fax: +65 6481 1011

Co. Reg. No. 201212455W

Date:

12 April 2018

SLG2135C

Model: Chassis:

Vehicle No:

TOYOTA PRIUS HYBRID 1.8 CVT

ZVW50-6008397

Third Party Insurer:

AIG

Third Party Veh No:

SLW5695Z

Date of Accident:

10 APRIL 2018

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	Buch	(RV \$395.60
1	REAR BUMPER SIDE RETAINER LH		fn \$112.76
10	REAR BUMPER CLIP	\$5.71	Ma \$57.10
1	REAR FENDER LH		B \$852.40
1	ROCKER SIDE SKIRTING LH		N \$379.60
12	ROCKER SIDE SKIRTING CLIP LH	\$7.31	n ~ \$87.72
1	REAR DOOR LH		\$1,121.40
1	REAR DOOR WEATHERSTRIP LH		\$221.80
1	REAR DOOR RUBBER SEAL LH		S= \$249.80
1	REAR DOOR POWER WINDOW REGULATOR LH		× \$230.80
1	REAR DOOR POWER WINDOW MOTOR LH		\$768.90
1	REAR DOOR POWER WINDOW CHANNEL LH		\$146.71
1	REAR DOOR INNER TRIM BOARD LH	Se	\$1,357.61
8	REAR DOOR INNER TRIM BOARD CLIP	\$7.21	~~ \$57.68
1	FRONT DOOR LH	De	11 R \$1,126.60
1	FRONT DOOR WEATHERSTRIP LH		Su \$221.80
1	REAR 15' WHEEL CAP LH		Pullson \$128.70
		SUB TOTAL	\$7,516.98
		Less 25%	-\$1,879.25
		PARTS TOTAL	\$5,637.74

LKK Auto Consultants hence notify

- the Repairer of the following:
- . To resurvey before/after spray painting.
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel: +65 6472 1313 Fax: +65 6472 2112

Branch office: 9A Serangoon North Ave 5 Singapore 554500 Tel: +65 6484 9919 Fax: +65 6481 1011

Co. Reg. No. 201212455W

Date:

12 April 2018

Third Party Insurer:

AIG

Vehicle No:

SLG2135C

Third Party Veh No:

SLW5695Z

Model:

TOYOTA PRIUS HYBRID 1.8 CVT

Date of Accident:

10 APRIL 2018

Chassis:

ZVW50-6008397

ESTIMATE

WINSON	TOTAL	\$8,927.74	
	LABOUR TOTAL	\$3,290.00	
TO DISMANTLE & REINSTALL REAR LH DOOR INNER COMPONENT MECHANISM TO FACILITATE REPAIR WITH CHECK FOR FUNCTION		\$150.00	601
TO DISMANTLE & REINSTALL FRONT LH DOOR INNER COMPONENT MECHANISM TO FACILITATE REPAIR WITH CHECK FOR FUNCTION		\$150.00	601
TO SEND VEHICLE FOR 3D COMPUTERISED CHECK & ADJUSTED WHEEL ALIGNMENT		\$60.00	
TO DISMANTLE AND REINSTALL REAR LH SPORT RIMS CHECK UNDE	nn \$150.00	X	
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR		\$60.00	501
TO CHECK WIRING WITH WATER LEAKAGE TEST		\$60.00	201
TO TUFF KOTE / ANTI-RUST		\$60.00	_
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTI	ON	\$1,400.00	900
LABOUR CHARGES: TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PO	RTION	\$1,200.00	0000