

ASS. REC. BY:

REF: CS/CTU18007075 / Alqbez

Special Instruction:

SURVIVOR

Alqbez

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTU

Date/Time:

17/04/2018 11:51am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLH24663

Insured:

at Workshop m/s

Performance

Tel:

8121 4400

of

303 Alexandra Rd

Policy No:

DMPCCN1741621700

Claim No:

SNM1800190201

Sum Insured:

Excess:

\$ 1000.00

Make of Veh:

(Client's Record)

D.O.A.

11/04/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

17/04/2018 12pm

Person Contacted:

Irene Tay

Vehicle: IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLH 24663 - X

18/4/2018 Report via merimen.

18/4/18 @ 4.04pm Alfred informed C/A & ex: \$1000 by merimen.

19/4/18 @ 9.49am Informed Inthiran C/A & ex: \$1000 by email.

15/11/18 @ 5.47pm Confirmed with Caroline final fig \$ 35532.20, 21 days.
(Red \$ 8924.25, 20%)

Surveyor: John

REF:

2929H

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV
 To inspect Vehicle No: SLH 24665
 at Workshop m/s PERFORMANCE
 of _____
 Insured: CTI
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: 1000
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 98k
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 21 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLH 24665 Yr Regn: 2016 / OCT
 Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /
 Truck / Trailer or _____
 Make: B.M.W 116D 50R HB c.c. 1496
 Colour: BLACK A/C: Insured / Std / NI / NA
 Sp. Reading: 19277 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WBA1V72050V724908
 Gen. Cond: Good / ☒ Fair / ☐ Poor / ☐ Burnt
 Steering: Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or _____
 Brake: Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or _____
 Modi: Nil / ☒ S/Rim / ☐ STD A/Rim or _____
 Tyre Size: F: 205/55R16
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /
 TOYO / YOKO or _____

Front		Rear	
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm	
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm	
D.O.A. <u>11/04/18</u>		D.O.I. <u>17/04/18</u>	

Survey held at PERFORMANCE

Des. of Damages: Frt / Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

FRT O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 15 NOV 2018

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 21

15/11/18 10:55

☐ : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:

Transportation:

21

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

\$ + RS \$ _____

Photos

Others

Report Format: MER-OD

Lump Sum / I.B.I. (\$ _____)

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Apr 2018		17 Apr 2018 12:08 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	KEITH CHU		
Vehicle Reg. No.:	SLH2466S	Date of Loss:	11/04/2018 00:00 - :59
Claim Type:	OD / SNM18D01902C01	Policy/Cover Note No.:	DMPCSN1741621700 (Third Party Only)
		Excess:	S\$1,000.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/04/2018]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Catherine Chong (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Tuesday, 17 April, 2018 11:59 AM
To: Inthiran Thurasamy; Claims Dept of CTI
Cc: keith.chu@outlook.sg; assignments@lkkauto.com
Subject: RE: SLH2466s DOA 11.04.18

Dear Sir,

Will inform LKK to do the survey.

Regards

Irene Tay
Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389-6192
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: irene.tay@sg.cntaiping.com
Website: www.sg.cntaiping.com

-----Original Message-----

From: Inthiran Thurasamy [mailto:inthiran.thurasamy@simedarby.com.sg]
Sent: Tuesday, 17 April, 2018 9:10 AM
To: Irene Tay <irene.tay@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: keith.chu@outlook.sg
Subject: RE: SLH2466s DOA 11.04.18

Dear Sir/Madam,

Kindly arrange the survey asap. The claim has submitted on 13.04.18@ 6.11p.m. Your insured Mr.Keith would like have an update on the claim and want the repair to be conducted asap.

We hope your good office will expedite on the matter.

Thank you.

Warm regards
Inthiran
Customer Service Advisor
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Body & Paint Department

H/P : 81214600

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

-----Original Message-----

From: Inthiran Thurasamy
Sent: Monday, 16 April, 2018 1:56 PM
To: 'irene.tay@sg.cntaiping.com'
Subject: FW: SLH2466s DOA 11.04.18

Dear Irene,

I understand that you will be handling the claim. Please arrange for survey. The vehicle in our workshop.

Thank you.

Warm regards
Inthiran
Customer Service Advisor
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Body & Paint Department
H/P : 81214600

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

-----Original Message-----

From: Inthiran Thurasamy
Sent: Friday, 13 April, 2018 6:11 PM
To: (claimsdept@sg.cntaiping.com)
Subject: SLH2466s DOA 11.04.18

Dear Sir/Madam,

Please see attached for the OD claim and arrange for survey.
The vehicle in our workshop

Thank you.

Warm regards
Inthiran
Customer Service Advisor
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Body & Paint Department
H/P : 81214600

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 16 November 2018 5:47 PM
To: PBSP; Rasul (LKKAUTO); SUR; CS A Team
Subject: RE: Pending Confirmation on COR

Dear Caroline,

WITHOUT PREJUDICE

SLH 2466S – confirm final fig \$35,532.20 before excess \$1,000.00 & GST and 21 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@sinedarby.com.sg>
Sent: Friday, 16 November 2018 2:14 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: Pending Confirmation on COR

Dear Rasul and Case Handlers

Please let us have your reply to confirm COR on the following cases.

1. SLH2466S
2. SLB1106U
3. WC08833
4. SJG8384J
5. SJP171L
6. SLN5445B
7. SGZ37A
8. SKT2690J

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Thursday, 15 November 2018 4:20 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: VEHICLE SLH 2466S (YOUR REF: SNM18D01902C01)

This mail is associated with :
***SLH2466S (SNM18D01902C01)**
OD
Apr 11 2018 12:00AM
[KEITH CHU]
Performance Motors Limited

Dear Irene,

We have received supplementary of \$6,602.60 from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident, within authorise limit and is economical to repair.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 19 April 2018 9:49 AM
To: Inthiran Thurasamy
Cc: SUR; (claimsdept@sg.cntaiping.com); Keith Leo Chi Yung; Teng Wai Khan
Subject: RE: SLH 2466S doa : 11/04/18

Dear Inthiran,

As instructed by our client, please proceed to repair the insured vehicle **SLH 2466S (excess \$1,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Inthiran Thurasamy [mailto:inthiran.thurasamy@simedarby.com.sg]
Sent: Thursday, 19 April 2018 8:37 AM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>; Admin A <admin-a@lkkauto.com>; irene.tay@sg.cntaiping.com
Cc: SUR <sur@lkkauto.com>; (claimsdept@sg.cntaiping.com) <claimsdept@sg.cntaiping.com>; Keith Leo Chi Yung <keith.leo.chiyung@simedarby.com.sg>; Teng Wai Khan <teng.wai.khan@simedarby.com.sg>
Subject: RE: SLH 2466S doa : 11/04/18

Dear Irene/LKK,

Please advise us on authorisation. The vehicle has surveyed on 17.04.18 and till now not authorise. If there is any issue to authorise the repair, please advise us and your insured Mr.Keith.

Thank you.

Warm regards

Inthiran

Customer Service Advisor

Performance Motors Limited

303 Alexandra Road

Sime Darby Performance Centre

Singapore 159941

Body & Paint Department

H/P : 81214600

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	17 Apr 2018 12:07	Cim Veh Model Changed	(203838) BMW 1 SERIES 3.0 (A).	[I] Irene Tay Hui Ping
2	17 Apr 2018 12:07	Cim Created	Reg No: SLH2466S. Policy No: DMPCSN1741621700. Acct Date: 2018/04/11. Claim Type: OD. Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Performance Motors Limited (Alexandra). Ins.Status => Incoming Claim	[I] Irene Tay Hui Ping
3	17 Apr 2018 12:08	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):PLEASE SURVEY AND REVERT	[I] Irene Tay Hui Ping
4	17 Apr 2018 12:08	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/04/26	[I] Irene Tay Hui Ping
5	17 Apr 2018 12:08	Adj Mandate Set	Approved:0.00.	[I] Irene Tay Hui Ping
6	17 Apr 2018 13:07	Assignment 1st Accessed		[A] CATHERINE CHONG KAI LING
7	17 Apr 2018 14:53	Adj Adjuster Assigned	[None] -> MOHD RASUL	[A] CATHERINE CHONG KAI LING
8	18 Apr 2018 10:10	Adj Rpt Initiated		[A] DENISE TAY KWEE CHENG
9	18 Apr 2018 10:10	Cim Dtl Modified	Circumstances of Loss: -> 55.	[A] DENISE TAY KWEE CHENG
10	18 Apr 2018 10:10	Cim Dtl Modified	Claimant's ID: -> S8172929H.	[A] DENISE TAY KWEE CHENG
11	18 Apr 2018 10:10	Cim Dtl Modified	JPJ Reg. Date: -> 2016/10/26.	[A] DENISE TAY KWEE CHENG
12	18 Apr 2018 10:10	Cim Details Notified		[A] DENISE TAY KWEE CHENG
13	18 Apr 2018 11:00	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/04/26	[A] DENISE TAY KWEE CHENG
14	18 Apr 2018 11:03	Adj Mandate Request	Cur.Req:35598.50:DAMAGE CONSISTENT REPAIR COST ECONOMICAL	[A] DENISE TAY KWEE CHENG
15	18 Apr 2018 16:14	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/04/26. Mandate Remarks: Please proceed to authorize repairs UP TO \$35,598.50 before Excess of \$1,000.00. RE-INSPECTION of vehicle required.	[I] Alfred Toh
16	18 Apr 2018 16:14	Adj Mandate Set	Approved:35598.50:Please proceed to authorize repairs UP TO \$35,598.50 before Excess of \$1,000.00. RE-INSPECTION of vehicle required.Reinsp:Adj decides.	[I] Alfred Toh

Date From ◀ ▶ 📅 Date To ◀ ▶ 📅 Audit Type None ▼ Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1779855	18/04/2018 10:10	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLH2466S		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#18-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 18 Apr 2018

Preliminary Advice

Vehicle No	: SLH2466S	Accident Date	: 11/04/2018
Make	: BMW 1 SERIES	Policy No.	: DMPCSN1741621700
Assignment Date	: 17/04/2018	Excess	: S\$1,000.00
Date of Inspection	: 17/04/2018	Est. Duration of Repair	: 21.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	37,853.85
Revised Amount	:S\$	28,314.35
Check Items (Estimated)	:S\$	7,284.15
Total	:S\$	35,598.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	98,000.00
COE / PARF Rebate	:S\$	51,739.00
Salvage Value	:S\$	
Margin for Repair	:S\$	46,261.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2929H
Vehicle Details	
Vehicle No.:	SLH24665
Vehicle to be Exported:	No
Intended De-registration Date:	18 Apr 2018
Vehicle Make:	B.M.W.
Vehicle Model:	116D SDR HATCHBACK D5C LED
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	33769637B37D15A
Chassis No.:	WBA1V72050V724908
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$23,904.00
Original Registration Date:	27 Oct 2016
First Registration Date:	27 Oct 2016
Transfer Count:	1
Actual ARF Paid:	\$10,466.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Oct 2026
PARF Rebate Amount:	\$7,849.00
Intended COE Rebate Details	
COE Expiry Date:	26 Oct 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$56,889.00
COE Rebate Amount:	\$43,890.00
Total Rebate Amount:	\$51,739.00

The information contained herein is correct as at 18 Apr 2018.

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/04/2018 17:32
Date Of Accident	11/04/2018 19:30
Exact Location Of Accident	ECP EXPRESSWAY BEFORE BAYSHORE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH2466S
Insured/Policyholder	
Name Of Registered Owner	KEITH CHU
NRIC No	S8172929H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-84885033
Alternative Phone No	OFFICE-86660308

Vehicle Particulars

Manufacturer	BMW
Model	1 SERIES
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	
Cover Note Number	

Driver

Name of Driver	JOANNA HO YU FEN
NRIC No	S9202497J
Date Of Birth	30/01/1992
Occupation	INDOOR
Date Of Driving Pass	27/06/2013
Driving Experience	4 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-84885033
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 506 BISHAN STREET 11 #03-402
Postcode	570506
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	FRIEND
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	E6569K
Vehicle Make/Model/Colour	PEUGEOT
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TOH LEE HONG
NRIC/Passport Number	S7411416D
Contact Number	96788777
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REAR
No. Of Passenger (Including Driver)	2

Sketch Plan Pg. 1

12 Apr, 2018 7:31 AM

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

II. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre
Name:
NRIC/Fin No:
Date:
Signature:
Singapore 159041

Sketch Plan Pg. 2

12 Apr, 2018 7:31 AM

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 11 Apr, 730, I was driving along ECP Expressway, before exit to bayshore.

There was a truck in front of E6569K that G-braked. E6569K e-braked as well.

I was unable to stop in time.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Name:
Solicitor/Insurer:

Indirani D. Thirumalai
Perthamurugan Motors Limited
303 Alexandra Road
Singapore 119979

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2929H
Vehicle Details	
Vehicle No.:	SLH24665
Vehicle to be Exported:	No
Intended De-registration Date:	18 Apr 2018
Vehicle Make:	B.M.W.
Vehicle Model:	116D 5DR HATCHBACK DSC LED
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	33769637B37D15A
Chassis No.:	WBA1V72050V724908
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$23,904.00
Original Registration Date:	27 Oct 2016
First Registration Date:	27 Oct 2016
Transfer Count:	1
Actual ARF Paid:	\$10,466.00
PARF Eligibility Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Oct 2026
PARF Rebate Amount:	\$7,849.00
COE Details	
COE Expiry Date:	26 Oct 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$56,889.00
COE Rebate Amount:	\$43,890.00
Total Rebate Amount:	\$51,739.00

The information contained herein is correct as at 18 Apr 2018

OK

98,000
51,739
46,261
45K

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 119941
Tel: 63190300 (Sales & Admin)
63190311 (AfterSales)
Fax: 64747770

189, Tampong Arany Road
East Coast Centre
Singapore 479130
Tel: 63190888 (AfterSales)
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 119944
Tel: 63190528 (AfterSales)
63190533/330 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 46581
Date Estimated : 13/04/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 3

- ESTIMATE REPAIR FOR -

Keith Chu
12 Bedok Rise
#11-47

Singapore 465407

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLH2466S	V724908	27/10/2016	116d	0

DESCRIPTION

To replace front bumper, bonnet, fender right, wheel house right, front panel and attachments including knock out dent area cause by accident.

Painting front bumper, fender right, wheel house right and bonnet.

To supply front emboss number plate.

To tow accident vehicle to PML workshop.

To replace radiator assembly, fan housing with fan including pressure test, bleed cooling system and conduct checks for leak. (For all models except 7 series).

To replace charge air cooler including conduct checks for leak and proper function.

To replace air con condenser and air con hose including to vacuum system, top up freon gas and check for leak. (For all models except for 7 series).

To check steering geometry and conduct wheel alignment according to BMW specification (1X)

To remove and install front windscreen glass to facilitate repairs.

To conduct water leak tests.

To replace front dashboard panel and conduct checks for proper function.

To mount accident vehicle on celette bench to facilitate re-alignment of body/chassis in accordance with BMW specifications.

VALUE

10200 ~~11,080.00~~4098 3302 ~~3,669.00~~75 ~~83.00~~

195.00

702 ~~828.00~~451? ~~531.00~~852 ~~1,063.00~~451 ~~531.00~~nn? ~~574.00~~nn? ~~75.00~~nn 671? ~~787.00~~nn 2507 ~~2,980.00~~

- photo



305, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

365, Kampong Arang Road
East Coast Centre
Singapore 475180
Tel: 63190888 (AfterSales)
Fax: 63649773

319, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63139528 (AfterSales)
63139533/334 (Motorsad)
Fax: 64739601 (AfterSales)
64739624 (Motorsad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 46581
Date Estimated : 13/04/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLH2466S	V724908	27/10/2016	116d	0

DESCRIPTION

VALUE

To conduct chassis alignment measuring check using Car-O-Liner measuring system accordance with BMW specification.

na 451 531.00

To carry out body cavity preservation.
(For cut panel).

451 531.00

To carry out body cavity preservation.
(Per panel).

300 200 236.00

Sundries.

150.00

Total Labour 1: 23,732.00

DESCRIPTION

QTY PRIC

VALUE

CLAMP
Foil
RADIATOR MODULE MOUNT LH
RADIATOR MODULE MOUNT RH
RADIATOR UPPER SEALING
RADIATOR
RADIATOR EXPANSION TANK
FAN HOUSING WITH FAN 300W
CHARGE AIR COOLER
FRT RH FENDER
BONNET
BRACKET CABLE HARNESS
SIDE PANEL BRACKET FRT RH 3
FRT RH 2 SIDE PANEL BRACKET
FRT RH 2 SIDE PANEL BRACKET
BONNET LH HINGE
BONNET RH HINGE
FRT BUMPER TOP MOUNT
FRT LH DEFORMATION ELEMENT
FRT RH DEFORMATION ELEMENT
RH CLOSED GRID (BASIS)
IMPACT ABSORBER TOP
GRILLE MIDDLE BOTTOM
FRT BUMPER LH INSERT
FRT BUMPER RH INSERT
FRT BUMPER PANEL PRIMED
SET PDC HOLDER FRONT
SET PMA HOLDERS FRT/REAR
GRILLE LH (BASIS)
GRILLE RH (BASIS)
LH LOWER PART OF HOOK LOCK

10 3.20
1 2.15
1 75.70
1 75.70
1 33.40
1 706.10
1 192.70
1 1,157.95
1 609.75
1 546.00
1 1,122.10
2 28.25
1 32.15
1 32.15
1 32.15
1 71.50
1 71.50
1 361.65
1 97.40
1 97.40
1 93.20
1 42.45
1 115.50
1 32.15
1 32.15
1 786.20
1 23.10
1 21.25
1 81.95
1 81.95
1 85.80

30 na 3.20
XSL 2.15
CRA 75.70
CRA 75.70
na 33.40
BFI 706.10
? CRA 192.70
CRA 1,157.95
BFI 609.75
PA 546.00
BFI 1,122.10
SVC BFI 66.50
na 32.15
na 32.15
na 32.15
BFI 71.50
BFI 71.50
CRA 361.65
CRA 97.40
CRA 97.40
CRA 93.20
CRA 42.45
CRA 115.50
XSL 32.15
na 32.15
TSG 786.20
na X 2 23.10
na X 2 21.25
CRA 81.95
CRA 81.95
BFI 85.80

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401188W GST Reg. No. M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

189, Rongpong Asean Road
East Coast Centre
Singapore 438188
Tel: 63190088 (AfterSales)
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190028 (AfterSales)
63190033/339 (Motorrad)
64798801 (AfterSales)
64798824 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 46581
Date Estimated : 13/04/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 3 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLH2466S	V724908	27/10/2016	116d	0

DESCRIPTION	QTY	PRIC	VALUE
RH LOWER PART OF HOOK LOCK	1	85.80	85.80
TWIST PROTECTION	2	5.35	10.70
BONNET CATCH BRACKET	2	24.65	49.30
BONNET BOWDEN CABLE HOOD REAR	1	35.90	35.90
BONNET BOWDEN CABLE HOOD FRT	1	35.90	35.90
FRT W/SCREEN MOULDING	1	50.40	50.40
BUMP STOP	10	3.25	32.50
FRONT PANEL V STRUT	1	107.05	107.05
RH SUPPORT	1	53.95	53.95
FRONT CROSSLINK	1	160.55	160.55
RH DEFLECTOR LIP	1	19.50	19.50
FRT RH WHEEL HOUSING COVER FRT SECT	1	104.00	104.00
AIR DUCT RADIATOR	1	56.65	56.65
AIR DUCT MIDDLE LOWER SECTION	1	51.50	51.50
PLAQUE 82MM	1	69.50	69.50
LH HEADLIGHT LED TECHNOLOGY	1	2,263.60	2,263.60
RH HEADLIGHT LED TECHNOLOGY	1	2,263.60	2,263.60
RH FOG LIGHT	1	276.40	276.40
CONDENSER AIR CONDITIONING	1	979.45	979.45
BLIND RIVET HEMLOCK 813	9	2.65	23.85
BLIND RIVET AVIBVLB	4	0.55	2.20
(DG/SL) ADHESIVE GLUE	1	381.70	381.70
PUNCH RIVET N5	11	0.55	6.05
(DG) CLEANER R1 (100ML)	1	23.85	23.85
BLIND RIVET N7 150 STUCK	43	2.75	118.25
(DG/SL) ADHESIVE SET K6	1	53.05	53.05
(S/L) SEAM SEAL 300ML	1	33.80	33.80

Total Parts : 14,121.85

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Old Party / Uninsured losses / Direct Settlement

17/04/18 @ 1240

Rahul

90010068

Claim No.

Excess \$ 750

Sign

Authorised Yes / C

Time

YES / SURVEYOR Yes / No

Labour 1	:	23,732.00
Parts 21 days	:	14,121.85
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,649.77
Grand Total	:	40,503.62

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

44456.45

11000.00

Performance Motors Limited

A member of the Sincere Group
Co. Reg. No. 197401559W. GST Reg. No. M3-0020881-J



FINAL REPORT

Estimate No. : b1 46581
Date Estimated : 13/04/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -

Keith Chu
12 Bedok Rise
#11-47

Singapore 465407

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE		
SLH2466S	V724908	27/10/2016	116d	0		
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT			
To replace front bumper and attachments, front LH/RH fenders and attachments, bonnet and attachments, support bracket with VIN wheelhouse, RH supporting strut wheelhouse interior, front LH/RH deformation elements, front RH lower deformation element, front panel v strut, LH/RH support, front crosslink, air duct radiator and attachments, RH foglight include pulling and straightening on accident areas, to make good the RH wheelhousing/ chassis and knocking out dents caused by the accident	10200.00		10,200.00			
* To spray paint front bumper, front LH/RH fenders, front RH wheelhousing/chassis and bonnet	4098.00		4,098.00			
To supply front emboss number plate.	83.00		83.00			
To tow accident vehicle to PML workshop.	195.00		195.00			
To replace radiator assembly, fan housing with fan include pressure tests, bleed cooling system and conducting checks for leak	702.00		702.00			
* To replace charge air cooler include conducting checks for leak and proper function	451.00		451.00			
To replace air con condenser and air con hose include vacuum system, top up freon gas and conducting checks for leak	852.00		852.00			
To check steering geometry and conduct wheel alignment in accordance with BMW specifications (1x)	451.00		451.00			
# To replace RH LED technology headlights include programming and conducting checks for proper function	451.00		451.00			un
# To reconnect all electrical components and control units include replacement of damaged parts and conducting tests for proper function	451.00		451.00			un
To carry out body cavity preservation. (For cut panel).	451.00		451.00			

Performance Motors Limited

A member of the Simi Group
Co. Reg. No. 197401509W, GST Reg. No. M2-000081-X



FINAL REPORT

* To carry out body cavity preservation. (Per panel).	300.00	300.00
# To replace intake silencer and attachments include conducting checks for leak and proper function	451.00	451.00
# To diagnose and replace front RH repair cable (LED), electric fan cable set include resetting and conducting checks for proper function	451.00	451.00
Sundries	150.00	150.00

19,737

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
CLAMP	3.20	10.00		32.00
# BLIND RIVET *	1.25	6.00		7.50
# ACOUSTIC COVER FRT *	135.65	1.00		135.65
# COVER ACOUSTIC *	193.60	1.00		193.60
# INTAKE DUCT *	67.55	1.00		67.55
# INTAKE DUCT *	67.55	1.00		67.55
# INTAKE MANIFOLD FRONT *	45.05	1.00		45.05
# PIPE *	23.00	1.00		23.00
# INTAKE GRILLE *	20.30	1.00		20.30
# FILTERED AIR PIPE *	355.35	1.00		355.35
# BRACKET FOR INTAKE SILENCER LH *	38.35	1.00		38.35
# INTAKE SILENCER *	446.65	1.00		446.65
# BRACKET UPPER *	20.50	1.00		20.50
# SUPPORT SLEEVE *	3.70	1.00		3.70
RADIATOR MODULE MOUNT LH	75.70	1.00		75.70
RADIATOR MODULE MOUNT RH	75.70	1.00		75.70
# MODULE MOUNTING *	14.45	1.00		14.45
RADIATOR UPPER SEALING	33.40	1.00		33.40
RADIATOR	706.10	1.00		706.10
RADIATOR EXPANSION TANK	192.70	1.00		192.70
FAN HOUSING WITH FAN 300W	1,157.95	1.00		1,157.95
CHARGE AIR COOLER	609.75	1.00		609.75
# SUPPORT BRACKET WITH VIN WHILHOUSE *	465.15	1.00		465.15
# RH SUPPORTING STRUT WHEEL HOUSE INT *	264.30	1.00		264.30
# FRT LH FENDER *	546.00	1.00		546.00
FRT RH FENDER	546.00	1.00		546.00
BONNET	1,122.10	1.00		1,122.10
# CLOSING PLATE CARRIER SUPPORT *	97.40	1.00		97.40
SIDE PANEL BRACKET FRT RH 3	32.15	1.00		32.15
FRT RH 2 SIDE PANEL BRACKET	32.15	1.00		32.15
FRT RH 2 SIDE PANEL BRACKET	32.15	1.00		32.15
BONNET LH HINGE	71.50	1.00		71.50
BONNET RH HINGE	71.50	1.00		71.50
FRT BUMPER TOP MOUNT	361.65	1.00		361.65
FRT LH DEFORMATION ELEMENT	97.40	1.00		97.40
FRT RH DEFORMATION ELEMENT	97.40	1.00		97.40
# FRT RH LOWER DEFORMATION ELEMENT *	82.65	1.00		82.65
FRT BUMPER RH INSERT	7.15	1.00		7.15
RH CLOSED GRID (BASIS)	93.20	1.00		93.20
IMPACT ABSORNER TOP	42.45	1.00		42.45

2374.50

Performance Motors Limited

A member of the Gine-Duffy Group
Co. Reg. No. 107401559W, GST Reg. No. M3-0030081-3



FINAL REPORT

GRILLE MIDDLE BOTTOM	115.50	1.00	115.50
FRT BUMPER RH INSERT	32.15	1.00	32.15
FRT BUMPER PANEL PRIMED	786.20	1.00	786.20
GRILLE LH (BASIS)	81.95	1.00	81.95
GRILLE RH (BASIS)	81.95	1.00	81.95
# LICENCE PLATE BASE ECE *	67.60	1.00	67.60
LH LOWER PART OF HOOK LOCK	85.80	1.00	85.80
RH LOWER PART OF HOOK LOCK	85.80	1.00	85.80
TWIST PROTECTION	5.35	2.00	10.70
BONNET CATCH BRACKET	24.65	2.00	49.30
BONNET BOWDEN CABLE HOOD FRT	35.00	1.00	35.00
# SOUND INSULATING ENGINE HOOD *	163.30	1.00	163.30
FRONT PANEL V STRUT	107.05	1.00	107.05
# LH SUPPORT *	53.95	1.00	53.95
RH SUPPORT	53.95	1.00	53.95
# MOUNT FOR HOOD LH *	7.70	1.00	7.70
# MOUNT FOR HOOD RH *	7.70	1.00	7.70
FRONT CROSSLINK	160.55	1.00	160.55
# LOCK PANEL *	9.50	1.00	9.50
RH DEFLECTOR LIP	19.50	1.00	19.50
FRT RH WHEEL HOUSING COVER FRT SECT	104.00	1.00	104.00
AIR DUCT RADIATOR	56.65	1.00	56.65
AIR DUCT MIDDLE LOWER SECTION	51.50	1.00	51.50
# FRONT ENGINE HOOD SEALING *	20.00	1.00	20.00
PLAQUE 82MM	69.50	1.00	69.50
# REPAIR CABLE SET ELECTRIC FAN 300-6 *	165.55	1.00	165.55
# FRT RH REPAIR CABLE (LED) *	335.00	1.00	335.00
RH HEADLIGHT LED TECHNOLOGY	2,263.60	1.00	2,263.60
# SET LED MODULES *	120.45	1.00	120.45
# CONTROL UNIT FRT LIGHT ELECTRONIC *	893.90	1.00	893.90
RH FOG LIGHT	276.40	1.00	276.40
CONDENSER AIR CONDITIONING	979.45	1.00	979.45
# ANTI-FREEZE 1.5 LITRES *	19.75	3.00	59.25

7470.40

SUPPLEMENTARY ITEMS

Total Labour :	19,737.00
Total Parts :	15,795.20
Total Labour & Parts :	35,532.20
Deduction for Excess :	1,000.00
Total Repair Costs less Excess:	34,532.20
GST @7%:	2,417.25
Grand Total :	36,949.45

Performance Motors Limited

A member of the Straits Dairy Group
Co. Reg. No. T07401559W, GST Reg. No. M3-0030881-J



SUPPLEMENTARY

Estimate No. b1 46581
Date Estimated 13/04/2018
Prepared By Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -

Keith Chu
12 Bedok Rise
#11-47

Singapore 465407

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SLH2466S	V724908	27/10/2016	116d	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To replace RH LED technology headlights include programming and conducting checks for proper function	451.00		451.00 ✓
# To reconnect all electrical components and control units include replacement of damaged parts and conducting tests for proper function	451.00		451.00 ✓
# To replace intake silencer and attachments include conducting checks for leak and proper function	451.00		451.00 ✓
# To diagnose and replace front RH repair cable (LED), electric fan cable set include resetting and conducting checks for proper function.	451.00		451.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET *	1.25	6.00		7.50 ✓
# ACOUSTIC COVER FRT *	135.65	1.00		135.65 ✓
# COVER ACOUSTIC *	193.60	1.00		193.60 ✓
# INTAKE DUCT *	67.55	1.00		67.55 ✓
# INTAKE DUCT *	67.55	1.00		67.55 ✓
# INTAKE MANIFOLD FRONT *	45.05	1.00		45.05 ✓
# PIPE *	23.00	1.00		23.00 ✓
# INTAKE GRILLE *	20.30	1.00		20.30 ✓
# FILTERED AIR PIPE *	355.35	1.00		355.35 ✓
# BRACKET FOR INTAKE SILENCER LH *	38.35	1.00		38.35 ✓
# INTAKE SILENCER *	446.65	1.00		446.65 ✓
# BRACKET UPPER *	20.50	1.00		20.50 ✓
# SUPPORT SLEEVE *	3.70	1.00		3.70 ✓
# MODULE MOUNTING *	14.45	1.00		14.45 ✓
# SUPPORT BRACKET WITH VIN WHILHOUSE *	465.15	1.00		465.15 ✓
# RH SUPPORTING STRUT WHEEL HOUSE INT *	264.30	1.00		264.30 ✓
# FRT LH FENDER *	546.00	1.00		546.00 ✓
# CLOSING PLATE CARRIER SUPPORT *	97.40	1.00		97.40 ✓
# FRT RH LOWER DEFORMATION ELEMENT *	82.65	1.00		82.65 ✓
# LICENCE PLATE BASE ECE *	67.60	1.00		67.60 ✓
# SOUND INSULATING ENGINE HOOD *	163.30	1.00		163.30 ✓
# LH SUPPORT *	53.95	1.00		53.95 ✓

Performance Motors Limited

A member of the Silver Derby Group
Co. Reg. No. 107401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

# MOUNT FOR HOOD LH *	7.70	1.00	7.70	new
# MOUNT FOR HOOD RH *	7.70	1.00	7.70	new
# LOCK PANEL *	9.50	1.00	9.50	new
# FRONT ENGINE HOOD SEALING *	20.00	1.00	20.00	new
# REPAIR CABLE SET ELECTRIC FAN 300-6 *	165.55	1.00	165.55	cut
# FRT RH REPAIR CABLE (LED) *	335.00	1.00	335.00	cut
# SET LED MODULES *	120.45	1.00	120.45	new
# CONTROL UNIT FRT LIGHT ELECTRONIC *	893.90	1.00	893.90	new
# ANTI-FREEZE 1.5 LITRES *	19.75	3.00	59.25	new

Total Labour :	1,804.00
Total Parts :	4,798.60
Total Labour & Parts :	6,602.60

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Apr 2018		17 Apr 2018 12:08 Edit Adj Rpt	S\$35,532.20 Edit Estimates	S\$35,532.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: KEITH CHU , ID: S8172929H									
Vehicle Reg. No.: SLH2466S		Date of Loss: 11/04/2018 00:00 - :59 [17 Months and 15 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / SNM18D01902C01		Policy/Cover Note No.: DMPCSN1741621700 (Third Party Only)							
		Excess: S\$1,000.00							
Repairer: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 26/04/2018]									
Adj Asg. Remarks: PLEASE SURVEY AND REVERT									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- CHINA_TAIPIING (16/11/2018): Re: Kindly assist to amend the make & model of vehicle SLH 2466S (YOUR REF: ... - CHINA_TAIPIING (18/04/2018): Alert - Adj Mandate Approved (S\$35598.50) - SLH2466S - Claim Handler: Irene Tay ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLH2466S (SNM18D01902C01)
 OD
 Apr 11 2018 12:00AM
 [KEITH CHU]
 Performance Motors Limited

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View View in Browser

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/04/18 11:00	Adjuster Immediate Advice	Load HTML	☐

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/04/18 11:05	General View	Load JPG	☒
2	18/04/18 11:05	General View	Load JPG	☒
3	18/04/18 11:05	General View	Load JPG	☒
4	18/04/18 11:05	General View	Load JPG	☒
5	18/04/18 11:05	General View	Load JPG	☒
6	18/04/18 11:05	General View	Load JPG	☒
7	18/04/18 11:05	General View	Load JPG	☒
8	18/04/18 11:05	General View	Load JPG	☒
9	18/04/18 11:05	General View	Load JPG	☒
10	18/04/18 11:05	General View	Load JPG	☒
11	18/04/18 11:05	General View	Load JPG	☒
12	18/04/18 11:05	General View	Load JPG	☒
13	18/04/18 11:05	General View	Load JPG	☒
14	18/04/18 11:05	General View	Load JPG	☒
15	18/04/18 11:05	General View	Load JPG	☒
16	18/04/18 11:05	General View	Load JPG	☒
17	18/04/18 11:05	General View	Load JPG	☒
18	18/04/18 11:05	General View	Load JPG	☒
19	18/04/18 11:05	General View	Load JPG	☒
20	18/04/18 11:05	General View	Load JPG	☒
21	18/04/18 11:05	General View	Load JPG	☒
22	18/04/18 11:05	General View	Load JPG	☒
23	18/04/18 11:05	General View	Load JPG	☒
24	18/04/18 11:05	General View	Load JPG	☒
25	18/04/18 11:05	General View	Load JPG	☒
26	18/04/18 11:05	General View	Load JPG	☒
27	18/04/18 11:05	General View	Load JPG	☒
28	18/04/18 11:05	General View	Load JPG	☒
29	18/04/18 11:05	General View	Load JPG	☒
30	18/04/18 11:05	General View	Load JPG	☒
31	18/04/18 11:05	General View	Load JPG	☒
32	18/04/18 11:05	General View	Load JPG	☒
33	18/04/18 11:05	General View	Load JPG	☒
34	18/04/18 11:05	General View	Load JPG	☒
35	18/04/18 11:05	General View	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	18/04/18 11:05	General View	 Load JPG	☒
37	18/04/18 11:05	General View	 Load JPG	☒
38	18/04/18 11:05	General View	 Load JPG	☒
39	18/04/18 11:05	General View	 Load JPG	☒
40	18/04/18 11:05	General View	 Load JPG	☒
41	18/04/18 11:05	General View	 Load JPG	☒
42	18/04/18 11:05	General View	 Load JPG	☒
43	18/04/18 11:05	General View	 Load JPG	☒
44	18/04/18 11:05	General View	 Load JPG	☒
45	18/04/18 11:05	General View	 Load JPG	☒
46	18/04/18 11:05	General View	 Load JPG	☒
47	18/04/18 11:05	General View	 Load JPG	☒
48	18/04/18 11:05	General View	 Load JPG	☒
49	18/04/18 11:05	General View	 Load JPG	☒
50	18/04/18 11:05	General View	 Load JPG	☒
51	18/04/18 11:05	General View	 Load JPG	☒
52	18/04/18 11:05	General View	 Load JPG	☒
53	18/04/18 11:05	General View	 Load JPG	☒
54	18/04/18 11:05	General View	 Load JPG	☒
55	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
56	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
57	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
58	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
59	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
60	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
61	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
62	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
63	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
64	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
65	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
66	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
67	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
68	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
69	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
70	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
71	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
72	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
73	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
74	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
75	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
76	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
77	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
78	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
79	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
80	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
81	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
82	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
83	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
84	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
85	16/11/18 17:40	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
86	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
87	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
88	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
89	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
90	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
91	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
92	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
93	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
94	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
95	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
96	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
97	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
98	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
99	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
100	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
101	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
102	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
103	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
104	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
105	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
106	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
107	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
108	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
109	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
110	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
111	16/11/18 17:40	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	17/04/18 14:07	ESTIMATE	 Load PDF	
2	17/04/18 14:07	SATISFACTION VOUCHER	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/04/18 11:13	ESTIMATE	 Load PDF	
2	15/11/18 16:11	SUPPLEMENTARY LIST	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI18007079/R1QBE2

Date: 26/11/2018

REFERENCE

Insured/Claimant: KEITH CHU Policy No: DMPCSN1741621700
Date of Loss: 11/04/2018 Nature of Claim: OD Claim No: SNM18D01902C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLH2466S
Make & Model: BMW 116D, 1.5 (A) Engine No: 33769637B37D15A
Reg. Date: 27/10/2016 (Man. Year: 2016) Chassis No: WBA1V72050V724908
Colour: Black Odometer: 19277 km
Engine Capacity: 1496 cc
Market Value/New Car Price: S\$98,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,189.40	16,028.20	3,161.20	16.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	25,796.00	19,504.00	6,292.00	24.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	44,985.40	35,532.20	9,453.20	21.01
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	43,985.40	34,532.20	9,453.20	21.49
+ GST 7.00/7.00% (S\$)	3,078.98	2,417.25	661.73	21.49
Nett Amount (S\$)	47,064.38	36,949.45	10,114.93	21.49

INSPECTION

Date of Assignment: 17/04/2018
Date Inspected: 17/04/2018 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 21.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Nov 2018)
Parts: 144	BMW 116D 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLH2466S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT EMBOSS PLATE	Bent	83.00 FS	*83.00 FS
2	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
3	10		*CLAMP	Necessary	32.00 FS	*32.00 FS
4	1		*FOIL	Serviceable	2.15 F	*- F
5	1		*RADIATOR MODULE MOUNT LH	Cracked	75.70 FS	*75.70 FS
6	1		*RADIATOR MODULE MOUNT RH	Cracked	75.70 FS	*75.70 FS
7	1		*RADIATOR UPPER SEALING	Necessary	33.40 FS	*33.40 FS
8	1		*RADIATOR	Bent	706.10 FS	*706.10 FS
9	1		*RADIATOR EXPANSION TANK	Cracked	192.70 FS	*192.70 FS
10	1		*FAN HOUSING WITH FAN 300W	Cracked	1,157.95 FS	*1,157.95 FS
11	1		*CHARGE AIR COOLER	Bent	609.75 FS	*609.75 FS
12	1		*FRT RH FENDER	Bent	546.00 FS	*546.00 FS
13	1		*BONNET	Buckled	1,122.10 FS	*1,122.10 FS
14	2		*BRACKET CABLE HARNESS	Serviceable	56.50 FS	*- FS
15	1		*SIDE PANEL BRACKET FRT RH 3	Necessary	32.15 FS	*32.15 FS
16	1		*FRT RH 2 SIDE PANEL BRACKET	Necessary	32.15 FS	*32.15 FS
17	1		*FRT RH 2 SIDE PANEL BRACKET	Necessary	32.15 FS	*32.15 FS
18	1		*BONNET LH HINGE	Bent	71.50 FS	*71.50 FS
19	1		*BONNET RH HINGE	Bent	71.50 FS	*71.50 FS
20	1		*FRT BUMPER TOP MOUNT	Cracked	361.65 FS	*361.65 FS
21	1		*FRT LH DEFORMATION ELEMENT	Cracked	97.40 FS	*97.40 FS
22	1		*FRT RH DEFORMATION ELEMENT	Cracked	97.40 FS	*97.40 FS
23	1		*RH CLOSED GRID (BASIS)	Cracked	93.20 FS	*93.20 FS
24	1		*IMPACT ABSORNER TOP	Cracked	42.45 FS	*42.45 FS
25	1		*GRILLE MIDDLE BOTTOM	Cracked	115.50 FS	*115.50 FS
26	1		*FRT BUMPER LH INSERT	Serviceable	32.15 FS	*- FS
27	1		*FRT BUMPER RH INSERT	Necessary	39.30 FS	*39.30 FS
28	1		*FRT BUMPER PANEL PRIMED	Deformed	786.20 FS	*786.20 FS
29	1		*SET PDC HOLDER FRONT	Not Necessary	23.10 FS	*- FS
30	1		*SET PMA HOLDERS FRT / REAR	Not Necessary	21.25 FS	*- FS
31	1		*GRILLE LH (BASIS)	Cracked	81.95 FS	*81.95 FS
32	1		*GRILLE RH (BASIS)	Cracked	81.95 FS	*81.95 FS
33	1		*LH LOWER PART OF HOOK LOCK	Bent	85.80 FS	*85.80 FS
34	1		*RH LOWER PART OF HOOK LOCK	Jammed	85.80 FS	*85.80 FS
35	2		*TWIST PROTECTION	Necessary	10.70 FS	*10.70 FS
36	2		*BONNET CATCH BRACKET	Bent	49.30 FS	*49.30 FS
37	1		*BONNET BOWDEN CABLE HOOD REAR	Serviceable	35.90 FS	*- FS
38	1		*BONNET BOWDEN CABLE HOOD FRT	Cut	35.90 FS	*35.00 FS
39	1		*FRT W/SCREEN MOULDING	Not Necessary	50.40 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	10		*BUMP STOP	Not Necessary	32.50 FS	*- FS
41	1		*FRONT PANEL V STRUT	Bent	107.05 FS	*107.05 FS
42	1		*RH SUPPORT	Bent	53.95 FS	*53.95 FS
43	1		*FRONT CROSSLINK	Bent	160.55 FS	*160.55 FS
44	1		*RH DEFLECTOR LIP	Cracked	19.50 FS	*19.50 FS
45	1		*FRT RH WHEEL HOUSING COVER FRT SECT	Deformed	104.00 FS	*104.00 FS
46	1		*AIR DUCT RADIATOR	Cracked	56.65 FS	*56.65 FS
47	1		*AIR DUCT MIDDLE LOWER SECTION	Cracked	51.50 FS	*51.50 FS
48	1		*PLAQUE 82MM	Necessary	69.50 FS	*69.50 FS
49	1		*LH HEADLIGHT LED TECHNOLOGY	Serviceable	2,263.60 FS	*- FS
50	1		*RH HEADLIGHT LED TECHNOLOGY	Broken	2,263.60 FS	*2,263.60 FS
51	1		*RH FOG LIGHT	Cracked	276.40 FS	*276.40 FS
52	1		*CONDENSER AIR CONDITIONING	Bent	979.45 FS	*979.45 FS
53	9		*BLIND RIVET HEMLOCK 813	Not Necessary	23.85 FS	*- FS
54	4		*BLIND RIVET AVIBVLB	Not Necessary	2.20 FS	*- FS
55	1		*(DG/SL) ADHESIVE GLUE	Not Necessary	381.70 FS	*- FS
56	11		*PUNCH RIVET N5	Not Necessary	6.05 FS	*- FS
57	1		*(DG) CLEANER R1 (100ML)	Not Necessary	23.85 FS	*- FS
58	1		*BLIND RIVET N7 150 STUCK (43PCS)	Not Necessary	118.25 FS	*- FS
59	1		*(DG/SL) ADHESIVE SET K6	Not Necessary	53.05 FS	*- FS
60	1		*(S/L) SEAM SEAL 300ML	Not Necessary	33.80 FS	*- FS
61	6		*BLIND RIVET	Necessary	7.50 FS	*7.50 FS
62	1		*ACOUSTIC COVER FRT	Cracked	135.65 FS	*135.65 FS
63	1		*COVER ACOUSTIC	Cracked	193.60 FS	*193.60 FS
64	1		*INTAKE DUCT	Cracked	67.55 FS	*67.55 FS
65	1		*INTAKE DUCT	Cracked	67.55 FS	*67.55 FS
66	1		*INTAKE MANIFOLD FRONT	Cracked	45.05 FS	*45.05 FS
67	1		*PIPE	Bent	23.00 FS	*23.00 FS
68	1		*INTAKE GRILLE	Cracked	20.30 FS	*20.30 FS
69	1		*FILTERED AIR PIPE	Bent	355.35 FS	*355.35 FS
70	1		*BRACKET FOR INTAKE SILENCER LH	Bent	38.35 FS	*38.35 FS
71	1		*INTAKE SILENCER	Cracked	446.65 FS	*446.65 FS
72	1		*BRACKET UPPER	Necessary	20.50 FS	*20.50 FS
73	1		*SUPPORT SLEEVE	Necessary	3.70 FS	*3.70 FS
74	1		*MODULE MOUNTING	Necessary	14.45 FS	*14.45 FS
75	1		*SUPPORT BRACKET WITH VIN WHLHOUSE	Bent	465.15 FS	*465.15 FS
76	1		*RH SUPPORTING STRUT WHEEL HOUSE INT	Bent	264.30 FS	*264.30 FS
77	1		*FRT LH FENDER	Bent	546.00 FS	*546.00 FS
78	1		*CLOSING PLATE CARRIER SUPPORT	Cracked	97.40 FS	*97.40 FS
79	1		*FRT RH LOWER DEFORMATION ELEMENT	Cracked	82.65 FS	*82.65 FS
80	1		*LICENCE PLATE BASE ECE	Deformed	67.60 FS	*67.60 FS
81	1		*SOUND INSULATING ENGINE HOOD	Deformed	163.30 FS	*163.30 FS
82	1		*LH SUPPORT	Bent	53.95 FS	*53.95 FS
83	1		*MOUNT FOR HOOD LH	Necessary	7.70 FS	*7.70 FS
84	1		*MOUNT FOR HOOD RH	Necessary	7.70 FS	*7.70 FS
85	1		*LOCK PANEL	Necessary	9.50 FS	*9.50 FS
86	1		*FRONT ENGINE HOOD SEALING	Necessary	20.00 FS	*20.00 FS
87	1		*REPAIR CABLE SET ELECTRIC FAN 300-6	Cut	165.55 FS	*165.55 FS
88	1		*FRT RH REPAIR CABLE (LED)	Cut	335.00 FS	*335.00 FS
89	1		*SET LED MODULES	Not Working	120.45 FS	*120.45 FS
90	1		*CONTROL UNIT FRT LIGHT ELECTRONIC	Not Working	893.90 FS	*893.90 FS
91	3		*ANTI-FREEZE 1.5 LITRES	Necessary	59.25 FS	*59.25 FS

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Total Parts (S\$)	19,189.40	16,028.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER, BONNET, FENDER RIGHT, WHEEL HOUSE RIGHT, FRONT PANEL AND ATTACHMENTS INCLUDING KNOCK OUT DENT AREA CAUSE BY ACCIDENT	New	11,050.00	10,200.00
2	PAINTING FRONT BUMPER, FENDER RIGHT, WHEEL HOUSE RIGHT AND BONNET	New	4,098.00	4,098.00
3	TO TOW ACCIDENT VEHICLE TO PML WORKSHOP	New	195.00	195.00
4	TO REPLACE RADIATOR ASSEMBLY, FAN HOUSING WITH FAN INCLUDING PRESSURE TEST, BLEED COOLING SYSTEM AND CONDUCT CHECKS FOR LEAK (FOR ALL MODELS EXCEPT 7 SERIES)	New	826.00	702.00
5	TO REPLACE CHARGE AIR COOLER INCLUDING CONDUCT CHECKS FOR LEAK AND PROPER FUNCTION	New	531.00	451.00
6	TO REPLACE AIR CON CONDENSER AND AIR CON HOSE INCLUDING TO VACUUM SYSTEM, TOP UP FREON GAS AND CHECK FOR LEAK (FOR ALL MODELS EXCEPT FOR 7 SERIES)	New	1,003.00	852.00
7	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION (1X)	New	531.00	451.00
8	TO REMOVE AND INSTALL FRONT WINDSCREEN GLASS TO FACILITATE REPAIRS	New	574.00	0.00
9	TO CONDUCT WATER LEAK TESTS	New	75.00	0.00
10	TO REPLACE FRONT DASHBOARD PANEL AND CONDUCT CHECKS FOR PROPER FUNCTION	New	797.00	0.00
11	TO MOUNT ACCIDENT VEHICLE ON CELETTE TO FACILITATE RE-ALIGNMENT OF BODY / CHASSIS IN ACCORDANCE WITH BMW SPECIFICATIONS	New	2,950.00	0.00
12	TO CARRY OUT BODY CAVITY PRESERVATION. (FOR CUT PANEL)	New	531.00	451.00
13	TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL)	New	300.00	300.00
14	TO REPLACE RH LED TECHNOLOGY HEADLIGHTS INCLUDE PROGRAMMING AND CONDUCTING CHECKS FOR PROPER FUNCTION	New	451.00	451.00
15	TO RECONNECT ALL ELECTRICAL COMPONENTS AND CONTROL UNTIS INCLUDE REPLACEMENT OF DAMAGED PARTS AND CONDUCTING TESTS FOR PROPER FUNCTION	New	451.00	451.00
16	TO REPLACE INTAKE SILENCER AND ATTACHMENTS INCLUDE CONDUCTING CHECKS FOR LEAK AND PROPER FUNCTION	New	451.00	451.00
17	TO DIAGNOSE AND REPLACE FRONT RH REPAIR CABLE (LED), ELECTRIC FAN CABLE SET INCLUDE RESETING AND CONDUCTING CHECKS FOR PROPER FUNCTION	New	451.00	451.00
18	TO CONDUCT CHASSIS ALIGNMENT MEASURING CHECK USING CAR-O-LINER MEASURING SYSTEM ACCORDANCE WITH BMW SPECIFICATION	New	531.00	0.00
Gross Labour Cost (S\$)			25,796.00	19,504.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >