



SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
1 Soon Lee Street #04-44/45
Pioneer Centre
Singapore 627605
Tel: 626204438 Fax : 6484 1111

TO	: AIG	DATE	: 16-Apr-18
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT :			
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SJR2748A
ADDRESS	:	MODEL	: KIA CERATO
TEL. NO.	:	CHASSIS NO	:
OWNER'S INSURANCE :			
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>	DATE :		
	TIME :		
THIRD PARTY REQUESTOR / CONTACT :			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOT LID	1	\$ 747.00	\$ <i>Rx</i> 747.00
2	BOOT LID LAMP LH	1	\$ 185.00	\$ <i>at</i> 185.00
3	BOOT LID LOGO 'KIA'	1	\$ 55.00	\$ <i>g</i> 55.00 <i>net</i>
4	BOOT LID EMBLEM 'CERATO'	1	\$ 43.00	\$ <i>x</i> 43.00 <i>net</i>
5	BOOT LID EMBLEM 'FORTE'	1	\$ 47.00	\$ <i>x</i> 47.00 <i>net</i>
6	BOOT LID STOPPER	2	\$ 19.00	\$ <i>x</i> 38.00
7	BOOT LID HINGE	2	\$ 148.00	\$ <i>x</i> 296.00
8	BOOT LID INSULATOR	1	\$ 231.00	\$ <i>x</i> 231.00
9	BOOT LID WEATHER STRIP	1	\$ 148.00	\$ <i>at</i> 148.00
10	BOOT LID LOCK	1	\$ 174.00	\$ <i>x</i> 174.00
11	TAIL LAMP	1	\$ 179.00	\$ <i>an</i> 179.00
12	TAIL LAMP PANEL LH	1	\$ 260.00	\$ <i>Rx</i> 260.00

13	REAR BUMPER	1	\$ 601.00	\$ <i>del</i> 601.00
14	REAR BUMPER LOWER LIP	1	\$ 247.00	\$ <i>an</i> 247.00
15	REAR BUMPER SIDE RETAINER	1	\$ 16.00	\$ <i>nh</i> 16.00
16	REAR BUMPER REINFORCEMENT BRACKET	1	\$ 16.00	\$ <i>x</i> 16.00
17	REAR BUMPER REINFORCEMENT	1	\$ 394.00	\$ <i>over</i> 394.00
18	REAR BUMPER SPONGE	1	\$ 189.00	\$ <i>an</i> 189.00
19	REAR FENDER LH	1	\$ 907.00	\$ <i>Rx</i> 907.00
20	REAR FENDE AIR VENT LH	1	\$ 54.00	\$ <i>int</i> 54.00
21	REAR FENDER INNER COWLING LH	1	\$ 98.00	\$ <i>fn</i> 98.00
22	REAR WINDSCREEN MOULDING	1	\$ 142.00	\$ <i>x</i> 142.00
23	REAR END PANEL	1	\$ 382.00	\$ <i>Rx</i> 382.00
24	REAR WHEEL BEARING LH	1	\$ 318.00	\$ <i>x</i> 318.00
25	REAR SHOCK ABSOBER	1	\$ 410.00	\$ <i>x</i> 410.00
26	REAR AXLE	1	\$ 2,187.00	\$ <i>x</i> 2,187.00
27	REAR BUMPER SENSOR	1	\$ 310.00	\$ <i>dis</i> 310.00

TOTAL PRICE \$ 8,674.00
 LESS 10% \$ 867.40
SUB TOTAL PRICE \$ 7,806.60

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIPS SET	1	\$ 65.00	\$ <i>30</i> 65.00
2	BOOT LID SEALANT	1	\$ 80.00	\$ <i>x</i> 80.00
3	BOOT LID INSULATOR CLIP SET	1	\$ 65.00	\$ <i>x</i> 65.00
4	BOOT LID EMBLEM 'C&C	1	\$ 80.00	\$ <i>x</i> 80.00
5	TAIL LAMP CLIP SET	1	\$ 22.00	\$ <i>an</i> 22.00
6	TAIL LAMP PANEL SEALANT	1	\$ 80.00	\$ <i>x</i> 80.00
7	REAR FENDER SEALANT	1	\$ 80.00	\$ <i>x</i> 80.00
8	REAR FENDER INNER COWLING CLIP SET	1	\$ 79.00	\$ <i>20</i> 79.00
9	REAR FENDER INNER TRIM CLIP SET	1	\$ 79.00	\$ <i>x</i> 79.00
10	REAR WINDSCREEN SEALANT	1	\$ 80.00	\$ <i>x</i> 80.00
11	REAR WINDSCREEN INNER SEAL	1	\$ 60.00	\$ <i>x</i> 60.00
12	REAR END PANEL INSULATION SEAL	1	\$ 120.00	\$ <i>x</i> 120.00
13	REAR END PANEL TOP GARNISH CLIP SET	1	\$ 30.00	\$ <i>x</i> 30.00

TOTAL \$ 920.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, WELDING GRAZING, CUT, JOIN, STRAIGHTEN ALL AFFECTED PARTS	\$ 1,800.00	900 700	
2	TO PUTTY, POLISH, SPRAY PAINT, WAX ALL AFFECTED PANELS	\$ 1,500.00	800 600	
3	TUFF COAT	\$ 250.00	30	
4	WIRING CHECK	\$ 120.00	30	
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 180.00	50	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	30	
7	REMOVE AND REFIX UNDERCARRIAGE	\$ 450.00	X	
8	TRANSFER BOOTLID MECHANISM	\$ 80.00	X	
9	CONDUCT WATER LEAKAGE TEST	\$ 100.00	20	
10	REMOVE AND REFIX REAR WINDSCREEN	\$ 120.00	X	
11	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT	\$ 120.00	X	

TOTAL \$ 4,800.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,726.60
TOTAL LABOUR COST : \$ 4,800.00
TOTAL REPAIR COST : \$ 13,526.60

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

Taufiq 97495719.
- wp'

16/4/18

Lumpsum

Resurvey after repair

5 days

Sur @ lkkauto.com

LKK Auto Consultants will notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____