

S. PEC. BY:

REF:

CS/CT118007084/Ubn2

Special Instruction:

ASSIGNMENT (Office)

S. PEACER

Mulmen

From (Person):

Jawyn Tay

of

CT1

Date/Time:

17042018 430pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKJ 8065C

Insured:

SLP 873X

at Workshop m/s

LBA Automotive

Tel:

of

Blk 1 Kaki Bukit Ave 6 #02-47

Policy No:

DMPCSN173767190D

Claim No:

SNM18D01939C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

13042018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp1

H.O.D. Endorsement:

Date/Time:

17042018 516pm

Person Contacted:

Karen

Vehicle

IN OUT

Date/Time

Action/Instruction (✓) Estimate

SKJ 8065C - X

SLP 873X - CT4 / ASM17021918 / Upa382

DUA: 161117

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKJ8065C

at Workshop n/s: LBA

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 73

IDAC Accident Report: _____ Consistent? : Yes or No

GLA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time Action / Instruction

R/4/18 vehicle tow out to CBC claims o/s already.

Veh No: SKJ8065C Yr Regn: 5-13

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA/

Make: mer seat A200 1525

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 80371 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD1760432J059034

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Disorder / Jammed / Leaked / Burnt or

Brake: Disorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 205/50R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 13/4/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear
The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 20 APR 2018

Date/Time, File Pass to?

☒ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 2014-typist

Report Format: merimen

Lump Sum / I.B.I.: (\$ _____)

Days Of Repair: 6

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ - RS - SI

Photos

Others

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Apr 2018		17 Apr 2018 16:30 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS			[Created by insurer]	
Insured:	CHIN HUI LAN, ID: S1551758A			
Main Claimant:	LIM SIEW KEE, ID: S1384549B			
Vehicle Reg. No.:	SKJ8065C	Date of Loss:	13/04/2018 14:00 - :59	
Claim Type:	TP / SNM18D01939C02	Policy/Cover Note No.:	DMPCSN1737671700	
Vehicle Reg. No. (Insured):	SLP873X	Policy No. (Claimant):		
		Excess:	\$0.00	
Repairer:	LBA Automotive Pte. Ltd. (HQ) 1 Kaki Bukit Ave 6, #02-47 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 65095524			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/04/2018]			
Adj Asg. Remarks:	DEAR MARCUS, PLEASE CONDUCT THIRD PARTY SURVEY, CHECK CONSISTENCY OF THE DAMAGES ON WITHOUT PREJUDICE BASIS. KINDLY LET US HAVE YOUR RECOMMENDED REPAIR AMOUNT IF THERE IS NO ESTIMATE PROVIDED DURING PRE REPAIR.			

ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			

ALL ASSOCIATED TASKS						View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	4549B

Vehicle Details

Vehicle No.:	SKJ8065C
Vehicle to be Exported:	Yes
Intended De-registration Date:	16 Apr 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	A200 BLUE EFFICIENCY
Primary Colour:	Black
Manufacturing Year:	2013
Engine No.:	27091030125269
Chassis No.:	WDD1760432J059034
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$24,613.00
Original Registration Date:	15 May 2013
First Registration Date:	15 May 2013
Transfer Count:	0
Actual ARF Paid:	\$16,459.00 8229

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 May 2023
PARF Rebate Amount:	\$12,344.00

Intended COE Rebate Details

COE Expiry Date:	14 May 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$62,999.00
COE Rebate Amount:	\$31,981.00
Total Rebate Amount:	\$44,325.00

The information contained herein is correct as at 16 Apr 2018

OK



ANNOUNCING Henly Enterprises Co as sgCarMart Premium Dealer for the 6th Consecutive Year

Contact us at 63363133 / 96351017 for your Hire Purchase needs and COE renewal loans at attract

Post an Advertisement


Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Coe Renewal Honda Civic 1.8A



\$2800 Downpayment Monthly
From \$738 Onwards. Lowest
3.68%P.A@GV Cars Financing.
GV Credit Pte Ltd StarAd


[Browse by Category](#)
[Sort b](#)
6 vehicles

[Advant](#)

Make Model Price Depreciation Reg Date Eng Cap Mil

Search Selection
Mercedes Benz A200

Any

Any

2013

Any



Mercedes-Benz A-Class A200

\$77,800
\$13,210 /yr
01-Aug-2013
1,595 cc
44

One Owner, Low Mileage Done At 44000Km, C&C Unit And Maintained By Agent. Accident Free, New Paint. View To App
Call Now, Don't Miss.

Cycle & Carriage.Fulco Motor Dealer

Posted: 16-Apr-2018 Tags: 2013 Mercedes-Benz A200, Mercedes-Benz A200, Mercedes-Benz, A200, Used Mercedes-Benz



Mercedes-Benz A-Class A200

\$81,888
\$13,350 /yr
18-Oct-2013
1,595 cc
72

Lowest Depreciation. Meticulously Well Maintained By Lady Owner. C&C Unit. Pristine Interior/Exterior Condition. Buy Wi
And High Loan Available. Call Now For A Viewing Appo...

Monster Motors Pte Ltd

Posted: 13-Apr-2018 Tags: 2013 Mercedes-Benz A200, Mercedes-Benz A200, Mercedes-Benz, A200, Used Mercedes-Benz



Mercedes-Benz A-Class A200 Urban

\$82,800
\$13,560 /yr
05-Sep-2013
1,595 cc
64

1 Owner, Low Mileage Done, Serviced By C&C, Flexible Loan Package And Interest, Ex Bankruptcy And Bad Credit Welco
Faster Auto Trading

Posted: 07-Apr-2018 Tags: 2013 Mercedes-Benz A200, Mercedes-Benz A200, Mercedes-Benz, A200, Used Mercedes-Benz



Mercedes-Benz CLA-Class CLA200

\$91,800
\$14,770 /yr
23-Sep-2013
1,595 cc
64

Higher Spec Model! Responsive And Fuel Efficient Unit! Drive Away With \$9k Down Payment, 1 Owner Only! Well Mainta
Car In Excellent Condition. High Trade In And Loan Availa...

Posted: 02-Apr-2018 Tags: 2013 Mercedes-Benz CLA200, Mercedes-Benz CLA200, Mercedes-Benz, CLA200, Used Mercedes

[Car Buying](#)
[Car Selling](#)
[Car Ownership](#)
[Compare](#)


LBA AUTOMOTIVE PTE.LTD

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

SLP873X

ESTIMATE

DATE : 16.04.2018

VEHICLE NO : SKJ8065C

MAKE/MODEL : MERS A200

ACC DATE : 13.04.2018

PARTICULAR

QTY

UNIT PRICE

AMOUNT

SS

SS

LIST PRICE

1	1	REAR TAILGATE	1,768.00	1,768.00	—
2	2	REAR TAILGATE HINGE RH/LH	82.00	164.00	X
3	2	REAR TAILGATE DAMPER RH/LH	125.00	250.00	X
4	1	REAR TAILGATE RUBBER	204.00	204.00	—
5	1	REAR TAILGATE LOCK	245.00	245.00	—
6	1	REAR TAILGATE LOCK CATCH	35.00	35.00	X
7	1	REAR TAILGATE INNER TRIM	385.00	385.00	?
8	1	REAR TAILGATE EMBLEM 'LOGO'	69.00	69.00	—
9	1	REAR TAILGATE EMBLEM 'A200'	76.00	76.00	—
10	2	REAR TAILLAMP RH/LH	456.00	912.00	?
11	1	REAR BUMPER	1,533.00	1,533.00	—
12	2	REAR BUMPER PDC SENSOR	285.00	570.00	—
13	1	REAR BUMPER PDC SENSOR WIRE	183.00	183.00	?
14	1	REAR BUMPER TOW COVER	56.00	56.00	—
15	1	REAR BUMPER LOWER LID	335.00	335.00	—
16	2	REAR BUMPER HOLDER RH/LH	69.00	138.00	—
17	1	REAR BUMPER CENTRE GUIDE	162.00	162.00	?
18	1	REAR BUMPER REINFORCEMENT	455.00	455.00	?
19	2	REAR BUMPER SIDE RETAINER RH/LH	59.00	118.00	?
20	1	REAR EXHAUST BOX	1,276.00	1,276.00	X
21	1	REAR EXHAUST BOX HEAT SHIELD	217.00	217.00	X
22	3	REAR EXHAUST MOUNTING	16.00	48.00	X
23	1	REAR END PANEL	865.00	865.00	?
24	1	REAR END PANEL GARNISH	128.00	128.00	?
25	1	REAR SPARE TYRE PANEL	868.00	868.00	X
26	1	REAR SPARE TYRE PANEL CARDBOARD	716.00	716.00	?
				11,776.00	
				LESS 10%	
				1,177.60	
				10,598.40	

SPECIAL NETT ITEMS

1	1	REAR WINDSCREEN SPONGE TAPE	20.00	20.00	✓
2	1	(SET) REAR WINDSCREEN SEALANT	80.00	80.00	40
3	1	(SET) REAR NUMBER PLATE WITH CASING	50.00	50.00	40
4	1	(SET) REAR BUMPER CLIP	45.00	45.00	✓
				195.00	

LBA AUTOMOTIVE PTE.LTD

PARTICULAR	UNIT PRICE	AMOUNT
QTY	SS	SS
LABOUR CHARGES :		
1		1,400.00 800
	TO KNOCK OUT DENT, CUT/WELD REAR PANEL AND REPLACE ACCIDEN PARTS	
2	TO SPRAY PAINTING ON ACCIDENT PORTION	1,200.00 1080
3	TO CHECK WIRING	30.00 ✓
4	TO REMOVE, REFIX WINDSCREEN	120.00 ✓
5	TO TRANSFER REAR TAILGATE PARTS	100.00 60
6	TO REMOVE, REFIX CUSHION AND INNER TRIM	150.00 80
7	TO REMOVE, REPLACE REAR EXHAUST BOX	11 150.00 X
8	TO TUFF KOTE	60.00 ✓
		3,210.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 14,003.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18007084/UVBN2

Date: 24/04/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN1737671700
Claimant Vehicle No :	SKJ8065C	Insured Vehicle No :	SLP873X
Date of Loss:	13/04/2018	Nature of Claim:	TP
		Claim No:	SNM18D01939C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKJ8065C	Engine No:	27091030125269
Make & Model:	MERCEDES-BENZ A200, 1.6 FL AMG LINE (A)	Chassis No:	WDD1760432J059034
Reg. Date:	15/05/2013 (Man. Year: 2013)	Odometer:	80371 km
Colour:	Black		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50R17	Rear Tyre Size:	205/50R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,793.40	4,639.60	6,153.80	57.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,210.00	2,230.00	980.00	30.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	14,003.40	6,869.60	7,133.80	50.94

INSPECTION

Date of Assignment:	17/04/2018	
Date Inspected:	17/04/2018	Inspected At:
		LBA Automotive Pte. Ltd. (HQ)
		1 Kaki Bukit Ave 6, #02-47 Autobay @
		Kaki Bukit
		Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

VEHICLE CONVERT TO OD CLAIMS

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$3,531.60 NETT)

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 Apr 2018)
Parts: 144	MERCEDES-BENZ A200 1.6 FL AMG LINE (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKJ8065C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Badly Dented	1,768.00 FL	*1,768.00 FL
2	2		*REAR TAILGATE HINGE RH/LH	Not Necessary	164.00 FL	*- FL
3	2		*REAR TAILGATE DAMPER RH/LH	Not Necessary	250.00 FL	*- FL
4	1		*REAR TAILGATE RUBBER	Twisted	204.00 FL	*204.00 FL
5	1		*REAR TAILGATE LOCK	Twisted/Shorted	245.00 FL	*245.00 FL
6	1		*REAR TAILGATE LOCK CATCH	Not Necessary	35.00 FL	*- FL
7	1		*REAR TAILGATE INNER TRIM	*Check	385.00 FL	*- FL
8	1		*REAR TAILGATE EMBLEM LOGO	Necessary	69.00 FL	*69.00 FL
9	1		*REAR TAILGATE EMBLEM A200	Necessary	76.00 FL	*76.00 FL
10	2		*REAR TAILLAMP RH/LH	*Check	912.00 FL	*- FL
11	1		*REAR BUMPER	Distorted	1,533.00 FL	*1,533.00 FL
12	2		*REAR BUMPER PDC SENSOR	Shorted	570.00 FL	*570.00 FL
13	1		*REAR BUMPER PDC SENSOR WIRE	*Check	183.00 FL	*- FL
14	1		*REAR BUMPER TOW COVER	Twisted	56.00 FL	*56.00 FL
15	1		*REAR BUMPER LOWER LID	Deformed	335.00 FL	*335.00 FL
16	2		*REAR BUMPER HOLDER RH/LH	Bent	138.00 FL	*138.00 FL
17	1		*REAR BUMPER CENTRE GUIDE	*Check	162.00 FL	*- FL
18	1		*REAR BUMPER REINFORCEMENT	*Check	455.00 FL	*- FL
19	2		*REAR BUMPER SIDE RETAINER RH/LH	*Check	118.00 FL	*- FL
20	1		*REAR EXHAUST BOX	Repair	1,276.00 FL	*- FL
21	1		*REAR EXHAUST BOX HEAT SHIELD	Not Necessary	217.00 FL	*- FL
22	3		*REAR EXHAUST MOUNTING	Not Necessary	48.00 FL	*- FL
23	1		*REAR END PANEL	*Check	865.00 FL	*- FL
24	1		*REAR END PANEL GARNISH	*Check	128.00 FL	*- FL
25	1		*REAR SPARE TYRE PANEL	Repair	868.00 FL	*- FL
26	1		*REAR SPARE TYRE PANEL CARDBOARD	*Check	716.00 FL	*- FL
27	1		*REAR WINDSCREEN SPONGE TAPE	Necessary	20.00 FS	*20.00 FS
28	1		*SET REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
29	1		*SET REAR NUMBER PLATE WITH CASING	Bent	50.00 FS	*40.00 FS
30	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,971.00	5,139.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,177.60	499.40

Total Parts (\$\$)	10,793.40	4,639.60
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENT,CUT/WELD REAR PANEL AND REPLACE ACCIDENT PARTS	New	1,400.00	800.00
2	TO SPRAY PAINTING ON ACCIDENT PORTION	New	1,200.00	1,080.00
3	TO CHECK WIRING	New	30.00	30.00
4	TO REMOVE,REFIX WINDSCREEN	New	120.00	120.00
5	TO TRANSFER REAR TAILGATE PARTS	New	100.00	60.00
6	TO REMOVE,REFIX CUSHION AND INNER TRIM	New	150.00	80.00
7	TO REMOVE,REPLACE REAR EXHAUST BOX	New	150.00	-
8	TO TUFF KOTE	New	60.00	60.00
Gross Labour Cost (S\$)			3,210.00	2,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >