

ASS. REC. BY:

REF:

CA/EG718007090/Sqbm

Special Instruction:

Surveyor:

Sebastian

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EGL

Date/Time:

17/04/2018 10:45am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB 5586m

Insured:

GV 2752B

at Workshop m/s

SMRT

Tel:

6866 2672

of

60 Woodlands Ind Park Et

Policy No:

Claim No:

GV2752B/SU/PI

Sum Insured:

Excess:

Make of Veh:

D.O.A. 14042018

(Client's Record)

CA / REV / REP. / REV 24 HRS WP

H.O.D. Endorsement:

Date/Time:

17/04/2018 11:49am

Person Contacted:

Shanti

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHB 5586m - X
	GV 2752B - X
19/4/18 @ 4.23pm	revised to Steve Lim by email.
	Final est \$5261.06 (Red \$6989.29, 37%)

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TPRES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lump Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or


The UIC / Chassis frame / Body Structure affected due to collision.

Yr Regn:

C.C.

A/C: Insured / Std / NI / NA

T/Radio: Insured / Std / NI / NA



Rear

R/Bal.

L/Bal.

D.O.I.

RECEIVED 11 MAY 2018 (NO GIA Report)

RECEIVED 14 MAY 2018

Gate/Time, File Pass to?

Date/Time, File Return to?

Report Format:

Lump Sum / I.B.I. (\$)

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$
Survey Fee:
Transportation.

) \$ + RS. \$

) Photos

) Others

TOTAL

350

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Tuesday, 17 April, 2018 10:45 AM
To: 'admin-d@lkkauto.com'
Subject: OI : GV2752B / TP : SHB5586M/LKK / DOA : 14/04/2018
Attachments: GV2752B - SAS.pdf; SHB5586M - SAS.pdf; SHB5586M - ESTIMATE.pdf; SHB5586M - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **SMRT AUTOMOTIVE SERVICES PTE LTD**.

ADDRESS : WOODLANDS SMRT DEPOT
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

PERSON TO CONTACT : SHANTI @ 6866 2671/2

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and third party SAS (**note: reports not to be released to any Third Party**).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 17.04.2018
Our Reference: GV 2752B/SL/pl
Your Reference: SHB 5586M

Sent via Fax

or

Email

BThaiyalN@smrt.com.sg

To: SMRT AUTOMOTIVE SERVICES PTE LTD

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SHB 5586M
Insured's Vehicle: GV 2752B
Date Of Accident: 14.04.2018

We acknowledge receipt of your request for PRS on: 17.04.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* **LKK**

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☐ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
- ☐ Your request for inspection does not have your client's GIA report, kindly forward a copy.
- ☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
- ☐ Our Insured's driver has not reported the accident to us todate.
- ☒ Others: OFFICER-IN-CHARGE - STEVE LIM

Prepared by:		Pei Li	6829 9194	<u>claims@ergo.com.sg</u>
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 19 April 2018 4:23 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.); 'Steve Lim'
Cc: SUR; assignments
Subject: RE: GV2752B / TP : SHB5586M/LKK / DOA : 14/04/2018
Attachments: CSEGI18007090Sqb.pdf

Dear Steve,

Enclosed herewith preliminary advice of SHB 5586M.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 17 April 2018 11:51 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: GV2752B / TP : SHB5586M/LKK / DOA : 14/04/2018

Dear Pei Li,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Tuesday, 17 April, 2018 10:45 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: OI : GV2752B / TP : SHB5586M/LKK / DOA : 14/04/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **SMRT AUTOMOTIVE SERVICES PTE LTD,**

ADDRESS : WOODLANDS SMRT DEPOT
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: GV2752B/SL/pl

Date: 19th April 2018

Our Ref: CS/EG118007090/Sqb

Without Prejudice

The Motor Claims Department
ERGO Insurance Pte Ltd

Attn: Pei Li

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SHB 5586M


We thank you for the instruction on 17/04/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 17/04/2018 at the premises of M/s SMRT and have the following to report:-

Workshop Estimate Amount	: S\$ <u>12,250.34</u>
Revised Estimate Amount	: S\$ <u>4,834.78</u>
"Check" Items Amount	: S\$ <u>1,002.74</u>
Market Value	: S\$ <u>-</u>
Salvage Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the n/s rear portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 5 days.

We have NOT authorise repair.

Yours faithfully

Sebastian
Automotive Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHB5586M
Vehicle to be Exported:	No
Intended De-registration Date:	18 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZRS110085
Chassis No.:	JTDKB3FU0003575695
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	30 Nov 2017
First Registration Date:	30 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Nov 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	29 Nov 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$33,596.00
COE Rebate Amount:	\$31,974.00
Total Rebate Amount:	\$35,724.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 18 Apr 2018

OK

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5586M
 Ref. No : TAX/04/18/2079
 Reg. Date : 30/11/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : LIM SEAH PEE
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 14/04/2018 05:10:00 PM
 Accident Reported Date / Time : 16/04/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095577
 Special Instruction to ARC,if any :
 DROVE IN / GV2752B
 Prepared Date : 16/04/2018 12:54:19 PM



Sebastian
 17/4/18.
 - Part by part repair.
 - Question Mark Item
 Photo
 - Photo Before Paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU003575695

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 1,836.00	0.00
Total Material Charges	: 6,507.97	6,507.97
Other Charges	: 1,060.00	0.00
TOTAL	: 10,417.97	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 7.00	0.00
Prepared / Adjusted By	:	5 days.
Arc / Surveyor Sign Off Date	: 16/04/2018 03:59:30 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 16/04/2018 03:59:30 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	1,014.00	0.00 600
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR FENDER LH	378.00	0.00 200
TO RESPRAY REAR LH WHEEL HOUSE	180.00	0.00 ?
TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0.00 ?
TO RESPRAY RIM	180.00	0.00 50
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 100
TO RESPRAY SPOILER	180.00	0.00 50
TO RESPRAY FILLER RR BUMPER LH	180.00	0.00 50
Total Spray Painting & Panel Beating	1,836.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 30
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 60
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 50
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 30
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 30
TO REMOVE AND REFIT TYRE	120.00	0.00 X
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	1,060.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
6160247160			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	25.00	618.60	Replace	Replace	No
6163247900			PANEL, QUARTER WHEEL HOUSE, OUTER LH	1	286.80	25.00	215.10	Replace	Replace	No
5831647010			EXTENSION, REAR FLOOR SIDE PANEL, LH	1	76.20	25.00	57.15	Replace	Replace	No
6294047010			DUCT ASSY, QUARTER VENT, RH & LH	1	65.00	25.00	48.75	Replace	Replace	No
5387647110			LINER, FR FENDER, LH	1	194.30	25.00	145.72	Replace	Replace	No
4261147450			WHEEL, DISC	1	1,555.10	25.00	1,166.32	Replace	Replace	No
			TYRE	1	126.74	0.00	126.74	Replace	Replace	No
5215947913			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace	No
5256647900			FILLER, RR BUMPER, LH	1	119.90	25.00	89.92	Replace	Replace	No
5257647040			RETAINER, RR BUMPER, LH	1	111.50	25.00	83.62	Replace	Replace	No
5259247040			SEAL, RR BUMPER, LH	1	85.20	25.00	63.90	Replace	Replace	No
8159147010			LENS & BODY ASSY, RR BUMPER, LH	1	486.80	10.00	438.12	Replace	Replace	No
8156147151			LENS & BODY, REAR COMBINATION LAMP, LH	1	438.10	10.00	394.29	Replace	Replace	No
5246247030			PAD, RR BUMPER, RH & LH, 1	2	3.80	25.00	5.70	Replace	Replace	No
5246247020			PAD, RR BUMPER, RH & LH, 2	2	3.80	25.00	5.70	Replace	Replace	No
5246247010			PAD, RR BUMPER, RH & LH, 3	2	3.80	25.00	5.70	Replace	Replace	No
5219147030			SEAL, RR BUMPER ARM, RH & LH	2	11.00	25.00	16.50	Replace	Replace	No
5216116010			CLIPS PIECE, FRT & RR BUMPER	10	1.50	25.00	11.25	Replace	Replace	No
5245347010			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace	No
5839947030			COVER, REAR FLOOR UNDER, LH	1	234.30	25.00	175.72	Replace	Replace	No
7680147110A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	25.00	668.40	Replace	Replace	No
7544147090			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No
7544247130			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No
			STICKER SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
75403480 10			EMBLEM SUB-ASSY REAR	1	46.30	25.00	34.72	Replace	Replace	No <i>ARC</i>
76085479 16			SPOILER SUB-ASSY, REAR	1	1,322.10	25.00	991.57	Replace	Replace	No <i>R</i>
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace ?	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No <i>ARC</i>
TOTAL MATERIALS								6,508.03	6,507.97	
TOTAL MATERIALS(Discounted)								6,507.97	6,507.97	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

17250.34



Attached
Supplementary

Handwritten: 23-4-18 / 11:02
23-4-18 / 15:02
Guan

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Handwritten: 17-4-18/15:02

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5586M
Ref. No : TAX/04/18/2079
Reg. Date : 30/11/2017
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS4
Name of Driver : LIM SEAH PEE
Type of Accident : SIDE SWIPE
Date / Time of Accident : 14/04/2018 05:10:00 PM
Accident Reported Date / Time : 16/04/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : Sebastian
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024095577
Special Instruction to ARC, if any :
DROVE IN / GV2752B - ERGO P/R
BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL
SURVEYOR SEBASTIAN (LKK) & Email : sebastianeang @lkkauto.com HP:90036121
Prepared Date : 16/04/2018 12:54:19 PM



Recording Camera

☐ ☒

Radio Antenna

☐ ☒

1st witness

Date 17-4-18

2nd witness

Date

E 1/2 F
KM 25715

Vehicle to Wega Date In: 18/04 Towing:
Time In: 17:18 Driver: HWS
Wega Job No: 04/0250
Vehicle sent to SMART Date In: 24/4/18 Towing:
Time In: 11:00/15 Driver: Guan
Received by (SMART):

Handwritten: 24/4/18 11:50 QC PASS

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU003575695

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,014.00	800.00
Total Spray Painting Charges :	1,836.00	650.00
Total Material Charges :	3,997.53	3,551.05
Other Charges :	1,060.00	260.00
TOTAL :	7,907.53	5,261.05
Lum Sum Total :	0.00	0.00
No. of Repair Days :	7.00	6.00
Prepared / Adjusted By :		SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date :	16/04/2018 03:59:30 PM	17/04/2018 03:02:29 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 16/04/2018 03:59:30 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1804-0727

Invoice No :

Quotation Date : 30/4

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	1,014.00	800.00 /
Total Labour	1,014.00	800.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR FENDER LH	378.00	200.00 /
TO RESPRAY REAR LH WHEEL HOUSE	180.00	0.00
TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0.00
TO RESPRAY RIM	180.00	50.00 /
TO REPSRAY REAR BUMPER	378.00	200.00 /
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100.00 /
TO RESPRAY SPOILER	180.00	50.00 /
TO RESPRAY FILLER RR BUMPER LH	180.00	50.00 /
Total Spray Painting & Panel Beating	1,836.00	650.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30.00 /
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30.00 /
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60.00 /
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00 /
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	50.00 /
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30.00 /
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30.00 /
TO REMOVE AND REFIT TYRE	120.00	0.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	1,060.00	260.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
6160247160			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	25.00	618.60	Replace	Replace	No <i>OT</i>
6163247900			PANEL, QUARTER WHEEL HOUSE, OUTER LH	0	286.80	25.00	0.00	Replace	Not given	No <i>NW</i>
5831647010			EXTENSION, REAR FLOOR SIDE PANEL, LH	1	76.20	25.00	57.15	Replace	Check	No <i>NW</i>
6294047010			DUCT ASSY, QUARTER VENT, RH & LH	1	65.00	25.00	48.75	Replace	Replace <i>S</i>	No <i>Defon</i>
5387647110			LINER, FR FENDER, LH	1	194.30	25.00	145.72	Replace	Replace	No <i>CRK</i>
4261147450			WHEEL, DISC	1	1,555.10	25.00	1,166.32	Replace	Replace	No <i>CRK</i>
			TYRE	0	126.74	0.00	0.00	Replace	Not given	No <i>NW</i>
5215947913			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace	No <i>CRK</i>
5256647900			FILLER, RR BUMPER, LH	1	119.90	100.00	0.00	Replace	Repair	No <i>CRK</i>
5257647040			RETAINER, RR BUMPER, LH	1	111.50	25.00	83.63	Replace	Replace <i>S</i>	No <i>Defon</i>
5259247040			SEAL, RR BUMPER, LH	1	85.20	25.00	63.90	Replace	Replace <i>S</i>	No <i>CRK</i>
8159147010			LENS & BODY ASSY, RR BUMPER, LH	1	486.80	10.00	438.12	Replace	Replace	No <i>CRK</i>
8156147151			LENS & BODY, REAR COMBINATION LAMP, LH	1	438.10	10.00	394.29	Replace	Replace	No <i>CRK</i>
5246247030			PAD, RR BUMPER, RH & LH, 1	2	3.80	25.00	5.70	Replace	Check	No <i>X</i>
5246247020			PAD, RR BUMPER, RH & LH, 2	2	3.80	25.00	5.70	Replace	Check	No <i>X</i>
5246247010			PAD, RR BUMPER, RH & LH, 3	2	3.80	25.00	5.70	Replace	Check	No <i>X</i>
5219147030			SEAL, RR BUMPER ARM, RH & LH	2	11.00	25.00	16.50	Replace	Check	No <i>X</i>
5216116010			CLIPS PIECE, FRT & RR BUMPER	10	1.50	25.00	11.25	Replace	Replace	No <i>MEC</i>
5245347010			GUARD, RR BUMPER, LOWER	0	558.30	25.00	0.00	Replace	Not given	No <i>X</i>
5839947030			COVER, REAR FLOOR UNDER, LH	1	234.30	25.00	175.73	Replace	Check	No <i>X</i>
7680147110A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	100.00	0.00	Replace	Repair	No <i>CRK</i>
7544147090			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No <i>CRK</i>
7544247130			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No <i>CRK</i>
			STICKER SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No <i>CRK</i>
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No <i>CRK</i>
7540348010			EMBLEM SUB-ASSY REAR	1	46.30	25.00	34.72	Replace	Replace	No <i>CRK</i>

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
7608547916			SPOILER SUB-ASSY, REAR	1	1,322.10	100.00	0.00	Replace	Repair	No <i>R</i>
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Check	No <i>X</i> <i>WV</i>
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No <i>N/C</i>
TOTAL MATERIALS							3,997.56	3,551.06		
TOTAL MATERIALS(Discounted)							3,997.53	3,551.05		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

$$\begin{array}{r}
 3551.06 \\
 + 800.00 \\
 + 910.00 \\
 \hline
 5261.06
 \end{array}$$

Sebastian
 4/5/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD			Ref : CS/EGI18007090/Sqbn2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985			Date : 15-05-2018	
			Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GV 2752B	Veh. Inspected	SHB 5586M	
Policy No.		Coverage (\$)	0.00	
Claim No.	GV2752B/SL/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	17/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU003575695	Colour	MAROON	
Odometer	25715	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/04/2018	Inspection Date	17/04/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5586M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	PANEL SUB-ASSY FENDER REAR LH (DISC 25%)	DENTED	824.80	618.60
1	DUCT ASSY, QUARTER VENT, RH & LH (DISC 25%)	DEFORMED	65.00	48.75
1	LINER, FR FENDER, LH (DISC 25%)	CRACKED	194.30	145.72
1	WHEEL, DISC (DISC 25%)	CUT	1,555.10	1,166.32
1	COVER, RR BUMPER ASSY (DISC 25%)	CRACKED	423.90	317.92
1	RETAINER, RR BUMPER, LH (DISC 25%)	DEFORMED	111.50	83.63
1	SEAL, RR BUMPER, LH (DISC 25%)	CRACKED	85.20	63.90
10	CLIPS PIECE, FRT & RR BUMPER @\$1.50 (DISC 25%)	NECESSARY	15.00	11.25
1	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR (DISC 25%)	NECESSARY	52.30	39.22
1	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR (DISC 25%)	NECESSARY	52.30	39.22
1	EMBLEM SUB-ASSY REAR (DISC 25%)	NECESSARY	46.30	34.72
1	LENS & BODY ASSY, RR BUMPER, LH (DISC 10%)	CRACKED	486.80	438.12
1	LENS & BODY, REAR COMBINATION LAMP, LH (DISC 10%)	CRACKED	438.10	394.29
1	STICKER SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	PANEL, QUARTER WHEEL HOUSE, OUTER LH	NOT NECESSARY	286.80	-
1	EXTENSION REAR FLOOR SIDE PANEL, LH	NOT NECESSARY	76.20	-
1	TYRE	NOT NECESSARY	126.74	-
2	PAD RR BUMPER, RH & LH, 1 @\$3.80	NOT NECESSARY	7.60	-
2	PAD RR BUMPER, RH & LH, 2 @\$3.80	NOT NECESSARY	7.60	-
2	PAD RR BUMPER, RH & LH, 3 @\$3.80	NOT NECESSARY	7.60	-
2	SEAL RR BUMPER ARM, RH & LH @\$11.00	NOT NECESSARY	22.00	-
1	GUARD, RR BUMPER, LOWER	NOT NECESSARY	558.30	-
1	COVER, REAR FLOOR UNDER, LH	NOT NECESSARY	234.30	-
1	SENSOR REVERSE	NOT NECESSARY	180.00	-
1	FILLER RR BUMPER, LH	TO REPAIR SEE LABOUR	119.90	-
1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	TO REPAIR SEE LABOUR	891.20	-

Report Ref No. CS/EG18007090/Sqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPOILER SUB-ASSY, REAR	TO REPAIR SEE LABOUR	1,322.10	-
			8,340.34	3,551.06
	LABOUR			
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	PANEL BEATING AND BODY WORK, INCLUSIVE OF THE REPAIR OF FILLER RR BUMPER, LH, TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY AND SPOILER SUB-ASSY, REAR.		1,014.00	800.00
	SPRAY PAINT.		1,836.00	650.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	30.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	30.00
	TO DO WHEEL ALIGNMENT/TYRE BALANCING.		120.00	60.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	30.00
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.		120.00	50.00
	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.		120.00	30.00
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).		120.00	30.00
	TO REMOVE AND REFIT TYRE.	NOT NECESSARY	120.00	-
			3,910.00	1,710.00
	GRAND TOTAL		12,250.34	5,261.06
	RECOMMENDED COST OF REPAIRS			5,261.06

Report Ref No. CS/EGI18007090/Sqbn2

YEANG WAI KEEN
Automotive Assessor

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.