

ASS. REC. BY:

REF: 18/CTU8007093 / Gvbz Special Instruction:

SURVIVOR
MULANIN

GR

ASSIGNMENT (Office)

From (Person): Irene Tay of CT Date/Time: 17042018 1:27pm

Estimated Cost: Bill to:

OD / IP / WS / TP / RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBB 4555E Insured: SDW 4988E

at Workshop m/s Mulanin Tel: 9755 7336. | 6864 0637

of 10 Tues Apr 18

Policy No: DmpCSN1756031700 Claim No: SNM18001905CD.

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 11.04.2018

CA / REV / REP. / REV 24 HRS Wpr 20042018 @ 1130am - 48 Cheng, South St 1
H.O.D. Enforcement:

Date/Time: 17042018 1:40 pm Person Contacted: Le Wei Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	GBB 4555E - x
	SDW 4988E - x
30/5/18	@ 958am Le Wei said waiting for spare parts
29/6/18	@ 440pm Le Wei said vehicle has not send in for repair
2/7/18	Submit preli report

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Apr 2018		17 Apr 2018 13:27 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	REBECCA CHING SOO OOI, ID: S7070542G								
Main Claimant:	HENG REFRIGERATION AND ELECTRICAL ENGINEERING								
Vehicle Reg. No.:	GBB4555E	Date of Loss:	11/04/2018 10:00 - :59						
Claim Type:	TP / SNM18D01905C02	Policy/Cover Note No.:	DMPCSN1756031700 (Comprehensive)						
Vehicle Reg. No. (Insured):	SDW4988E	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Motorviva Pte Ltd (HQ) 10 Tuas Avenue 18, 638894 Tuas - Tel: 68640695								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/04/2018]								
Adj Asg. Remarks:	EST \$5779.34, ASSIGN MARCUS CHUA AS SJE.								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	4600W
Vehicle Details	
Vehicle No.:	GBB4555E
Vehicle to be Exported:	No
Intended De-registration Date:	23 Apr 2018
Vehicle Make:	FIAT
Vehicle Model:	DUCATO 2.3JTD SWB
Primary Colour:	White
Manufacturing Year:	2007
Engine No.:	F1AE0481D0478624
Chassis No.:	ZFA25000001144842
Maximum Power Output:	-
Open Market Value:	\$31,078.00
Original Registration Date:	26 Mar 2009
First Registration Date:	26 Mar 2009
Transfer Count:	0
Actual ARF Paid:	\$1,554.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	25 Mar 2019
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$5,300.00
COE Rebate Amount:	\$504.00
Total Rebate Amount:	\$504.00

The information contained herein is correct as at 23 Apr 2018

OK



MOTORVIVA PTE LTD

10 Tuas Avenue 18 Singapore 638894
Tel: +65 6665 2518 (Sales) +65 6448 2686 (Service)
Fax: +65 6561 7956 (Sales) +65 6442 5571 (Service)
Website: www.goldbell.com.sg
Co. Reg. No.: 1995076142

DATE : 12/4/2018

TO : HENG REFRIGERATION AND ELECTRICAL E
ATTN : MR SEAH
OFFICE / MOBILE : 9694 5525
EMAIL ADDRESS : -

FROM : MOTORVIVA PTE LTD
ATTN : MR LI LEWEI
OFFICE / MOBILE : 6864-0637 / 9755-7336
FAX NO. : 6863-0425

VEHICLE NO. : GBB4555E
MODEL NO. : FIAT DUCATO-2.3 D JTD SWB
CHASSIS NO. : ZFA25000001144842
ENGINE NO. : F1AE0481D0478624
REG. DATE : 30/03/2009

REF. NO. : GBE/SVC/SALES-4616/180412
D.O.A. : 11/4/2018
POLICY NO. : VCA/P/1839321
CLAIM TYPE : TP CLAIM - CHINA TAIPING

WORKSHOP : 10 TUAS AVE 18

S/N	PART NO.	DESCRIPTION	QUANTITY	PRICE
1	1364511080	FRONT DOOR RHS <i>X Repair.</i>	1	\$ 3,006.72
2	1350621080	FRONT DOOR HINGE RHS <i>X LNN</i>	1	\$ 107.09
3	1358220080	FRONT DOOR CHECK RHS <i>X LNN</i>	1	\$ 120.74
4	735422811	FRONT DOOR MOULDING RHS <i>L SCK</i>	1	\$ 189.78 ✓
5	735432334	SIDE MIDDLE MOULDING RHS <i>L SCK</i>	1	\$ 130.49 ✓
SUB-TOTAL :				\$ 3,554.82
LESS 10% :				\$ 355.48
BALANCE :				\$ 3,199.34

SPECIAL-NETT ITEMS

1	COMPANY DETAILS STICKER / <i>ML</i>	1	\$ 30.00 ✓
PARTS TOTAL :			\$ 3,229.34

LABOUR CHARGES

1	TO REMOVE & REFIT DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC.	\$ 1,800.00	<i>300</i>
2	TO PUTTY, CLEAN, SPRAY PAINT & POLISH	\$ 600.00	<i>425</i>
3	TO REMOVE AND REFIX FRONT DOOR COMPARTMENT.	\$ 120.00	<i>X ML</i>
4	SUNDRIES	new \$ 30.00	<i>10</i>
LABOUR TOTAL :		\$ 2,550.00	
GRAND TOTAL :		\$ 5,779.34	

PREPARED BY : LI LEWEI

DATE / TIME : *20/4/18*

SURVEYOR : *Guo Qiang*

MOBILE NO. : *8288 0282*

OFFICE FAX NO. :

EMAIL ADDRESS : *Guo.Qiang@lkkauto.com*

2 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To remove and/or after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation and part prices on a "no prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



MOTORVIVA PTE LTD

10 Tuas Avenue 18 Singapore 638894

Tel: +65 6665 2518 (Sales) +65 6448 2686 (Service)

Fax: +65 6561 7956 (Sales) +65 6442 5571 (Service)

Website: www.goldbell.com.sg

Co. Reg. No.: 199507614Z

REPAIR TYPE : PART-BY-PART / LUMP SUM

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS : _____

REMARKS : _____

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118007093/GVBN2
Date: 05/07/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN1756031700
Claimant Vehicle No :	GBB4555E	Insured Vehicle No :	SDW4988E
Date of Loss:	11/04/2018	Nature of Claim:	TP
		Claim No:	SNM18D01905C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB4555E	Engine No:	F1AE0481D0478624
Make & Model:	FIAT DUCATO, 2.3 D JTD SWB (Typ 250) (M)	Chassis No:	ZFA25000001144842
Reg. Date:	26/03/2009 (Man. Year: 2007)	Odometer:	200822 km
Colour:	White		
Engine Capacity:	2287 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/70R15	Rear Tyre Size:	225/70R15
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,259.34	328.24	2,931.10	89.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,520.00	725.00	1,795.00	71.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	5,779.34	1,053.24	4,726.10	81.78

INSPECTION

Date of Assignment:	17/04/2018	Inspected At:	48 Changi South ST 1
Date Inspected:	20/04/2018		Repairer: Motorviva Pte Ltd (HQ)
			10 Tuas Avenue 18
			Singapore 638894

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 05 Jul 2018)
 Parts: N/A FIAT DUCATO 2.3 D JTD SWB (Typ 250) (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for GBB4555E)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RHS	Repair	3,006.72 FL	*- FL
2	1		*FRONT DOOR HINGE RHS	Not Necessary	107.09 FL	*- FL
3	1		*FRONT DOOR CHECK RHS	Not Necessary	120.74 FL	*- FL
4	1		*FRONT DOOR MOULDING RHS	Scratched	189.78 FL	*189.78 FL
5	1		*SIDE MIDDLE MOULDING RHS	Scratched	130.49 FL	*130.49 FL
6	1		*COMPANY DETAILS STICKER	Necessary	30.00 FS	*30.00 FS
7	1		*SUNDRIES	Necessary	30.00 FS	*10.00 FS
Sub Total (S\$)					3,614.82	360.27
- List Item Discount on L Items 10.00/10.00% (S\$)					355.48	32.03
Total Parts (S\$)					3,259.34	328.24

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT DAMAGED PARTS,CUT,WELD,PANEL BEAT,STRAIGHTEN & REALIGN,ETC	New	1,800.00	300.00
2	TO PUTTY,CLEAN,SPRAY PAINT & POLISH	New	600.00	425.00
3	TO REMOVE AND REFIX FRONT DOOR COMPARTMENT	New	120.00	-
Gross Labour Cost (S\$)			2,520.00	725.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >