

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

16-Apr-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8783 R

|          |                                                    |    |          |
|----------|----------------------------------------------------|----|----------|
| 1 pc     | Front bumper <i>x repair</i>                       | \$ | 531.00   |
| 1 pc     | Front bumper emblem <i>x</i>                       | \$ | 44.00    |
| 1 pc     | Front bumper lip <i>missing</i>                    | \$ | 52.00    |
| 1 pc     | Front bumper inner sponge <i>x</i>                 | \$ | 110.00   |
| 1 pc     | Front bumper reinforcement <i>x</i>                | \$ | 328.00   |
| 1 pc     | Front bumper n/s fog lamp cover @ \$66.00 <i>x</i> | \$ | 66.00    |
| 1 pc     | Front bumper n/s protector @ \$51.00 <i>x</i>      | \$ | 51.00    |
| 1 pc     | Bonnet grille @ \$386.00 <i>x repair</i>           | \$ | 386.00   |
|          |                                                    | \$ | 1,568.00 |
| Less 10% |                                                    | \$ | 156.80   |
|          |                                                    | \$ | 1,411.20 |

### S/NETT

|       |                                      |    |       |
|-------|--------------------------------------|----|-------|
| 1 pc  | Front no. plate with casing <i>✓</i> | \$ | 50.00 |
| 1 set | Front bumper clips <i>x</i>          | \$ | 48.00 |

Sundry \$ ~~50.00~~ *20*

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

\$ ~~180.00~~ *x*

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front bumper

\$ ~~650.00~~ *200 360*

To putty and spray painting on bonnet grille, front bumper

\$ ~~400.00~~ *360*

To apply rustproofing on the repaired and replaced panels.

\$ ~~200.00~~ *x*

\$ 2,989.20

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

- To resurvey before/after repair
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Ka Lin (CIC)*  
*11 16/4/8 1626hr*  
*2 Pys*  
*4s*  
*After Repair photo*