

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

16-Apr-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8044 R

1 pc	Front bumper ✓	\$	531.00
1 pc	Front bumper emblem ✓	\$	44.00
1 pc	Front bumper n/s side retainer @ \$16.00 ✕	\$	16.00
1 pc	Front bumper n/s upper bracket @ \$16.00 ✕	\$	16.00
1 pc	Front bumper n/s support bracket @ \$16.00 ✕	\$	16.00
1 pc	Front bumper sponge ✕	\$	110.00
1 pc	Front bumper reinforcement ✕	\$	328.00
1 pc	Front bumper centre grille ✕	\$	174.00
1 pc	Front bumper n/s fog lamp cover @ \$66.00 ✓	\$	66.00
1 pc	Front bumper n/s protector @ \$51.00 ✓	\$	51.00
1 pc	Front bumper lower lip ✕ <i>142</i>	\$	38.00
		\$	1,390.00
		Less 10%	\$ 139.00
			<u>\$ 1,251.00</u>

S/NETT

1 set	Front bumper clips ✓	\$	48.00
	Sundry	\$	50.00 ✕
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 ✕
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc	\$	650.00 <i>200</i>
	To putty and spray painting on front bumper, bonnet grille ✕	\$	400.00 <i>180</i>
	To apply rustproofing on the repaired and replaced panels.	\$	200.00 ✕
			<u>\$ 2,779.00</u>

LKK Auto Consultants hence notify
the Repairer of the following:

• To resurvey before/after spray painting
• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Kelvin (LKK)

16/4/18 1346L

2 days

PIP Before Part p 66