

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

16-Apr-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6440 M

1 pc	Front o/s door ✓	\$	761.00
2 pcs	Front o/s door hinge @\$34.00 X	\$	68.00
1 pc	o/s rocker panel garnish X repair	\$	286.00
1 pc	Rear o/s door X repair	\$	791.00
2 pcs	Rear o/s door hinge @\$34.00 X	\$	68.00
1 pc	o/s wheel cover ✓	\$	116.00
		\$	2,090.00
Less 10%		\$	209.00
		\$	1,881.00

S/NETT

1 pc	rear o/s fender sticker ✓	\$	60.00
1 pc	o/s door sticker ✓	\$	100.00
1 set	o/s rocker panel garnish clips X	\$	28.00

Sundry \$ ~~50.00~~ 20

To check wheel alignment \$ ~~80.00~~ X

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs. \$ ~~180.00~~ 50

To dismantle and refit the inner component of Front o/s door into new shell door *Front only* \$ ~~150.00~~ 50

To dismantle and refit the inner component of rear o/s door into new shell door \$ ~~150.00~~ X

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear o/s fender \$ ~~700.00~~ 400

To putty and spray painting on rear o/s fender, rear o/s door, front o/s door, o/s rocker panel garnish \$ ~~800.00~~ 720

To apply rust proofing on the repaired and replaced panels. \$ ~~150.00~~ 50

\$ 4,329.00

LKK Auto Consultancy
To apply rust proofing on the repaired and replaced panels.
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Acknowledged by Repairer

Signature:

Date:

Kelvin LKK

16/4/18 1605h

3 days

4/5

After Repair photo