



GST / ROC Company No :

201101753C

u

Third Party Insurer :

AIG

Insured's Veh No :

SLB9461R

Date of accident :

15/04/2018

Grab Rentals Pte Ltd
18 Sin Ming Lane
#01-08 Midview City
Singapore 573960

not Alhamd
like
17/4/18
Take photo before repairing.
Sdy.

Quotation No : AR/QO18/04-1069

Quotation Date : 16/04/2018

P/P - \$5149.60 confirmed.

Estimate To Repair

HONDA VEZEL HYBRID 1.5X AUTO

Vehicle No :

SLW3494A

Chassis No :

RU3-1222437

Pages :

1 of 1

S/NO	QUANTITY	DESCRIPTION	AMOUNT
SPARE PARTS			
1	1 SET	REAR WINDSCREEN MOULDING <i>rec</i>	\$160.00
2	1 PC	REAR GATE <i>body</i>	\$1,010.00
3	1 PC	REAR GATE "VEZEL" PLATE <i>rec</i>	\$45.00
4	1 PC	REAR GATE "HYBRID" PLATE <i>rec</i>	\$60.00
5	1 PC	REAR GATE INNER RUBBER <i>rec</i>	\$120.00
6	1 PC	REAR GATE LOCK <i>rec</i>	\$105.00
7	1 PC	REAR GATE INNER TRIMBOARD <i>11</i>	\$225.00
8	12 PC	INNER TRIM CLIPS @ \$5.90 <i>11</i>	\$70.80
9	1 PC	REAR BUMPER (CENTRE) <i>7.5</i>	\$810.00
10	1 PC	REAR BUMPER LH (CORNER) <i>22/12</i>	\$185.00
11	1 PC	REAR BUMPER RETAINER LH <i>3.5</i>	\$35.00
12	10 PC	REAR BUMPER CLIPS @ \$5.90 <i>rec</i>	\$59.00
13	1 PC	REAR END PANEL <i>22/300</i>	\$550.00
14	1 PC	REAR END PANEL TOP TRIM <i>11</i>	\$95.00
15	1 PC	REAR BUMPER REFLECTOR LH <i>11</i>	\$165.00
16	1 PC	REAR GATE LAMP LH <i>5.2</i>	\$435.00
17	1 PC	REAR FENDER PROTECTOR LH <i>11</i>	\$225.00
18	6 PC	PROTECTOR CLIPS @ \$5.90 <i>11</i>	\$35.40
			<i>422-2020</i>
			\$4,390.20
			<i>3217-60</i>
			\$878.04
			\$3,512.16
			<i>Rec in tail lamp \$488</i>
MISC ITEMS			
19	1 PC	REVERSE SENSOR <i>shower</i>	\$250.00
20	1 PC	REAR WINDSCREEN <i>gun sealant</i>	\$65.00
Total			\$315.00
LABOUR & MISC. CHARGES			
1		WIRE CHECKING	\$30.00
2		REMOVE & REFIX REAR WINDSCREEN	\$120.00
3		REMOVE & REFIX HYBRID SYSTEM	\$280.00
4		TRANSFER REAR GATE COMPONENT FROM OLD TO NEW	\$120.00
5		CAVITY PROTECTION ON ALL AFFECTED AREAS	\$100.00

Please conduct the survey at

Pegasus Engineering @ SME c/o 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883

GARY 8338 8418



GST / ROC Company No : 201101753C

Third Party Insurer : AIG

Insured's Veh No : SLB9461R

Date of accident : 15/04/2018

Grab Rentals Pte Ltd
18 Sin Ming Lane
#01-08 Midview City
Singapore 573960

Quotation No : AR/QO18/04-1069

Quotation Date : 16/04/2018

Estimate To Repair HONDA VEZEL HYBRID 1.5X AUTO

Vehicle No : SLW6494A

Chassis No : RU3-1222437

Pages : 1 of 1

S/NO	QUANTITY	DESCRIPTION	AMOUNT
6		LABOUR CHARGE	\$850.00
7		SPRAY PAINTING	\$850.00
		Total	\$2,350.00
			1660
		<i>Ex List 3217.60</i> <i>SN 240</i> <i>LC 1660</i> <i>Total 5117.60</i>	<i>p- 4062</i> <i>3249.60</i> <i>5149.60</i>
		Sub Total	\$6,177.16
		GST (7.00%)	\$432.40
		Total	\$6,609.56

Please conduct the survey at

Pegasus Engineering @ SME c/o 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883

GARY 8338 8418



GST / ROC Company No : 201101753C

Third Party Insurer : AIG

Insured's Veh No : SLB9461R

Date of accident : 15/04/2018

Grab Rentals Pte Ltd
18 Sin Ming Lane
#01-08 Midview City
Singapore 573960

Quotation No : AR/QO18/04-1069

Quotation Date : 16/04/2018

SUPPLEMENTARY

HONDA VEZEL HYBRID 1.5X AUTO

Vehicle No :

SLW6494A

Chassis No :

RU3-1222437

Pages : 1 of 1

S/NO	QUANTITY	DESCRIPTION	AMOUNT
1		PARTS	
		REAR LH TAIL LAMP	C47/ CM \$488.00 ✓
			\$488.00
		LESS 20%	\$97.60
			\$390.40
		Sub Total	\$390.40
		GST (7.00%)	\$27.33
		Total	\$417.73

Please conduct the survey at

Pegasus Engineering @ SME c/o 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883

GARY 8338 8418