

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 9362D

DATE 16/4/2018 11:00

MAKE :

MODEL : HYUNDAI i40

DLK

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>X 1400</i>			\$ 603.60
	Rear Bumper Clips <i>X 11</i>			\$ 22.00
	Rear Bumper Reflector Lamp (RH) <i>X 32.00</i>			\$ 32.00
	Rear Wheel Hub Cap, RH <i>X 150.70</i>			\$ 150.70
	<i>Rear RH Fender x repair</i>			
	SUB TOTAL			\$ 808.30
	LESS 20%			\$ 161.66
	DISCOUNTED TOTAL			\$ 646.64
	Rear Bumper Reverse Sensor <i>X 135.70</i>			\$ 135.70
				\$ 135.70
	Labour Charge			
	Panel Beating			\$ 500.00 <i>300</i>
	Spray Painting Charge			\$ 500.00 <i>400</i>
	Wiring Charge			\$ 50.00 <i>20</i>
	Tuff Kote			\$ 50.00 <i>X 11</i>
	R/Refix Reverse Sensor			\$ 120.00 <i>X 11</i>
	Rear Wheel Alignment			\$ 80.00 <i>X 11</i>
	TOTAL LABOUR			\$ 1,300.00
	ESTIMATE TOTAL			\$ 2,082.34
<i>Ka hui 16/4/18</i> <i>16/4/18 1235hr</i> <i>2 Days</i> <i>P/P</i> <i>After Repair photo</i>				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged parts during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modifications is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				