

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD6729B

MAKE : HYUNDAI

MODEL : i40

Date: 16.04.2018

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	Front Bumper ✓			\$ 1,052.20
10	Front Bumper Clips ✓		\$2.20	\$ 22.00
1	Front Bumper Top Bracket – LH ✓			\$ 22.40
1	Front Bumper Bracket – LH ✓			\$ 24.60
1	Headlamp ✕			\$ 1,388.00
1	Headlamp Support Panel ✕			\$ 1,067.50
1	Front Fender – LH ✓			\$ 619.00
1	Wheel Cover – LH ✓			\$ 150.70
SUB TOTAL				\$ 4,346.40
LESS 20%				869.28
DISCOUNTED TOTAL				\$ 3,477.12
1	Advertisement – LHF Fender ✓			\$ 100.00
				\$ 100.00
Labour Charge				300
1	Panel Beating			\$ 400.00
1	Spray Painting Charge			\$ 400.00
1	Wiring Charge			\$ 50.00 ✕
1	Tuff Kote			\$ 50.00 ✕
1	Front Wheel Alignment			\$ 120.00 ✕
TOTAL LABOUR				\$ 900.00
ESTIMATE TOTAL				\$ 4,477.12

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Kalvin (K/K)
16/4/18 1535hrs
2 Parts
45
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: