

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 3170G

DATE 14/4/2018 10:19

MAKE :

MODEL : HYUNDAI i40

Cheng

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ 603.60
	Rear Bumper Reinforcement ?			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket ?			\$ 49.00
	Rear Bumper Clips ✓			\$ 22.00
	Rear Bumper Sponge ?			\$ 143.40
	Rear Bumper Under Cover ✓			\$ 225.00
	SUB TOTAL			\$ 1,907.35
	LESS 20%			\$ 381.47
	DISCOUNTED TOTAL			\$ 1,525.88
	Rear Bumper Reverse Sensor ✓			\$ 135.70
	Rear Bumper Rubber Mat ✓			\$ 50.00
				\$ 185.70
	Labour Charge			
	Panel Beating			\$ 250.00 ²⁰⁰
	Spray Painting Charge			\$ 250.00 ²⁰⁰
	Wiring Charge			\$ 50.00 ^X
	R/Refix Reverse Sensor			\$ 120.00 ²⁰
	TOTAL LABOUR			\$ 670.00
	ESTIMATE TOTAL			\$ 2,381.58

Kalvin iUUK
16/4/18 1040hrs
2 hrs.
P/P
Before Paint pth

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged parts for survey
- Parts prices are subject to change
- Third party survey is not "Prejudice" but
- No illegal modification allowed
- Supplementary survey is surveyed and is subject to final survey by Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.