

ASS. REC. BY:

REF: CS/FCI 8007110 / Kqber

Special Instruction:

Surveyor:

ASSIGNMENT (Office)From (Person): WJS Aung Yin Min of FCI Date/Time: 17/04/2018 226pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKG 484JT Insured: SHA 8196Rat Workshop m/s MBM Wheelpower Tel: 86865188of 160 Sin Ming Dr #06-05Policy No: \_\_\_\_\_ Claim No: D18002863MFSH

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 11-04-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS' 18042018Date/Time: 17042018 331pm Person Contacted: Joseph H.O.D. Endorsement: \_\_\_\_\_Vehicle IN / OUT

Date/Time	Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate
	<u>SKG 484JT - X</u>
	<u>SHA 8196R - CS/DW11000386 / Rgg1</u>
<u>19/4/18 @ 3.23pm</u>	<u>revised to Aung Yin Min by email.</u>
	<u>816578-20 email</u>

DIA: D5012011

REF: FQ

## ASSIGNMENT

From: Date: 18042018

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKG 4842T

at Workshop m/s MBM Wheelpower

of 160 Sin Ming Ave #06-02

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Joseph -

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 82456

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'DS'

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKG 4842T Yr Regn: 09/12

Type: ☒ M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Bmw M6 C.C. 2879

Colour: Matt Grey A/C: Insured / Std / NI / NA

Sp. Reading: 53253 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBALW 32050C 799084

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: Inorder / ☒ Jammed / Leaked / Burnt orBrake: Inorder / ☒ Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/35ZR20

R: 295/30ZR20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 2 mm

L/Bal. 2 mm

D.O.A. 11/4/18

Survey held at

Rear

R/Bal. 3 mm

L/Bal. 3 mm

D.O.I. 18/4/18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

CLIP &amp; UIC


The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

19/4 15h pass to Customer

28/2 017048.00 Confirmed (Red to 19063.30, 53%)  
no lump sum

RECEIVED 01 MAR 2019

  
 11/3/2019

Date/Time, File Pass to?

11/01/3 J. Monty

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$) 7P (17048)

☐ : Preli. Report☐ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 3

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS SI

Photo

Other

TOTAL

27x19 = 405

1701405

50

40490150

32

807

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

**FIRST CAPITAL INSURANCE LTD**

Ref : CS/FCI18007110/Kqb

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 17-04-2018



Code : FCI2

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	SHA 8196R	Veh. Inspected	SKG 4842T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	17/04/2018

**2. Vehicle Particulars & Condition**

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

**4. Description of Damages**

--	--

**5. General Information**

Accident Date	11/04/2018	Inspection Date	18/04/2018
Survey held at	160 SIN MING DRIVE #06-02		
Repairer	MBM WHEELPOWER PTE LTD		

**5a. Remarks**

--	--

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	13-04-2018	<b>Our Ref No.</b> D18002863MFSH
<b>Accident Date</b>	11-04-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHA8196R	<b>Third Party Vehicle.</b> SKG4842T
<b>Survey Location</b>	160 Sin Ming Drive #06-02 Sin Ming Autocity	
<b>Contact Person.</b>	JOSEPH	
<b>Contact No.</b>	62628888/ 86865188	<b>Fax No.</b> 62509015
<b>Survey Type</b>	DIRECT SETTLEMENT:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	MBM WHEELPOWER PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	AUNGYM	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Thursday, 19 April 2018 3:23 PM  
**To:** 'Claim Workflow System'; assignments  
**Cc:** AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18002863MFSH/1  
**Attachments:** CSFC118007110Kqb.pdf

Dear Yin Min,

Enclosed herewith preliminary advice of SKG 4842T.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Tuesday, 17 April 2018 3:33 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18002863MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Tuesday, 17 April, 2018 2:26 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [AUNGYINMIN@MSFIRSTCAPITAL.COM.SG](mailto:AUNGYINMIN@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18002863MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002863MFSH

Date: 19 April 2018

Our Ref: CS/FCI18007110/Kqb

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SKG 4842T .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 18/04/2018 at the premises of M/s MBM WHEELPOWER. and have the following to report:-

Workshop Estimate Amount	: S\$ 28,046.50 .
Revised Estimate Amount	: S\$ 4,975.80 .
"Check" Items Amount	: S\$ 18,389.20 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages  
at the o/s front portion & undercarriage.



Yours faithfully

KONG SENG CHEONG  
Licensed Appraiser

## Enquire PARF/COE Rebate for Registered Vehicle

## Vehicle Owner Particulars

Owner ID Type:

Foreign Identification Number

Owner ID:

6439L

## Vehicle Details

Vehicle No.:

SKG4842T

Vehicle to be Exported:

No

Intended De-registration Date:

30 Apr 2018

Vehicle Make:

B.M.W.

Vehicle Model:

640I 3.0 AT 2DR SR LED DSC NAV HUD

Primary Colour:

Silver

Manufacturing Year:

2011

Engine No.:

14517975N55B30A

Chassis No.:

WBALW32050C799084

Maximum Power Output:

235.0 kW (315 bhp)

Open Market Value:

\$69,498.00

Original Registration Date:

10 Sep 2012

First Registration Date:

10 Sep 2012

Transfer Count:

1

Actual ARF Paid:

\$69,498.00

## Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

09 Sep 2022

PARF Rebate Amount:

\$48,648.00

## Intended COE Rebate Details

COE Expiry Date:

09 Sep 2022

COE Category:

E - Open Category

COE Period(Years):

10

QP Paid:

\$93,990.00

COE Rebate Amount:

\$38,354.00

Total Rebate Amount:

\$87,002.00

The information contained herein is correct as at 14 Apr 2018

OK

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	13/04/2018 16:25
Date Of Accident	11/04/2018 02:45
Exact Location Of Accident	LAVENDER STREET AT ESSO PETROL STATION
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKG4842T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ANISH JAIN
Passport No/FIN	G5096439L
Email Address	ANISH_1710@AHOO.COM
Mobile Phone No	(LOCAL) +65-83852999
Alternative Phone No	OTHERS-83852999

#### Vehicle Particulars

Manufacturer	BMW
Model	M6
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

#### Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01003020
Cover Note Number	

#### Driver

Name of Driver	SWAROOP KUMAR GOTRU
NRIC No	S8165153A
Date Of Birth	15/03/1981
Occupation	INDOOR
Date Of Driving Pass	17/01/2015
Driving Experience	3 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98004709
Fax Number	
Contact Number	
Email Address	SWARROOP_GOTRU@YAHOO.COM



Address	51 MEYER ROAD #18-04
Postcode	437874
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - BUSINESS PARTNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : VINAY ANAND BUSI GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO WITH WORKSHOP
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA8196R
Vehicle Make/Model/Colour	COMFORT HYUNDAI
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	YAP HOCK LIONG
NRIC/Passport Number	S1749863J
Contact Number	82222893
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 13 APR 2019

16:28hs

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.: Poh Kwee Choo  
S6840583A

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I parked my friend car BMW M6 on 11.04.2018 @ ESSO petrol Bunk, Lavender street in order to withdraw cash at OCBC ATM.

I got down the car who is driver at that point and withdrawing cash. In a moment of time I heard a loud crashing sound & unfortunately I had to notice the compact Red Gro Hyundai car SHA 8196R crashed into the lan out of road & entered petrol Bunk & rammed into my friend car that was parked. My friend who was sitting inside the car was Not Hurt fortunately.

You had been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a **Fourteen (14) days clause** whereby the claim must be made within the stipulated timeframe from the day of occurrence.

Reporting Only

Claim OD

Claim TP

☒ Claim OD / TP at other workshop

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 3 APR 2018

Reporting Centre Personnel's Signature  
Name: Poh Kwee Choo  
NRIC/FIN No.: S6840583A

# MBM WHEELPOWER PTE LTD



Your Ref: SHA8196R

Our Ref: SKG4842T

To: FIRST CAPITAL INSURANCE

CC

Fax

*Not withain  
Presony B4 pain  
6 days*

Date: 16/4/2018  
From: Joseph  
Fax: 62509015  
Contact: 86865188  
Make / Model: B.M.W M6  
Chassis No.: WBALW32050C799084  
Engine No.: 14517975N55B30A  
Year of Make: 2011  
Accident Date: 11 April 2018

ESTIMATE FOR VEHICLE NO. : SKG4842T

DESCRIPTION	QTY	List Price
HEAD LAMP RH	1	\$ 4,950.00
HEAD LAMP BRACKET RH	1	\$ 150.00
FRONT BUMPER	1	\$ 2,100.00
FRONT BUMPER CLIPS	10	\$ 50.00
FRONT BUMPER RH BRACKET	1	\$ 110.00
FRONT FOG LAMP RH	1	\$ 455.00
FRONT FOG LAMP COVER RH	1	\$ 85.00
HEAD LAMP NOZZLE RH	1	\$ 230.00
HEAD LAMP NOZZLE COVER RH	1	\$ 90.00
FRONT RH FENDER	1	\$ 1,650.00
FRONT RH FENDER INNER SHIELD	1	\$ 220.00
FRONT RH FENDER INNER SHIELD CLIPS	10	\$ 50.00
FRONT CROSS MEMBER	1	\$ 2,162.00
FRONT RH SHOCK ABSORBER	1	\$ 1,755.00
FRONT RH UPPER ARM	1	\$ 628.00
FRONT RH LOWER ARM	1	\$ 680.00
FRONT RH THRUST ARM	1	\$ 585.00
FRONT RH WHEEL HUB	1	\$ 563.00
FRONT RH WHEEL HUB BEARING	1	\$ 302.00
FRONT STABILIZER BAR RH	1	\$ 3,955.00
FRONT STABILIZER LINK RH	1	\$ 210.00
FRONT RH TIE ROD	1	\$ 405.00

FRONT RH TIE ROD END  
FRONT RH BRAKE DISC  
FRONT RH BRAKE DISC COVER

1	\$	87	285.00 ✓
1	\$	Sm	305.00 x
1	\$	Sm	110.00 x
Total: \$			22,085.00
LESS 10% \$			(2,208.50)
\$			<b>19,876.50</b>

#### SPECIAL NETT

FRONT BUMPER SENSOR  
TYRE  
RIM *Pr?*  
WRAPPING STICKER

1 SET	\$	Sm	400.00 x
1	\$	?	480.00
1	\$	nd	2,600.00 ✓
2	\$	(B11)	1,800.00 ✓

#### LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.

\$ 400  
1,400.00

TO REMOVE, REFIT / REPLACE UNDERCARRIAGE

\$ 240 350.00

TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT

\$ 80 120.00

TO REMOVE & REPLACE FRONT BUMPER SENSORS

\$ 100.00 ?

TO CHECK & RECONNECT ALL NECESSARY WIRING

\$ 20 120.00

TO SPRAY PAINT ON THE AFFECTED AREAS

\$ 500 800.00

Total: \$	28,046.50
7% GST: \$	1,963.26
<b>Grand Total: \$</b>	<b>30,009.76</b>

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Mbm wheelpower pte ltd

160 SIN MING DRIVE

#06-02

SIN MING AUTOCITY


t 62828888 f 64529823

Company Registration Number : 200204110W

# MBM WHEELPOWER PTE LTD

Your Ref: SHA8196R

Our Ref: SKG4842T



To: FIRST CAPITAL INSURANCE

CC

Fax

Date: 16/4/2018  
 From: Joseph  
 Fax: 62509015  
 Contact: 86865188  
 Make / Model: B.M.W M6  
 Chassis No.: WBALW32050C799084  
 Engine No.: 14517975N55B30A  
 Year of Make: 2011  
 Accident Date: 11 April 2018

*Not within  
 Presumy B4 parts  
 6 days  
 816578.20*

ESTIMATE FOR VEHICLE NO.: SKG4842T

DESCRIPTION	QTY	List Price
HEAD LAMP RH ✓ → 4480	1	\$ 4,950.00 2
HEAD LAMP BRACKET RH ✓	1	\$ 150.00 2
FRONT BUMPER ✓ 1955	1	\$ 2,100.00 2
FRONT BUMPER CLIPS ✓	10	\$ 50.00 2
FRONT BUMPER RH BRACKET	1	\$ 110.00 X
FRONT FOG LAMP RH	1	\$ 455.00 X
FRONT FOG LAMP COVER RH	1	\$ 85.00 X
HEAD LAMP NOZZLE RH	1	\$ 230.00 X
HEAD LAMP NOZZLE COVER RH	1	\$ 90.00 X
FRONT RH FENDER	1	\$ 1,650.00 X
FRONT RH FENDER INNER SHIELD	1	\$ 220.00 ✓
FRONT RH FENDER INNER SHIELD CLIPS	10	\$ 50.00 ✓
FRONT CROSS MEMBER	1	\$ 2,162.00 X
FRONT RH SHOCK ABSORBER → 1571	1	\$ 1,755.00 2
FRONT RH UPPER ARM	1	\$ 628.00 X
FRONT RH LOWER ARM ✓ 580	1	\$ 680.00 2
FRONT RH THRUST ARM	1	\$ 585.00 2
FRONT RH WHEEL HUB	1	\$ 563.00 X
FRONT RH WHEEL HUB BEARING	1	\$ 302.00 ✓
FRONT STABILIZER BAR RH ✓ → 37116778089 83285.00	1	\$ 3,955.00 2
FRONT STABILIZER LINK RH → 125	1	\$ 210.00 2
FRONT RH TIE ROD ✓ 8260	1	\$ 405.00 2

*151395  
 - 106  
 13855.50*

FRONT RH TIE ROD END  
FRONT RH BRAKE DISC  
FRONT RH BRAKE DISC COVER

1	\$	<i>21</i> 285.00 ✓
1	\$	<i>Sm</i> 305.00 X
1	\$	<i>Sm</i> 110.00 X
Total: \$		22,085.00
LESS 10% \$		(2,208.50)
\$		19,876.50

#### SPECIAL NETT

FRONT BUMPER SENSOR  
TYRE X  
RIM X *Pr?*  
WRAPPING STICKER X

1 SET	\$	<i>Sm</i> 400.00 X
1	\$	<i>Sm ?</i> 480.00 X
1	\$	<i>Pr</i> <i>Sm</i> 2,600.00 X
2	\$	<i>Sm</i> (B11) 1,800.00 ?

#### LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.

\$ *400* 1,400.00

TO REMOVE, REFIT / REPLACE UNDERCARRIAGE

\$ *240* 350.00

TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT

\$ *80* 120.00

TO REMOVE & REPLACE FRONT BUMPER SENSORS

\$ 100.00 *50*

TO CHECK & RECONNECT ALL NECESSARY WIRING

\$ *20* 120.00

TO SPRAY PAINT ON THE AFFECTED AREAS

\$ *500* 800.00

Total: \$	28,046.50
7% GST: \$	1,963.26
Grand Total: \$	30,009.76

*32031.30*

*36 111.30*



# MBM WHEELPOWER PTE LTD

Your Ref: SHA8196R

Our Ref: SKG4842T



To: FIRST CAPITAL INSURANCE

CC

Fax

Date: 8/6/2018  
From: Joseph  
Fax: 62509015  
Contact: 86865188  
Make / Model: B.M.W M6  
Chassis No.: WBALW32050C799084  
Engine No.: 14517975N55B30A  
Year of Make: 2011  
Accident Date: 11 April 2018

SUPPLEMENTARY FOR VEHICLE NO.: SKG4842T

## SPECIAL NETT

TYRE - MICHELIN 245/35ZR20  
RIM - 20" VOSSEN CAST RIMS  
WRAPPING STICKER

4405N 80/5N  
1/4pcs \$ CUT 2,200.00  
1/4pcs \$ DO 13255N 5,300.00  
2 portion \$ M 920.00 -

## LABOUR

TOWING

\$ (Bill) 95.00 ✓  
Total: \$ 8,515.00  
7% GST: \$ 596.05  
Grand Total: \$ 9,111.05


Mbm wheelpower pte ltd  
160 SIN MING DRIVE  
#06-02  
SIN MING AUTOCITY  
t 62828888 f 64529823

Company Registration Number : 200204110W

# MBM WHEELPOWER PTE LTD

Your Ref: SHA8196R

Our Ref: SKG4842T



To: FIRST CAPITAL INSURANCE

CC

Fax

Date: 1/2/2019  
From: Joseph  
Fax: 62509015  
Contact: 86865188  
Make / Model: B.M.W M8  
Chassis No.: WBALW32050C799084  
Engine No.: 14517975N55B30A  
Year of Make: 2011  
Accident Date: 11 April 2018

SUPPLEMENTARY ESTIMATE FOR VEHICLE NO. : SKG4842T

DESCRIPTION

FRONT SUPPORT AIR DUCT

51647211512

QTY		List Price
1	\$	522.00
Total: \$		522.00
LESS 10% \$		(52.20)
\$		469.80

Mbm wheelpowerpte ltd  
160 SIN MING DRIVE #06-02  
SIN MING AUTOCITY  
t62826888 f64529823

Company Registration Number : 200204110W


NAME: MBM WHEELPOWER PTE LTD

Add (H): 176 SIN MING DRIVE

#01-15 SIN MING AUTOCARE

SINGAPORE 575721

Contact: 6548 3198



Veh No. SKG4842T

M/M: BMW F13 640I

GST REG NO: 200504627K

Tax Invoice: 21001968

Invoice Date: 09.05.2018


S/N	Qty	Particular	Unit Price	Amount
01.	1 Set	TO SUPPLY & INSTALL 3M SATIN GREY WRAP FOR RHF FENDER & FRONT BUMPER	\$ 920.00	\$ 920.00

SUB TOTAL: \$ 920.00

7% GST \$ 64.40

E. & O.E Total S\$ \$ 984.40

The above items are received in good order  
and condition by

  
Joseph Tan  
Claims Advisor  
8686 5188

Customer's Signature/Co.Stamp



for KBS Motorsport Pte Ltd

Terms & Conditions:

kbs motorsport pte ltd

1 Commonwealth Lane, #01-11/12/13 one Commonwealth Building, S 149544

t 64515 333 f 64525 333

NAME: MBM WHEELPOWER

Add (H): 160 Sin Ming Drive,

#06-02 Sin Ming Autocity

S 575722

Contact: +603-40232525

Fax +603-40218499



Veh No. SKG4842T

M/M: BMW F13 640I

GST REG NO: 200504627K

Tax Invoice: INVA1103325

Invoice Date: 30.04.2018

S/N	Qty	Particular	Unit Price	Amount
01.	4 Pcs	Vossen 20" Cast Rims	\$ 5,300.00	\$ 5,300.00


SUB TOTAL: \$ 5,300.00

7% GST \$ 371.00

E. & O.E Total S\$ \$ 5,671.00

The above items are received in good order  
and condition by

Customer's Signature/Co. Stamp



for KBS Motorsport Pte Ltd

Terms & Conditions:

kbs motorsport pte ltd

1 Commonwealth Lane, #01-11/12/13 one Commonwealth Building, S 149544

t 64515 333 f 64525 333

## Rex Tan

---

**From:** KJ@vossenwheels.com  
**Sent:** Thursday, 12 April 2018 3:10 AM  
**To:** Rex Tan  
**Cc:** Patrick Lim | KBS Motorsports  
**Subject:** RE: CV3 20" Rim Replacement  
**Attachments:** CV3R SILVER ANGLE 1.jpg; CV3R GRAPHITE ANGLE 1.jpg

Hello Rex,

The CV3 wheel was discontinued in 2016. We have replace the wheel model with the new CV3R.

### CV3R Differences

- The spokes are slightly bigger
- Vossen logo is embossed
- New color finish options
- Where spoke meets the barrel the wheel now flares out

KJ

**From:** Rex Tan <rex.tan@kbsmotorsports.com.sg>  
**Sent:** Wednesday, April 11, 2018 5:49 AM  
**To:** KJ@vossenwheels.com  
**Cc:** Patrick Lim | KBS Motorsports <patrick@kbsmotorsports.com.sg>  
**Subject:** CV3 20" Rim Replacement

Dear KJ,

Can we still order CV3 20" rim? It is for a BMW F12 640i?

Needed the front rim 1 pc for replacement, customer went into accident, we ordered since 2013, attached invoice for your reference.

I need to know the order lead time & price, you can ignore the color, customer re-spray before.



# 城市拖車服務 CITY LINK TOWING SERVICE

REG NO : 52841959E  
MAILING ADD : BLK 43 TEBAN GARDENS ROAD, #02-389 SINGAPORE 600043  
HP : 96910664  
Service in Singapore and Malaysia

Insurance

Cash/W.O. No. 12121

Messers : MBM Service Date : 12/4/18  
Vehicle No : SKG H842 T Vehicle Model : \_\_\_\_\_  
Location From : 462 Crawford Lane Time Arrived : \_\_\_\_\_  
Location To : Sing Time Completed : \_\_\_\_\_  
Order By : \_\_\_\_\_ Contact No : 98004209  
Issued By : \_\_\_\_\_ Received By : \_\_\_\_\_  
Remarks : use Dolly and Tow Tow Truck No : \_\_\_\_\_

## ADDITIONAL SERVICES :

Accident	Breakdown <input checked="" type="checkbox"/>	Jump. Start	Vehicle Over Turn
Multi Story Car Park	Basement Car Park	Change Tyre & Towing	Crane Up
Using King Dolly <input checked="" type="checkbox"/>	Use Car Carrier	Door Opening Service	Dismantle Shaft
Transport Charged	Collection Car Key	Unloading Cargo	Waiting T.P - lo
Low Bodykit & Spoiler	Loaded Cargo	Causeway	2nd Link
Day Service <input checked="" type="checkbox"/>	Night Service	Mid-Nigh Service	Use Winch

ERP Charged \$ \_\_\_\_\_ CBD Charged \$ \_\_\_\_\_ Parking Charged \$ \_\_\_\_\_

Towing Amount \$ #95/2

注意：本公司對所拖之車輛，在運行中如有任何損失或破壞，一概由車主自行負責。  
NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18007110/Kqbe2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 05-03-2019		
		Code : FCI2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHA 8196R	Veh. Inspected	SKG 4842T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18002863MFSH	Excess (\$)	0.00	
Assign From		Assign Date	17/04/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	B.M.W. M6 (A)	c.c	2979	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WBALW32050C799084	Colour	METALLIC GREY	
Odometer	53253	Steering	JAMMED	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	235/35Z R20	MICHELIN	8 mm	
L/H Front Tyre	235/35Z R20	MICHELIN	8 mm	
R/H Rear Tyre	295/30Z R20	MICHELIN	3 mm	
L/H Rear Tyre	295/30Z R20	MICHELIN	3 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT AND UNDERCARRIAGE PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	11/04/2018	Inspection Date	18/04/2018	
Survey held at	160 SIN MING DRIVE #06-02			
Repairer	MBM WHEELPOWER PTE LTD			
<b>5a. Remarks</b>				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>6 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKG 4842T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	HEAD LAMP RH	MTG CRACKED	4,950.00	4,480.00
1	HEAD LAMP BRACKET RH	NECESSARY	150.00	150.00
1	FRONT BUMPER	BUCKLED / MTG DISTORTED	2,100.00	1,955.00
10	FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	FRONT BUMPER RH BRACKET	TO REPAIR SEE LABOUR	110.00	-
1	FRONT FOG LAMP RH	SERVICEABLE	455.00	-
1	FRONT FOG LAMP COVER RH	SERVICEABLE	85.00	-
1	HEAD LAMP NOZZLE RH	SERVICEABLE	230.00	-
1	HEAD LAMP NOZZLE COVER RH	SERVICEABLE	90.00	-
1	FRONT RH FENDER	TO REPAIR SEE LABOUR	1,650.00	-
1	FRONT RH FENDER INNER SHIELD	DISTORTED	220.00	220.00
10	FRONT RH FENDER INNER SHIELD CLIPS	NECESSARY	50.00	50.00
1	FRONT CROSS MEMBER	SERVICEABLE	2,162.00	-
1	FRONT RH SHOCK ABSORBER	BENT	1,755.00	1,571.00
1	FRONT RH UPPER ARM	SERVICEABLE	628.00	-
1	FRONT RH LOWER ARM	DISTORTED	680.00	580.00
1	FRONT RH THRUST ARM	DISTORTED	585.00	585.00
1	FRONT RH WHEEL HUB	SERVICEABLE	563.00	-
1	FRONT RH WHEEL HUB BEARING	NECESSARY	302.00	302.00
1	FRONT STABILIZER BAR RH	BENT	3,955.00	3,285.00
1	FRONT STABILIZER LINK RH	DISTORTED	210.00	125.00
1	FRONT RH TIE ROD	BENT	405.00	260.00
1	FRONT RH TIE ROD END	BENT	285.00	285.00
1	FRONT RH BRAKE DISC	SERVICEABLE	305.00	-
1	FRONT RH BRAKE DISC COVER	SERVICEABLE	110.00	-
1	FRONT SUPPORT AIR DUCT (ADDITIONAL)	CRACKED	522.00	522.00
	LESS 10% DISCOUNT		-2,260.70	-1,442.00
			20,346.30	12,978.00

Report Ref No. CS/FCI18007110/Kqbe2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET FRONT BUMPER SENSOR (SN)	SERVICEABLE	400.00	-
1	TYRE (SN)	SERVICEABLE	480.00	-
1	RIM (SN)	SERVICEABLE	2,600.00	-
2	WRAPPING STICKER (SN)	SERVICEABLE	1,800.00	-
4	TYRE - MICHELIN 245/35ZR20 (SN) (\$550.00) (80%) (ADDITIONAL)	CUT-1PC ONLY	2,200.00	440.00
4	RIM - 20" VOSSEN CAST RIMS (SN) (ADDITIONAL)	DENTED-1PC ONLY	5,300.00	1,325.00
2	WRAPPING STICKER (SN) (ADDITIONAL)	NECESSARY	920.00	920.00
			13,700.00	2,685.00
	<b><u>LABOUR</u></b>			
	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER RH BRACKET AND FRONT RH FENDER.		1,400.00	400.00
	TO REMOVE, REFIT / REPLACE UNDERCARRIAGE.		350.00	240.00
	TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT.		120.00	80.00
	TO REMOVE & REPLACE FRONT BUMPER SENSORS.		100.00	50.00
	TO CHECK & RECONNECT ALL NECESSARY WIRING.		120.00	20.00
	TO SPRAY PAINT ON THE AFFECTED AREAS.		800.00	500.00
	TOWING. (ADDITIONAL)		95.00	95.00
			2,985.00	1,385.00
	<b>GRAND TOTAL</b>		<b>37,031.30</b>	<b>17,048.00</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>17,048.00</b>

Report Ref No. CS/FCI18007110/Kqbe2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.