

S. REC. BY:

REF:

CS/CT18007114/Krbn2

Special Instruction:

Survivor

Maimen

## ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time:

17042018 2:59pm

Estimated Cost:

Bill to:

OD / ☒ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ 3044Y

Insured:

GZ 4796R

at Workshop m/s

Optima Werkz

Tel:

6484 9919

of

9A Serangoon North Ave 5

Policy No:

DMCVSN3038801700

Claim No:

SNM18001962 C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

13042018

CA / REV / REP. / REV 24 HRS wpi

18042018

H.O.D. Endorsement:

Date/Time:

17042018 3:47pm

Person Contacted:

Riza

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction ( ☒ ) Estimate

SLQ 3044Y - X

GZ 4796R - NBA / DMC17011584 / Y

DUA: 140614

Confirm \$3485.98 @ 5 days

Red: \$1655.06, 3/.





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                         |                                                                      |                 |                          |  |
|-------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------|-----------------|--------------------------|--|
| CHINA TAIPING INSURANCE (S) PTE LTD                                                                                                       |                                                                      |                 | Ref : CS/CTI18007114/Krb |  |
| 3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERS SINGAPORE 079909                                                                                 |                                                                      |                 | Date : 17-04-2018        |  |
|                                                                                                                                           |                                                                      |                 | Code : CTI               |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                         |                                                                      |                 |                          |  |
| Insured Veh.                                                                                                                              | GZ 4796R                                                             | Veh. Inspected  | SLQ 3044Y                |  |
| Policy No.                                                                                                                                | DMPCSN3038801700                                                     | Coverage (\$)   | 0.00                     |  |
| Claim No.                                                                                                                                 | SNM18D01962C02                                                       | Excess (\$)     | 0.00                     |  |
| Assign From                                                                                                                               | MERIMEN (IRENE TAY)                                                  | Assign Date     | 17/04/2018               |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                             |                                                                      |                 |                          |  |
| Make & Model                                                                                                                              | c.c                                                                  |                 | 0                        |  |
| Engine No.                                                                                                                                | HIDDEN                                                               | Year of Reg.    |                          |  |
| Chassis No.                                                                                                                               |                                                                      | Colour          |                          |  |
| Odometer                                                                                                                                  | -                                                                    | Steering        |                          |  |
| Brakes                                                                                                                                    |                                                                      | Modification    |                          |  |
| General                                                                                                                                   |                                                                      |                 |                          |  |
| <b>3. Conditions of Tyres</b>                                                                                                             |                                                                      |                 |                          |  |
|                                                                                                                                           | Size                                                                 | Make            | Balance                  |  |
| R/H Front Tyre                                                                                                                            |                                                                      |                 | mm                       |  |
| L/H Front Tyre                                                                                                                            |                                                                      |                 | mm                       |  |
| R/H Rear Tyre                                                                                                                             |                                                                      |                 | mm                       |  |
| L/H Rear Tyre                                                                                                                             |                                                                      |                 | mm                       |  |
| <b>4. Description of Damages</b>                                                                                                          |                                                                      |                 |                          |  |
|                                                                                                                                           |                                                                      |                 |                          |  |
| <b>5. General Information</b>                                                                                                             |                                                                      |                 |                          |  |
| Accident Date                                                                                                                             | 13/04/2018                                                           | Inspection Date | 18/04/2018               |  |
| Survey held at                                                                                                                            | OPTIMA WERKZ PTE LTD<br>9A SERANGOON NORTH AVE 5<br>SINGAPORE 554500 |                 |                          |  |
| <b>5a. Remarks</b>                                                                                                                        |                                                                      |                 |                          |  |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                      |                 |                          |  |

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

| Case | Notified    | Est Submitted | Adj Assigned                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status                               |
|------|-------------|---------------|--------------------------------|---------|---------------|------------|--------------------------------------|
| Main | 17 Apr 2018 |               | 17 Apr 2018<br>14:59<br>Assign |         |               |            | <b>New Assignment</b><br>Cancel Case |

| Main                                                                                                                                                                                                                                                                                                                                                                                     | Reference | Claim Details              | Documents              | Show All               |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------------------------|------------------------|------------------------|
| <b>CLAIM SUBFOLDER DETAILS</b> [Created by insurer]                                                                                                                                                                                                                                                                                                                                      |           |                            |                        |                        |
| Insured:                                                                                                                                                                                                                                                                                                                                                                                 |           |                            |                        |                        |
| Main Claimant: <b>OPTIMA WERKZ PTE LTD</b>                                                                                                                                                                                                                                                                                                                                               |           |                            |                        |                        |
| Vehicle Reg. No.:                                                                                                                                                                                                                                                                                                                                                                        |           | <b>SLQ3044Y</b>            | Date of Loss:          | 13/04/2018 00:00 - :59 |
| Claim Type:                                                                                                                                                                                                                                                                                                                                                                              |           | <b>TP / SNM18D01962C02</b> | Policy/Cover Note No.: | DMCVSN3038801700       |
| Vehicle Reg. No. (Insured):                                                                                                                                                                                                                                                                                                                                                              |           | <b>GZ4796R</b>             | Policy No. (Claimant): |                        |
|                                                                                                                                                                                                                                                                                                                                                                                          |           | Excess:                    | S\$0.00                |                        |
| Repairer: <b>Optima Werkz Pte Ltd (HQ)</b> 9A Serangoon North Ave 5, 554500 Serangoon - Tel:                                                                                                                                                                                                                                                                                             |           |                            |                        |                        |
| Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Irene Tay Hui Ping</b> - 638986192]                                                                                                                                                                                                                                      |           |                            |                        |                        |
| Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Final Rpt due 26/04/2018]                                                                                                                                                                                                                                                                                       |           |                            |                        |                        |
| Adj Asg. Remarks: EST \$5141.04, ASSIGN KENNETH KONG AS SJE.                                                                                                                                                                                                                                                                                                                             |           |                            |                        |                        |
| <b>ASSOCIATED MAIL RECEIVED</b> View All Compose Case Mail                                                                                                                                                                                                                                                                                                                               |           |                            |                        |                        |
| There are no mail for this case.                                                                                                                                                                                                                                                                                                                                                         |           |                            |                        |                        |
| <div> <div> <div>ALL ASSOCIATED TASKS</div> <div> <div>Due Date</div> <div>Priority</div> <div>Type</div> <div>Task Group</div> <div>Subject</div> <div>Handler</div> <div>Assigned By</div> <div>Completed On</div> <div>Created On</div> <div>Done?</div> </div> </div> <div> <div>View All</div> <div>Search Tasks</div> <div>Create New Task</div> <div>Complete</div> </div> </div> |           |                            |                        |                        |
| No results.                                                                                                                                                                                                                                                                                                                                                                              |           |                            |                        |                        |

# OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 16 April 2018

Third Party Insurer: CHINA TAIPING

Vehicle No: SLQ3044Y

Third Party Veh No: GZ4796R

Model: TOYOTA AQUA HYBRID 1.5S

Date of Accident: 13 April 2018

Chassis: NHP10-6597991

## ESTIMATE

| QTY         | DESCRIPTION                               | UNIT S\$                  | AMOUNT S\$       |         |
|-------------|-------------------------------------------|---------------------------|------------------|---------|
| 1           | REAR TAILGATE                             |                           | By \$820.00      | ✓       |
| 1           | REAR TAILGATE LOGO EMBLEM                 |                           | Re \$45.90       | ✓       |
| 1           | REAR TAILGATE AQUA EMBLEM                 |                           | Re \$48.60       | ✓       |
| 1           | REAR TAILGATE HYBRID SYNERGY DRIVE        |                           | Re \$70.50       | ✓       |
| 1           | REAR TAILGATE OUTER GARNISH               |                           | Ref/imp \$201.60 | ✓       |
| 4           | REAR TAILGATE OUTER GARNISH CLIP          | \$6.28                    | Re \$25.12       | ✓       |
| 1           | REAR TAILGATE WINDSCREEN MOULDING         |                           | Re \$120.00      | ✓       |
| 1           | REAR TAILGATE WEATHERSTRIP                |                           | Re \$291.80      | X       |
| 1           | REAR TAILGATE MECHANISM LOCK              |                           | Ref \$452.71     | X       |
| 1           | REAR BUMPER                               |                           | Re \$408.31      | ✓       |
| 2           | REAR BUMPER SIDE RETAINER LH + RH         | <del>115.70</del> \$68.28 | Ref \$136.56     | ✓       |
| 8           | REAR BUMPER CLIP                          | \$5.78                    | Re \$46.24       | ✓       |
| 1           | REAR BUMPER REINFORCEMENT                 |                           | Re \$278.40      | X       |
| 2           | REAR BUMPER REINFORCEMENT BRACKET LH + RH | \$115.70                  | Re \$231.40      | X       |
| 1           | REAR BUMPER LOWER UNDER COVER             |                           | CM \$139.10      | ✓       |
| 2           | REAR TAILLAMP LOWER BRACKET LH + RH       | \$42.57                   | Re \$85.14       | X       |
| SUB TOTAL   |                                           |                           | \$3,401.38       | 2514.64 |
| Less 25%    |                                           |                           | \$850.35         | 628.66  |
| PARTS TOTAL |                                           |                           | \$2,551.04       | 1885.98 |

| QTY       | SPECIAL NETT                                 | UNIT S\$ | AMOUNT S\$     |      |
|-----------|----------------------------------------------|----------|----------------|------|
| 1         | REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER |          | Re \$100.00    | 4050 |
| 1         | REAR BUMPER REVERSE SENSOR                   |          | Short \$280.00 | 2000 |
| S/N TOTAL |                                              |          | \$380.00       | 2400 |

Not Authorized  
I.B.I  
Resurvey Bk paint  
5 days

## OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

|             |                         |                      |               |
|-------------|-------------------------|----------------------|---------------|
| Date:       | 16 April 2018           | Third Party Insurer: | CHINA TAIPING |
| Vehicle No: | SLQ3044Y                | Third Party Veh No:  | GZ4796R       |
| Model:      | TOYOTA AQUA HYBRID 1.5S | Date of Accident:    | 13 April 2018 |
| Chassis:    | NHP10-6597991           |                      |               |

### ESTIMATE

#### LABOUR CHARGES:

|                                                                                                     |            |         |
|-----------------------------------------------------------------------------------------------------|------------|---------|
| TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION                                        | \$1,000.00 | 500     |
| TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION                                         | \$800.00   | 600     |
| TO TUFF KOTE / ANTI-RUST                                                                            | \$40.00    | 300     |
| TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR                                                  | \$60.00    | 500     |
| TO REMOVE AND REINSTALL REAR WINDSCREEN PERFORM AND WATER LEAK TEST                                 | \$150.00   | 1200    |
| TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR | \$160.00   | 800     |
| LABOUR TOTAL                                                                                        | \$2,210.00 | 1360.00 |

WINSON

TOTAL

\$5,141.04

P - 1885.98

IN - 240.00

L - 1360.00

P/P \$ 3485.98 ✓ ok

# OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 16 April 2018

Third Party Insurer:

CHINA TAIPING

Vehicle No: SLQ3044Y

Third Party Veh No:

GZ4796R

Model: TOYOTA AQUA HYBRID 1.5S

Date of Accident:

13 April 2018

Chassis: NHP10-6597991

## ESTIMATE

| QTY         | DESCRIPTION                               | UNIT S\$                 | AMOUNT S\$              |   |
|-------------|-------------------------------------------|--------------------------|-------------------------|---|
| 1           | REAR TAILGATE                             |                          | <i>By</i> \$820.00      | ✓ |
| 1           | REAR TAILGATE LOGO EMBLEM                 |                          | <i>Me</i> \$45.90       | ✓ |
| 1           | REAR TAILGATE AQUA EMBLEM                 |                          | <i>Me</i> \$48.60       | ✓ |
| 1           | REAR TAILGATE HYBRID SYNERGY DRIVE        |                          | <i>Me</i> \$70.50       | ✓ |
| 1           | REAR TAILGATE OUTER GARNISH               |                          | <i>Del/eng</i> \$201.60 | ✓ |
| 4           | REAR TAILGATE OUTER GARNISH CLIP          | \$6.28                   | <i>Me</i> \$25.12       | ✓ |
| 1           | REAR TAILGATE WINDSCREEN MOULDING         |                          | <i>Me</i> \$120.00      | ✓ |
| 1           | REAR TAILGATE WEATHERSTRIP                |                          | <i>Me</i> \$291.80      | X |
| 1           | REAR TAILGATE MECHANISM LOCK              |                          | <i>dd</i> \$452.71      | ✓ |
| 1           | REAR BUMPER                               |                          | <i>Am</i> \$408.31      | ✓ |
| 2           | REAR BUMPER SIDE RETAINER LH + RH         | <i>old price</i> \$68.28 | <i>d/s</i> \$136.56     | ✓ |
| 8           | REAR BUMPER CLIP                          | \$5.78                   | <i>Me</i> \$46.24       | ✓ |
| 1           | REAR BUMPER REINFORCEMENT                 |                          | <i>R</i> \$278.40       | ? |
| 2           | REAR BUMPER REINFORCEMENT BRACKET LH + RH | \$115.70                 | <i>R</i> \$231.40       | ? |
| 1           | REAR BUMPER LOWER UNDER COVER             |                          | <i>cra for</i> \$139.10 | ✗ |
| 2           | REAR TAILLAMP LOWER BRACKET LH + RH       | \$42.57                  | <i>Sm</i> \$85.14       | X |
| SUB TOTAL   |                                           |                          | \$3,401.38              |   |
| Less 25%    |                                           |                          | -\$850.35               |   |
| PARTS TOTAL |                                           |                          | \$2,551.04              |   |

| QTY       | SPECIAL NETT                                 | UNIT S\$ | AMOUNT S\$            |       |
|-----------|----------------------------------------------|----------|-----------------------|-------|
| 1         | REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER |          | <i>Me</i> \$100.00    | 405m  |
| 1         | REAR BUMPER REVERSE SENSOR                   |          | <i>Short</i> \$280.00 | 2005m |
| S/N TOTAL |                                              |          | \$380.00              |       |

*Not Authorized*  
*L.B.I*  
*Resurvey Bk paint*  
*4 days*  
*5*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

|             |                         |                      |               |
|-------------|-------------------------|----------------------|---------------|
| Date:       | 16 April 2018           | Third Party Insurer: | CHINA TAIPING |
| Vehicle No: | SLQ3044Y                | Third Party Veh No:  | GZ4796R       |
| Model:      | TOYOTA AQUA HYBRID 1.5S | Date of Accident:    | 13 April 2018 |
| Chassis:    | NHP10-6597991           |                      |               |

## ESTIMATE

### LABOUR CHARGES:

|                                                                                                     |            |     |
|-----------------------------------------------------------------------------------------------------|------------|-----|
| TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION                                        | \$1,000.00 | 500 |
| TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION                                         | \$800.00   | 600 |
| TO TUFF KOTE / ANTI-RUST                                                                            | \$40.00    | 30  |
| TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR                                                  | \$60.00    | 50  |
| TO REMOVE AND REINSTALL REAR WINDSCREEN PERFORM AND WATER LEAK TEST                                 | \$150.00   | 120 |
| TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR | \$160.00   | 60  |

|              |            |
|--------------|------------|
| LABOUR TOTAL | \$2,210.00 |
|--------------|------------|

|        |       |            |
|--------|-------|------------|
| WINSON | TOTAL | \$5,141.04 |
|--------|-------|------------|

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118007114/KRBN2

Date: 04/06/2018

**REFERENCE**

|                       |                                               |                      |                  |
|-----------------------|-----------------------------------------------|----------------------|------------------|
| Handling Insurer:     | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:           | DMCVSN3038801700 |
| Claimant Vehicle No : | SLQ3044Y                                      | Insured Vehicle No : | GZ4796R          |
| Date of Loss:         | 13/04/2018                                    | Nature of Claim:     | TP               |
|                       |                                               | Claim No:            | SNM18D01962C02   |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                     |             |              |
|-----------------------------|-------------------------------------|-------------|--------------|
| Reg No:                     | SLQ3044Y                            | Engine No:  | 1NZR513430   |
| Make & Model:               | TOYOTA AQUA HYBRID, 1.5 E S CVT (A) | Chassis No: | NHP106597991 |
| Reg. Date:                  | 04/07/2017 (Man. Year: 2017)        | Odometer:   | 57954 km     |
| Colour:                     | Metallic Pearl White                |             |              |
| Engine Capacity:            | 1496 cc                             |             |              |
| Market Value/New Car Price: | N/A                                 |             |              |
| Sum Insured (S\$):          | Market Value/New Car Price          |             |              |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |             |                  |            |
|-------------------|-------------|------------------|------------|
| Front Tyre Size:  | 195/55R15   | Rear Tyre Size:  | 195/55R15  |
| Front Left Side:  | Dunlop 4 mm | Rear Left Side:  | HIFLY 8 mm |
| Front Right Side: | Dunlop 4 mm | Rear Right Side: | HIFLY 8 mm |

The above values represent the remaining tyre treads depth

**COST OF CLAIMS**

|                               | Repairer's      | Adjuster's      | Difference      | Diff %       |
|-------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts                         | 2,931.03        | 2,125.98        | 805.05          | 27.47        |
| Miscellaneous Items           | 0.00            | 0.00            | 0.00            |              |
| Labour                        | 2,210.00        | 1,360.00        | 850.00          | 38.46        |
| Paintwork Labour              | 0.00            | 0.00            | 0.00            |              |
| Towing                        | 0.00            | 0.00            | 0.00            |              |
| <b>Gross Total (S\$)</b>      | <b>5,141.03</b> | <b>3,485.98</b> | <b>1,655.05</b> | <b>32.19</b> |
| <b>+ GST 7.00/7.00% (S\$)</b> | <b>359.87</b>   | <b>244.02</b>   | <b>115.85</b>   | <b>32.19</b> |
| <b>Nett Amount (S\$)</b>      | <b>5,500.90</b> | <b>3,730.00</b> | <b>1,770.90</b> | <b>32.19</b> |

**INSPECTION**

|                             |            |               |                                                                           |
|-----------------------------|------------|---------------|---------------------------------------------------------------------------|
| Date of Assignment:         | 17/04/2018 | Inspected At: | Optima Werkz Pte Ltd (HQ)<br>9A Serangoon North Ave 5<br>Singapore 554500 |
| Date Inspected:             | 18/04/2018 |               |                                                                           |
| Estimated Period of Repair: | 5.0 days   |               |                                                                           |

Adjuster: KENNETH KONG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

|                      |                                                                                                                                                                              |                                                                      |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 31 May 2018)                        |
| <b>Parts:</b>        | 144                                                                                                                                                                          | TOYOTA AQUA HYBRID 1.5 E S CVT (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                    |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SLQ3044Y)                                                                                                                                    |                                                                      |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                      |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                      |

## Recommended Parts

| No. | Qty | Part No. | Particulars                                   | Condition     | Repairer's | Amount     |
|-----|-----|----------|-----------------------------------------------|---------------|------------|------------|
| 1   | 1   |          | *REAR TAILGATE                                | Bent          | 820.00 FL  | *820.00 FL |
| 2   | 1   |          | *REAR TAILGATE LOGO EMBLEM                    | Necessary     | 45.90 FL   | *45.90 FL  |
| 3   | 1   |          | *REAR TAILGATE AQUA EMBLEM                    | Necessary     | 48.60 FL   | *48.60 FL  |
| 4   | 1   |          | *REAR TAILGATE HYBRID SYNERGY DRIVE           | Necessary     | 70.50 FL   | *70.50 FL  |
| 5   | 1   |          | *REAR TAILGATE OUTER GARNISH                  | Dented/Warped | 201.60 FL  | *201.60 FL |
| 6   | 4   |          | *REAR TAILGATE OUTER GARNISH CLIP             | Necessary     | 25.12 FL   | *25.12 FL  |
| 7   | 1   |          | *REAR TAILGATE WINDSCREEN MOULDING            | Necessary     | 120.00 FL  | *120.00 FL |
| 8   | 1   |          | *REAR TAILGATE WEATHERSTRIP                   | Serviceable   | 291.80 FL  | *- FL      |
| 9   | 1   |          | *REAR TAILGATE MECHANISM LOCK                 | Dented        | 452.71 FL  | *452.71 FL |
| 10  | 1   |          | *REAR BUMPER                                  | Buckled       | 408.31 FL  | *408.31 FL |
| 11  | 2   |          | *REAR BUMPER SIDE RETAINER LH & RH            | Distorted     | 136.56 FL  | *136.56 FL |
| 12  | 8   |          | *REAR BUMPER CLIP                             | Necessary     | 46.24 FL   | *46.24 FL  |
| 13  | 1   |          | *REAR BUMPER REINFORCEMENT                    | Repair        | 278.40 FL  | *- FL      |
| 14  | 2   |          | *REAR BUMPER REINFORCEMENT BRACKET LH & RH    | Repair        | 231.40 FL  | *- FL      |
| 15  | 1   |          | *REAR BUMPER LOWER UNDER COVER                | Cracked       | 139.10 FL  | *139.10 FL |
| 16  | 2   |          | *REAR TAILLAMP LOWER BRACKET LH & RH          | Serviceable   | 85.14 FL   | *- FL      |
| 17  | 1   |          | *REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER | Necessary     | 100.00 FS  | *40.00 FS  |
| 18  | 1   |          | *REAR BUMPER REVERSE SENSOR                   | Shorted       | 280.00 FS  | *200.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                 |                 |
|------------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>3,781.38</b> | <b>2,754.64</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | <b>850.35</b>   | <b>628.66</b>   |
| <b>Total Parts (\$\$)</b>                                  | <b>2,931.03</b> | <b>2,125.98</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                      | Particulars                                                                                         | Lab.Type | Repairer's | Amount   |
|-------------------------|-----------------------------------------------------------------------------------------------------|----------|------------|----------|
| <b>Labour Items</b>     |                                                                                                     |          |            |          |
| 1                       | TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION                                        | New      | 1,000.00   | 500.00   |
| 2                       | TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION                                         | New      | 800.00     | 600.00   |
| 3                       | TO TUFF KOTE/ANTI-RUST                                                                              | New      | 40.00      | 30.00    |
| 4                       | TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR                                                  | New      | 60.00      | 50.00    |
| 5                       | TO REMOVE AND REINSTALL REAR WINDSCREEN PERFORM AND WATER LEAK TEST                                 | New      | 150.00     | 120.00   |
| 6                       | TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR | New      | 160.00     | 60.00    |
| Gross Labour Cost (S\$) |                                                                                                     |          | 2,210.00   | 1,360.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >