

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

*Not Authorised
Recovery After Paving*

MCQUEEN BIKES PTE LTD

c/o 46 Lenton Plain
Singapore 786548

Date : 17/04/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: BAJAJ PULSAR RS200 / FBM6460Z	
1 pc	mirror assembly (L/H) <i>Brw</i>	56.00
1 pc	mirror assembly (R/H) <i>Wt</i>	56.00
1 pc	front lever brake longer <i>0.1</i>	28.00
1 pc	weight handle bar <i>0.1</i>	16.00
1 pc	silencer end chamber assembly <i>0.1</i>	189.00
1 pc	tube rear hugger mounting (RS200) AL <i>✓ Dented</i>	38.00
1 pc	rear assembly hugger <i>R</i>	52.00
1 pc	bolt mirror mounting thread L/H <i>2 Nec</i>	6.00
1 pc	bolt mirror mounting thread R/H <i>2 Nec</i>	6.00
1 pc	rear tyre x svc	150.00
1 pc	Number Plate <i>✓ Bent</i> <i>S/Hett</i>	25.00 <i>✓</i>
	To change tyre & Perform wheel balancing	NH 30.00 X
	To provide transport service charge	60.00 25.00
	To remove & replace the parts mentioned above Panel beat & realign the necessary affected areas	380.00 120.00
	To check wiring system	30.00 10.00
	To apply Putty & Spray Paint On affected areas	380.00 150.00
	To Perform Computerised alignment	NH 40.00 X