

15/5/2010

INS. CASE OWNER:

CC # /EQI1800

LKK:

IDAC:


Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :\$

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

YL 1675L

SEJ 4197G

SEJ 4197G

SEJ 4197G



INSRS:

WSP:

Tel:

Liability:

RMKS:

01



INSRS:

WSP:

Tel:

Liability:

RMKS:




INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

URGENT

Date/ Time

18/4/18
MURM

SEJ 4197G-X

YL 1675L - 46/41/800000/12/18/18

18/4/18

Call CND confirm accident details
and NCB issue letter send to
01

INVESTIGATION REPORT FORWARDED TO EQ.

25/10/19

FTE - type mandate

23/3/2020

file 3 mktm

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI: (by EQ).

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days)

Reduction:

%

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email:

Call:

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. 21

Repair Cost:

SS

16426.53

Loss of Rental (LOR):

SS

2550.00

(

17

days)

Loss of Use (LOU):

SS

-

(\$

x

days)

Loss of Income (LOI):

SS

-

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GIA/LTA Search

SS

2.00

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

18978.53

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email:

Call:

Payee 1:

SS

18978.53

Name 1:

Lai Hui (Mang Kee) Motor Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$4000

ASS. REC. BY:

REF:

EQ 1

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

14

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKJ 41976

Yr Regn:

03, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Estima

C.C:

2362

Colour:

M. Gray

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ACR 50. 0158825

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

R:

225/50R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

12/4/18

Rear

R/Bal.

8

mm

L/Bal.

8

mm

D.O.I.

17/4/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt & o/s body & Res

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

18/4

File pass to Catherine

PIP \$ 15351.90 (bod \$ 1242.25 / 8%)

14 + 2 Sum + 1P4 - 1CP4 = 1 day

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

来發 (明 记) 摩 哆 有 限 公 司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0019014
Kwa Lip Oon

Page 1 of 4
Your ref. TP-YL 1675L EQ
Job No
Our ref. 18.04.14
Payment
Date 16/4/2018

Attn

Vehicle No SKJ 4197G
Vehicle Model . Toyota Estima
Accident on . . 12/4/2018

Not Authorized
1.B.1
Returning B4ipain
B15351.90 ✓ dlc
14 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	✓ Front top radiator grille	220.00		CM 220.00 ✓
5.00	Pcs	✓ Front top radiator clips	2.00		Ne 10.00 ✓
1.00	Pc	✓ Front Toyota logo emblem	35.00		m.1 35.00 ✓
1.00	Pc	✓ Front bumper	240.00		Bz 240.00 ✓
4.00	Pc	✓ Front bumper lower grille	115.00		See 115.00 ✓
4.00	Pc	✓ Front bumper lower grille chrome moulding	60.00		See 60.00 ✓
1.00	Pc	✓ Front bumper side retainer LH	25.00		D.1 25.00 ✓
1.00	Pc	✓ Front bumper side retainer RH	25.00		D.1 25.00 ✓
1.00	Pc	✓ Front fender LH	170.00		Bz 170.00 ✓
1.00	Pc	✓ Front fender RH	170.00		Bz 170.00 ✓
1.00	Pc	✓ Front fender inner shield LH	75.00		CM 75.00 ✓
1.00	Pc	✓ Front fender inner shield RH	75.00		CM 75.00 ✓
10.00	Pcs	✓ Front fender inner shield clips	1.00		Ne 10.00 ✓
1.00	Pc	✓ Front fender garnish LH	110.00		Ne 110.00 ✓
1.00	Pc	✓ Front fender garnish RH	110.00		Ne 110.00 ✓
1.00	Pc	Front fender inner bracket RH 2	75.00		CM 75.00 ✓
1.00	Pc	✓ Front headlamp LH	600.00		CM 600.00 ✓
1.00	Pc	✓ Front headlamp RH	600.00		CM 600.00 ✓

2350

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大快修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明 记) 摩 哆 有 限 公 司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No: EST0019014
Kwa Lip Oon

Page: 2 of 4
Your ref.: TP-YL 1675L EQ
Job No.:
Our ref: 18.04.14
Payment:
Date: 16/4/2018

Attn

Vehicle No SKJ 4197G
Vehicle Model . Toyota Estima
Accident on : 12/4/2018

Quantity	Unit	Description	Unit price	Disc. pct	Amount	
1.00	Pc	✓ Wiper tank	38.00		✓ 38.00	✓
1.00	Pc	✓ Front door LH	600.00		✓ 600.00	✓
1.00	Pc	✓ Front door RH	600.00		✓ 600.00	✓
1.00	Pc	✓ Front door garnish LH	430.00		✓ 430.00	✓
1.00	Pc	✓ Front door garnish RH	430.00		✓ 430.00	✓
1.00	Pc	✓ Rear door garnish RH	430.00		✓ 430.00	✓
1.00	Pc	Front shock absorber LH	165.00		✓ 165.00	✓
1.00	Pc	Front shock absorber RH	165.00		✓ 165.00	✓
1.00	Pc	Front knuckle arm LH	175.00		✓ 175.00	✓
1.00	Pc	Front knuckle arm RH	175.00		✓ 175.00	✓
1.00	Pc	Front ball joint LH	68.00		✓ 68.00	✓
1.00	Pc	Front ball joint RH	68.00		✓ 68.00	✓
1.00	Pc	Front stabilizer linkage LH	55.00		✓ 55.00	✓
1.00	Pc	Front stabilizer linkage RH	55.00		✓ 55.00	✓
1.00	Pc	Front wheel bearing with hup LH	165.00		✓ 165.00	✓
1.00	Pc	Front wheel bearing with hup RH	165.00		✓ 165.00	✓
1.00	Pc	Front lower arm LH	125.00		✓ 125.00	✓
1.00	Pc	Front lower arm RH	125.00		✓ 125.00	✓
1.00	Pc	Front sport rim LH	750.00		✓ 750.00	✓
1.00	Pc	Front sport rim RH	750.00		✓ 750.00	✓
					5284	

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。
除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明 记) 摩 哆 有 限 公 司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0019014
Kwa Lip Oon

Page 3 of 4
Your ref. TP-YL 1675L EQ
Job No.
Our ref 18.04.14
Payment
Date 16/4/2018

Attn

Vehicle No SKJ 4197G
Vehicle Model : Toyota Estima
Accident on : 12/4/2018

Quantity	Unit	Description	Unit price	Disc pct	Amount
1.00	Pc	✓ Rear tailgate	600.00		<i>Bu</i> 600.00 ✓
1.00	Pc	✓ Rear Toyota logo emblem	20.00		<i>mc</i> 20.00 —
1.00	Pc	✓ Rear Estima emblem	30.00		<i>mc</i> 30.00 —
1.00	Pc	✓ Rear Aeras emblem	20.00		<i>mc</i> 20.00 —
1.00	Pc	✓ Rear tailgate handle garnish	90.00		<i>x</i> 90.00 x
1.00	Pc	✓ Rear bumper	220.00		<i>Bu</i> 220.00 —
1.00	Pc	✓ Rear bumper side retainer RH	18.00		<i>mc</i> 18.00 —
Total amount of parts supplied - S\$9257.00					<u>908</u>
1.00		15% of parts supplied.	1,388.55		1,388.55
Special nett item:					
1.00	Set	Rear reversing sensor with installation	200.00		<i>CM</i> 200.00 ✓
Labour & Misc:					
1.00		Towing fee	80.00		80.00 <i>60</i>

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大快修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明 记) 摩 哆 有 限 公 司
LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
 RCB No: 199407592C

ESTIMATE

EST. No EST0019014
 Kwa Lip Con

Page 4 of 4
 Your ref. TP-YL 1675L EQ
 Job No
 Our ref. 18.04.14
 Payment
 Date 16/4/2018

Attn

Vehicle No SKJ 4197G
 Vehicle Model . Toyota Estima
 Accident on . 12/4/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To transfer front door inner trim board LH & RH	80.00		80.00 ✓
1.00		To remove and refix tailgate handle + rear camera	60.00		60.00 ✓
1.00		To check wheel alignment	60.00		60.00 ✓
1.00		To remove and renew front suspension parts, etc	350.00		350.00 320 ✓
1.00		To straighten front body, to knock dents on front door pillar LH and renew of parts	1,800.00		1,800.00 1500 ✓
1.00		To straighten rear body, to knock dents on rear end panel, floor panel and renew of parts	900.00		900.00 600 ✓
1.00		To spray paint	2,000.00		2,000.00 ✓

Sub-Total 16,175.55
 GST 7.00% 1,132.29
 Total S\$ 17,307.84

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明 记) 摩 哆 有 限 公 司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE SUPPLEMENTARY

EST. No EST0019014
Kwa Lip Oon

Page 1 of 2
Your ref. TP-YL 1675L EQ
Job No 69396
Our ref 13.04.14
Payment
Date 25/4/2018

Attn

Vehicle No SKJ 4197G
Vehicle Model . Toyota Estima
Accident on . 12/4/2018

Quantity	Unit	Description	Unit price	Disc pct.	Amount
SUPPLEMENTARY ITEM:					
1.00	Pc	Front door lower hinge LH	30.00		30.00
1.00	Pc	Front door top hinge LH	30.00		30.00
1.00	Pc	Front door lower hinge RH	30.00		30.00
1.00	Pc	Front door top hinge RH	30.00		30.00
1.00	Pc	Front door black tape LH - 1	22.00		22.00
1.00	Pc	Front door black tape LH - 2	22.00		22.00
1.00	Pc	Front door black tape LH - 3	28.00		28.00
1.00	Pc	Front door black tape LH - 4	16.00		16.00
1.00	Pc	Front door black tape RH - 1	22.00		22.00
1.00	Pc	Front door black tape RH - 2	22.00		22.00
1.00	Pc	Front door black tape RH - 3	28.00		28.00
1.00	Pc	Front door black tape RH - 4	16.00		16.00
1.00	Pc	Rear windscreen moulding	38.00		38.00
1.00	Pc	Front fender seal LH	15.00		15.00
1.00	Pc	Front fender seal RH	15.00		15.00

Total amount of parts supplied - S\$364.00

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。
除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."