

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No : EST0019014
Kwa Lip Oon

Page : 1 of 4
Your ref : TP-YL 1675L EQ
Job No :
Our ref : 18.04.14
Payment :
Date : 16/4/2018

Attn :

Vehicle No : SKJ 4197G
Vehicle Model : Toyota Estima
Accident on : 12/4/2018

Not Authorized
1.2.1
Running B4 pain
11 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Front top radiator grille	220.00		CM 220.00 ✓
5.00	Pcs	Front top radiator clips	2.00		RM 10.00 ✓
1.00	Pc	Front Toyota logo emblem	35.00		RM 35.00 ✓
1.00	Pc	Front bumper	240.00		RM 240.00 ✓
1.00	Pc	Front bumper lower grille	115.00		✓ 115.00 ✓
1.00	Pc	Front bumper lower grille chrome moulding	60.00		✓ 60.00 ✓
1.00	Pc	Front bumper side retainer LH	25.00		Diz 25.00 ✓
1.00	Pc	Front bumper side retainer RH	25.00		Diz 25.00 ✓
1.00	Pc	Front fender LH	170.00		RM 170.00 ✓
1.00	Pc	Front fender RH	170.00		RM 170.00 ✓
1.00	Pc	Front fender inner shield LH	75.00		CM 75.00 ✓
1.00	Pc	Front fender inner shield RH	75.00		CM 75.00 ✓
10.00	Pcs	Front fender inner shield clips	1.00		RM 10.00 ✓
1.00	Pc	Front fender garnish LH	110.00		Diz 110.00 ✓
1.00	Pc	Front fender garnish RH	110.00		Diz 110.00 ✓
1.00	Pc	Front fender inner bracket RH	75.00		CM 75.00 ✓
1.00	Pc	Front headlamp LH	600.00		CM 600.00 ✓
1.00	Pc	Front headlamp RH	600.00		CM 600.00 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予修理公司准确的测量方式和大铁修理。此外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明 记) 摩 哆 有 限 公 司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0019014
Kwa Lip Oon

Page 2 of 4
Your ref. TP-YL 1675L EQ
Job No.
Our ref. 18.04.14
Payment
Date 16/4/2018

Attn

Vehicle No SKJ 4197G
Vehicle Model : Toyota Estima
Accident on ... 12/4/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00	Pc	Wiper tank	38.00		38.00
1.00	Pc	Front door LH	600.00		600.00
1.00	Pc	Front door RH	600.00		600.00
1.00	Pc	Front door garnish LH	430.00		430.00
1.00	Pc	Front door garnish RH	430.00		430.00
1.00	Pc	Rear door garnish RH	430.00		430.00
1.00	Pc	Front shock absorber LH	165.00		165.00
1.00	Pc	Front shock absorber RH	165.00		165.00
1.00	Pc	Front knuckle arm LH	175.00		175.00
1.00	Pc	Front knuckle arm RH	175.00		175.00
1.00	Pc	Front ball joint LH	68.00		68.00
1.00	Pc	Front ball joint RH	68.00		68.00
1.00	Pc	Front stabilizer linkage LH	55.00		55.00
1.00	Pc	Front stabilizer linkage RH	55.00		55.00
1.00	Pc	Front wheel bearing with hup LH	165.00		165.00
1.00	Pc	Front wheel bearing with hup RH	165.00		165.00
1.00	Pc	Front lower arm LH	125.00		125.00
1.00	Pc	Front lower arm RH	125.00		125.00
1.00	Pc	Front sport rim LH	750.00		750.00
1.00	Pc	Front sport rim RH	750.00		750.00

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0019014
Kwa Lip Oon

Page 3 of 4
Your ref. TP-YL 1675L EQ
Job No.
Our ref 18.04.14
Payment
Date 16/4/2018

Attn

Vehicle No SKJ 4197G
Vehicle Model : Toyota Estima
Accident on ... 12/4/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00	Pc	Rear tailgate	600.00		<i>By</i> 600.00 ✓
1.00	Pc	Rear Toyota logo emblem	20.00		<i>nc</i> 20.00 ✓
1.00	Pc	Rear Estima emblem	30.00		<i>nc</i> 30.00 ✓
1.00	Pc	Rear Aeras emblem	20.00		<i>nc</i> 20.00 ✓
1.00	Pc	Rear tailgate handle garnish	90.00		<i>nc</i> 90.00 x
1.00	Pc	Rear bumper	220.00		<i>nc</i> 220.00 ✓
1.00	Pc	Rear bumper side retainer RH	18.00		<i>nc</i> 18.00 ✓
Total amount of parts supplied - S\$9257.00					
1.00		15% of parts supplied:	1,388.55		1,388.55
Special nett item:					
1.00	Set	Rear reversing sensor with installation	200.00		<i>CRH</i> 200.00 ✓
Labour & Misc:					
1.00		Towing fee	80.00		80.00 <i>bol</i>

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。
除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0019014
Kwa Lip Oon

Page 4 of 4
Your ref. TP-YL 1675L EQ
Job No.
Our ref. 18.04.14
Payment
Date 16/4/2018

Attn

Vehicle No SKJ 4197G
Vehicle Model : Toyota Estima
Accident on ... 12/4/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To transfer front door inner trim board LH & RH	80.00		80.00 ✓
1.00		To remove and refix tailgate handle + rear camera	60.00		60.00 ✓
1.00		To check wheel alignment	60.00		60.00 ✓
1.00		To remove and renew front suspension parts, etc	350.00		350.00 320 ✓
1.00		To straighten front body, to knock dents on front door pillar LH and renew of parts	1,800.00		1,800.00 1500 ✓
1.00		To straighten rear body, to knock dents on rear end panel, floor panel and renew of parts	900.00		900.00 800 ✓
1.00		To spray paint	2,000.00		2,000.00 ✓

Sub-Total 16,175.55
GST 7.00% 1,132.29
Total S\$ 17,307.84

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理除外，还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the supp dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAIC Deluxe oven heater for re-spraying all motor vehicles."