

15/5/2010

INS. CASE OWNER:

CC 3 / CTI1800

LKK:

IDAC:

Surveyor:

Edwin

DOI:

ASSIGNMENT

16/4/18

Date / Time:

16/4/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SPR 7941K

Name of Insured:

LENTOR AMBULANCE Pte

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A:

13/4/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

MIEW WAN SENG

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

SMM180019300/114405

Policy No.:

DMCVSN 180019300

Make / Model:

MITSUB

Place of Accident:

JTE TRNS WY.

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

GVB 7776X

SHR 54679

SPR 7941K

SHL 8716B



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS: 01



INSRS:

WSP:

Tel:

Liability:

RMKS: TP

Date / Time

19/4/18

VIC

3/5/2018

10am

4/5/2018

pehkin 9:45am

9:50am

02/05/18

10/07/18

02/08/18

08/08/18

10/08/18

SHL 8716B - X

SPR 7941K - X

RECEIVED 14 AUG 2018

(Call OJD at 9838 0683, no body pickup, tomorrow will call again)

Spoke to OJD (Mr Chow) at 9838 0683. OJD confirmed about the accident statement.

Spoke to Mr Ronie Tong (Lentor Ambulance), informed him about TP claim and HCD issue. Agreed to settle and aware the HCD issue. send letter to OJ.

MIAU880.

TYPE REPORT WHILE PENDING TP LOD

ORIGINAL TP LOD IN.

REPORT DONE

GIVE WARRANT TO OJ BY BUKIL

OJ APPROVED WARRANT.

SEND 1st OFFER TO TP.

RECEIVED ORIG. SIGNED OJ. TP

ACCEPTED OFFER. ALL FOS IN ORDER.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Jic-Ok

7/5

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others: TP SCENE PHOTOS

PRELIMINARY ADVICE

Date/Time:

17/4/18

Sent By:

Am

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

P/P

SS

9,694.58

(5 days)

Reduction:

19 %

Email

Call

FINAL SETTLEMENT

Date/Time:

08/08/18

Confirm with:

WIKIKU

Email

Call

Final Liability:

(w/acc)

%

100

(Agreed / Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

(w/acc)

SS

10,873.20

Loss of Rental (LOR):

SS

681.50

(5.5 days)

x \$ 115.00

Loss of Use (LOU):

SS

279.00

x 55 days)

Loss of Income (LOI):

SS

-

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

7.19

Medical:

SS

-

Disbursement:

SS

-

Legal Cost

SS

-

Total:

SS

11,288.19

Global Sum S\$:

11,280.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

11,280.00

Name 1:

COMPTON P/L

ENGINEERING PTE LTD

Payee 2: (Strike if N.A.)

SS

-

Name 2:

-

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-

106/11113

REF:

Owner: Kalvin

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / INS / TP RES / OD RES / EVA / INV / MV

To Insp ed Vehicle No: _____

at Work stop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: - % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHC 8316B Yr Regn: 6 Aug, 2015Type: M.Car / M.Cycle / Bus / Van / Lorry / ~~Truck~~ / Prime Mover /

Truck / Trailer or

Make: Hyundai Ix0 c.c. 1685Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 405934 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHLB414A6407 6842Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 13/4/8 D.O.I. 16/4/8Survey held at CD4E (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	total est: \$ 11,927.46 CTI
	PIP \$ 9,694.68 PIP
	CRPD: \$ 2,232.88 (19%)

Date/Time, File Pass to?

☐ : Prel. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

S + RS, SI

☐ : Interview (\$ _____)

Photos



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI18007121/K1hb3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 17-04-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJP 7941K	Veh. Inspected	SHC 8316B	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	17/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	13/04/2018	Inspection Date	16/04/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTI18007121/K1hb3

Date: 17.04.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC8316B


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 16.04.2018 at the premises of M/s ComfortDelGro Engineering Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	10,712.34
Revised Estimate Amount	: S\$	6,231.22
"Check" Items Amount	: S\$	1,855.52
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

Shu Pei (LKKAUTO)

From: Angie Foo <angie.foo@sg.cntaiping.com>
Sent: Wednesday, 18 April 2018 4:22 PM
To: Shu Pei (LKKAUTO)
Cc: Chong Boon Sen; Admin A; Vic (LKKAUTO)
Subject: OUR REF: SNM18D01973C02/1/LKKDS & YR REF: SHC8316B (TP : LKK REF - CC3/CTI18007121/K1hb3)on 13.04.2018
Attachments: SNM18D01973C02 20180418 TO INSURED-SJP7941K- LKKDirectSettlementAccidentNotReportedLtr.pdf; MSNH18050176-SJP7941K.pdf

Dear Shu Pei,

We refer to your email of 17th April 2018.

We attached a copy of Assignment Letter and Insured's SAS Report for your necessary action.

Kindly take note, the claim handler on this case is Chong Boon Sen 6389 6171 and do not email to me for offer or mandate.

Thank you.

Regards,
Angie Foo
Executive
Motor Division
Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Co.Reg.No.200208384E
DID: 6389 6186
Fax: 6224 7478 /6224 7175
Email: angie.foo@sg.cntaiping.com
Email: claimsdept@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Tuesday, 17 April, 2018 6:07 PM
To: Claims Dept of CTI
Cc: Angie Foo; Chong Boon Sen; Admin A; Vic (LKKAUTO)
Subject: Direct Settlement - Accident Involving SJP7941K (OI : CTI - TBA) and SHC8316B (TP : LKK REF - CC3/CTI18007121/K1hb3)on 13.04.2018

WITHOUT PREJUDICE

Dear Boon Sen,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHC 8316B at M/s ComfortDelGro Engineering Pte Ltd (Loyang).

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2360.

Thank you

Best Regards

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.sg.cntaiping.com
Co. Reg. No. 200208384E

Our Reference: **SNM18D01973/C02/1**

Date : **18 APRIL 2018**

via Ordinary & Registered Mail

LENTOR AMBULANCE PTE LTD
51 LENTOR AVENUE

SINGAPORE 786876

Dear Sir / Madam

ACCIDENT INVOLVING SJP7941K AND SHC8316B ON 13 APRIL 2018
ALONG CTE TOWARDS CITY NEAR 7.5KM MARK

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHC8316B**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will soon contact you for more information about the accident. Kindly render your assistance and co-operation accordingly.

We understand that you or your driver has not filed an accident report within 24 hours as per Motor Claims Framework. We would urge you to comply with the condition to file your accident report with your vehicle (whether damaged or not) to us IMMEDIATELY through **LKK Auto Consultants Pte Ltd** or any of **our authorized workshops**. You may log onto our website www.sg.cntaiping.com for location of the respective workshops.

We regret to advice that we and/or **LKK Auto Consultants Pte Ltd** will not be handling the third party claim and your NO CLAIM DISCOUNT will be penalized upon renewal of your policy if you fail to comply with the condition of reporting.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : VIC
Ref : TP-LKK REF-CC3/CT118007121/K1HB3
Contact No : 6841 2360
via Email : vicalpeh@lkkauto.com

CC : Agent - (AN0584A) - HUANG GUOQING, TERRY

F02/LKKDSANR-2013

Date/Time: 13.04.2018 18:09

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 3817675

JC NO: 305141630

CUSTOMER

MS COMFORT TRANSPORTATION PTE LTD
CUSTOMER NO 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755

(O)

(R)

(P)

COUNT CARD NO.

REGN NO

SHC8316B

MILEAGE

MAKE

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

13.04.2018 13:20

DATE/TIME IN

YR OF MANU

06.08.2015

TARGET DATE

CHASSIS CODE

KMHLB41UMGU076842

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 13.04.2018

ATURE: 3P 13.04.18/B > CHINA TAIPING

/NO

LABOR CODE

DESCRIPTION

WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

acknowledgement Slip

Exit Pass

Vehicle No.: SHC8316B

FZ

Vehicle No.:

SHC8316B

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 8316B

DATE 13/4/2018 14:19

CHINA
LKL

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid			\$ 1,681.40
	Boot Lid Rubber			\$ 115.80
	Boot Lid Lock Upper			\$ 137.90
	Boot Lid Lock Lower			\$ 31.70
	Boot Lid 'H' Emblem			\$ 27.20
	Boot Lid CRDI Plate			\$ 41.00
	Boot Lid Lamp (LH/RH)		\$ 556.80	\$ 1,113.60
	Bootlid Moulding			\$ 85.00
	Bootlid i40 Emblem			\$ 41.00
	Bootlid Lower Garnish			\$ 398.00
	Rear Bumper			\$ 603.60
	Rear Bumper Reinforcement			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH)		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket		\$ 49.00	\$
	Rear Bumper Clips			\$ 22.00
	Rear Bumper Sponge			\$ 143.40
	Rear Bumper Under Cover			\$ 225.00
	Tail Lamp (LH/RH)		\$ 565.60	\$ 1,131.20
	Rear Panel			\$ 592.30
	Rear Panel Garnish			\$ 57.70
	Rear Panel Lower Panel			\$ 495.50
	Exhaust Pipe Insulator, LH			\$ 58.55
	Exhaust Silencer, LH			\$ 954.00
	Exhaust Pipe Hanger, LH			\$ 58.55
	Exhaust Pipe Centre			\$ 1,150.30
	Tail Lamp Panel (LH)			\$ 545.90
	Exhaust Silencer (RH)			\$ 954.00
	Tail Lamp Clip			\$ 5.50
	SUB TOTAL			\$ 10,127.05
	LESS 20%			\$ 2,025.41
	DISCOUNTED TOTAL			\$ 8,101.64
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00
	Rear No. Plate			\$ 25.00
	Rear Bumper Reverse Sensor			\$ 135.70
	Rear Bumper Rubber Mat			\$ 50.00
	Labour Charge			\$ 240.70
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 1,000.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Remove/Refix Exhaust Pipe			\$ 150.00
	Remove/Refix Rear Upholstery			\$ 50.00
	TOTAL LABOUR			\$ 2,370.00
	ESTIMATE TOTAL			\$ 10,712.34

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date:

Kalin / 16/4/18 11:52

243073

P/P

Before Part photo

\$50

11927.46

DATE : 18.04.2018

[illegible]

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 19.04.2018
Time: 19:10:36
Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS: COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305141630
REGN NO : SHC8316B
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 06.08.2015
DATE/TIME IN : 13.04.2018 13:20
ACCIDENT DATE : 13.04.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0577-G	I40VC PANEL ASSY-TRUNK LI	1	1,681.40	20.00	1,345.12
0002	04-01-0103-0800-G	I40VC SYMBOL MARK-TRUNK L	1	27.20	20.00	21.76
0003	04-01-0103-0787-G	I40VC EMBLEM-I40	1	41.00	20.00	32.80
0004	04-01-0103-0786-G	I40VC EMBLEM-CRDI	1	41.00	20.00	32.80
0005	28-01-0103-0005-A	(I40/SONATA)REAR BOOT LOG	1	20.00	2.00-	20.00
0006	28-01-0103-0006-A	(I40/SONATA)REAR BOOT TEL	1	10.00	0.20	10.00
0007	04-01-0103-0784-G	I40VC MLDG-BACK PANEL	1	398.00	20.00	318.40
0008	04-01-0103-0785-G	I40VC MLDG-CR PIECE	1	85.00	20.00	68.00
0009	04-01-0103-0780-G	I40V2 MT'G CLIP-RR COMBI	1	5.50	20.00	4.40
0010	04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1	603.60	20.00	482.88
0011	04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1	225.00	20.00	180.00
0012	04-01-0103-0739-G	I40VC ABSORBER-RR BUMPER	1	143.40	20.00	114.72
0013	04-01-0103-0740-G	I40VC BEAM-RR BUMPER#	1	504.35	20.00	403.48

COMFORTDELGRO ENGINEERING PTE LTD

Date: 19.04.2018

REPAIR ESTIMATE

Time: 19:10:36

Page: 2

COMPANY: THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS: COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305141630
 REGN NO : SHC8316B
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 06.08.2015
 DATE/TIME IN : 13.04.2018 13:20
 ACCIDENT DATE : 13.04.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0014 04-01-0103-0742-G	I40VC STAY-RR BUMPER LH	1	180.00	20.00	144.00
0015 04-01-0103-0743-G	I40VC STAY-RR BUMPER RH	1	180.00	20.00	144.00
0016 04-01-0103-0907-G	I40VC BRKT ASSY-RR BUMPER	1	49.00	20.00	39.20
0017 04-01-0103-0581-A	I40VC LAMP ASSY-RR COMB O	1	565.60	20.00	452.48
0018 04-01-0103-0585-A	I40VC LAMP ASSY-RR COMB O	1	565.60	20.00	452.48
0019 04-01-0103-0696-G	I40VC PANEL ASSY-BACK #	1	592.30	20.00	473.84
0020 04-01-0103-1053-G	I40VC TRIM-TRANSVERSE RR	1	57.70	20.00	46.16
0021 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60
0022 04-01-0103-1150-A	I40VC PROTECTOR MAT	1	50.00	2.00-	50.00
0023 09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1	135.70	0.20	135.70
0024 FNPS	NO PLATE(S)	1 N	25.00	0.02-	25.00
0025 04-01-0103-2159-G	I40VC MEMBER ASSY-RR FLOO	1	495.50	20.00	396.40

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 19.04.2018
Time: 19:10:36
Page: 3

COMPANY: THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS: COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305141630
REGN NO : SHC8316B
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 06.08.2015
DATE/TIME IN : 13.04.2018 13:20
ACCIDENT DATE : 13.04.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0026 04-01-0103-0710-G	I40VC EXTENSION ASSY-QTR	1	545.90	20.00	436.72
0027 02-01-0103-0053-G	I40VC MUFFLER ASSY-LH	1	954.00	20.00	763.20
0028 02-01-0103-0054-G	I40VC MUFFLER ASSY-RH	1	954.00	20.00	763.20
0029 02-01-0103-0086-G	I40VC PIPE-EXHAUST FR	1	1,150.30	20.00	920.24

SUB-TOTAL : 8,294.58

JOB NATURE

0000 L	PANEL BEATING	600.00
0001 L	SPRAY PAINTING CHARGE	600.00
0002 L	WIRING CHARGE	20.00
0003 L	TUFF KOTE	20.00
0004 L	REMOVE/REFIX REVERSE SENSOR	20.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 19.04.2018

Time: 19:10:36

Page: 4

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305141630
REGN NO : SHC8316B
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 06.08.2015
DATE/TIME IN : 13.04.2018 13:20
ACCIDENT DATE : 13.04.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0005 L REMOVE/REFIX EXHAUST PIPE

90.00

0006 L REMOVE/REFIX REAR UPHOLSTERY

50.00

SUB-TOTAL : 1,400.00

TOTAL : 9,694.58

MVA NAME & SIGNATURE
DATE:

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 8316B

DATE 13/4/2018 14:19

MAKE :

MODEL : HYUNDAI i40

CHINA
LAL

FZ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid ✓			\$ 1,681.40
	Boot Lid Rubber ✕			\$ 115.80
	Boot Lid Lock Upper ✕			\$ 137.90
	Boot Lid Lock Lower ✕			\$ 31.70
	Boot Lid 'H' Emblem ✓			\$ 27.20
	Boot Lid CRDI Plate ✓			\$ 41.00
	Boot Lid Lamp (LH/RH) ✕	\$	556.80	\$ 1,113.60
	Bootlid Moulding ✓			\$ 85.00
	Bootlid i40 Emblem ✓			\$ 41.00
	Bootlid Lower Garnish ✓			\$ 398.00
	Rear Bumper ✓			\$ 603.60
	Rear Bumper Reinforcement ✓			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) ✓	\$	180.00	\$ 360.00
	Rear Bumper Side Bracket ?	\$	49.00	\$ 98.00
	Rear Bumper Clips ✓			\$ 22.00
	Rear Bumper Sponge ✓			\$ 143.40
	Rear Bumper Under Cover ✓			\$ 225.00
	Tail Lamp (LH/RH) ✓	\$	565.60	\$ 1,131.20
	Rear Panel ✓			\$ 592.30
	Rear Panel Garnish ✓			\$ 57.70
	Rear Panel Lower Panel ✕ ✓			\$ 495.50
	Exhaust Pipe Insulator, LH ?			\$ 58.55
	Exhaust Silencer, LH ?			\$ 954.00
	Exhaust Pipe Hanger, LH ?			\$ 58.55
	Exhaust Pipe Centre ?			\$ 1,150.30
SUB TOTAL				\$ 10,127.05
LESS 20%				\$ 2,025.41
DISCOUNTED TOTAL				\$ 8,101.64
	Boot Lid Comfort Logo & Tel No. Sticker ✓			\$ 30.00
	Rear No. Plate ✓			\$ 25.00
	Rear Bumper Reverse Sensor ✓			\$ 135.70
	Rear Bumper Rubber Mat ✓			\$ 50.00
Acknowledged by Repairer				\$ 240.70
	Labour Charge			\$ 600
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 1,000.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Remove/Refix Exhaust Pipe			\$ 150.00
TOTAL LABOUR				\$ 2,370.00
ESTIMATE TOTAL				\$ 10,712.34

LKK Auto Consultants pen notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

DISCOUNTED TOTAL

Acknowledged by Repairer

Signature:

Date:

Kalin / 16/4/18 11:15L
3 DYS
P/P
Before P.21 photo

Nett

Nett

Nett

Nett

Nett

Nett

Nett

Nett

Nett

Nett

Nett

Nett

Nett

Nett

Nett

Nett

Nett

Nett

Our Job Ref No : 305141630
Date : 19.04.2018

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK Fax :
Attn : KALVIN
Vehicle Reg No. : SHC8316B Date of Accident : 13.04.2018


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA TAIPING — SJP7941K
2. The finalized amount shall be:

(a) Spare Parts after List discount	\$8,294.58
(b) Labour Charges	\$1,400.00
Total for Part-By-Part Repair Cost	\$9,694.58
(c.) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: 20%	\$0.00
Final Lumpsum Repair cost	\$0.00

3. Estimated normal period for repairs: 3+2= 5 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : FAUZY BIN MOKHTAR
Tel : 62148319
Fax : 65468156

Signature : 
Name : Kahr
Date : 23/4/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI18007121/K1hb3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 16-08-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJP 7941K	Veh. Inspected	SHC 8316B
Policy No.	DMCVSN1809331800	Coverage (\$)	0.00
Claim No.	SNM18D01973C02/1/LKKDS	Excess (\$)	0.00
Assign From		Assign Date	16/04/2018

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KMHLB41UMGU076842	Colour	BLUE
Odometer	405934	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	HANKOOK	7 mm
L/H Front Tyre	205/60 R16	HANKOOK	7 mm
R/H Rear Tyre	205/60 R16	HANKOOK	7 mm
L/H Rear Tyre	205/60 R16	HANKOOK	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/04/2018	Inspection Date	16/04/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8316B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOT LID	DENTED	1,681.40	1,681.40
1	BOOT LID RUBBER	SERVICEABLE	115.80	-
1	BOOT LID LOCK UPPER	SERVICEABLE	137.90	-
1	BOOT LID LOCK LOWER	SERVICEABLE	31.70	-
1	BOOT LID 'H' EMBLEM	NECESSARY	27.20	27.20
1	BOOT LID CRDI PLATE	NECESSARY	41.00	41.00
2	BOOT LID LAMP (LH/RH) @\$556.80	SERVICEABLE	1,113.60	-
1	BOOTLID MOULDING	CUT	85.00	85.00
1	BOOTLID I40 EMBLEM	NECESSARY	41.00	41.00
1	BOOTLID LOWER GARNISH	CRACKED	398.00	398.00
1	REAR BUMPER	DEFORMED	603.60	603.60
1	REAR BUMPER REINFORCEMENT	CRACKED	504.35	504.35
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$180.00	BENT	360.00	360.00
1	REAR BUMPER SIDE BRACKET	NECESSARY	49.00	49.00
1	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER SPONGE	TORN	143.40	143.40
1	REAR BUMPER UNDER COVER	CRACKED	225.00	225.00
2	TAIL LAMP (LH/RH) @\$565.60	CRACKED	1,131.20	1,131.20
1	REAR PANEL	DENTED	592.30	592.30
1	REAR PANEL GARNISH	CRACKED	57.70	57.70
1	REAR PANEL LOWER PANEL	DENTED	495.50	495.50
1	EXHAUST PIPE INSULATOR ,LH	SERVICEABLE	58.55	-
1	EXHAUST SILENCER ,LH	BENT	954.00	954.00
1	EXHAUST PIPE HANGER ,LH	TO REPAIR SEE LABOUR	58.55	-
1	EXHAUST PIPE CENTRE	BENT	1,150.30	1,150.30
1	TAILLAMP PANEL (LH)	DENTED	545.90	545.90
1	EXHAUST SILENCER (RH)	BENT	954.00	954.00
1	TAIL LAMP CLIP	NECESSARY	5.50	5.50

Report Ref No. CC3/CTI18007121/K1hb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-2,316.69	-2,013.47
			9,266.76	8,053.88
	<u>SPECIAL NETT ITEMS</u>			
1	BOOT LID COMFORT LOGO & TEL NO.STICKER (SN)	NECESSARY	30.00	30.00
1	REAR NO.PLATE (SN)	CRACKED	25.00	25.00
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	135.70	135.70
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
			240.70	240.70
	<u>LABOUR</u>			
	PANEL BEATING .INCLUSIVE OF THE REPAIR OF EXHAUST PIPE HANGER ,LH .		1,000.00	600.00
	SPRAY PAINTING CHARGE.		1,000.00	600.00
	WIRING CHARGE.		50.00	20.00
	TUFF KOTE.		50.00	20.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	20.00
	REMOVE/REFIX EXHAUST PIPE.		150.00	90.00
	REMOVE/REFIX REAR UPHOLSTERY.		50.00	50.00
			2,420.00	1,400.00
GRAND TOTAL			11,927.46	9,694.58
RECOMMENDED COST OF REPAIRS				9,694.58

Report Ref No. CC3/CTI18007121/K1hb3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.