

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHC 8316B

DATE 13/4/2018 14:19

MAKE :

MODEL : HYUNDAI i40

CHINA  
LRL  
FZ

| Qty              | Parts Description/ Labour                   | Type | Unit Price | Amount       |
|------------------|---------------------------------------------|------|------------|--------------|
|                  | Boot Lid ✓                                  |      |            | \$ 1,681.40  |
|                  | Boot Lid Rubber ✕                           |      |            | \$ 115.80    |
|                  | Boot Lid Lock Upper ✕                       |      |            | \$ 137.90    |
|                  | Boot Lid Lock Lower ✕                       |      |            | \$ 31.70     |
|                  | Boot Lid 'H' Emblem ✓                       |      |            | \$ 27.20     |
|                  | Boot Lid CRDI Plate ✓                       |      |            | \$ 41.00     |
|                  | Boot Lid Lamp (LH/RH) ✕                     |      | \$ 556.80  | \$ 1,113.60  |
|                  | Bootlid Moulding ✓                          |      |            | \$ 85.00     |
|                  | Bootlid i40 Emblem ✓                        |      |            | \$ 41.00     |
|                  | Bootlid Lower Garnish ✓                     |      |            | \$ 398.00    |
|                  | Rear Bumper ✓                               |      |            | \$ 603.60    |
|                  | Rear Bumper Reinforcement ✓                 |      |            | \$ 504.35    |
|                  | Rear Bumper Reinforcement Bracket (LH/RH) ✓ |      | \$ 180.00  | \$ 360.00    |
|                  | Rear Bumper Side Bracket ?                  |      | \$ 49.00   | \$ 98.00     |
|                  | Rear Bumper Clips ✓                         |      |            | \$ 22.00     |
|                  | Rear Bumper Sponge ✓                        |      |            | \$ 143.40    |
|                  | Rear Bumper Under Cover ✓                   |      |            | \$ 225.00    |
|                  | Tail Lamp (LH/RH) ✓                         |      | \$ 565.60  | \$ 1,131.20  |
|                  | Rear Panel ✓                                |      |            | \$ 592.30    |
|                  | Rear Panel Garnish ✓                        |      |            | \$ 57.70     |
|                  | Rear Panel Lower Panel ✕                    |      |            | \$ 495.50    |
|                  | Exhaust Pipe Insulator, LH ?                |      |            | \$ 58.55     |
|                  | Exhaust Silencer, LH ?                      |      |            | \$ 954.00    |
|                  | Exhaust Pipe Hanger, LH ?                   |      |            | \$ 58.55     |
|                  | Exhaust Pipe Centre ?                       |      |            | \$ 1,150.30  |
| SUB TOTAL        |                                             |      |            | \$ 10,127.05 |
| LESS 20%         |                                             |      |            | \$ 2,025.41  |
| DISCOUNTED TOTAL |                                             |      |            | \$ 8,101.64  |
|                  | Boot Lid Comfort Logo & Tel No. Sticker     |      |            | \$ 30.00     |
|                  | Rear No. Plate                              |      |            | \$ 25.00     |
|                  | Rear Bumper Reverse Sensor                  |      |            | \$ 135.70    |
|                  | Rear Bumper Rubber Mat                      |      |            | \$ 50.00     |
| Labour Charge    |                                             |      |            | \$ 240.70    |
|                  | Panel Beating                               |      |            | \$ 1,000.00  |
|                  | Spray Painting Charge                       |      |            | \$ 1,000.00  |
|                  | Wiring Charge                               |      |            | \$ 50.00     |
|                  | Tuff Kote                                   |      |            | \$ 50.00     |
|                  | Remove/Refix Reverse Sensor                 |      |            | \$ 120.00    |
|                  | Remove/Refix Exhaust Pipe                   |      |            | \$ 150.00    |
| TOTAL LABOUR     |                                             |      |            | \$ 2,370.00  |
| ESTIMATE TOTAL   |                                             |      |            | \$ 10,712.34 |

DISCOUNTED TOTAL

SUB TOTAL

LESS 20%

LKK Auto Consultants shall notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kalin 16/4/18  
11:15L  
3 Days  
P/P  
Before P.24 photo

Nett

Nett

Nett

Nett