

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0456/2018/GW
Date : 17-Apr-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Yarman Jehangir Vachha
Address : 36 Strudee Road
#24-12
Singapore 207855
Telephone : HP +65 91157805
Type of Claim : Third Party Claims
Policy No. : 1700055583
Vehicle No : **SJD 8876 Y**
Model Code : Audi Q5 Sport 2.0 TFSI Qu
Model / Year : Sep-17
Engine No : DAX 005966
Chassis No : WAUZZZF7H2025716
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 16-Apr-18
Place of Accident : Tanglin Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJD 8876 Y.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor assy. Check function.	S/N \$ 280.00 ✓	
2	To remove and transfer rear lid's convenience lock system, wire harness for tail lights and rear lid hydraulic assy.	S/N \$ 360.00 ✓	
3	To dismantle and renew rear bumper and rear lid. Align to position. Inspect rhs rear fender for damage. Re-organise rear crash management components. Reinstall all parts removed.	\$ 2,100.00 1000	
4	To respray rear bumper, lower spoiler, rear lid, wheel arch trims and rhs rear fender.	\$ 3,700.00 2700	
5	To renew rear windscreen.	S/N \$ 480.00 ✓	
6	To carry out diagnostic check.	S/N \$ 192.00 ✓	
7	To carry out paint paint protection.	S/N \$ 880.00 600.	
8	To install solar film	S/N \$ 400.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>8,392.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJD 8876 Y.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>Deformed</i>	\$ 1,488.00	✓
2	REAR BUMPER SPACER HOLDER <i>Not New</i>	2 \$ 13.00	X
3	REAR BUMPER COVER <i>Deformed</i>	\$ 1,024.00	✓
4	REAR BUMPER SPOILER	\$ 718.00	✓
5	REAR BUMPER CLOSING ELEMNT <i>Not New</i>	\$ 81.00	X.
6	REAR BUMPER TRIM <i>Not New</i>	\$ 201.00	X.
7	REAR BUMPER TAIL LIGHT-RH <i>cracked</i>	\$ 619.00	✓
8	REAR WHEEL COVER-LH/RH <i>New</i>	2 \$ 938.00	✓
9	REAR BUMPR SENSOR <i>Not New</i>	2 \$ 421.00	X
10	REAR BUMPER SENSOR SEAL RING <i>Not New</i>	4 \$ 15.00	X.
11	REAR LID <i>Deformed.</i>	\$ 3,776.00	✓
12	REAR LID ATTACHMENT PARTS <i>New</i>	\$ 104.00	✓
13	PACKING ADHESIVE <i>New</i>	\$ 15.00	✓
14	AUDI EMBLEM	\$ 108.00	✓
15	INSCRIPTION " Q5 "	\$ 83.00	✓
16	INSCRIPTION " TFSI "	\$ 83.00	✓
17	INSCRIPTION " QUATTRO "	\$ 83.00	✓
18	REAR BUMPER SPOILER FIXING PARTS <i>New</i>	\$ 17.00	✓
19	FOAM STRIPS	\$ 17.00	✓
20	REAR WINDSCREEN <i>New</i>	\$ 1,020.00	✓
SUB-TOTAL SPARE PARTS CHARGES		: \$ 10,824.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJD 8876 Y.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	PRIMER <i>new</i>	\$ 19.00	✓
22	REAR WINDSCREEN MOLDING-LH/RH <i>2</i>	2 \$ 402.00	✓
23	REAR WINDSCREEN SEALANT <i>new</i>	S/N \$ 200.00	✓
24	SUNDRIES <i>?</i>	\$ 400.00	?
TOTAL SPARE PARTS CHARGES		: \$ 11,845.00	
TOTAL LABOUR CHARGES		\$ 8,392.00	
GRAND TOTAL		\$ 20,237.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name
Surveyed Date
Authorised Date
Excess Cost
Liability
Remarks

: Adrian Lim
: 19/04/18
: LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• Illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant