

15/02/10

INS. CASE OWNER:

Binnre

CC 4, AIG 1800 7139, T 4352

LKK:

IDAC:

STANDARD

Taufik

ASSIGNMENT

DOI:

16-04-18

Date / Time:

16-04-18

Registered in Merimen:

17-04-18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SCB1743E

Claim No.:

55 335175265G

Name of Insured:

JAYAKUMAR GANAPATHY

Policy No.:

2100458785

Insured Tel No.:

HP: 98288909

Make / Model:

Lexus

Excess Sec II :SS

D.O.A: 25/03/2018

Place of Accident:

Tessensohw Rd

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SJK 34812



INSRS:

WSP: SE Auto.
Tel: (1 Soon we).
Liability:

RMKS:



INSRS:

WSP:
Tel:
Liability:

RMKS:



INSRS:

WSP:
Tel:
Liability:

RMKS:



INSRS:

WSP:
Tel:
Liability:

RMKS:

Date/ Time

19/11/18
08:11

SJK 34812 - X ; SCB1743E - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):
Non-Reporting ltr (2nd):
Non-Reporting ltr (Final):
Notification ltr (if non-pickup):

19/11/18 @ 3:30pm
Called OI, Mr Jayakumar. Not pick up.
Called OI. Not pick up.
- sent letter to OI.

Call OI: 19/11/18
After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)	<input type="checkbox"/>	<input type="checkbox"/>
After call ltr to OI:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Authorisation To Act:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Release Voucher:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Final Repair Bill:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Car Rental Invoice:	<input type="checkbox"/>	<input type="checkbox"/>
Towing Invoice	<input type="checkbox"/>	<input type="checkbox"/>
LTA / GIA:	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Medical Bill:	<input type="checkbox"/>	<input type="checkbox"/>
PIR:	<input type="checkbox"/>	<input type="checkbox"/>
Mandate/Reject Instruction:	<input type="checkbox"/>	<input type="checkbox"/>
LOD	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Payment Breakdown Form:	<input type="checkbox"/>	<input type="checkbox"/>
Post-Repair Photos:	<input type="checkbox"/>	<input type="checkbox"/>
Others:	<input type="checkbox"/>	<input type="checkbox"/>

27/11/18 - File pass to Taufik to finalise
- FINALISED
- TP LOD IN BY EMAIL

26/07/19 - SEND 1ST OFFER TO TP
- TP ACCEPTED OFFER.
- ALL DOCS IN ORDER.
- TO CLOSE.

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by: Email Call

Repair Cost: US \$3,500.00 (6 days) Reduction: 75 %

FINAL SETTLEMENT Date/Time: 26/07/19 Confirm with: JULIE Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: NIL. If NO or B 28, Ass. Lia: (OI EXTING BUILDING)

Repair Cost: (w/acc) \$3,745.00

Loss of Rental (LOR): \$ (days)

Loss of Use (LOU): \$360.00 (\$60 x 6 days)

Loss of Income (LOI): \$ (\$ x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search \$2.00

Medical: \$ -

Disbursement: \$ - (e.g. Tow/ Independent)

Legal Cost \$ -

Total: \$4,107.00 Global Sum \$: -

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: \$4,107.00 Name 1: GK AUTOMOBILE PTY LTD

Payee 2: (Strike if N.A.) \$ - Name 2: -

Payee 3: (Strike if N.A.) \$ - Name 3: -



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG18007139/T1pa3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 17-04-2018	
Code : AIG			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLB 1743E	Veh. Inspected	SJK 3481Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	17/04/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	25/03/2018	Inspection Date	16/04/2018
Survey held at	SK AUTOMOBILE PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



SK Automobile Pte Ltd
 (Co Reg. No. 201500047H)
 1 Soon Lee Street #04-44/45
 Pioneer Centre
 Singapore 627605
 Tel: 626204438 Fax : 6484 1111

TO	: AIG	DATE	: 12-Apr-18
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SJK3481Z
ADDRESS	:	MODEL	: HYUNDAI 'ELANTRA
TEL. NO.	:	CHASSIS NO	:
OWNER'S INSURANCE	:		
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>	DATE :		
	TIME :		
THIRD PARTY REQUESTOR / CONTACT : MICHAEL 90183598 / KUMAR 98973736			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR DOOR RH	1	\$ 754.00	\$ bt 754.00
2	REAR DOOR INNER LOCK RH	1	\$ 227.20	\$ dis 227.20 photo
3	REAR DOOR INNER TRIM RH	1	\$ 448.00	\$ xm 448.00
4	REAR DOOR HINGE RH	2	\$ 58.00	\$ Ry 116.00
5	REAR DOOR LOCK CATCHER RH	1	\$ 28.00	\$ Ry 28.00
6	REAR DOOR WEATHER STRIP RH	1	\$ 174.80	\$ ne 174.80
7	REAR BUMPER	1	\$ 489.00	\$ de 489.00 de ✓
8	REAR BUMPER RETAINER RH	1	\$ 54.50	\$ ne 54.50 ne ✓
9	REAR BUMPER MUD FLAP	1	\$ 112.00	\$ xm 112.00 xm ✓
10	REAR BUMPER REFLECTOR RH	1	\$ 120.00	\$ xm 120.00 xm ✓
11	REAR FENDER RH	1	\$ 985.00	\$ Ry 985.00
12	REAR FENDER INNER COWLING RH	1	\$ 98.70	\$ x 98.70
13	REAR WINDSCREEN MOULDING	1	\$ 129.80	\$ x 129.80
14	TAIL LAMP RH	1	\$ 876.00	\$ nm 876.00
15	BRAKE PUMP	1	\$ 510.00	\$ x 510.00
16	ABS SENSOR	1	\$ 387.00	\$ x 387.00
17	REAR WHEEL RIM RH	1	\$ 1,054.00	\$? 1,054.00 300 bt ✓
18	REAR AXLE	1	\$ 2,410.00	\$ nm 2,410.00
19	REAR SHOCK ABSORBER RH	1	\$ 348.00	\$ x? 348.00 bt ✓
20	REAR WHEEL BEALING RH	1	\$ 321.00	\$ x? 321.00 bt ✓

TOTAL PRICE \$ 9,643.00
 LESS 20% \$ 1,928.60
 SUB TOTAL PRICE \$ 7,714.40

2668.50
 20% 2134.80

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP SET	1	\$ 65.00	\$ new 65.00
2	TAIL LAMP CLIP SET	1	\$ 40.00	\$ new X 40.00
3	REAR FENDER RH SEALANT	1	\$ 80.00	\$ X 80.00
4	REAR FENDER INNER COWLING CLIP SET	1	\$ 117.00	\$ new X 117.00
5	REAR FENDER INNER TRIM CLIPS SET	1	\$ 117.00	\$ new X 117.00
6	REAR WINDSCREEN SEALANT	1	\$ 80.00	\$ new X 80.00
7	REAR WINDSCREEN INNER SEAL	1	\$ 60.00	\$ new X 60.00
8	REAR DOOR SEALANT RH	1	\$ 80.00	\$ new 80.00
9	REAR DOOR FRAME STEP GARNISH CLIP RH SET	1	\$ 65.00	\$ new X 65.00
10	REAR DOOR INNER TRIM CLIP RH SET	1	\$ 65.00	\$ new 65.00
11	REAR WHEEL TYRE	1	\$ 450.00	\$ new X 450.00

TOTAL \$ 1,219.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	800 950
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	700
3	TUFF COAT	\$ 250.00	30
4	WIRING CHECK	\$ 60.00	30.
5	REMOVE AND REFIX UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 380.00	50.
6	FOUR WHEEL ALIGNMNET	\$120.00	80.
7	ABS LIGHT RESET	\$350.00	X 44
8	TRANSFER REAR DOOR MECHANISM	\$80.00	60.
9	REMOVE & REINSTALL REAR WINDOW GLASS	\$80.00	X 44
10	CONDUCT WATER LEAKAGE TEST	\$ 80.00	20.
11	REMOVE AND REPLACE REAR WINDSCREEN	\$ 120.00	X 44
12	REMOVE AND REFIT REAR UNDERCARRIGE	\$ 550.00	photo 150 ✓
13	MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 280.00	100.

TOTAL

\$5,550.00

2170

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,933.40
TOTAL LABOUR COST : \$ 5,550.00
TOTAL REPAIR COST : \$ 14,483.40

APPROVED DETAILS
EXCESS :
NO. OF WORKING DAY: :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

Parts 2134.80
SN - 120
Labour - 2170

4424.80

4535.00*

6 days

Taufik 97495749

-wp

6/4/18 1730

sur@lkkauto.com

Lumpsum

Resurvey after repair

6 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Catherine Chong (LKK Auto)

From: Supramaniam, Darshene <Darshene.Supramaniam@aig.com>
Sent: Monday, 16 April, 2018 2:44 PM
To: 'admin-a@lkkauto.com'; 'assignments@lkkauto.com'
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Lim, Sheng Yang; Chan, Yoke Shi; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Fan, Winnie-LW; Md Ishak, Mohd Imran
Subject: FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING MOTOR VEHICLES NO SLB1743E AND SJK3481Z ON 25 MARCH 2018
Attachments: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING MOTOR VEHICLES NO SLB1743... (51.4 KB); SJK3481Z GIA.PDF; SJK3481Z ARRANGE.PDF

Hi,

Please refer to the enclosed request from SK Automobile Pte Ltd.

Claim no : 5533517526SG003
Case Owner : Tan Bennie

If you have any queries/concerns, please let us know.
Kindly assist to assign **Mohammed Rasul** as Single Joint Expert as requested.

Thank you.

Best Regards,

Darshene Supramaniam
AIG
Express Claims Adjuster II, FNOL SG Claims Operations - Auto
Shared Services - Malaysia | Global Business Services

Level 12, Menara Worldwide, 198 Jalan Bukit Bintang. 55100 Kuala Lumpur, Malaysia
Tel +603 2719 6000 ext 100-2208 | Fax +603 2719 6150

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

16-04-2018 @ 2:50pm
Michael veh in.
Taufiq.

Hsiao Tong (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 25 April 2018 10:59 AM
To: Pioneer Workshop; SUR; Hsiao Tong (LKKAuto); Taufikh (LKKAuto)
Cc: Simon Koh; JING XIONG KHOO; SK Admin
Subject: RE: SJK3481Z CHECK ITEMS
Attachments: 1.jpeg; 2.jpeg; 3.jpeg; 4.jpeg; 5.jpeg; 6.jpeg; 7.jpeg; 8.jpeg; 9.jpeg; 10.jpeg; 11.jpeg; 12.jpeg; 13.jpeg; 14.jpeg; 15.jpeg; 16.jpeg

Dear Sir,

Thank you for your email

Dear Hsiao Tong/Taufikh,

[CC4/AIG18007139/T1pa3](#)

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Pioneer Workshop [mailto:pioneer@skauto.com.sg]
Sent: Wednesday, 25 April 2018 10:56 AM
To: SUR <sur@lkkauto.com>
Cc: Simon Koh <simon@skauto.com.sg>; JING XIONG KHOO <xiongskauto@gmail.com>; SK Admin <admin@skauto.com.sg>
Subject: SJK3481Z CHECK ITEMS

Hi Taufick,

Please find the attachments of check item photos.

1. Rear door inner lock RH
2. Rear wheel rim RH
3. Rear shock absorber RH
4. Rear wheel bearing RH

--
Thanks & Regards,
Prasanna Kumar,
SK Automobiles,
Hp.no - 98973736.

SK Automobile Pte Ltd

23 Kaki Bukit Ave 4 #03-01

Vicom Inspection Centre (South Wing) S(415933)

Tel: +65 6789 5155 Fax: +65 6783 5155

Co. Reg No.201500047H GST Reg No. 201500047H

Date : 16.05.2019
Your Ref : SLB 1743E
To : AIG ASIA PACIFIC INSURANCE PTE LTD
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Thru : LKK AUTO CONSULTANTS PTE LTD
Attn : MOTOR CLAIM DEPARTMENT

Dear Sir/Mdm,

RE: THIRD PARTY CLAIM FOR SJK 3481Z & SLB 1743E on 25.03.2018

We refer to the above matter.


Attached copies of the following for your perusal:

- 1) Tax Invoice No. IV19-90218 (S\$3,745.00) -AMEND-
- 2) Loss Of Use 06 days @ S\$140.00 (S\$840.00).
- 3) Letter Of Authorisation
- 4) LTA Search Fee (S\$2.00)

Please look into the above claim and let us have your payment of **S\$4,587.00** the soonest.

Thank You.

Yours faithfully,


Julie
E-mail: julie@skauto.com.sg





ROC No.: 201500047H
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (South Wing) S415933
Tel: 6789 5155 Fax: 6783 5155

LETTER OF AUTHORIZATION

To Workshop : SK Automobile Pte Ltd
Fr Owner's Name : Loh Tsee Fong
Company (if any) : -
Address : 6 Happy Avenue Central S(369899)
NRIC No : S1693835A
Accident on : 25.3.18 involving vehicle(s) SLB 1743E
Along : Tessonsohn Rd Before Civil Service

I/we, Loh Tsee Fong the owner of motor vehicle, registration no. SJK34612 hereby do authorize you to commence repairs to my abovementioned vehicle.

I/We confirm that you are authorized to handle the repair of the vehicle and/or to negotiate and settle my claims relating to the above mentioned accident, which I/we may have, against the other third party/parties or insurers (excluding my own insurer) and/or to instruct lawyers on my/our behalf, to facilitate the third party claim for me/us.

You are hereby authorized to execute and/or sign any documents/discharge vouchers/agreements regarding my/our claim/case for my convenience. You are also hereby authorized to receive on my/our behalf monies/claims, correspondences in connection with this said claim.

I/We confirm that in the event of an unsuccessful claim against the negligent party, and/or my own insurer for the damages caused to my vehicle, I agree to pay all repair costs, car rental and any incidental expenses incurred by you or to lodge an own damage (only for comprehensive cover) to cover the expenses incurred.

Witness's Name : Juli

Date : _____

Witness's Signature : [Signature]

Owner's Signature : [Signature]



ROC No.: 201500047H
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (South Wing) S415933
Tel: 6789 5155 Fax: 6783 5155

To: ALG ASIA PACIFIC Insurance Pte Ltd


Dear Sir/Madam


Accident involving SJK 3481Z and SLB1743E on 25.3.18
At/along Tessonsohn Rd Before Civil Service

I/We, Loh Tsee Fong, am the registered
owner of the motor vehicle no. SJK 3481Z

Please note that I have assigned all compensation monies due to me/us in the above said accident to
M/S SK Automobile Pte Ltd.

I/We, hereby authorized you to release all compensation monies pertaining to the above-mentioned
accident to M/S SK Automobile Pte Ltd and forward your settlement cheque to M/S SK Automobile
Pte Ltd whom I have authorized to collect the said compensation/monies.


Signature of Claimant


Witness



...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt.	Adj Submitted	Ins Auth'ed	Status
Main	26 Mar 2018 Edit Reg		16 Apr 2018 00:00 Edit Adj Rpt	S\$3,500.00 Edit Estimates	S\$3,500.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	JAYAKUMAR GANAPATHY, ID: S27049381		
Main Claimant:	LOH TSEE FOONG (DR), ID: S1693835A		
Vehicle Reg. No.:	SJK3481Z	Date of Loss:	25/03/2018 13:00 - :59 [5 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 5533517526SG	Policy/Cover Note No.:	2100458285 (Comprehensive)
Vehicle Reg. No. (Insured):	SLB1743E	Policy No. (Claimant):	5095501755
		Excess:	
Repairer:	SK Automobile Pte Ltd (Toh Guan) 48 Toh Guan Road East #01-121, Enterprise Hub, 608586 Jurong East - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 26/04/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (18/04/2018): TP GIA REPORT

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJK3481Z (5533517526SG)**
[SLB1743E]
TP
LOH TSEE FOONG (DR)
Mar 25 2018 1:00PM
[JAYAKUMAR GANAPATHY]
SK Automobile Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View	View in Browser ▼	
Letters/Correspondences					
			1 per page ▼	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	1	Edit	
Assessment Reports					
			1 per page ▼	<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	18/04/18 09:40	Accident Statement From:OD - Reg. No: SLB1743E, Claimant: JAYAKUMAR GANAPATHY	1	Load HTM	
Photos/Images					
			3 per page ▼	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/04/18 13:52	Odometer Reading	1	Load JPG	<input checked="" type="checkbox"/>
2	19/04/18 13:52	Chassis Number	1	Load JPG	<input checked="" type="checkbox"/>
3	19/04/18 13:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	19/04/18 13:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	19/04/18 13:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	19/04/18 13:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	19/04/18 13:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	19/04/18 13:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	19/04/18 13:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	19/04/18 13:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	19/04/18 13:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	19/04/18 13:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	19/04/18 13:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	19/04/18 13:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	19/04/18 13:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	19/04/18 13:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	19/04/18 13:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	19/04/18 13:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	19/04/18 13:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	19/04/18 13:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	19/04/18 13:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	19/04/18 13:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	19/04/18 13:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	19/04/18 13:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	19/04/18 13:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
26	19/04/18 13:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
27	19/04/18 13:52	General View	1	Load JPG	<input checked="" type="checkbox"/>
28	19/04/18 13:52	General View	1	Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
29	19/04/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>
30	19/04/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>
31	19/04/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>
32	19/04/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>
33	19/04/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>
34	19/04/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>
35	19/04/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>
36	19/04/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>
37	19/04/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>
38	19/04/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>
39	19/04/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>
40	19/04/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>
41	19/04/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>
42	19/04/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>
43	19/04/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>
44	19/04/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>
45	19/04/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>
46	19/04/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>
47	19/04/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>
48	19/04/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>
49	19/04/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>
50	19/04/18 13:52	General View	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/04/18 00:46	TP ESTIMATE - MARKED	Load PDF	
2	19/04/18 00:46	TP GIA REPORT	Load PDF	
3	26/07/19 08:46	LETTER TO OI	Load PDF	
4	08/08/19 16:34	AUTHORISATION TO ACT	Load PDF	
5	08/08/19 16:34	RELEASE VOUCHER	Load PDF	
6	08/08/19 16:34	WORKSHOP INVOICE	Load PDF	
7	08/08/19 16:34	GIA SEARCH	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
 Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLB1743E (Insd veh)	Model:	HYUNDAI ELANTRA 1.6 AD GLS (A)
	SJK3481Z (TP veh)		
Date of Accident:	25/03/2018		

Global Sum Settlement	:	[] Yes	[X] No	
Repair Estimate	:		<input checked="" type="checkbox"/>	\$ 15,497.24
Final Repair Cost	:		<input checked="" type="checkbox"/>	\$ 3,745.00
Loss of Use	:		<input checked="" type="checkbox"/>	\$ 360.00 6.00 days at \$60.00 per day
Rental (if any)	:		<input checked="" type="checkbox"/>	\$ days
LTA / GIA Search Fee	:		<input checked="" type="checkbox"/>	\$ 2.00
Others:	:		<input checked="" type="checkbox"/>	\$
	:		<input checked="" type="checkbox"/>	\$
Final Settlement Sum	:		<input checked="" type="checkbox"/>	\$ 4,107.00
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)				
A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)				
B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____				
BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)				
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	SK Automobile Pte Ltd	:	\$ 4,107.00
2)		:	\$
3)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

08 Aug
2019

Date

**Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill
(if any)**

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18007139/T1HA3S2
Date: 08/08/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100458285
Claimant Vehicle No : SJK3481Z **Insured Vehicle No :** SLB1743E
 Date of Loss: 25/03/2018 Nature of Claim: TP Claim No: 5533517526SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJK3481Z**
 Make & Model: HYUNDAI ELANTRA, 1.6 AD GLS (A) Engine No: G4FGHU691243
 Reg. Date: 17/10/2017 (Man. Year: 2017) Chassis No: KMHD841CMJU560554
 Colour: Silver Odometer: 6242 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm
 Front Right Side: Nexen 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,933.40	2,254.80	6,678.60	74.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,550.00	2,170.00	3,380.00	60.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,483.40	4,424.80	10,058.60	69.45
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	14,483.40	3,500.00	10,983.40	75.83
+ GST 7.00/7.00% (S\$)	1,013.84	245.00	768.84	75.83
Nett Amount (S\$)	15,497.24	3,745.00	11,752.24	75.83
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,107.00		

INSPECTION

Date of Assignment: 16/04/2018
 Date Inspected: 16/04/2018 Inspected At: SK Automobile Pte Ltd (Toh Guan)
 48 Toh Guan Road East #01-121, Enterprise Hub
 Singapore 608586
 Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH	Bent	754.00 FL	*754.00 FL
2	1		*REAR DOOR INNER LOCK RH	Distorted	227.20 FL	*227.20 FL
3	1		*REAR DOOR INNER TRIM RH	Not Necessary	448.00 FL	*- FL
4	2		*REAR DOOR HINGE RH	Repair	116.00 FL	*- FL
5	1		*REAR DOOR LOCK CATCHER RH	Repair	28.00 FL	*- FL
6	1		*REAR DOOR WEATHER STRIP RH	Necessary	174.80 FL	*174.80 FL
7	1		*REAR BUMPER	Deformed	489.00 FL	*489.00 FL
8	1		*REAR BUMPER RETAINER RH	Necessary	54.50 FL	*54.50 FL
9	1		*REAR BUMPER MUD FLAP	Not Necessary	112.00 FL	*- FL
10	1		*REAR BUMPER REFLECTOR RH	Not Necessary	120.00 FL	*- FL
11	1		*REAR FENDER RH	Repair	985.00 FL	*- FL
12	1		*REAR FENDER INNER COWLING RH	Not Necessary	98.70 FL	*- FL
13	1		*REAR WINDSCREEN MOULDING	Not Necessary	129.80 FL	*- FL
14	1		*TAIL LAMP RH	Not Necessary	876.00 FL	*- FL
15	1		*BRAKE PUMP	Not Necessary	510.00 FL	*- FL
16	1		*ABS SENSOR	Not Necessary	387.00 FL	*- FL
17	1		*REAR WHEEL RIM RH	Bent	1,054.00 FL	*300.00 FL
18	1		*REAR AXLE	Not Necessary	2,410.00 FL	*- FL
19	1		*REAR SHOCK ABSORBER RH	Bent	348.00 FL	*348.00 FL
20	1		*REAR WHEEL BEARING RH	Bent	321.00 FL	*321.00 FL
21	1		*SET REAR BUMPER CLIP	Necessary	65.00 FS	*30.00 FS
22	1		*SET TAIL LAMP CLIP	Not Necessary	40.00 FS	*- FS
23	1		*REAR FENDER RH SEALANT	Necessary	80.00 FS	*30.00 FS
24	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	117.00 FS	*- FS
25	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	117.00 FS	*- FS
26	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
27	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	60.00 FS	*- FS
28	1		*REAR DOOR SEALANT RH	Necessary	80.00 FS	*30.00 FS
29	1		*SET REAR DOOR FRAME STEP GARNISH CLIP RH	Not Necessary	65.00 FS	*- FS
30	1		*SET REAR DOOR INNER TRIM CLIP RH	Necessary	65.00 FS	*30.00 FS
31	1		*REAR WHEEL TYRE	Not Necessary	450.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	10,862.00	2,788.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,928.60	533.70
Total Parts (\$\$)	8,933.40	2,254.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVAL AND REPLACING PARTS.	New	1,800.00	950.00
2	TO SPRAY PAINT AFFECTED AREA.	New	1,400.00	700.00
3	TUFF COAT.	New	250.00	30.00
4	WIRING CHECK.	New	60.00	30.00
5	REMOVE AND REFIX UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR.	New	380.00	50.00
6	FOUR WHEEL ALIGNMENT.	New	120.00	80.00
7	ABS LIGHT RESET.	New	350.00	0.00
8	TRANSFER REAR DOOR MECHANISM.	New	80.00	60.00
9	REMOVE & REINSTALL REAR WINDOW GLASS.	New	80.00	0.00
10	CONDUCT WATER LEAKAGE TEST.	New	80.00	20.00
11	REMOVE AND REPLACE REAR WINDSCREEN.	New	120.00	0.00
12	REMOVE AND REFIT REAR UNDERCARRIAGE.	New	550.00	150.00
13	MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	New	280.00	100.00
Gross Labour Cost (S\$)			5,550.00	2,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >