



SK Automobile Pte Ltd
 (Co Reg. No. 201500047H)
 1 Soon Lee Street #04-44/45
 Pioneer Centre
 Singapore 627605
 Tel: 626204438 Fax : 6484 1111

TO	: AIG	DATE	: 12-Apr-18
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SJK3481Z
ADDRESS	:	MODEL	: HYUNDAI 'ELANTRA
TEL. NO.	:	CHASSIS NO	:
OWNER'S INSURANCE	:		
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>	DATE :		
	TIME :		
THIRD PARTY REQUESTOR / CONTACT : MICHAEL 90183598 / KUMAR 98973736			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR DOOR RH	1	\$ 754.00	\$ <i>bt</i> 754.00
2	REAR DOOR INNER LOCK RH	1	\$ 227.20	\$ <i>dis</i> 227.20
3	REAR DOOR INNER TRIM RH	1	\$ 448.00	\$ <i>x</i> 448.00
4	REAR DOOR HINGE RH	2	\$ 58.00	\$ <i>Ry</i> 116.00
5	REAR DOOR LOCK CATCHER RH	1	\$ 28.00	\$ <i>Ry</i> 28.00
6	REAR DOOR WEATHER STRIP RH	1	\$ 174.80	\$ <i>nc</i> 174.80
7	REAR BUMPER	1	\$ 489.00	\$ <i>Ry</i> 489.00
8	REAR BUMPER RETAINER RH	1	\$ 54.50	\$ <i>x</i> 54.50
9	REAR BUMPER MUD FLAP	1	\$ 112.00	\$ <i>x</i> 112.00
10	REAR BUMPER REFLECTOR RH	1	\$ 120.00	\$ <i>x</i> 120.00
11	REAR FENDER RH	1	\$ 985.00	\$ <i>Ry</i> 985.00
12	REAR FENDER INNER COWLING RH	1	\$ 98.70	\$ <i>x</i> 98.70
13	REAR WINDSCREEN MOULDING	1	\$ 129.80	\$ <i>x</i> 129.80
14	TAIL LAMP RH	1	\$ 876.00	\$ <i>x</i> 876.00
15	BRAKE PUMP	1	\$ 510.00	\$ <i>x</i> 510.00
16	ABS SENSOR	1	\$ 387.00	\$ <i>x</i> 387.00
17	REAR WHEEL RIM RH	1	\$ 1,054.00	\$ <i>?</i> 1,054.00
18	REAR AXLE	1	\$ 2,410.00	\$ <i>x</i> 2,410.00
19	REAR SHOCK ABSORBER RH	1	\$ 348.00	\$ <i>x?</i> 348.00
20	REAR WHEEL BEALING RH	1	\$ 321.00	\$ <i>R?</i> 321.00

TOTAL PRICE \$ 9,643.00
 LESS 20% \$ 1,928.60
 SUB TOTAL PRICE \$ 7,714.40

photo-

*de ✓
nc ✓*

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP SET	1	\$ 65.00	\$ new 65.00 30
2	TAIL LAMP CLIP SET	1	\$ 40.00	\$ X 40.00
3	REAR FENDER RH SEALANT	1	\$ 80.00	\$ X 80.00 30 new
4	REAR FENDER INNER COWLING CLIP SET	1	\$ 117.00	\$ X 117.00
5	REAR FENDER INNER TRIM CLIPS SET	1	\$ 117.00	\$ X 117.00
6	REAR WINDSCREEN SEALANT	1	\$ 80.00	\$ X 80.00
7	REAR WINDSCREEN INNER SEAL	1	\$ 60.00	\$ X 60.00
8	REAR DOOR SEALANT RH	1	\$ 80.00	\$ new 80.00 30
9	REAR DOOR FRAME STEP GARNISH CLIP RH SET	1	\$ 65.00	\$ X 65.00
10	REAR DOOR INNER TRIM CLIP RH SET	1	\$ 65.00	\$ new 65.00 30
11	REAR WHEEL TYRE	1	\$ 450.00	\$ X 450.00

TOTAL \$ 1,219.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00		800 950
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00		700
3	TUFF COAT	\$ 250.00		30
4	WIRING CHECK	\$ 60.00		30.
5	REMOVE AND REFIX UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 380.00		50.
6	FOUR WHEEL ALIGNMNET	\$120.00		80.
7	ABS LIGHT RESET	\$350.00		X
8	TRANFER REAR DOOR MECHANISM	\$80.00		60.
9	REMOVE & REINSTALL REAR WINDOW GLASS	\$80.00		X
10	CONDUCT WATER LEAKAGE TEST	\$ 80.00		20.
11	REMOVE AND REPLACE REAR WINDSCREEN	\$ 120.00		X
12	REMOVE AND REFIT REAR UNDERCARRIGE	\$ 550.00		photo. 150?
13	MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 280.00		100.

TOTAL

\$5,550.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,933.40
TOTAL LABOUR COST : \$ 5,550.00
TOTAL REPAIR COST : \$ 14,483.40

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAY::
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

Taufik 97495749
-wp
6/4/18 @ 1730
sur@lkkauto.com.
Lumpsum
Resurvey after repair
6 days.

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: