

REF:

ASS. REC. BY: Adrian King**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No**CA / REV / REP. / 24 HRS**

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJW6451C Yr Regn: 2008 / AprilType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Fit C.C. 1339Colour: White A/C: Insured / Std / NI / NASp. Reading: 145494 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GE61052338Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/55R15R: 195/55R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 16/04/18Survey held at Hua MerryDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-------------|-----------------------------------|
| | TP Chirn. Pending COE Renewal. |
| | US \$ 2600 (Reel \$ 555.72 / 68%) |
| | MV: 32K (New 5yr COE), |
| | PV: |
| | Nett: |

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS \$ _____

Photos _____

Others _____

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

62052



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|----------------------------|---|--|
| CHINA TAIPING INSURANCE (S) PTE LTD | | Ref : CC6/CTI18007140/Apa3 | | |
| 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909 | | Date : 17-04-2018 |  | |
| | | Code : CTI | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | PA 2977Z | Veh. Inspected | SJW 6451C | |
| Policy No. | DMBISN1650821701 | Coverage (\$) | 0.00 | |
| Claim No. | SNM18D02015C02 | Excess (\$) | 0.00 | |
| Assign From | | Assign Date | 17/04/2018 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | c.c | | 0 | |
| Engine No. | HIDDEN | Year of Reg. | | |
| Chassis No. | | Colour | | |
| Odometer | - | Steering | | |
| Brakes | | Modification | | |
| General | | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | | | mm | |
| L/H Front Tyre | | | mm | |
| R/H Rear Tyre | | | mm | |
| L/H Rear Tyre | | | mm | |
| 4. Description of Damages | | | | |
| | | | | |
| 5. General Information | | | | |
| Accident Date | 14/04/2018 | Inspection Date | 16/04/2018 | |
| Survey held at | HUA MENG SPRAY PAINTING WKSP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

RADIAH BINTE OSMAN
BLK 128 MARSILING RISE
#09-168
S730128

TP Chin
Xiao Tony

Date : 07.06.2018
Vehicle no : SJW 6451 C
Make/Model : HONDA FIT
Accident date : 14.04.2018

| No | Description | Qty | Amount (\$\$) |
|-------------------|---|-----|-------------------------|
| List Items | | | |
| 1 | Bonnet hinges @ \$33.60 <i>new</i> | 2 | \$ 67.2 x |
| 2 | Bonnet lock <i>new</i> | 1 | \$ 95.1 x |
| 3 | Bonnet lock bracket | 1 | \$ 55.2 x |
| 4 | Bonnet H sticker <i>new</i> | 1 | \$ 35 ✓ |
| 5 | Front grille <i>new</i> | 1 | \$ 75 x |
| 6 | Front grille HONDA emblem <i>new</i> | 1 | \$ 22.9 x |
| 7 | Front bumper <i>new</i> | 1 | \$ 503.2 ✓ |
| 8 | Front bumper side holder @ \$30.00 <i>new</i> | 2 | \$ 60 ✓ |
| 9 | Front bumper reinforcement <i>new</i> | 1 | \$ 213.5 ✓ |
| 10 | Front bumper lower lip <i>new</i> | 1 | \$ 68.5 x |
| 11 | Front head lamp @ \$552.10 <i>LH cracked</i> | 2 | \$ 1104.2 <i>552.10</i> |
| 12 | Front bumper fog lamp @ \$277.90 <i>new</i> | 2 | \$ 555.8 x |
| 13 | Front head lamp lower bracket <i>LH cracked</i> | 2 | \$ 55 <i>27.50</i> |
| 14 | Front support panel <i>new</i> | 1 | \$ 385.9 x |
| 15 | Air con condenser <i>new</i> | 1 | \$ 704.4 x |
| | | | \$ 4000.9 |
| Less 20% Disc | | | \$ 800.18 |
| Total | | | \$ 3200.72 |

Special Nett Items

| | | | |
|-------|-----------------------------------|---|--------------------|
| 1 | Bonnet <i>cracked</i> | 1 | \$ 1100 <i>900</i> |
| 2 | Front grille rim <i>cracked</i> | 1 | \$ 850 <i>520</i> |
| 3 | Front LH head lamp rim <i>new</i> | 1 | \$ 155 <i>65</i> |
| Total | | | \$ 2105 |

Labour Cost

| | | |
|-------------|---|--------------------|
| 1 | Remove & reinstall air con fill in gas | \$ 150 x |
| 2 | Remove, replace & repair consistent to the accident | \$ 1500 <i>450</i> |
| 3 | Respray painting | \$ 1100 <i>250</i> |
| 4 | Tuff kote | \$ 100 x |
| Total | | \$ 2850 |
| Grand Total | | \$ 8155.72 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 3278.04
L/S: 2.8K
OA Days

2.8K

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Saturday, 14 July 2018 4:51 PM
To: 'Claims Dept of CTI'
Cc: 'Irene Tay'; Admin A
Subject: RE: Direct Settlement - Accident Involving PA2977Z (OI : CAI - SNM18D02015C02) and SJW6451C (TP : LKK REF - CC6/CTI18007140/Apa3) on 14.04.2018
Attachments: TP ESTIMATE.pdf; Preliminary Advice - SJW 6451C.pdf; LKK Survey Photos.pdf

Dear Sirs/Madam,

We refer to the above matter.

Enclosed for your perusal is: -

- Estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lucas Lee [<mailto:lucas.lee@sg.cntaiping.com>]

Sent: Friday, 27 April, 2018 3:58 PM

To: Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving PA2977Z (OI : CAI - SNM18D02015C02) and SJW6451C (TP : LKK REF - CC6/CTI18007140/Apa3) on 14.04.2018

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Irene Tay

Lucas Lee

Claims Department (Motor)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6181

Fax (65) 6222 7175

Email: lucas.lee@sg.cntaiping.com

Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAuto) [<mailto:Meikwan@lkkauto.com>]

Sent: Tuesday, 24 April, 2018 1:22 PM

To: Claims Dept of CTI

Cc: Irene Tay; Lucas Lee; Hsiao Tong (LKKAuto); Joy Irene (LKKAuto); Asher Sng (LKKAuto); Admin A; Claims Dept of CTI

Subject: Direct Settlement - Accident Involving PA2977Z (OI : CAI - TBA) and SJW6451C (TP : LKK REF - CC6/CTI18007140/Apa3) on 14.04.2018

WITHOUT PREJUDICE

Dear Sir/ Madam,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SJW 6451C at M/s Hua Meng Spray Painting Workshop - Kaki Bukit.

Enclosed for your perusal is:

- TP GIA report

Please be informed that the estimated cost of repair and preliminary advice is not ready yet.

We will revert to you on preliminary advice in due course.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBLAVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: SNM18D02015C02

Our ref: CC6/CTI18007140/Apa3

Date: 14.07.2018

The Motor Claims Department
M/S China Taiping Insurance (Singapore) Pte. Ltd

Dear Sir/Madam

PRELIMINARY ADVICE OF VEHICLE NO.

SJW 6451C


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 16.04.2018 at the premises of M/s HUA MENG SPRAY PAINTING WKSP and have the following to report:-

| | | |
|--------------------------|-------|----------|
| Workshop Estimate Amount | : S\$ | 8,155.72 |
| Revised Estimate Amount | : S\$ | 3,278.04 |
| "Check" Items Amount | : S\$ | - |
| Market Value | : S\$ | - |
| LTA Reimbursement Value | : S\$ | - |
| Nett Value | : S\$ | - |

Description of Damage:

The vehicle sustained damages at the
FRONT PORTION



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 04 days

Yours faithfully,

ADRIAN LING

Licensed Appraiser



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.sg.cntaiping.com
Co. Reg. No. 200206384E

Our Reference: **SNM18D02015/C02/1**

Date : **27 APRIL 2018**

via Ordinary & Registered Mail

**HUP HOE COACH SERVICE
BLK 148 WOODLANDS ST 13
#11-839
SINGAPORE 730148**

Dear Sir / Madam

**ACCIDENT INVOLVING PA2977Z AND SJW6451C ON 14 APRIL 2018
ALONG MARSILING RISE(BLK 131 OSCP)**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SJW6451C** , is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd
Attn : HSIAO TONG
Ref : CC6/CTI18007140/APA3
Contact No : 67423197
via Email : HSIAOTONG@LKKAUTO.COM

CC : Agent - (AN0580A) - ODDS & EVEN

F01/LKKDS-2013

THE BIG STORY | Update your MyTransport.SG mobile app now on [iOS](#) and [Google Play](#). | You can now use your credit / debit card (MasterCard or VISA or

[Home](#) / [LTA eServices](#) / [Online Enquiries](#) / [Enquire Vocational Licence Status](#)

ENQUIRE VOCATIONAL LICENCE STATUS

[PRINT THIS ARTICLE](#)
[SHARE THIS ARTICLE](#)

Enquiry E-Service for Vocational Licence Holders

Welcome to LTA eService Enquiry E-Service for Vocational Licence Holders

This e-service allows Vocational Licence (VL) holders and other interested parties to check on the status of a VL. To use this enquiry feature, you will need to enter both the NRIC/Foreign Identification Number (FIN) and the date of birth of the VL holder.

You can enquire on the status of all [types of VL](#), as listed below:

- Private Hire Car Driver's Vocational Licence
- Taxi Driver's Vocational Licence
- Omnibus Driver's Vocational Licence
- General Bus Driver's Vocational Licence
- Bus Attendant's Vocational Licence
- Trishaw Rider's Vocational Licence

* **NRIC No/FIN** (e.g. S1234567A, F1234567A)

* **Date of Birth** - - (Format: DD-MM-YYYY)

[PROCEED](#) [RESET](#)

Fields marked * are required.

STATUS OF VOCATIONAL LICENCE

The information contained herein is correct as at 03-May-2018

Name SOH KEE GUAN

Licence Number S7040441

Date of Birth 25-Nov-1970

TYPE OF VOCATIONAL LICENCE

| VL Type | Status | Expiry Date |
|---|--------|-------------|
| General Bus Driver's Vocational Licence | Valid | 22-10-2020 |
| Bus Attendant's Vocational Licence | Valid | 22-10-2020 |

[FAQs](#)
[BACK TO TOP](#)

I WANT TO ...

[drive](#)
[buy](#)
[sell](#)
[maintain](#)
[participate](#)

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Friday, 28 September 2018 4:54 PM
To: claimsdept@sg.cntaiping.com
Cc: Irene Tay; Admin A
Subject: RE: Direct Settlement - Accident Involving PA2977Z (OI : CAI - SNM18D02015C02) and SJW6451C (TP : LKK REF - CC6/CTI18007140/Apa3) on 14.04.2018
Attachments: LKKInspection.pdf; LKKAdjustment1.pdf; LKK Survey Photos.pdf; LKK Resurvey Photos.pdf; TP LOD_SJW 6451C.pdf

Hi All,

Kindly ignore my mandate below as the total amount is less than \$3,000.00.

We will proceed to settle the matter with third party and close file in due course.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)
Sent: Saturday, 15 September 2018 9:13 AM
To: 'Claims Dept of CTI' <claimsdept@sg.cntaiping.com>
Cc: 'Irene Tay' <irene.tay@sg.cntaiping.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving PA2977Z (OI : CAI - SNM18D02015C02) and SJW6451C (TP : LKK REF - CC6/CTI18007140/Apa3) on 14.04.2018

Your Ref: **SNM18D02015C02**

LKK Ref: CC6/CTI18007140/Apa3s2

Dear Sirs/Mdm,

ACCIDENT INVOLVING PA 2977Z(OI) & SJW 6451C(TP) ON 14/04/2018

We refer to the above matter.

The accident occurred when our insured driver reversed and hit onto third party vehicle. Liability is not in our driver's favour.

We had informed OI about third party claim. OI agreed to settle at best and aware NCD issue.

We seek your approval to offer Third Party repairer "**HUA MENG SPRAY PAINTING WORKSHOP**" as follows: -

| | Amount Claimed | Amount Revised |
|-------------------|----------------|----------------|
| 1. Cost of Repair | \$ 8,155.72 | \$ 2,600.00 |

| | | |
|--------------------------------------|-------------|------------------------------|
| 2. Loss of Rental (3days x \$120.00) | \$ 360.00 | \$ 300.00 (3days x \$100.00) |
| 3. LTA/ GIA Search Fee | \$ 7.49 | \$ 7.49 |
| Total | \$ 8,523.21 | <u>\$ 2,907.49</u> |

**04days recommendation for repair.

Relevant supporting claim documents are attached herewith for your perusal and reference.

The above is for your approval.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Saturday, 14 July 2018 4:51 PM

To: 'Claims Dept of CTI' <claimsdept@sg.cntaiping.com>

Cc: 'Irene Tay' <irene.tay@sg.cntaiping.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving PA2977Z (OI : CAI - SNM18D02015C02) and SJW6451C (TP : LKK REF - CC6/CTI18007140/Apa3) on 14.04.2018

Dear Sirs/Madam,

We refer to the above matter.

Enclosed for your perusal is: -

- Estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lucas Lee [<mailto:lucas.lee@sg.cntaiping.com>]

Sent: Friday, 27 April, 2018 3:58 PM

To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving PA2977Z (OI : CAI - SNM18D02015C02) and SJW6451C (TP : LKK REF - CC6/CTI18007140/Apa3) on 14.04.2018

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Irene Tay

Lucas Lee

Claims Department (Motor)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6181

Fax (65) 6222 7175

Email: lucas.lee@sg.cntaiping.com

Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAUTO) [<mailto:Meikwan@lkkauto.com>]

Sent: Tuesday, 24 April, 2018 1:22 PM

To: Claims Dept of CTI

Cc: Irene Tay; Lucas Lee; Hsiao Tong (LKKAUTO); Joy Irene (LKKAUTO); Asher Sng (LKKAUTO); Admin A; Claims Dept of CTI

Subject: Direct Settlement - Accident Involving PA2977Z (OI : CAI - TBA) and SJW6451C (TP : LKK REF - CC6/CTI18007140/Apa3) on 14.04.2018

WITHOUT PREJUDICE

Dear Sir/ Madam,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SJW 6451C at M/s Hua Meng Spray Painting Workshop - Kaki Bukit.

Enclosed for your perusal is:

- TP GIA report

Please be informed that the estimated cost of repair and preliminary advice is not ready yet.

We will revert to you on preliminary advice in due course.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Hsiao Tong (LKKAuto)

From: Hua Meng <huameng@live.com.sg>
Sent: Friday, 28 September 2018 5:00 PM
To: Hsiao Tong (LKKAuto)
Subject: Re: ACCIDENT INVOLVING SJW 6451 C & PA 2977 Z ON 14.04.2018

Dear HsiaoTong

Please let us have your DV asap.

Thanks & Regards
June

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Sent: Friday, September 28, 2018 4:53:59 PM
To: Hua Meng
Subject: RE: ACCIDENT INVOLVING SJW 6451 C & PA 2977 Z ON 14.04.2018

Without Prejudice

Hi June,

We refer to the above matter.

We propose settlement at a global sum of **\$2,900.00(all-in).**

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hua Meng <huameng@live.com.sg>
Sent: Friday, 28 September 2018 4:40 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: Re: ACCIDENT INVOLVING SJW 6451 C & PA 2977 Z ON 14.04.2018
Importance: High

Dear HsiaoTong

We refer the LOD we sent dated 01.08.2018.

We have no receive any reverts .Thus ,sorry to inform you we have to pass the matter to lawyer.

Thanks & Regards

June

From: Hua Meng <huameng@live.com.sg>

Sent: Wednesday, August 1, 2018 4:28:35 PM

To: Hsiao Tong

Subject: ACCIDENT INVOLVING SJW 6451 C & PA 2977 Z ON 14.04.2018

Dear HsiaoTong

We refer above mentioned accident.

We would like to inform that we have finalized with your surveyor.

Kindly revert your offer.

Your prompt reply will be appreciated by us.

We enclose relevant documents for your attention.

Thanks & regards,

June

Hua Meng Spray Painting Workshop

1 Kaki Bukit Ave 6, Blk C

#01-61 Autobay @ Kaki Bukit

S 417883

Tel: 6746 5519

Fax: 6743 4896



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|--|------------------------------|------------|---|
| CHINA TAIPING INSURANCE (S) PTE LTD | | Ref : CC6/CTI18007140/Apa3s2 | | |
| 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909 | | Date : 05-10-2018 | |  |
| | | Code : CTI | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | PA 2977Z | Veh. Inspected | SJW 6451C | |
| Policy No. | DMBISN1650821701 | Coverage (\$) | 0.00 | |
| Claim No. | SNM18D02015C02 | Excess (\$) | 0.00 | |
| Assign From | | Assign Date | 16/04/2018 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | HONDA FIT | c.c | 1339 | |
| Engine No. | HIDDEN | Year of Reg. | 2008 | |
| Chassis No. | GE61052338 | Colour | WHITE | |
| Odometer | 145494 | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 195/55R15 | BRIDGESTONE | 6 mm | |
| L/H Front Tyre | 195/55R15 | BRIDGESTONE | 6 mm | |
| R/H Rear Tyre | 195/55R15 | BRIDGESTONE | 6 mm | |
| L/H Rear Tyre | 195/55R15 | BRIDGESTONE | 6 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 14/04/2018 | Inspection Date | 16/04/2018 | |
| Survey held at | HUA MENG SPRAY PAINTING WKSP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883 | | | |
| 5a. Remarks | | | | |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 4 Working Days | | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJW 6451C

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|----------------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 2 | BONNET HINGES @ \$33.60 | NOT NECESSARY | 67.20 | - |
| 1 | BONNET LOCK | NOT NECESSARY | 95.10 | - |
| 1 | BONNET LOCK BRACKET | NOT NECESSARY | 55.20 | - |
| 1 | BONNET H STICKER | NECESSARY | 35.00 | 35.00 |
| 1 | FRONT GRILLE | NOT NECESSARY | 75.00 | - |
| 1 | FRONT GRILLE HONDA EMBLEM | NOT NECESSARY | 22.90 | - |
| 1 | FRONT BUMPER | DEFORMED | 503.20 | 503.20 |
| 2 | FRONT BUMPER SIDE HOLDER @ \$30.00 | NECESSARY | 60.00 | 60.00 |
| 1 | FRONT BUMPER REINFORCEMENT | BENT | 213.50 | 213.50 |
| 1 | FRONT BUMPER LOWER LIP | NOT NECESSARY | 68.50 | - |
| 2 | FRONT HEAD LAMP @ \$552.10 | N/S CRACKED | 1,104.20 | 552.10 |
| 2 | FRONT BUMPER FOG LAMP @ \$277.90 | NOT NECESSARY | 555.80 | - |
| 2 | FRONT HEAD LAMP LOWER BRACKET | N/S CRACKED | 55.00 | 27.50 |
| 1 | FRONT SUPPORT PANEL | TO REPAIR SEE LABOUR | 385.90 | - |
| 1 | AIR CON CONDENSER | NOT NECESSARY | 704.40 | - |
| | LESS 20% DISCOUNT | | -800.18 | -278.26 |
| | | | 3,200.72 | 1,113.04 |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | BONNET (SN) | CRACKED | 1,100.00 | 900.00 |
| 1 | FRONT GRILLE RIM (SN) | CRACKED | 850.00 | 500.00 |
| 1 | FRONT LH HEAD LAMP RIM (SN) | NECESSARY | 155.00 | 65.00 |
| | | | 2,105.00 | 1,465.00 |
| <u>LABOUR</u> | | | | |
| | REMOVE & REINSTALL AIR CON FILL IN GAS. | NOT NECESSARY | 150.00 | - |
| | REMOVE, REPLACE & REPAIR CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL. | | 1,500.00 | 450.00 |
| | RESPRAY PAINTING. | | 1,100.00 | 250.00 |
| | TUFF KOTE. | NOT NECESSARY | 100.00 | - |
| | | | 2,850.00 | 700.00 |

Report Ref No. CC6/CTI18007140/Apa3s2



| | | | |
|---|--|----------|----------|
| GRAND TOTAL | | 8,155.72 | 3,278.04 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | 2,600.00 |

Report Ref No. CC6/CTI18007140/Apa3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.