



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLN 4133 H

*Not Authorized
1.B.1
Resurvey Beppit*

Parts	(a) Cost / List Price Items	\$	11,390.38
	Plus/Less 25%	\$	2,847.60
	Total of Cost / List	\$	8,542.79
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	200.00
Total Parts Cost		\$	8,742.79
Labour		\$	5,120.00
Total		\$	13,862.79

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 17/4/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 08 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : Le

Date: 17/4/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLN 4133 H**
Make & Model : **TOYOTA PRIUS**
Chassis No. : **JTDKB3FU803556649**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	1	\$200.00	S.N	?
2	Rear bumper <i>CRA</i>	1	\$497.50		✓
3	Rear bumper clip <i>na</i>	10	\$40.00		✓
4	Rear bumper side retainer LH <i>di'l</i>	1	\$112.70		✓
5	Rear bumper side retainer RH <i>sn</i>	1	\$112.70		X
6	Rear bumper reinforcement <i>RC</i>	1	\$398.90		X
7	Rear bumper lower garnish centre <i>di'l</i>	1	\$582.60		✓
8	Rear bumper lower garnish LH <i>CRA</i>	1	\$149.70		✓
9	Rear bumper under cover <i>CRA</i>	1	\$355.20		✓
10	Rear bumper under cover LH <i>CRA</i>	1	\$187.60		✓
11	Rear bumper under cover clip <i>na</i>	4	\$14.00		✓
12	Tail lamp LH - UPPER	1	\$498.75		?
13	Tail lamp LH - LOWER	1	\$511.60		?
14	Tail end panel <i>RH</i>	1	\$596.60		✓
15	Tail end panel garnish <i>sn</i>	1	\$151.60		X
16	Tail end panel garnish clip <i>na</i>	10	\$35.00		X
17	Boot weatherstrip <i>sn</i>	1	\$353.10		X
18	LH rear fender <i>RH</i>	1	\$883.60		✓
19	LH rear fender undershield <i>CRA</i>	1	\$92.30		✓
20	LH rear fender undershield clip <i>na</i>	10	\$30.00		✓
21	LH rear fender air duct <i>del</i>	1	\$115.60		✓
22	LH rear inner trim <i>Re form</i>	1	\$387.63		✓
23	LH rear lower arm	1	\$398.65		?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLN 4133 H**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU803556649**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	LH rear knuckle arm <i>RM</i>	1	\$895.60		✓
25	LH rear knuckle bearing <i>RM</i>	1	\$421.90		✓
26	LH rear wheel hub <i>RM</i>	1			
27	LH rear wheel hub lock nut	1	\$17.30		✓
28	LH rear shock absorber	1	\$359.40		✓
29	LH rear shock absorber top mouting	1	\$165.70		✓
30	LH rear shock absorber stopper	1	\$85.70		✓
31	LH rear rim <i>RM</i>	1	\$1,555.10		✓
32	LH rear tyre	1	\$350.00		✓
33	LH rear hub cab <i>RM</i>	1	\$195.95		✓
34	LH side skirt	1	\$798.40		✓
35	LH side skirt clip	10	\$40.00		✓
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLN 4133 H** Submit By : **Carmen Lim**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER,END PANEL,LHR FENDER, LHR DOOR,LH SIDE SKIRT,TAILOOR,SPARE TYRE WELL PANEL)	\$2,000.00	12000
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER,END PANEL,LHR FENDER, LHR DOOR,LH SIDE SKIRT,TAILOOR,SPARE TYRE WELL PANEL)	\$1,800.00	10000
3	To check wiring	\$50.00	200
4	To remove & refit reverse sensor to assit work load	\$120.00	500
5	To tuff coat	\$250.00	600
6	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	1200
7	To remove & refit undercarriage to assist work load.	\$250.00	?
8	To do wheel alignment.	\$120.00	600
9	To remove & refit Door trim, door glass, window regulator, door lock to assist work load. ~ ~	\$120.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Labour

Vehicle No. : **SLN 4133 H** Submit By : **Carmen Lim**
Make & Model : TOYOTA PRIUS Year of Manufacture : 2017

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.