



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLN 4133 H

Parts	(a) Cost / List Price Items	\$	11,390.38
	Plus/Less 25%	\$	2,847.60
	Total of Cost / List	\$	8,542.79
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	200.00
Total Parts Cost		\$	8,742.79
Labour		\$	5,120.00
Total		\$	13,862.79

The above total will be subjected to 7% G.S.T.

Finalised

9594.16

7398.54

7195.62

5780

9975.62

8975.58

Not Authorized
1.B1
Resurvey B4 print

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items, if any, to be resurveyed and is subject to final approval from Insurer's Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor

Company

Survey conducted on

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 08 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$

(e) Signature of surveyor

Date: 17/4/18



**ESTEEM
PERFORMANCE**

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65 6484 1221 Fax: +65 6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. :
Make & Model :
Chassis No. :

SLN 4133 H

TOYOTA PRIUS

JTDKB3FU803556649

Submit By :
Year Manufacture :
Engine No. :
Cost / List :

Carmen Lim
2017

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	1	\$200.00	S.N	X
2	Rear bumper	1	\$497.50	✓	✓
3	Rear bumper clip	10	\$40.00	✓	✓
4	Rear bumper side retainer LH	1	\$112.70	✓	✓
5	Rear bumper side retainer RH	1	\$112.70		X
6	Rear bumper reinforcement	1	\$398.90		X
7	Rear bumper lower garnish centre	1	\$582.60	✓	✓
8	Rear bumper lower garnish LH	1	\$149.70	✓	✓
9	Rear bumper under cover	1	\$355.20	✓	✓
10	Rear bumper under cover LH	1	\$187.60	✓	✓
11	Rear bumper under cover clip	4	\$14.00	✓	✓
12	Tail lamp LH - UPPER	1	\$498.75		X
13	Tail lamp LH - LOWER	1	\$511.60		X
14	Tail end panel	1	\$596.60	✓	✓
15	Tail end panel garnish	1	\$151.60		X
16	Tail end panel garnish clip	10	\$35.00		X
17	Boot weatherstrip	1	\$353.10		X
18	LH rear fender	1	\$883.60	✓	✓
19	LH rear fender undershield	1	\$92.30	✓	✓
20	LH rear fender undershield clip	10	\$30.00	✓	✓
21	LH rear fender air duct	1	\$115.60	✓	✓
22	LH rear inner trim	1	\$387.63	✓	✓
23	LH rear lower arm	1	\$398.65	✓	✓

Note, if any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

4443-74
4443-68

Spare Parts

Vehicle No. :
Make & Model :
Chassis No. :

SLN 4133 H

TOYOTA PRIUS

JTDKB3FU803556649

Submit By :
Year Manufacture :
Engine No. :
Cost / List

Carmen Lim

2017

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	LH rear knuckle arm <i>RT</i>	1	\$895.60 ✓		✓
25	LH rear knuckle bearing <i>LM</i>	1	\$421.90 ✓		✓
26	LH rear wheel hub	1			
27	LH rear wheel hub lock nut <i>LM</i>	1	\$17.30		X
28	LH rear shock absorber <i>RT</i>	1	\$359.40 ✓		✓
29	LH rear shock absorber top mounting <i>LM</i>	1	\$165.70		X
30	LH rear shock absorber stopper <i>LM</i>	1	\$85.70		X
31	LH rear rim <i>RM</i>	1	\$1,555.10 ✓		✓
32	LH rear tyre <i>LM</i>	1	\$350.00		X
33	LH rear hub cap <i>CM</i>	1	\$195.95 ✓		✓
34	LH side skirt <i>LM</i>	1	\$798.40		X
35	LH side skirt clip <i>LM</i>	10	\$40.00		X
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

2427.95

ESTEEM PERFORMANCE PTE LTD

BLK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-259 SINGAPORE 569536

Tel:64841221 Fax:64847829

Spare Parts

Vehicle No. :

SLN 4133 H

Make & Model :

TOYOTA PRIUS

Chassis No. :

JTDKB3FU803556649

Submit By :

CARMEN LIM

Year Manufacture :

2017

Engine No. :

Cost / List**Supplementary**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH rear door <i>Bu</i>	1	\$1,221.40 ✓		
2	LH rear door hinge top <i>R</i>	1	\$78.34	X	
3	LH rear door hinge bottom <i>Rif</i>	1	\$78.34 ✓		
4	LH rear door lock <i>R</i>	1	\$437.80	X	
5	LH rear door checker <i>Ln</i>	1	\$155.60	X	
6	LH rear door weatherstrip <i>Ln</i>	1	\$187.30	X	
7	LHR door glass outer moulding lower <i>Ln</i>	1	\$133.70	X	
8	LHR door glass outer moulding upper <i>Ln</i>	1	\$127.83 ✓		
9	LHR power window motor <i>Ln</i>	1	\$578.40	X	
10	LHR power window regulator <i>Ln</i>	1	\$198.73	X	
11	LH rear door quarter glass <i>Ln</i>	1	\$122.75	X	
12	LH rear door quarter glass moulding <i>Ln</i>	1	\$75.80	X	
13	LH Taillamp panel <i>R</i>	1	\$123.15	X	
14	LH Taillamp clip assy <i>Ln</i>	4	\$10.00 ✓		
15	LH rear fender mudflat <i>Ln</i>	1	\$95.30 ✓		
16	Floor panel LH <i>Bu</i>	1	\$189.60 ✓		
17		1			
18		1			
19		1			
20		4			
21		1			
22		1			
23		1			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

1722-47 ✓



**ESTEEM
PERFORMANCE**

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/255, 569536,
Tel: +65-6484 1221 Fax: +65 6484 7529 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLN 4133 H**
Make & Model : **TOYOTA PRIUS**

Submit By : **Carmen Lim**
Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, LHR FENDER, LHR DOOR, LH SIDE SKIRT, TAILDOOR, SPARE TYRE WELL PANEL)	\$2,000.00	1200
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, LHR FENDER, LHR DOOR, LH SIDE SKIRT, TAILDOOR, SPARE TYRE WELL PANEL)	\$1,800.00	1000
3	To check wiring	\$50.00	20
4	To remove & refit reverse sensor to assist work load	\$120.00	50
5	To tuff coat	\$250.00	60
6	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	120
7	To remove & refit undercarriage to assist work load.	\$250.00	?
8	To do wheel alignment.	\$120.00	50
9	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.	\$120.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

7780 ✓

Labour

Vehicle No. : SLN 4133 H
Make & Model : TOYOTA PRIUS

Submit By : Carmen Lim
Year of Manufacture : 2017

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.