


MBM WHEELPOWER PTE LTD



Your Ref: SJK6861R

Our Ref: SKB6582G

To: AXA

CC

Email

Fax

*Not Authorized
11 Lm 8?
Resurvey After Paint
10 days*

Date: 16/4/2018

From: Joseph

Fax: 62509015

Contact: 86865188

Make / Model: BMW 520i

Chassis No.: WBANT12030CX30478

Engine No.: B350I526N46B20BE

Year of Make: 2009

Accident Date: 11/4/2018

ESTIMATE FOR VEHICLE NO. : SKB6582G

DESCRIPTION	QTY	List Price
REAR RH DOOR	1	\$ <i>B</i> 1,800.00 ✓
RER RH DOOR LOCK	1	\$ <i>Ja</i> 755.00 ✓
REAR RH DOOR STRIKER	1	\$ 125.00 ?
REAR RH DOOR WEATHERSTRIP	1	\$ <i>na</i> 180.00 <i>50/50</i>
REAR RH DOOR HANDLE OUTER	1	\$ <i>CM</i> 485.00 ✓
REAR RH DOOR INNER TRIM	1	\$ <i>Bu</i> 2,750.00 —
REAR RH DOOR POWER WINDOW MOTOR	1	\$ 345.00 ?
REAR RH DOOR REGULATOR	1	\$ 315.00 ?
RER RH DOOR HINGE UPPER	1	\$ <i>R</i> 65.00 X
REAR RH DOOR HINGE LOWER	1	\$ <i>K</i> 65.00 X
REAR RH DOOR CHECKER	1	\$ <i>Sn</i> 90.00 X
REAR RH WINDOW LOWER MOULDING CHROME	1	\$ <i>na</i> 235.00 ✓
REAR RH WINDOW UPPER MOULDING CHROME	1	\$ <i>SeR</i> 175.00 ✓
REAR RH WINDOW GLASS	1	\$ <i>Shotton</i> 605.00 ✓
REAR RH WINDOW TRIM	1	\$ 175.00 ?
REAR RH WINDOW SEAL	1	\$ <i>na</i> 100.00 ✓
REAR RH QUARTER GLASS	1	\$ 295.00 ?
REAR RH QUARTER GLASS MOULDING	1	\$ <i>SeR</i> 50.00 ✓
REAR WINDSCREEN	1	\$ <i>Sn</i> 1,980.00 X
REAR WINDSCREEN MOULDING	1	\$ <i>na</i> 330.00 —
REAR RH FENDER	1	\$ <i>B</i> 1,840.00 ✓
REAR RH FENDER INNERSHIELD	1	\$ <i>Sn</i> 165.00 X
REAR RH WHEEL HOUSE	1	\$ 680.00 ?

FUEL TANK	1	\$	<i>PL</i> 1,850.00	X
FUEL TANK CAP	1	\$	<i>211</i> 45.00	✓
FUEL TANK TUBE	1	\$	210.00	?
FUEL TANK COVER	1	\$	<i>211</i> 50.00	✓
TAIL LAMP RH	1	\$	<i>530</i> 530.00	✓
BOOTLID	1	\$	<i>N</i> 1,695.00	X
BOOTLID LOGO	1	\$	<i>M</i> 180.00	✓
REAR "520I" EMBLEM	1	\$	<i>M</i> 125.00	✓
RIM	2	\$	<i>PL</i> 1,125.00	X
REAR CROSSMEMBER	1	\$	2,240.00	?
REAR RH SHOCK ABSORBER	1	\$	545.00	?
REAR RH KNUCKLE ARM	1	\$	1,365.00	?
REAR RH WHEEL HUB	1	\$	185.00	?
REAR RH WHEEL BEARING	1	\$	195.00	?
REAR RH UPPER ARM	1	\$	515.00	?
REAR RH LOWER ARM	1	\$	1,015.00	?
REAR STABILIZER BAR	1	\$	<i>SL</i> 405.00	X
REAR RH STABILIZER BAR LINK	1	\$	<i>SL</i> 100.00	X
REAR RH TIE ROD END	1	\$	180.00	?
REAR RH DRIVE SHAFT	1	\$	<i>N</i> 1,420.00	X
REAR LH SHOCK ABSORBER	1	\$	545.00	?
REAR LH KNUCKLE ARM	1	\$	1,365.00	?
REAR LH WHEEL HUB	1	\$	185.00	?
REAR LH WHEEL BEARING	1	\$	195.00	?
REAR LH UPPER ARM	1	\$	515.00	?
REAR LH LOWER ARM	1	\$	1,015.00	?
REAR LH STABILIZER BAR LINK	1	\$	100.00	?
REAR LH TIE ROD END	1	\$	180.00	?
REAR LH DRIVE SHAFT	1	\$	<i>N</i> 1,420.00	X

TOTAL:	\$	33,100.00
LESS 10%:	\$	(3,310.00)
PARTS TOTAL:	\$	29,790.00

SPECIAL NETT

TYRE

1

\$

Pn

480.00

50km

ANTIRUST COATING

\$

120.00

*60l***LABOUR**

TOWING (KING DOLLY)

\$

(Bill)

150.00

?

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. TO HEAT, WELD & CUT-OUT THE REAR RH FENDER, REAR RH WHEEL HOUSE. INCLUDING TO STRAIGHTEN, KNOCK-OUT OF THE REAR BUMPER, RH ROCKER PANEL GARNISH, ETC

\$

1,200.00

900l

TO REMOVE & REPLACE WINDOW QUARTER GLASS

\$

100.00

60l

TO REMOVE & REPLACE REAR WINDSCREEN

\$

160.00

120l

TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS

\$

160.00

120l

TO REMOVE AND REPLACE FUEL TANK FIXTURE AND TO UPHOLSTERY TO FACILITATE REPAIRS

\$

150.00

60l

TO REMOVE & REFIT INNER LININGS & GARNISHES TO FACILITATE REPAIR

\$

120.00

x

TO REMOVE, RENEW & REFIT OF THE REAR RH UNDERCARRIAGE

\$

350.00

?

TO REMOVE, RENEW & REFIT OF THE REAR LH UNDERCARRIAGE

\$

350.00

?

TO CONDUCT CHASSIS ALIGNMENT ON CAR-O-LINER

\$

380.00

?

TO CHECK ALL WIRING AND RESET TO THE SAME

\$

120.00

30l

TO SPRAY PAINT ON THE AFFECTED AREA

\$

1,000.00

750l

Total: \$ 34,630.00

7% GST: \$ 2,424.10

Grand Total: \$ 37,054.10**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: