

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

18 APR 2018

Estimate No.	: b1 46633	Page No. : 1 of 2
Date Estimated	: 17/04/2018	
Prepared By	: Inthiran A/L Thurasamy	

- ESTIMATE REPAIR FOR - Leow Huan Nam 19 Mimosa Place Singapore 805544	- ACCOUNT - 121 AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Chartis Building Singapore 079120
--	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS3840E	G581088	18/08/2017	520D	0

DESCRIPTION	VALUE
To replace front bumper, fender right and attachments.	1700 2,550.00
Panting front bumper and fender right.	1730 1,923.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 177.00
To replace left or right headlight including program and conduct tests for proper function.	401? 531.00
To replace tyre and wheel rim including balancing. (1x).	74? 94.00
To check steering geometry and conduct wheel alignment according to BMW specification (1X)	451 531.00
To carry out body cavity preservation. (Per panel).	100? 118.00
Sundries.	? 150.00
Total Labour 1:	6,074.00

DESCRIPTION	QTY	PRIC	VALUE
LIGHT ALLOY RIM 8JX18 W SPK 632 - polish	1	961.75	Rx 961.75
HUB CAP WITH CHROME EDGE	1	35.75	? 35.75
FRT RH SIDE PANEL ALUMINIUM	1	906.50	Rx 906.50
FRT RH SIDE PANEL BRACKET 2	1	53.55	? 53.55
RH PROTECTIVE STRIP LINES (LUXURY)	1	64.60	? 64.60
RH FOG LAMP SUPPORT	1	78.75	? 78.75
GUIDE TOP RH	1	34.55	? 34.55
FRT BUMPER PANEL PRIMED (PMA/PDC)	1	1,290.35	del 1,290.35
SET MOUNTING PDC/PMA SENSOR FRT	1	62.95	? 62.95
RH HEADLIGHT LED AHL HIGH (ICON LIG	1	4,703.95	? 4,703.95
DECOUPING RING PDC TORQUE CONVERTER	2	5.05	re 10.10
PDC SENSOR SOPHISTOGRAU II WA90	1	368.80	wh 368.80

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 46633
Date Estimated : 17/04/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS3840E	G581088	18/08/2017	520D	0

Total Parts : 8,571.60

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 10/5/18 @ 1245 Claim No. _____

Date & Time 10/5/18 @ 1245 Excess S\$ _____

Surveyor's Name Tan Jiah Sign [Signature]

Surveyor's Tel 97495744 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail tanjiah@hkauto.com

No. of Working Days Recommend 5-6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Labour 1	:	6,074.00
Parts	:	8,571.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,025.19
Grand Total	:	15,670.79

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **