

22/03/2018

ASS. REC. BY:

REF:

CS/MS(18007162/Kqbl) Special Instruction:

SUPERVISOR

Kenneth

ASSIGNMENT (Office)

From (Person):

Vimmala

of

MS17

Date/Time:

18/04/2018 10:42am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLB 16C

Insured:

at Workshop n/s

Hui Yang Motor

Tel:

64515152

of

Blk 176 Sin Ming Ave #04-02

Policy No:

A98795104MCK

Claim No:

555719

Sum Insured:

Excess:

\$ 700.00

Make of Veh:

D.O.A. 17/04/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

18/04/2018 11:16am

Person Contacted:

Bel

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SLB 16C - x

17/4/18 @ 10:30am report to Vimmala via Messenger.

17/4/18 @ 11am Hui Yang informed C/A via Messenger.

17/4/18 @ 2:00pm informed Hui Yang C/A is EX: \$700 by email.

716 811328-90 Confirmed by email (Paid \$ 4967.60, 30%)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the Insurers of the CIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 08/06/2017 13:24
Date Of Accident 07/06/2017 20:55
Exact Location Of Accident AYE (CITY) AFTER JURONG TOWN HALL ENTRY
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHC1445H

Insured/Policyholder

Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD

Co Reg No 199303821R

Email Address FLEETSAFETY@CDGTAXI.COM.SG

Mobile Phone No OFFICE-65508768

Alternative Phone No

Vehicle Particulars

ASS. REC. BY:

REF: MSG/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Hui Yang

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: 700

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 158k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 07 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLB16C Yr Regn: 01 ^{1/2} 86

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Wagon
Make: Toy Vellpac c.c. 2493

Colour: M.P. White A/C: Insured / Std / NI / NA

Sp. Reading: 115265 T/Radio: Insured / Std / NI / NA

Eng/No: _____
C/No: AGH30 0017690

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STP A/Rim or

Tyre Size: F: 225/55R18
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or DAVARI

Front R/Bal. 2 mm

L/Bal. 2 mm

D.O.A. 17/4/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
19/6 File pass to Catherine
No lump sum.

RECEIVED 1-2 JUN 2018

[Signature]
8/6/2018

Date/Time, File Pass to?

11/12/16 *[Signature]*

: Prell. Report

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trlp: _____

Add Fee: : Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

Survey Fee:

Transportation:

5 - RS. \$

Photos

Others

TOTAL

200
0
200

Report Format: WEL-00

Lump Sum / I.B.I: (\$ 11378.90)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18007162/Kqb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 18-04-2018	
		Code : MSG	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SLB 16C
Policy No.	A28795104MCX	Coverage (\$)	0.00
Claim No.	555719	Excess (\$)	700.00
Assign From	MERIMEN (VIMMALA)	Assign Date	18/04/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	17/04/2018	Inspection Date	18/04/2018
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Apr 2018 Sendback Est	17 Apr 2018 12:32 S\$15,822.35	18 Apr 2018 10:42 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	SKYWAY MOTOR PTE LTD, Co. Reg. No.: 199904194N								
Vehicle Reg. No.:	SLB16C	Date of Loss:	17/04/2018 07:00 - :59 [27 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 555719	Policy/Cover Note No.:	A28795104MCX (Comprehensive) Coverage: 08/08/2017 - 07/08/2018						
		Excess:	S\$700.00						
Repairer:	Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmala D/O Raja Singam - 65942471]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 19/04/2018]								
Driver/Custodian:	MOHAMAD SALLEH BIN SABTU (39 / Male), NRIC: S7812835F								
Adj Asg. Remarks:	Car in, please survey before 12pm and revert. Premium is outstanding. Checking with the Agencies unit.								
ASSOCIATED MAIL RECEIVED									
			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All	Search Tasks	Create New Task	Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vimimala D/O Raja Singam

Date: 07 Jun 2018

Preliminary Advice

Vehicle No	: SLB16C	Accident Date	: 17/04/2018
Make	: TOYOTA VELLFIRE	Policy No.	: A28795104MCX
Assignment Date	: 18/04/2018	Excess	: S\$700.00
Date of Inspection	: 18/04/2018	Est. Duration of Repair	: 7.00
Inspection At	: HUI YANG MOTOR PTE LTD (HQ) 176 SIN MING DRIVE #04-02, SIN MING AUTOCARE SINGAPORE 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,291.50	
Revised Amount	:S\$	11,328.90	(INCLUSIVE OF CHECK ITEMS)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	11,328.90	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	158,000.00
COE / PARF Rebate	:S\$	79,787.00
Salvage Value	:S\$	
Margin for Repair	:S\$	78,213.00

Remarks

- (X) The vehicle is economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis. KINDLY APPROVE ON CHECK ITEMS.

No	Reinspection Photo	1	Load JPG	Thumbnail	Print
70	21/11/12 17:23	1	Load JPG	Thumbnail	Print
71	21/11/12 17:23	1	Load JPG	Thumbnail	Print
72	21/11/12 17:27	1	Load JPG	Thumbnail	Print
73	21/11/12 17:27	1	Load JPG	Thumbnail	Print
74	21/11/12 17:27	1	Load JPG	Thumbnail	Print
75	21/11/12 17:27	1	Load JPG	Thumbnail	Print
76	21/11/12 17:27	3	Load JPG	Thumbnail	Print
77	21/11/12 17:27	3	Load JPG	Thumbnail	Print
78	21/11/12 17:27	3	Load JPG	Thumbnail	Print
79	21/11/12 17:27	3	Load JPG	Thumbnail	Print
80	21/11/12 17:27	3	Load JPG	Thumbnail	Print
81	21/11/12 17:27	1	Load JPG	Thumbnail	Print
82	21/11/12 17:27	1	Load JPG	Thumbnail	Print
83	21/11/12 17:27	1	Load JPG	Thumbnail	Print
84	21/11/12 17:27	1	Load JPG	Thumbnail	Print
85	21/11/12 17:27	1	Load JPG	Thumbnail	Print
86	21/11/12 17:27	1	Load JPG	Thumbnail	Print
87	21/11/12 17:41	1	Load JPG	Thumbnail	Print
88	21/11/12 17:41	1	Load JPG	Thumbnail	Print
89	21/11/12 17:41	1	Load JPG	Thumbnail	Print
90	21/11/12 17:41	1	Load JPG	Thumbnail	Print
91	21/11/12 17:41	1	Load JPG	Thumbnail	Print
92	21/11/12 17:41	1	Load JPG	Thumbnail	Print
93	21/11/12 17:41	1	Load JPG	Thumbnail	Print
94	21/11/12 17:41	1	Load JPG	Thumbnail	Print
95	21/11/12 17:41	1	Load JPG	Thumbnail	Print
96	21/11/12 17:41	1	Load JPG	Thumbnail	Print
Documentation					
1 per page ▲					
No	Reinspection Photo	1	Load PDF	Thumbnail	Print
1	21/11/12 19:50	1	Load PDF	Thumbnail	Print
2	21/11/12 19:50	1	Load PDF	Thumbnail	Print
3	11/01/13 11:08	1	Load PDF	Thumbnail	Print
4	11/01/13 11:08	1	Load PDF	Thumbnail	Print
5	11/01/13 11:08	1	Load PDF	Thumbnail	Print
6	11/01/13 11:08	1	Load PDF	Thumbnail	Print
7	11/01/13 11:08	1	Load PDF	Thumbnail	Print
No	Finalized On				
1	19/11/12 09:04				

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured. Click 'Reset' to repopulate document checklist.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 19 April 2018 2:01 PM
To: hui_yang_motor@hotmail.com
Cc: SUR
Subject: VEHICLE SLB 16C (DOA: 17/04/2018)

Dear Sir/Madam,

As instructed by our client, please proceed to repair the insured vehicle **SLB 16C (excess \$700/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

UNKNOWN

Vehicle Make/Model/Colour

Details Of Properties

VEHICLE D

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name


Phone Number

Email Address

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	17 Apr 2018 11:46	Clim Veh Model Changed	(205032) TOYOTA VELLFIRE 2.5 Z G-EDITION CVT (A).	[R] Neo Wee Eek
2	17 Apr 2018 11:46	Clim Created	Reg No: SLB16C. Policy No: A28795104MCX. Acct Date: 2018/04/17. Claim Type: O D. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Hui Yang Motor Pte Ltd (HQ)	[R] Neo Wee Eek
3	17 Apr 2018 12:32	Clim Submitted	15822.35.	[R] Neo Wee Eek
4	17 Apr 2018 15:59	Clim Registration Modified	Init.Est.:->15,000 - 17,500.	[I] Vimmala D/O Raja Singam
5	17 Apr 2018 16:06	Clim Registration Modified	Excess: -> 700.00.	[I] Vimmala D/O Raja Singam
6	17 Apr 2018 16:10	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):Please survey and revert. Premium is outstanding. Checking with the Agencies unit.	[I] Vimmala D/O Raja Singam
7	17 Apr 2018 16:10	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/04/18	[I] Vimmala D/O Raja Singam
8	17 Apr 2018 16:10	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Vimmala D/O Raja Singam
9	18 Apr 2018 09:01	Assignment 1st Accessed		[A] Daniel Chong Boon Hee
10	18 Apr 2018 10:40	Adj Assignment Cancelled	Car in and Workshop not able to wait till tomorrow as Customer is chasing, IHS unable to attend (Morning - Appt full, Afternoon - Claims Sharing, DC-No survey till further instruction). As per Mala's instruction, to outsource.	[I] Pauline Soh Li Ping
11	18 Apr 2018 10:40	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Pauline Soh Li Ping
12	18 Apr 2018 10:42	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Car in, please survey before 12pm and revert. Premium is outstanding. Checking with the Agencies unit.	[I] Pauline Soh Li Ping
13	18 Apr 2018 10:42	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/04/19	[I] Pauline Soh Li Ping
14	18 Apr 2018 10:42	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Pauline Soh Li Ping
15	18 Apr 2018 11:09	Assignment 1st Accessed		[A] CATHERINE CHONG KAI LING
16	18 Apr 2018 13:40	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] CATHERINE CHONG KAI LING
17	19 Apr 2018 10:12	Adj Rpt Initiated		[A] SHIAU CHAN
18	19 Apr 2018 10:20	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/05/18	[A] SHIAU CHAN
19	19 Apr 2018 10:20	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/05/18	[A] SHIAU CHAN
20	19 Apr 2018 10:22	Adj Mandate Request	Cur.Req:15058.85:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
21	19 Apr 2018 11:11	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/05/18. Mandate Remarks: Check items \$5920.60 to be verified	[I] Eng Huey Ni
22	19 Apr 2018 11:11	Adj Mandate Set	Approved:9138.25;Check items \$5920.60 to be verified	[I] Eng Huey Ni

Date From



Date To



Audit Type None

Go

ACTIVITY

[18/04/2018 10:36] Pauline Soh Li Ping:
Car in and Workshop not able to wait till tomorrow as Customer is chasing, IHS unable to attend (Morning - Appt full, Afternoon - Claims Sharing, DC-No survey till further instruction). As per Mala's instruction, to outsource.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1778674	17/04/2018 11:46	Motor	Hui Yang Motor Pte Ltd(HQ)	Hui Yang Motor Pte Ltd (HQ)	SLB16C		xx.xx
1781290	19/04/2018 10:12	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLB16C		10.70

Vehicle Registration Number of Driver's Own Vehicle (if applicable)
Insurance Company of Driver's Own Vehicle (if applicable)

General Information of the Accident

Type Of Accident Collision- Head to Rear (TP Hit Insured)
Weather Conditions Clear
Road Surface Dry

Other Information

Was any body injured in the Accident? No
Was any other material or property damaged? Yes

Details of Police Action

Was the accident reported to the police? Yes
If Yes, Please state which Police Station
Police Station Name Marina Bay N.p.c
Police Station Address ROAD: 1 PRINCE EDWARD LINK , POSTCODE: 078872 , COUNTRY: Singapore
Police Station Contact TEL NO: - FAX NO:
Was notice of intended Prosecution given? No
If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT: T/20111209/9020.
Are accident photos available for attachment? Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number UNKNOWN
Vehicle Make/Model/Colour
Details Of Properties VEHICLE B
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number UNKNOWN
Vehicle Make/Model/Colour
Details Of Properties VEHICLE C
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vimimala D/O Raja Singam

Date: 19 Apr 2018

Preliminary Advice

Vehicle No	: SLB16C	Accident Date	: 17/04/2018
Make	: TOYOTA VELLFIRE	Policy No.	: A28795104MCX
Assignment Date	: 18/04/2018	Excess	: S\$700.00
Date of Inspection	: 18/04/2018	Est. Duration of Repair	: 7.00
Inspection At	: HUI YANG MOTOR PTE LTD (HQ) 176 SIN MING DRIVE #04-02, SIN MING AUTOCARE SINGAPORE 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,822.35
Revised Amount	:S\$	9,138.25
Check Items (Estimated)	:S\$	5,920.60
Total	:S\$	15,058.85

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	158,000.00
COE / PARF Rebate	:S\$	79,787.00
Salvage Value	:S\$	
Margin for Repair	:S\$	78,213.00

Remarks

(X) The vehicle is economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis. WE HAVE NOT AUTHORISE REPAIR.

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVENUE 6, #01-46/48/50
AUTOBAY, SINGAPORE 417883
TEL: 67465405/67467158 FAX: 67458520

Our Ref: 1212-15713

Date: 28 December 2012

Axa Insurance Singapore Pte Ltd
8 Shenton Way
#2-01 Axa Tower
Singapore 068811
Attn: Motor Claims Department

Dear Sir/Mdm,

**ACCIDENT ON 29/12/2011 INVOLVING VEHICLES SGC3653Y & SDV4235A
AT BLOCK 3017, BEDOK NORTH AVENUE 4 CARPARK**

With regards to the above, we are writing on behalf of the registered owner of vehicle SGC3653Y which was involved in the above-mentioned accident.

We are informed that the above accident was caused solely by the negligence of your insured vehicle SDV4235A. As a result of the accident, our client's vehicle was damaged and our client had instructed us to submit his claims for loss and expenses, particulars of which are as follows:

1) Cost of Repairs (inclusive of GST)	\$1,391.00
2) Loss of Use (3 days x @\$50.00)	\$150.00
3) GIA search fee	\$2.00

We hereby enclosed herewith the following documents for your consideration of the above claim.

- a) Original Invoice
- b) Certificate of Insurance
- c) SAS report
- d) Owner/Driver NRIC & Driving Licence
- e) Letter of Authorisation
- f) Vehicle Registration Log Card
- g) GIA search tax invoice/receipt

Kindly acknowledge receipt of the above documents and your favourable reply is much appreciated.

Yours faithfully,
FASTECH AUTO PTE LTD


email: claim@fastechnausg.com
Jennifer (Tel: 67465376/67467158)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4194N
Vehicle Details	
Vehicle No.:	SLB16C
Vehicle to be Exported:	No
Intended De-registration Date:	19 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VELLFIRE 2.5Z G-EDITION CVT 2WD 5DR
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	2ARH569327
Chassis No.:	AGH300017690
Maximum Power Output:	134.0 kW (179 bhp)
Open Market Value:	\$36,900.00
Original Registration Date:	01 Jan 2016
First Registration Date:	01 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$43,660.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Dec 2025
PARF Rebate Amount:	\$32,745.00
Intended COE Rebate Details	
COE Expiry Date:	31 Dec 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$61,103.00
COE Rebate Amount:	\$47,042.00
Total Rebate Amount:	\$79,787.00

The information contained herein is correct as at 19 Apr 2018

OK



- Boleh Land Election 2018
- Car fragrance
- Singapore Airlines pricing error

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

Porsche Boxster 2.7A With New 10 Year COE At \$105k.



Low Mileage Best Condition
Boxster Selling At \$10.5k Depre
A Year!
Direct Owner StarAd

PRIME MOTOR & LEASING
With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

Sort by Date Posted 20 results/page

5 vehicles

Toyota Vellfire

Advanced Search Submit

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Toyota Vellfire		Any	Any	2016	Any	Any	Any	Available



Toyota Vellfire 2.5A Z \$159,800 \$17,680 /yr 12-Apr-2016 2,493 cc 44,000 km MPV Available
Immaculate White Exterior Paired With Black Interior. The Most Popular And Elegant First Class MPV That Offers Tons Of Comfort, Spacious And Exterior Design That Makes Every Journey Enjoyable. Well Ta...
Posted: 17-Apr-2018 Tags: 2016 Toyota vellfire, Toyota Vellfire, Toyota, vellfire, Used Toyota



Toyota Vellfire 2.5A Z G-Edition \$188,800 \$19,400 /yr 23-Sep-2016 2,493 cc 43,310 km MPV Available
7 Seater 2-G-Edition! 1 Owner, Accident Free, High Specs Model With 4 Electric Powered Seats And 8 Way Executive Seats, Electric Power Tailgate. New Number Plate, Well Maintained Condition, View Now!
Posted: 16-Apr-2018 Tags: 2016 Toyota vellfire, Toyota vellfire, Toyota, vellfire, Used Toyota



Toyota Vellfire 2.5A Z A-Edition \$159,000 \$17,470 /yr 08-Apr-2016 2,493 cc 31,662 km MPV Available
Appointment For Viewing, Luxury High Spec MPV With Low Depreciation, 1st Owner, Low Mileage 31662Km, Mint Condition, Well Maintained By Owner, No Wear And Tear fixed Repairs, 100% Accident Free, One Of ...
HTS Motor
Posted: 12-Apr-2018 Tags: 2016 Toyota Vellfire, Toyota Vellfire, Toyota, vellfire, Used Toyota



Toyota Vellfire 2.5A Z \$175,899 \$18,080 /yr 27-Jun-2016 2,494 cc 50,000 km MPV Available
Agent Maintained. Still Under Warranty. Providing You With Spacious And Comfortable Interior. Fuel Efficiency Has Always Been The Priority Of Toyota. Captain Seat. Full Leather. Consignment Unit.
Posted: 10-Apr-2018 Tags: 2016 Toyota vellfire, Toyota vellfire, Toyota, vellfire, Used Toyota

Car Buying Car Selling Car Ownership Buying a pre-owned car, but Unsure of its Condition? Get, STA Car Evaluation
Car Aftermarket On The Move Lifestyle



Toyota Vellfire 2.5A Z A-Edition \$165,800 \$18,540 /yr 28-Jan-2016 2,493 cc 38,000 km MPV Available
1 Careful Owner. Original Condition Like Brand New Car. No Repair Needed. Still Under Warranty. Accident Free. Downpayment \$16.3k. Loan Up To 90%. High Approval Rate. High Trade In. Please Call Or SMS...
Posted: 06-Mar-2018 Tags: 2016 Toyota Vellfire, Toyota Vellfire, Toyota, vellfire, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/04/2018 10:03
Date Of Accident	17/04/2018 07:15
Exact Location Of Accident	ALONG BKE-PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB16C
Insured/Policyholder	
Name Of Registered Owner	SKYWAY MOTOR PTE LTD
Co Reg No	199904194N
Email Address	PEILIN@SKYWAY.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-63336333

Vehicle Particulars

Manufacturer	TOYOTA
Model	VELLFIRE-2.5 Z G-EDITION CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A28795104MCX
Cover Note Number	

Driver

Name of Driver	MOHAMAD SALLEH BIN SABTU
NRIC No	S7812835F
Date Of Birth	04/05/1978
Occupation	OUTDOOR
Date Of Driving Pass	16/07/2008
Driving Experience	9 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94773253
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 240 BUKIT PANJANG RING ROAD
#05-123

Postcode 670240

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1
NAME: : UNKNOW
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO THE ATTACHED SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLH2856A

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLA952E
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:




Reporting Centre Personnel's Signature
Name:
NRIC/TIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

Veh A - SLB16C
 Veh B - SCH 2856A
 Veh C - SCA 952E



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AT 0715 CAR A SLB16C WAS TRAVELLING TOWARDS BLK - PIE ON DAIRY FARM ROAD WHEN CAR B & C CAME TO A STATIONARY STOP WHICH CAR A COULD NOT REACT IN TIME TO STOP RESULTING TO HIT ON CAR B I WAS TRAVELLING AT 60 KM/H .

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Hui Yang Motor Pte Ltd (Co.Reg.No:201629438M)

176 Sin Ming Drive #04-02, Sin Ming AutoCare
Singapore 575721

Tel: 64515752 Fax: 64514658 Email: hui_yang_motor@hotmail.com

INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	A28795104MCX	Date of Loss:	17/04/2018
Vehicle Reg. No.:	SLB16C	Driveable?	
Driver Age/Info:	39 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SKYWAY MOTOR PTE LTD		
Driver:	MOHAMAD SALLEH BIN SABTU		

Make/Model:	TOYOTA VELLFIRE, 2.5 Z G-EDITION CVT (A)	Vehicle Reg. Date:	01/01/2016
Vehicle Colour:	PEARL WHITE	Chassis No:	AGH300017690
Engine No:	2ARH569327		
Odometer:	115265 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	18 days



*Not authorized
I.B.1
Resurvey B4 pain
Ex & Fuel*

Description of Accident/Loss	REFER TO GIA
Present Location:	HUI YANG MOTOR PTE LTD (HQ)

Ref: 162564315

COST OF CLAIMS	Amount
Parts	12,852.35
Miscellaneous Items	0.00
Labour	1,770.00
Paintwork Labour	1,200.00
Towing	0.00
Calculated Gross Total (S\$)	15,822.35
- Excess (S\$)	700.00
(S\$)	15,122.35
+ GST 7.00% (S\$)	1,058.56
Nett Amount (S\$)	16,180.91

This claim is handled by: NEO WEE EEK

16291.50

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Apr 2018)
Parts: M1-MPV TOYOTA VELLFIRE 2.5 Z G-EDITION CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Hui Yang Motor Pte Ltd/SLB16C/17/04/2018 12:32
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*front bonnet	0.00	0.00	*280.00 F	
2	1		*front bonnet chrome	0.00	0.00	*180.00 F	
3	2		*front bonnet hinge	0.00	0.00	*70.00 F	
4	1		*front bonnet inner cardboard	0.00	0.00	*180.00 F	?XVC
5	8		*front bonnet inner cardboard clip	0.00	0.00	*12.00 F	
6	1		*front bonnet inner lock	0.00	0.00	*55.00 F	
7	1		*front wiper garnish	0.00	0.00	*280.00 F	
8	2		*front wiper garnish side garnish CFTV	0.00	0.00	*70.00 F	4
9	2		*front headlamp	0.00	0.00	*2,500.00 F	
10	2		*front headlamp lower bracket	0.00	0.00	*110.00 F	?XR
11	2		*front headlamp garnish CIS m3cm	0.00	0.00	*110.00 F	2+
12	1		*front centre grille	0.00	0.00	*380.00 F	
13	1		*front centre grille TOYOTA logo	0.00	0.00	*45.00 F	
14	1		*front centre grille rubber	0.00	0.00	*45.00 F	
15	1		*front centre grille inner PCS sensor	0.00	0.00	*1,501.00 F	?XVC
16	1		*front centre grille top garnish	0.00	0.00	*150.00 F	
17	9		*front centre grille top garnish clip	0.00	0.00	*13.50 F	
18	2		*front centre grille parking sensor	0.00	0.00	*300.00 F	
19	2		*front centre grille parking sensor rubber	0.00	0.00	*30.00 F	
20	2		*front centre grille parking sensor outer garnish	0.00	0.00	*50.00 F	?XVC
21	1		*front bumper	0.00	0.00	*700.00 F	
22	2		*front bumper side retainer	0.00	0.00	*90.00 F	
23	1		*front bumper grille	0.00	0.00	*95.00 F	
24	1		*front bumper grille outer garnish	0.00	0.00	*120.00 F	
25	2		*front bumper fog lamp chrome	0.00	0.00	*160.00 F	
26	2		*front bumper fog lamp garnish	0.00	0.00	*150.00 F	?XVC
27	2		*front bumper fog lamp garnish cover	0.00	0.00	*110.00 F	
28	1		*front bumper reinforcement	0.00	0.00	*180.00 F	
29	1		*front bumper sponge	0.00	0.00	*55.00 F	?XVC
30	1		*front support panel	0.00	0.00	*580.00 F	
31	2		*front support panel side garnish	0.00	0.00	*110.00 F	
32	1		*front support panel centre pillar	0.00	0.00	*70.00 F	
33	2		*front horn	0.00	0.00	*140.00 F	?XVC
34	1		*front air duct	0.00	0.00	*75.00 F	?XVC
35	1		*front air duct hose	0.00	0.00	*25.00 F	?XVC
36	1		*front A/C condensor	0.00	0.00	*500.00 F	
37	1		*front A/C condensor pipe 1	0.00	0.00	*180.00 F	
38	1		*front A/C condensor pipe 2	0.00	0.00	*195.00 F	
39	1		*front A/C condensor motor	0.00	0.00	*170.00 F	
40	1		*front A/C condensor motor fan	0.00	0.00	*90.00 F	

Hui Yang Motor Pte Ltd/SLB16C/17/04/2018 12:32. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
41	1		*front radiator	0.00	0.00	<i>Pnc</i> *550.00 F ✓
42	1		*front radiator top hose	0.00	0.00	*45.00 F ? <i>KSC</i>
43	1		*front radiator lower hose	0.00	0.00	*45.00 F ? <i>KSC</i>
44	1		*front radiator cowling	0.00	0.00	<i>LAG</i> *95.00 F ? <i>110</i> ✓
45	1		*front radiator cowling lower garnish	0.00	0.00	*35.00 F ? <i>KSC</i>
46	1		*front radiator cowling motor	0.00	0.00	*180.00 F ? <i>KSC</i>
47	1		*front radiator cowling motor fan	0.00	0.00	*90.00 F ? <i>KSC</i>
48	1		*front RH fender	<i>Pnc</i> 0.00	0.00	*280.00 F ✓
49	1		*front RH fender inner front shield	<i>M/I</i> 0.00	0.00	*150.00 F ✓
50	8		*front RH fender inner front shield clip	<i>M</i> 0.00	0.00	*12.00 F ✓
51	1		*front number plate & casing	<i>CM</i> 0	0.00	*50.00 FS <i>85.50</i>

F=Franchise part. S=SpocNett.

Sub Total (S\$)	11,688.50
+ Margin on L,N Items 10.00% (S\$)	1,163.85
Total Parts (S\$)	12,852.35

Hui Yang Motor Pte Ltd/SLB16C/17/04/2018 12:32. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	spray painting	New	1,200.00 <i>900</i>
Labour Items			
2	remove & refit A/C condensor	New	120.00 <i>100</i>
3	remove & refit radiator	New	120.00 <i>50</i>
4	wiring	New	100.00 <i>20</i>
5	reprogram PCS unit	New	480.00 <i>? XNY</i>
6	labour	New	950.00 <i>700</i>
Gross Labour Cost (S\$)			2,970.00

Hui Yang Motor Pte Ltd/SLB16C/17/04/2018 12:32. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Kg

Hui Yang Motor Pte Ltd (Co. Reg. No: 201629438M)

176 Sin Ming Drive #04-02, Sin Ming AutoCare
Singapore 575721

Tel: 64515752 Fax: 64514658 Email: hui_yang_motor@hotmail.com

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	A28795104MCX	Date of Loss:	17/04/2018
Vehicle Reg. No.:	SLB16C	Driveable?	
Driver Age/Info:	39 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SKYWAY MOTOR PTE LTD		
Driver:	MOHAMAD SALLEH BIN SABTU		

Make/Model:	TOYOTA VELLFIRE, 2.5 Z G-EDITION CVT (A)	Vehicle Reg. Date:	01/01/2016
Vehicle Colour:	PEARL WHITE	Chassis No:	AGH300017690
Engine No:	2ARH569327		
Odometer:	115265 KM		

Paint Type:
Total Loss? **NO**
Est. Duration of Repair (day) *18 days*

FR

*Not with hold
1-B.1
Resurvey Bk paint
Ex @ 700*

Description of Accident/Loss: REFER TO GIA
Present Location: HUI YANG MOTOR PTE LTD (HQ)

Call 62564315

COST OF CLAIMS

	Amount
Parts	12,852.35
Miscellaneous Items	0.00
Labour	1,770.00
Paintwork Labour	1,200.00
Towing	0.00
Calculated Gross Total (S\$)	15,822.35
- Excess (S\$)	700.00
(S\$)	15,122.35
+ GST 7.00% (S\$)	1,058.56
Nett Amount (S\$)	16,180.91

This claim is handled by: **NEO WEE EEK**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Apr 2018)
 Parts: M1-MPV TOYOTA VELLFIRE 2.5 Z G-EDITION CVT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Hul Yang Motor Pte Ltd/SLB16C/17/04/2018 12:32
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
/1	1		*front bonnet	Bu	0.00	0.00	*280.00F	
/2	1		*front bonnet chrome	bu	0.00	0.00	*180.00F	
/3	2		*front bonnet hinge	Di	0.00	0.00	*70.00F	
4	1		*front bonnet inner cardboard	Bu	0.00	0.00	*180.00F	X
/5	8		*front bonnet inner cardboard clip	bu	0.00	0.00	*12.00F	
/6	1		*front bonnet inner lock	Di	0.00	0.00	*55.00F	
/7	1		*front wiper garnish	bu	0.00	0.00	*280.00F	
/8	2		*front wiper garnish side garnish @ 170	bu	0.00	0.00	*70.00F	
/9	2		*front headlamp	CM	0.00	0.00	*2,500.00F	
10	2		*front headlamp lower bracket	Bu	0.00	0.00	*110.00F	X
/11	2		*front headlamp garnish Cls mje m	n/s Bu	0.00	0.00	*110.00F	
/12	1		*front centre grille	CM	0.00	0.00	*380.00F	
/13	1		*front centre grille TOYOTA logo	bu	0.00	0.00	*45.00F	
/14	1		*front centre grille rubber	CM	0.00	0.00	*45.00F	
15	1		*front centre grille inner PCS sensor	Bu	0.00	0.00	*1,501.00F	X
/16	1		*front centre grille top garnish	Reform	0.00	0.00	*150.00F	
/17	9/10		*front centre grille top garnish clip @ 42 *TOPP = 30	bu	0.00	0.00	*13.50F	
/18	2		*front centre grille parking sensor	Sheet	0.00	0.00	*300.00F	
19	2		*front centre grille parking sensor rubber	bu	0.00	0.00	*30.00F	
20	2		*front centre grille parking sensor outer garnish	Bu	0.00	0.00	*50.00F	X
/21	1		*front bumper	Bu	0.00	0.00	*700.00F	
/22	2		*front bumper side retainer	Di	0.00	0.00	*90.00F	
/23	1		*front bumper grille	CM	0.00	0.00	*95.00F	
/24	1		*front bumper grille outer garnish	CM	0.00	0.00	*120.00F	
/25	2		*front bumper fog lamp chrome	CM	0.00	0.00	*160.00F	
26	2		*front bumper fog lamp garnish } 2 in 1	bu	0.00	0.00	*160.00F	X
/27	2		*front bumper fog lamp garnish cover	bu	0.00	0.00	*110.00F	X
/28	1		*front bumper reinforcement	Bu	0.00	0.00	*180.00F	X
29	1		*front bumper sponge		0.00	0.00	*55.00F	X
/30	1		*front support panel @ 115 x 115 PCS	Bu	0.00	0.00	*580.00F	
/31	2		*front support panel side garnish	CM	0.00	0.00	*110.00F	
/32	1		*front support panel centre pillar	Bu	0.00	0.00	*70.00F	
33	2		*front horn	Bu	0.00	0.00	*140.00F	X
34	1		*front air duct	Bu	0.00	0.00	*75.00F	X
35	1		*front air duct hose	Bu	0.00	0.00	*25.00F	X
/36	1		*front A/C condensor	Bu	0.00	0.00	*500.00F	X
37	1		*front A/C condensor pipe 1	Bu	0.00	0.00	*180.00F	X
38	1		*front A/C condensor pipe 2	Bu	0.00	0.00	*195.00F	X
39	1		*front A/C condensor motor	Bu	0.00	0.00	*170.00F	X
40	1		*front A/C condensor motor fan	Bu	0.00	0.00	*90.00F	X

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
/41	1		*front radiator	Per	0.00	0.00	*550.00F	✓
42	1		*front radiator top hose	Sn	0.00	0.00	*45.00F	✓
43	1		*front radiator lower hose	Sn	0.00	0.00	*45.00F	✓
/44	1		*front radiator cowling	CM	0.00	0.00	*95.00F	✓
46	1		*front radiator cowling lower garnish	Sn	0.00	0.00	*35.00F	✓
46	1		*front radiator cowling motor	Sn	0.00	0.00	*180.00F	✓
47	1		*front radiator cowling motor fan	Sn	0.00	0.00	*90.00F	✓
/48	1		*front RH fender	Per	0.00	0.00	*280.00F	✓
/49	1		*front RH fender inner front shield	M/I	0.00	0.00	*150.00F	✓
/50	8		*front RH fender inner front shield clip	M	0.00	0.00	*12.00F	✓
51	1		*front number plate & casing	CM	0	0.00	*50.00FS	✓

F=Franchise part. S=SpecNet.

Sub Total (S\$) 11,688.50
 + Margin on L,N Items 10.00% (S\$) 1,163.85
Total Parts (S\$) 12,852.35

Hui Yang Motor Pte Ltd/SLB16C/17/04/2018 12:32. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Jae Auto (Inv) Total cost Before GST \$2647.00
 cost + 10% \$2911.90

number plate IN = 45.00
 labour = 1770.00
 part by part = 11328.90 ✓

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab Type	Amount
<u>Paintwork Labour</u>			
1	spray painting	New	1,200.00 <i>900</i>
<u>Labour Items</u>			
2	remove & refit A/C condensor	New	120.00 <i>100</i>
3	remove & refit radiator	New	120.00 <i>50</i>
4	wiring	New	100.00 <i>20</i>
5	reprogram PCS unit	New	480.00 <i>nn</i> 8
6	labour	New	950.00 <i>700</i>
Gross Labour Cost (S\$)			2,970.00

Hui Yang Motor Pte Ltd/SLB16C/17/04/2018 12:32. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE
48A SUNGAI KADUT AVE SINGAPORE 729872
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

SIGN
+
CHOP



Dept Direct: 6417 8791

Dept Direct: 6417 8792

Dept Direct: 6417 8793

Dept Direct: 6417 8794

Wiper blade:

Wiper blade, Silver (Made in Korea)

Spark plug:

Spark plug (Made in Japan)

HUI YANG MOTOR PTE LTD
BLK 176 SIN MING DRIVE
#04-02 SIN MING AUTOCARE

SINGAPORE 575721
TEL: 64515752 / LEE83336725 FAX: 64514658
ATTN: LEE / AH WEI :98625891.

TAX INVOICE : AR201804-10136
DATE : 18/04/2018
CUSTOMER ID : HUI001
VEH REG. NO. : SLB16C
TERMS : 30 days
PAGE NO. : Page 1 of 1
CURR : SGD

SQ STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
1 T75311-58200 VELL-AGH30	RAD GRILLE EMBLEM	WH	1	450.00	450.00

(3)

NET TOTAL : 450.00
GST 7.00% : 31.50

E & OE TOTAL AMOUNT SGD : 481.50

[P] 18/04/2018 3:39:06PM

[E] 18/04/2018 3:38:39PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s)

JAE Auto Pte. Ltd.

Sales Executive : JASON



AR201804-10136

Goods Received in Good Order

Signature / Co Stamp / Date

This is computer generated document.

No signature is required.

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729872

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



HUI YANG MOTOR PTE LTD
BLK 176 SIN MING DRIVE
#04-02 SIN MING AUTOCARE

SINGAPORE 575721

TEL : 64515752 / LEE83336725 FAX : 64514658

ATTN : LEE / AH WEI :98625891.

TAX INVOICE : AR201804-1000
DATE : 18/04/2018
CUSTOMER ID : HUI00
VEH REG. NO. : SLB16C
TERMS : 30 day
PO NO. :
PAGE NO. : Page 1 of 4
CURR : SGE

SO STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. T53301-58060 VELL-AGH30	FRT BONET (1)	PA PL2-E1-03A	1	280.00	280.00
2. T90467-T0014/090S) ZSU60 ZRE171	(5) FRT BONET INSULATOR CLIP	PA PL2-K1-031	8	1.50	12.00
3. T53510-58090 VELL-AGH30	(6) FRT BONNET LOCK	PA PL2-G1-06E	1	55.00	55.00
4. T55708-58090 VELL-AGH30	(7) WIPER GARNISH	PA PL2-H1-09A	1	280.00	280.00
5. T81145-58401 VELL-AGH30	HEAD LAMP RH (9)	PA PL2-F1-023	1	1250.00	1,250.00
6. T53181-58060-A0 VELL-AGH30	(11) HEAD LAMP GARNISH RH	PA PL2-K1-05A	1	55.00	55.00
7. T53101-58290 VELL-AGH30	RAD GRILLE (17)	PA PL2-A1-05A	1	380.00	380.00

CONTINUE NEXT PAGE

[P] 18/04/2018 4:09:44PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[E] 18/04/2018 2:11:07PM



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

Change By: _____ Driver: _____

Dept Direct: 6417 6734 (VW, Audi, etc.)

Dept Direct: 6306 9611 (TOYOTA, etc.)

Dept Direct: 6417 6734 (Mitsubishi, Suzuki, etc.)

Dept Direct: 6417 6734 (Mazda, Ford, etc.)

Dept Direct: 6417 6734 (Honda, Subaru, etc.)

Dept Direct: 6417 6734 (NISSAN, etc.)

Wiper (Mitsubishi, Siper / Made in Germany)
Wiper (NGK / Made in Japan)

HUI YANG MOTOR PTE LTD
BLK 176 SIN MING DRIVE
#04-02 SIN MING AUTOCARE

SINGAPORE 575721
TEL : 64515752 / LEE83336725 FAX : 64514658
ATTN : LEE / AH WEI :98625891.

TAX INVOICE : AR201804-1000
DATE : 18/04/2018
CUSTOMER ID : HUI00
VEH REG. NO. : SLB160
TERMS : 30 day
PO NO. :
PAGE NO. : Page 2 of 4
CURR : SGL

SQ	STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
8	T89341-58060-A0 VELL-AGH30	BUMPER SENSOR (13)	PA PL2-G1-07A	2	150.00	300.00
9	T53039-58070 VELL-AGH30	RAD GRILLE RUBBER (14)	PA PL2-H1-04F	1	30.00	30.00
10	T89348-58160-A0 ALPHD-AGH30	<i>Return</i> REVERSE SENSOR COVER NO 6	PA PL2-K1-06C	2 <i>Return 25.00</i>		50.00
11	T52119-58540-A0 VELL-AGH30	(2) FRT BUMPER Z	PA PL4-E1-35	1	700.00	700.00
12	T53112-58160 VELL-AGH30	(33) FRT BUMPER LWR GRILLE Z	PA PL2-H1-06A	1	95.00	95.00
13	T53105-58020 VELL-AGH30	(24) FRT BUMPER CTR GARNISH	PA PL2-H1-07D	1	120.00	120.00
14	T52030-58140 VELL-AGH30	(25) FOG LAMP COVER RH Z	PA PL2-O1-061A	1	80.00	80.00

CONTINUE NEXT PAGE

[P] 18/04/2018 4:09:45PM

Goods Sold are not refundable for Cash

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[E] 18/04/2018 2:11:07PM



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

Change By: _____ Driver: _____

Dept Direct: 8417 8701 - 8702 8000

Dept Direct: 800 9011

Dept Direct: 800 9011

Dept Direct: 8417 8700

Dept Direct: 8417 8700

Dept Direct: 8417 8700

Dept Direct: 8417 8700

Wiper Blade: _____

Spark plug: _____

Wiper Blade: _____ (Made in Korea)
Wiper Blade: _____ (Made in Germany)
Spark plug: _____ (Made in Japan)

HUI YANG MOTOR PTE LTD
BLK 176 SIN MING DRIVE
#04-02 SIN MING AUTOCARE

SINGAPORE 575721
TEL : 64515752 / LEE83336725 FAX : 64514658
ATTN : LEE / AH WEI :98625891.

TAX INVOICE : AR201804-10006
DATE : 18/04/2018
CUSTOMER ID : HUI00
VEH REG. NO. : SLB16C
TERMS : 30 day!
PERSON : _____
PAGE NO. : Page 3 of 4
CURRENCY : SGE

SQ	STOCKID	DESCRIPTION	Stk Loc	QTY	UPRICE	AMOUNT
15	T52040-58140 VELL-AGH30	25 FOG LAMP COVER LH Z	PA PL2-M1-000	1	80.00	80.00
16	T52127-58280 VELL-AGH30	27 FRT BUMPER COVER RH Z	PA PL2-D1-0800	1	55.00	55.00
17	T52128-58280 VELL-AGH30	27 FRT BUMPER COVER LH Z	PA PL2-H1-000	1	55.00	55.00
18	T53205-58070 VELL-AGH30	29 SUPPORT TOP PANEL	PA PL2-F1-110	1	145.00	145.00
19	T53202-58050 VELL-AGH30	30 RAD SUPPORT PANEL RH	PA PL2-F1-0800	1	145.00	145.00
20	T52545-58070 VELL-AGH30	31 RAD SUPPORT S/GARNISH RH	PA PL2-M1-000	1	55.00	55.00
21	T52546-58070 VELL-AGH30	31 RAD SUPPORT S/GARNISH LH	PA PL2-K1-000	1	55.00	55.00

CONTINUE NEXT PAGE

[P] 18/04/2018 4:09:45PM
Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s)
ORIGINAL

[B] 18/04/2018 2:11:07PM



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

Single By: _____ Driver: _____

Dept Direct: 6417 8791 (1000 880)

Dept Direct: 6333 9411 Dept Direct: 6336 9411 Dept Direct: 6411 8792

Dept Direct: 6417 8791 Dept Direct: 6417 8791 Dept Direct: 6417 8791 Dept Direct: 6417 8791

Wiper Brand: _____ Wiper Model: Siper (Made in _____)
in Germany)

Spark Plug: _____ NGK (Made in Japan)

HUI YANG MOTOR PTE LTD
BLK 176 SIN MING DRIVE
#04-02 SIN MING AUTOCARE

SINGAPORE 575721
TEL : 64515752 / LEE83336725 FAX : 64514658
ATTN : LEE / AH WEI :98625891.

TAX INVOICE : AR201804-10000
DATE : 18/04/2018
CUSTOMER ID : HUI001
VEH REG. NO. : SLB16C
TERMS : 30 days
PO NO :
PAGE NO : Page 4 of 4
CURR : SGD

SO/STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
22 T90467-07166 JB33/ACV30/31R	CLIP FOR SHIELD	PA PL2-K1-06	8	1.50	12.00
22 T53805-58070 VELL-AGH30	FRT FENDER LINER RH	PA PL2-F1-10	1	150.00	150.00

NET TOTAL : 4,439.00
ADD GST 7.00% 310.73

E & OE TOTAL AMOUNT SGD : 4,749.73

[P] 18/04/2018 4:09:45PM
Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[R] 18/04/2018 2:11:07PM

JAE Auto Pte Ltd.
Sales Executive JASON



This is computer generated document.
No signature is required.

Goods received in Good Order

Signature / Co-Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

HUI YANG MOTOR PTE LTD
BLK 176 SIN MING DRIVE
#04-02 SIN MING AUTOCARE

SINGAPORE 575721
TEL: 64515752 / LEE83336725 FAX: 64514658
ATTN: LEE / AH WEI :98625891.



Wiper Blade: (Made in Korea) / (Made in Germany) / NDK (Made in Japan)

TAX INVOICE : AR201804-10001
DATE : 18/04/2018
CUSTOMER ID : HUI001
VEH REG. NO. : SLB16C
TERMS : 30 days
PAGE NO. : Page 1 of 1
CURE : SGD

SQ STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
✓ T75770-58081 VELL-AGH30	FRT BONET MLDG	U1	1	180.00	180.00
✓ T53410-58060 VELL-AGH30	FRT BONET HINGE RH	U1	1	35.00	35.00
3 ✓ T81185-58401 VELL-AGH30	HEAD LAMP LH	U1	1	1250.00	1,250.00
4 ✓ T88460-58040 VELL-AGH30	A/C CONDENSER	U1	1	500.00	500.00

NET TOTAL : 1,965.00
ADD GST 7.00% : 137.55

E & O E TOTAL AMOUNT SGD : 2,102.55

[P] 18/04/2018 4:07:55PM

[E] 18/04/2018 2:11:16PM

Goods Sold are not refundable for Cash
Interest Rate of 1.5% per month will be imposed on OverDue Account(s)

JAE Auto Pte. Ltd
Sales Executive : JASON



Goods Received in Good Order

This is computer generated document.
No signature is required.

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729572
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

HUI YANG MOTOR PTE LTD
BLK 176 SIN MING DRIVE
#04-02 SIN MING AUTOCARE

SINGAPORE 575721
TEL: 64515752 / LEE83336725 FAX: 64514658
ATTN: LEE / AH WEI :98625891.



TAX INVOICE : AR201804-10348
DATE : 19/04/2018
CUSTOMER ID : HUI001
VEH REG. NO. : SLB16C
TERMS : 30 days
PAGE NO. : Page 1 of 1
CURRENCY : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1 T16400-28711 VELL-AGH30	41 RADIATOR	III SUPPLIER	1	550.00	550.00
2 T16711-28420 VELL-ANH20	44 FAN COWLING	III SUPPLIER	1	110.00	110.00
3 T5221-58030 VELL-AGH30	28 FRT BUMPER REINFORCEMENT	III SUPPLIER	1	180.00	180.00
4 T53106-58090 VELL-AGH30	16 SUPPORT TOP GARNISH	III SUPPLIER	1	150.00	150.00
5 T53203-58060 VELL-AGH30	30 RAD SUPPORT PANEL LH	III SUPPLIER	1	145.00	145.00
6 T53209-58040 VELL-AGH30	32 BRACE PANEL	III SUPPLIER	1	70.00	70.00
7 T53420-58080 VELL-AGH30	3 FRT BONNET HINGE LH	III SUPPLIER	1	35.00	35.00
8 T53801-58070 VELL-AGH30	42 FRT FENDER RH	III SUPPLIER	1	280.00	280.00
9 T90467-07231 GRS190	17 RAD TOP SEAL CLIP	III SUPPLIER	10	2.00	20.00

TOTAL : 1,540.00
GST 7.00% : 107.80

E & O E TOTAL AMOUNT SGD : 1,647.80

[P] 19/04/2018 9:33:21AM

[B] 19/04/2018 9:29:28AM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s)

JAE Auto Pte. Ltd
Sales Executive : JASON



This is computer generated document.
No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

HUI YANG MOTOR PTE LTD
BLK 176 SIN MING DRIVE
#04-02 SIN MING AUTOCARE

SINGAPORE 575721
TEL : 64515752 / LEE83336725 FAX : 64514658
ATTN : LEE / AH WEI :98625891.



Dept Direct: 6417 8791

Dept Direct: 6200 9111

Dept Direct: 6417 8791

Dept Direct: 6417 8791

Dept Direct: 6417 8791

Wiper blades : Wiper blades, Sliper (Made in Korea)
in Germany)
Spark plug : 100% (Made in Japan)

TAX INVOICE : AR201804-10465
DATE : 19/04/2018
CUSTOMER ID : HUI001
VEH REG. NO. : SLB16C
TERMS : 30 days
PAGE NO. : Page 1 of 1
CURRENCY : SGD

SQ STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
1 T55754-58010 VELL-AGH30	WIPER S/GARNISH LH	WH	1	70.00	70.00
2 T52115-58070 VELL-AGH30	FRT BUMPER S/RETAINER RH	WH	1	45.00	45.00
3 T53028-28050 ACR50 AGH30	SUPPORT LWR PANEL	WH	1	145.00	145.00

TOTAL : 260.00
GST 7.00% : 18.20

JAE TOTAL AMOUNT SGD : 278.20

[P] 19/04/2018 10:34:48AM

[E] 19/04/2018 10:31:39AM

Goods Sold are not refundable for Cash
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.
Sales Executive : JASON



Goods received in Good Order

This is computer generated document.
No signature is required.

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450816 (Account)

WAREHOUSE:
48A SUNGAI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



HUI YANG MOTOR PTE LTD
BLK 176 SIN MING DRIVE
#04-02 SIN MING AUTOCARE

SINGAPORE 575721
TEL : 64515752 / LEE83336725 FAX : 64514658
ATTN : LEE / AH WEI :98625891.

TAX INVOICE : AR201804-1013
DATE : 18/04/2018
CUSTOMER ID : HUI00
VEH REG. NO. : SLB160
TERMS : 30 day
PAGE NO. : Page 1 of 1
CURR : SGI

SQ STOCKID	DESCRIPTION	Stk Loc	QTY	UPRICE	AMOUNT
1 T52116-58070 VELL-AGH30	FRT BUMPER S/RETAINER LH	SG L2-1B	1	45.00	45.00

NET TOTAL 45.00
ADJUST 7.00% 3.15
TOTAL AMOUNT SGD 48.15

[P] 18/04/2018 4:10:37PM
Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte Ltd
Sales Executive: JASON



This is computer generated document.
No signature is required.

ORIGINAL

Received in Good Order

Signature/Stamp/Date

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Apr 2018 Sendback Est	17 Apr 2018 12:32 S\$15,822.35	18 Apr 2018 10:42 Edit Adj Rpt	S\$11,328.90 Edit Estimates	S\$11,328.90 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	SKYWAY MOTOR PTE LTD, Co. Reg. No.: 199904194N								
Vehicle Reg. No.:	SLB16C	Date of Loss:	17/04/2018 07:00 - :59 [27 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 555719	Policy/Cover Note No.:	A28795104MCX (Comprehensive) Coverage: 08/08/2017 - 07/08/2018						
		Excess:	S\$700.00						
Repairer:	Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmala D/O Raja Singam - 65942471]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 18/05/2018]								
Driver/Custodian:	MOHAMAD SALLEH BIN SABTU (39 / Male), NRIC: S7812835F								
Adj Asg. Remarks:	Car in, please survey before 12pm and revert. Premium is outstanding. Checking with the Agencies unit.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (08/06/2018): Alert - Adj Mandate Approved (S\$11328.90) - SLB16C - Claim Handler: Vimmala D/O ... MSIG_SG (19/04/2018): Alert - Adj Mandate Approved (S\$9138.25) - SLB16C - Claim Handler: Vimmala D/O R... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLB16C (555719)
OD
Apr 17 2018 7:00AM
[SKYWAY MOTOR PTE LTD]
Hui Yang Motor Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports								1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hui Yang Motor Pte Ltd (HQ)			Thumbnail	Print			
1	17/04/18 12:32	Repairer Estimates			Load HTM				
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print			
1	19/04/18 10:20	Adjuster Immediate Advice			Load HTM				
2	07/06/18 14:21	Adjuster Immediate Advice			Load HTM				
Photos/Images								3 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)			Thumbnail	Print			
1	17/04/18 16:12	Photos - Before			Load PDF				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print			
1	19/04/18 10:21	General View			Load JPG	<input checked="" type="checkbox"/>			
2	19/04/18 10:21	General View			Load JPG	<input checked="" type="checkbox"/>			
3	19/04/18 10:21	General View			Load JPG	<input checked="" type="checkbox"/>			
4	19/04/18 10:21	General View			Load JPG	<input checked="" type="checkbox"/>			
5	19/04/18 10:21	General View			Load JPG	<input checked="" type="checkbox"/>			
6	19/04/18 10:21	General View			Load JPG	<input checked="" type="checkbox"/>			
7	19/04/18 10:21	General View			Load JPG	<input checked="" type="checkbox"/>			
8	19/04/18 10:21	General View			Load JPG	<input checked="" type="checkbox"/>			
9	19/04/18 10:21	General View			Load JPG	<input checked="" type="checkbox"/>			
10	19/04/18 10:21	General View			Load JPG	<input checked="" type="checkbox"/>			
11	19/04/18 10:21	General View			Load JPG	<input checked="" type="checkbox"/>			
12	19/04/18 10:21	General View			Load JPG	<input checked="" type="checkbox"/>			
13	19/04/18 10:21	General View			Load JPG	<input checked="" type="checkbox"/>			
14	19/04/18 10:21	General View			Load JPG	<input checked="" type="checkbox"/>			
15	19/04/18 10:21	General View			Load JPG	<input checked="" type="checkbox"/>			
16	19/04/18 10:21	General View			Load JPG	<input checked="" type="checkbox"/>			
17	19/04/18 10:21	General View			Load JPG	<input checked="" type="checkbox"/>			
18	19/04/18 10:21	General View			Load JPG	<input checked="" type="checkbox"/>			
19	19/04/18 10:21	General View			Load JPG	<input checked="" type="checkbox"/>			
20	19/04/18 10:21	General View			Load JPG	<input checked="" type="checkbox"/>			
21	19/04/18 10:21	General View			Load JPG	<input checked="" type="checkbox"/>			
22	19/04/18 10:21	General View			Load JPG	<input checked="" type="checkbox"/>			
23	19/04/18 10:21	General View			Load JPG	<input checked="" type="checkbox"/>			
24	19/04/18 10:21	General View			Load JPG	<input checked="" type="checkbox"/>			
25	19/04/18 10:21	General View			Load JPG	<input checked="" type="checkbox"/>			
26	19/04/18 10:21	General View			Load JPG	<input checked="" type="checkbox"/>			
27	19/04/18 10:21	General View			Load JPG	<input checked="" type="checkbox"/>			
28	19/04/18 10:21	General View			Load JPG	<input checked="" type="checkbox"/>			
29	19/04/18 10:21	General View			Load JPG	<input checked="" type="checkbox"/>			
30	19/04/18 10:21	General View			Load JPG	<input checked="" type="checkbox"/>			
31	19/04/18 10:21	General View			Load JPG	<input checked="" type="checkbox"/>			

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hui Yang Motor Pte Ltd (HQ)	Thumbnail	Print
32	19/04/18 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
33	19/04/18 10:21	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
34	19/04/18 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
35	19/04/18 10:21	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
36	19/04/18 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
37	19/04/18 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
38	07/06/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	07/06/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	07/06/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	07/06/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	07/06/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	07/06/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	07/06/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	07/06/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	07/06/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	07/06/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	07/06/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	07/06/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	07/06/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	07/06/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	07/06/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	07/06/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	07/06/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	07/06/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	07/06/18 14:17	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hui Yang Motor Pte Ltd (HQ)	Thumbnail	Print
1	17/04/18 12:28	Singapore Accident Statement	 Load TIF	
2	17/04/18 12:29	Singapore Accident Statement	 Load TIF	
3	17/04/18 12:29	Singapore Accident Statement	 Load TIF	
4	17/04/18 12:29	Singapore Accident Statement	 Load TIF	
5	17/04/18 12:29	Singapore Accident Statement	 Load TIF	
6	17/04/18 12:29	Singapore Accident Statement	 Load TIF	
7	17/04/18 12:31	Singapore Accident Statement	 Load TIF	
8	17/04/18 12:31	Singapore Accident Statement	 Load TIF	
9	17/04/18 12:31	Singapore Accident Statement	 Load TIF	
10	17/04/18 12:31	Singapore Accident Statement	 Load TIF	
11	17/04/18 12:31	Singapore Accident Statement	 Load TIF	
12	17/04/18 12:31	Singapore Accident Statement	 Load TIF	
13	17/04/18 12:31	Singapore Accident Statement	 Load TIF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	17/04/18 16:08	Driving licence validity status	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/04/18 10:20	ESTIMATE	 Load PDF	
2	07/06/18 14:19	REVISED ESTIMATE	 Load PDF	
3	13/06/18 11:18	Parts Invoice	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Repairer Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18007162/KQBE2

Date: 13/06/2018

REFERENCE

Insured/Claimant:	SKYWAY MOTOR PTE LTD	Policy No:	A28795104MCX
Date of Loss:	17/04/2018	Nature of Claim:	OD
			Claim No: 555719

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB16C	Engine No:	2ARH569327
Make & Model:	TOYOTA VELLFIRE, 2.5 Z G-EDITION CVT (A)	Chassis No:	AGH300017690
Reg. Date:	01/01/2016 (Man. Year: 2015)	Odometer:	115265 km
Colour:	Metallic Pearl White		
Engine Capacity:	2493 cc		
Market Value/New Car Price:	S\$158,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Davanti 8 mm	Rear Left Side:	Davanti 8 mm
Front Right Side:	Davanti 8 mm	Rear Right Side:	Davanti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,852.35	9,558.90	3,293.45	25.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,770.00	870.00	900.00	50.85
Paintwork Labour	1,200.00	900.00	300.00	25.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,822.35	11,328.90	4,493.45	28.40
- Excess (S\$)	700.00	700.00	0.00	0.00
(S\$)	15,122.35	10,628.90	4,493.45	29.71
+ GST 7.00/7.00% (S\$)	1,058.56	744.02	314.54	29.71
Nett Amount (S\$)	16,180.91	11,372.92	4,807.99	29.71

INSPECTION

Date of Assignment:	18/04/2018 Present Location:	Hui Yang Motor Pte Ltd (HQ)
Date Inspected:	18/04/2018 Inspected At:	176 Sin Ming Drive #04-02, Sin Ming AutoCare Singapore 575721
Estimated Period of Repair:	7.0 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 Jun 2018)	
Parts: M1-MPV	TOYOTA VELLFIRE 2.5 Z G-EDITION CVT (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLB16C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*front bonnet (WCP)	Buckled	280.00 F	*280.00 F
2	1		*front bonnet chrome (WCP)	Dented	180.00 F	*180.00 F
3	2		*front bonnet hinge (WCP)	Distorted	70.00 F	*70.00 F
4	1		*front bonnet inner cardboard (WCP)	Serviceable	180.00 F	*- F
5	8		*front bonnet inner cardboard clip (WCP)	Necessary	12.00 F	*12.00 F
6	1		*front bonnet inner lock (WCP)	Distorted	55.00 F	*55.00 F
7	1		*front wiper garnish (WCP)	Dented	280.00 F	*280.00 F
8	1		*front wiper garnish side garnish (WCP)	N/s Missing	70.00 F	*70.00 F
9	2		*front headlamp (WCP)	Cracked	2,500.00 F	*2,500.00 F
10	2		*front headlamp lower bracket (WCP)	Repair	110.00 F	*- F
11	1		*front headlamp garnish (WCP)	Os Mtg Cracked/Ns Serviceable	110.00 F	*55.00 F
12	1		*front centre grille (WCP)	Cracked	380.00 F	*380.00 F
13	1		*front centre grille TOYOTA logo (WCP)	Necessary	45.00 F	*450.00 F
14	1		*front centre grille rubber (WCP)	Cut	45.00 F	*30.00 F
15	1		*front centre grille inner PCS sensor (WCP)	Serviceable	1,501.00 F	*- F
16	1		*front centre grille top garnish (WCP)	Deformed	150.00 F	*150.00 F
17	10		*front centre grille top garnish clip (WCP)	Necessary	13.50 F	*20.00 F
18	2		*front centre grille parking sensor (WCP)	Shorted	300.00 F	*300.00 F
19	2		*front centre grille parking sensor rubber (WCP)	Serviceable	30.00 F	*- F
20	2		*front centre grille parking sensor outer garnish (WCP)	Serviceable	50.00 F	*- F
21	1		*front bumper (WCP)	Bent	700.00 F	*700.00 F
22	2		*front bumper side retainer (WCP)	Distorted	90.00 F	*90.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
23	1		*front bumper grille (WCP)	Cracked	95.00 F	*95.00 F
24	1		*front bumper grille outer garnish (WCP)	Cracked	120.00 F	*120.00 F
25	2		*front bumper fog lamp chrome (WCP)	Cracked	160.00 F	*160.00 F
26	2		*front bumper fog lamp garnish (WCP)	Not Necessary	150.00 F	*- F
27	2		*front bumper fog lamp garnish cover (WCP)	Dented	110.00 F	*110.00 F
28	1		*front bumper reinforcement (WCP)	Bent	180.00 F	*180.00 F
29	1		*front bumper sponge (WCP)	Serviceable	55.00 F	*- F
30	1		*front support panel (WCP)	Bent	580.00 F	*580.00 F
31	2		*front support panel side garnish (WCP)	Cracked	110.00 F	*110.00 F
32	1		*front support panel centre pillar (WCP)	Bent	70.00 F	*70.00 F
33	2		*front horn (WCP)	Serviceable	140.00 F	*- F
34	1		*front air duct (WCP)	Serviceable	75.00 F	*- F
35	1		*front air duct hose (WCP)	Serviceable	25.00 F	*- F
36	1		*front A/C condensor (WCP)	Punctured	500.00 F	*500.00 F
37	1		*front A/C condensor pipe 1 (WCP)	Serviceable	180.00 F	*- F
38	1		*front A/C condensor pipe 2 (WCP)	Serviceable	195.00 F	*- F
39	1		*front A/C condensor motor (WCP)	Serviceable	170.00 F	*- F
40	1		*front A/C condensor motor fan (WCP)	Serviceable	90.00 F	*- F
41	1		*front radiator (WCP)	Punctured	550.00 F	*550.00 F
42	1		*front radiator top hose (WCP)	Serviceable	45.00 F	*- F
43	1		*front radiator lower hose (WCP)	Serviceable	45.00 F	*- F
44	1		*front radiator cowling (WCP)	Cracked	95.00 F	*110.00 F
45	1		*front radiator cowling lower garnish (WCP)	Serviceable	35.00 F	Repair
46	1		*front radiator cowling motor (WCP)	Serviceable	180.00 F	*- F
47	1		*front radiator cowling motor fan (WCP)	Serviceable	90.00 F	*- F
48	1		*front RH fender (WCP)	Buckled	280.00 F	*280.00 F
49	1		*front RH fender inner front shield (WCP)	Missing	150.00 F	*150.00 F
50	8		*front RH fender inner front shield clip (WCP)	Necessary	12.00 F	*12.00 F
51	1		*front number plate & casing	Cracked	50.00 FS	*45.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	11,688.50	8,694.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	1,163.85	864.90
Total Parts (\$\$)	12,852.35	9,558.90

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	spray painting	New	1,200.00	900.00
Labour Items				
2	remove & refit A/C condensor	New	120.00	100.00
3	remove & refit radiator	New	120.00	50.00
4	wiring	New	100.00	20.00
5	reprogram PCS unit	New	480.00	-
6	labour	New	950.00	700.00
Gross Labour Cost (S\$)			2,970.00	1,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

