

DING AUTO PTE LTD
Blk 10 Sin Ming Industrial Estate Sector C
#01-20
Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

ESTIMATE REPORT

1ST Quotation

18/04/2018 11:14

JOB-NO: 85008255

OWNER'S PARTICULARS

NAME: LION CITY RENTALS PTE LTD

CONTACT:

Page 1 of 2

ADDRESS: 60 ANSON ROAD
MAPLETREE ANSON
LEVEL 11 SINGAPORE
079914

NOEMAIL@GMAIL.COM

VEHICLE DETAILS

LICENSE NO: SLG7666D

TRANS: AUTO

CHASSIS: MMBSTA13AHH003213

MAKE / MODEL: MITSUBISHI/ Others

ENGINE: 3A92UDN0732

OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TOWING CHARGES	1.00	150.00	0.00	150.00		Y	80 ✓
2 TO PLACE VEHICLE ON WORKBENCH	1.00	300.00	0.00	300.00		Y	200? photo
3 R & R REAR EXHAUST PIPE & MUFTLER	1.00	150.00	0.00	150.00		Y	X
4 R & R SPARE TYRE BOARD, REAR TRIMS & SEATS TO FACILITATE REPAIR	1.00	120.00	0.00	120.00		Y	60
5 TO CONDUCT WIRING & LIGHTING SYSTEM	1.00	120.00	0.00	120.00		Y	30
6 TO REMOVE, REFIX REAR WINDSCREEN GLASS	1.00	200.00	0.00	200.00		Y	X
7 R & R REAR BUMPER REVERSE SENSOR	1.00	150.00	0.00	150.00		Y	30.
8 R & R FUEL TANK ASSY	1.00	180.00	0.00	180.00		Y	X
9 TO REMOVE, REINSTALL UPHOLSTRY, INNER & TRIMS GARNISH	1.00	150.00	0.00	150.00		Y	40
10 TO APPLY RUST PROOFING, TUFFCOATING TREATMENT TO REPLACED	1.00	200.00	0.00	200.00		Y	60.
11 TO ALIGNMENT REAR CHASSIS	1.00	200.00	0.00	200.00		Y	7 photo.
12 TO REMOVE & REPLACE DAMAGED BODY PARTS, KNOCK OUT DENTS ON THE AFFECTED PORTION, ADJUST & REALIGN BACK TO THE SAME	1.00	3,200.00	0.00	3,200.00		Y	1300
13 TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS, ECT BOOTLID (INNER & OUTER) REAR BUMPER, BOTH REAR FENDER, REAR END PANEL, REAR SPARE TYRE COMPARTMENT & BOTH REAR DOOR	1.00	2,000.00	0.00	2,000.00		Y	1200
TOTAL:		7,120.00	0.00	7,120.00			

MATERIALS

1 REAR BUMPER	1.00	745.00	74.50	670.50	L	Y	de
2 REAR BUMPER SIDE RETAINER	2.00	60.00	6.00	54.00	L	Y	nei
3 REAR BUMPER CLIPS	10.00	35.00	3.50	31.50	L	Y	nei
4 REAR BUMPER REFLECTOR	2.00	50.00	5.00	45.00	L	Y	?
5 REAR BOOTLID	1.00	870.00	87.00	783.00	L	Y	bt
6 REAR BOOTLID HINGES	2.00	390.00	39.00	351.00	L	Y	Rp
7 REAR BOOTLID INNER LOCK	1.00	225.00	22.50	202.50	L	Y	bt
8 REAR BOOTLID "ATTRAGE" BADGE	1.00	35.00	3.50	31.50	L	Y	nei
9 REAR BOOTLID "CYCLE & CARRIGE" BADGE	1.00	40.00	4.00	36.00	L	Y	nei
10 REAR BOOTLID "MIT" EMBLEM	1.00	45.00	4.50	40.50	L	Y	nei

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
11 REAR BOOTLID OUTER CHROME MLDG	1.00	325.00	32.50	292.50	L	Y	X
12 REAR WEATHERSTRIP	1.00	155.00	15.50	139.50	L	Y	hi ✓
13 REAR END PANEL	1.00	415.00	41.50	373.50	L	Y	bt ✓
14 REAR END PANEL TOP GARNISH	1.00	75.00	7.50	67.50	L	Y	de ✓
15 REAR END PANEL TOP GARNISH CLIPS	4.00	20.00	2.00	18.00	L	Y	nr ✓
16 REAR SPARE TYRE COMPONENTS	1.00	955.00	95.50	859.50	L	Y	Rp ✓
17 REAR SPARE TYRE FLOOR BOARD	1.00	205.00	20.50	184.50	L	Y	Crn ✓
18 REAR SPARE TYRE FLOOR BOARD CARPET	1.00	155.00	15.50	139.50	L	Y	X
19 REAR TAILLAMP	2.00	590.00	59.00	531.00	L	Y	?
20 REAR TAILLAMP CLIP	4.00	24.00	2.40	21.60	L	Y	nr ✓
21 REAR FENDER	2.00	1,450.00	145.00	1,305.00	L	Y	Rp ✓
22 REAR FENDER SPLASH SHIELD	2.00	90.00	9.00	81.00	L	Y	X
23 REAR FENDER SPLASH SHIELD CLIPS	20.00	80.00	8.00	72.00	L	Y	X
24 REAR FENDER INNER TRIM	2.00	410.00	41.00	369.00	L	Y	X
25 REAR TAILLAMP COVER PANEL	2.00	390.00	39.00	351.00	L	Y	X
26 REAR FENDER TOP SIDE PANEL EXTENSION	2.00	410.00	41.00	369.00	L	Y	Rx ✓
27 REAR BOOTLID LICENSE PLATE LAMP	2.00	110.00	11.00	99.00	L	Y	X
28 REAR EXHAUST	1.00	595.00	59.50	535.50	L	Y	X
29 REAR EXHAUST MOUNTING	4.00	140.00	14.00	126.00	L	Y	X
30 REAR EXHAUST HEAT SHIELD	1.00	95.00	9.50	85.50	L	Y	X
31 REAR BOOTLID "SWITCH"	1.00	95.00	9.50	85.50	L	Y	?
32 REAR EXHAUST CENTRE PIPE	1.00	855.00	85.50	769.50	L	Y	X
33 REAR BUMPER REVERSE SENSOR	1.00	260.00	0.00	260.00	S	Y	200nw ✓
34 NUMBER PLATE & CASING	1.00	60.00	0.00	60.00	S	Y	X
TOTAL:		10,454.00	,013.40	9,440.60			
TOTAL PARTS & LABOUR :		17,574.00	1,013.40	16,560.60			

EXCESS/LOADING:\$ \$ 0.00

No. Of Day: 10 days

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$ \$

DATE OF SURVEY: 12 / 4 / 18SURVEYED BY: TanferCONTACT NO: 97495749

FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: