

ASS. REC. BY:

REF: CS/ICS18007168/Aidsn2 Special Instruction:

SUPERVISOR: Adrian ASSIGNMENT (Office)

From (Person): Muhammad Abdul Salam of JCS Date/Time: 17042018 4:19pm

Estimated Cost: _____ Bill to: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLG 29245 Insured: SJP 22805

at Workshop m/s Precise Auto Tel: _____

of Blk 1 Kaki Bukit Ave 6 #02-34

Policy No: _____ Claim No: DMPC1800142H/JG

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 13042018
(Client's Record)

CA / REV / REP. / REV 24 HRS w/p _____ H.O.D. Endorsement: _____

Date/Time: _____ Person Contacted: Arie Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	SLG 29245 - X
	SJP 22805 - CS/ICS18007161/UTB DUA: 130415

WBS 1

REF:

ASS. REC. BY: Adrian King

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SLG2924S Yr Regn: 2016, Sept
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Honda Civic C.C. 1498
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 35197 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MRHFC1660GT000029
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 225/40R18
 R: 225/40R18

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : **Yes** or **No**
 GIA / PR Seen: _____ Consistent? : **Yes** or **No**
 Est. Repairs: _____ days Res.: **Yes** or **No**
 Lum Sum: _____ % 3 Val.: **Yes** or **No**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

<u>Front</u>		<u>Rear</u>
R/Bal. <u>06</u> mm		R/Bal. <u>06</u> mm
L/Bal. <u>06</u> mm		L/Bal. <u>06</u> mm
D.O.A. _____		D.O.I. <u>18/04/18</u>

Survey held at Precise
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or _____

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP ECICS</u>
<u>15/4/19</u>	<u>Adrian confirmed 12 \$4200f and 7 days with Prime. (Red 3478.08, 45%)</u>
	<u>RECEIVED 16 APR 2019</u>

Date/Time, File Pass to? : **Preli. Report**
 : **Final Report**
 1) _____
 Date/Time, File Return to? _____
 2) _____

Days Of Repair: 7
 Resurvey No. of Trip: 2

Report Format: TP
 Lump Sum / I.B.I: (\$ 4200f)

Add Fee: : Site Insp (\$ _____))
 : Interview (\$ _____))
 : Tech. Invs (\$ _____))
 : Weekend (\$ _____))

Survey Fee: _____
 Transportation: _____
 S + RS: _____ \$
 Photos _____
 Others _____
 TOTAL: 360

Catherine Chong (LKK Auto)

From: Precise Auto Service <support@preciseauto.sg>
Sent: Wednesday, 18 April, 2018 10:58 AM
To: LKK
Subject: Fwd: ACCIDENT INVOLVING MOTOR VEHICLES SLG 2924 S AND SJP 2280 S ALONG TPE ON 13 APRIL 2018

Dear Catherine,

Herewith forward email from ECICS Insurance as below.

Thanks & Regards
Arine

----- Forwarded message -----

From: ECICS Claims <claims@ecics.com.sg>
Date: 17 April 2018 at 16:19
Subject: RE: ACCIDENT INVOLVING MOTOR VEHICLES SLG 2924 S AND SJP 2280 S ALONG TPE ON 13 APRIL 2018
To: Precise Auto Service <support@preciseauto.sg>, Izhar <izhar@chiaarul.com>, motorsurvey <motorsurvey@ecics.com.sg>
Cc: ECICS Claims <claims@ecics.com.sg>

Without Prejudice

Dear Arine,

Thank you for your email.

We will appoint LKK for the survey.

Aside to LKK

Please assist to arrange for PRI and conduct PRI by tomorrow 18.04.2018 @10am.

Thank you.

Regards,

Abdul Salam

Claims Division

ECICS Ltd

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg

From: Precise Auto Service [mailto:support@preciseauto.sg]

Sent: Tuesday, 17 April, 2018 3:53 PM

To: Izhar

Cc: ECICS Claims

Subject: Re: ACCIDENT INVOLVING MOTOR VEHICLES SLG 2924 S AND SJP 2280 S ALONG TPE ON 13 APRIL 2018

Dear Iz,

We are understanding the PRI sent third party insurance on dated 13-04-2018 @ 1449 hrs. Please be informed that we will start to repair our client vehicle and assign our own independent surveyor if third party insurance (M/s ECICS Insurance) failed to conduct PRI within by tomorrow **18-04-2018 @ 10am.**

Thank You.

Best Regards

Arine

On 13 April 2018 at 14:49, Izhar <izhar@chiaarul.com> wrote:

Your ref: SJP 2280 S

Our ref: SLG 2924 S (iz)

13 April 2018

Dear Sirs,

We act for Teo Yun Guan, Bryan-Mark, the owner of motor vehicle SLG 2924 S who has appointed us to act on their behalf to claim against your insured's vehicle no. SJP 2280 S in regards to the road traffic accident on 13 April 2018.

Please be informed that the said motor vehicle can be inspected at:-

Precise Auto Service

1 Kaki Bukit Avenue 6. #02-36

Autobay @ Kaki Bukit

Singapore 417883

Kindly contact Ms Yan Hong/ Arine at 6745 7367 to make the necessary arrangements.

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Regards,

Mr Izhar

M/s Chia S Arul LLC

151 Chin Swee Road

#03-09 Manhattan House

Singapore 169876

Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at info@chiaarul.com. Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

--

T : 6745 7367 | **F** : 6841 3390

E : support@preciseauto.sg

W: www.preciseauto.sg

A : 1 Kaki Bukit Ave 6, #02-33/34/36 AutoBay @ Kaki Bukit, Singapore 417883



Follow us on social media:




This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

--

T : 6745 7367 | **F** : 6841 3390
E : support@preciseauto.sg
W : www.preciseauto.sg
A : 1 Kaki Bukit Ave 6, #02-33/34/36 AutoBay @ Kaki Bukit, Singapore 417883



Follow us on social media:



> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8681F
Vehicle Details	
Vehicle No.:	SLG29245
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.5 TURBO VTIS SR
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	L15B71624698
Chassis No.:	MRHFC1660GT000029
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$26,078.00
Original Registration Date:	27 Sep 2016
First Registration Date:	27 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$23,510.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Sep 2026
PARF Rebate Amount:	\$17,632.00
Intended COE Rebate Details	
COE Expiry Date:	26 Sep 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,508.00
COE Rebate Amount:	\$42,827.00
Total Rebate Amount:	\$60,459.00

The information contained herein is correct as at 15 Apr 2019

OK

PRECISE AUTO SERVICE

NO 1 KAKI BUKIT AVE 6 #02-34 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

30-06-18

Date Of Accident : 13-04-18

Adrian

OUR REF : SLG 2924S/T/18

Teo Yun Quan, Bryan-Mark

Blk 308B Punggol Walk

#08-376

Singapore 822308

Date in/out : 13/04/18 to 25/04/18

TP ELICS

ahne

ESTIMATE BILL ON VEH. NO. : SLG 2924S

MODEL : HONDA CIVIC

CHASSIS NO. : MRHFC1660GT000029

LIST ITEM

Rear Bumper Fascia <i>Distalbed 687.</i>		671.50	✓
Rear Bumper Side Retainer LH	}	18.60	✓
Rear Bumper Attachment LH		23.40	✓
Rear Bumper Lower Diffuser <i>rehd.</i>		155.80	✓
Rear Bumper Tow Cover <i>renew</i>		18.40	+
Rear Bumper Side Garnish LH <i>rehd.</i>		28.40	✓
Rear Bumper Parking Sensor LH <i>2pc</i>	2pcs @ 198.20	396.40	✓
Rear Bumper Reinforcement <i>Bevt.</i>		160.80	✓
Rear Bumper Clips <i>new</i>	10pcs @ 5.50	55.00	30. ✓
Rear Bumper Lower Exhaust Garnish LH <i>new</i>		113.80	+
Boot Lid Keyless Sensor <i>enhd</i>		120.80	✓
Boot Lid <i>755.90 Dented.</i>		572.80	✓
Boot Lid Outer Garnish <i>enhd</i>		178.20	✓
Boot Lid Outer Garnish Clips <i>new</i>	8pcs @ 5.50	44.00	20 ✓
Boot Lid Lock <i>2pc</i>		91.80	✓
Boot Lid Weatherstripe <i>ht</i>		70.40	✓
Boot Lid Stopper <i>new</i>	2pcs @ 8.40	16.80	T ✓
Boot Lid Emblem "Civic" <i>new</i>		21.50	✓
Boot Lid Emblem <i>new</i>		21.40	✓
Boot Lid Badge		53.50	✓
Boot Lid Buzzer <i>enhd.</i>		168.40	✓
Tail Lamp LH <i>enhd 405</i>		268.50	✓

Tail Lamp Sealant		50.00	+
Tail Lamp Clips	2pcs @ 5.50	11.00	+
Tail Lamp Base Panel		68.90	✓
Rear End Panel		336.20	✓
Rear End Panel Top Trim		80.10	✓
Rear End Panel Top Trim Clips	4pcs @ 5.50	22.00	✓
Exhaust Silencer		792.80	x
Rear Fender Inner Trim Board LH		472.40	+
Rear Fender Inner Trim Board Clips	8pcs @ 5.50	44.00	+
		5,147.60	
	20% Less Discount	1,029.52	
		4,118.08	

3579.40
2863.52

SPECIAL NETT ITEM

Exhaust Silencer Chorme Pipe (Acc) Best 120 220.00 120

LABOUR CHARGE

Towing 80.00 +

To check wiring system 80.00 30

To tuff coat affected areas 180.00 80

To remove & refix Interior upholstery 120.00 80

To remove & refix exhaust silencer & straighten exhaust center pipe 180.00 20

To reset electrical module system 220.00 x

To respray affected areas 1,200.00 1000

To remove & refix boot lid mechanism 180.00 x

To renew damaged parts, straighten & repair and aligned all parts 1,100.00 1000

2270

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:

A-2K ✓

TOTAL: 7,678.08
GST 7%: 537.47
AMOUNT DUE: 8,215.55

total 5283.52
L/S A-2K
07 days ✓

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18007168/ACD3N2

Date: 17/04/2019

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	MPC18A00054502
Claimant Vehicle No :	SLG2924S	Insured Vehicle No :	SJP2280S
Date of Loss:	13/04/2018	Nature of Claim:	TP
			Claim No: DMPC1800142H/JG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG2924S	Engine No:	L15B71624698
Make & Model:	HONDA CIVIC, 1.5 (A)	Chassis No:	MRHFC1660GT000029
Reg. Date:	27/09/2016 (Man. Year: 2016)	Odometer:	35197 km
Colour:	White		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40R18	Rear Tyre Size:	225/40R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,338.08	2,983.52	1,354.56	31.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,340.00	2,270.00	1,070.00	32.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,678.08	5,253.52	2,424.56	31.58
Approved Total (Overridden) (S\$)		4,200.00		
(S\$)	7,678.08	4,200.00	3,478.08	45.30
+ GST 7.00/7.00% (S\$)	537.47	294.00	243.47	45.30
Nett Amount (S\$)	8,215.55	4,494.00	3,721.55	45.30

INSPECTION

Date of Assignment:	17/04/2018		
Date Inspected:	18/04/2018	Inspected At:	Precise Auto Service (HQ) No 1 Kaki Bukit Ave 6, #02-34/36 Singapore 417883
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Apr 2019)
Parts: 143	HONDA CIVIC 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG2924S)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA	Distorted	671.50 FL	*671.50 FL
2	1		*REAR BUMPER SIDE RETAINER LH	Necessary	18.60 FL	*18.60 FL
3	1		*REAR BUMPER ATTACHMENT LH	Necessary	23.40 FL	*23.40 FL
4	1		*REAR BUMPER LOWER DIFFUSER	Deformed	155.80 FL	*155.80 FL
5	1		*REAR BUMPER TOW COVER	Not Necessary	18.40 FL	*- FL
6	1		*REAR BUMPER SIDE GARNISH LH	Deformed	28.40 FL	*28.40 FL
7	2		*REAR BUMPER PARKING SENSOR LH	Damaged	396.40 FL	*396.40 FL
8	1		*REAR BUMPER REINFORCEMENT	Bent	160.80 FL	*160.80 FL
9	10		*REAR BUMPER CLIPS	Necessary	55.00 FL	*30.00 FL
10	1		*REAR BUMPER LOWER EXHAUST GARNISH LH	Not Necessary	113.80 FL	*- FL
11	1		*BOOT LID KEYLESS SENSOR	Cracked	120.80 FL	*120.80 FL
12	1		*BOOT LID	Dented	572.80 FL	*572.80 FL
13	1		*BOOT LID OUTER GARNISH	Cracked	178.20 FL	*178.20 FL
14	8		*BOOT LID OUTER GARNISH CLIPS	Necessary	44.00 FL	*20.00 FL
15	1		*BOOT LID LOCK	Damaged	91.80 FL	*91.80 FL
16	1		*BOOT LID WEATHERSTRIPE	Cut	70.40 FL	*70.40 FL
17	2		*BOOT LID STOPPER	Not Necessary	16.80 FL	*- FL
18	1		*BOOT LID EMBLEM CIVIC	Necessary	21.50 FL	*21.50 FL
19	1		*BOOT LID EMBLEM	Necessary	21.40 FL	*21.40 FL
20	1		*BOOT LID BADGE	Necessary	53.50 FL	*53.50 FL
21	1		*BOOT LID BUZZER	Cracked	168.40 FL	*168.40 FL
22	1		*TAIL LAMP LH	Cracked	268.50 FL	*268.50 FL
23	1		*TAIL LAMP SEALANT	Not Necessary	50.00 FL	*- FL
24	2		*TAIL LAMP CLIPS	Not Necessary	11.00 FL	*- FL
25	1		*TAIL LAMP BASE PANEL	Dented	68.90 FL	*68.90 FL
26	1		*REAR END PANEL	Dented	336.20 FL	*336.20 FL
27	1		*REAR END PANEL TOP TRIM	Cracked	80.10 FL	*80.10 FL
28	4		*REAR END PANEL TOP TRIM CLIPS	Necessary	22.00 FL	*22.00 FL
29	1		*EXHAUST SILENCER	Repair	792.80 FL	*- FL
30	1		*REAR FENDER INNER TRIM BOARD LH	Not Necessary	472.40 FL	*- FL
31	8		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	44.00 FL	*- FL
32	1		*EXHAUST SILENCER CHROME PIPE (ACC)	Bent	220.00 FS	*120.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,367.60	3,699.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,029.52	715.88
Total Parts (\$\$)	4,338.08	2,983.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	80.00	0.00
2	TO CHECK WIRING SYSTEM	New	80.00	30.00
3	TO TUFF COAT AFFECTED AREAS	New	180.00	80.00
4	TO REMOVE & REFIX INTERIOR UPHOLSTERY	New	120.00	80.00
5	TO REMOVE & REFIX EXHAUST SILENCER & STRAIGHTEN EXHAUST CENTER PIPE	New	180.00	80.00
6	TO RESET ELECTRICAL MODULE SYSTEM	New	220.00	0.00
7	TO RESPRAY AFFECTED AREAS	New	1,200.00	1,000.00
8	TO RMEOVE & REFIX BOOT LID MECHANISM	New	180.00	0.00
9	TO RENEW DAMAGED PARTS, STRAIGHTEN & REPAIR AND ALIGNED ALL PARTS	New	1,100.00	1,000.00
Gross Labour Cost (S\$)			3,340.00	2,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >