

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9426E**AAD1804-164***Not Authored
11/11/18*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHD 9426E

KL1LA69RJB072757

CHEVROLET

EPICA 2.0

14.4.2018

AIG

		PART		LIST
1	1	Rear Bumper	\$	<i>Bu</i> 1,202.00 ✓
2	1	Rear Bumper Beam	\$	<i>Bu</i> 239.94 ✓
3	1	Rear Bumper Centre Absorber	\$	<i>CM</i> 260.00 ✓
4	1	Rear Bumper Side Retainer RH	\$	<i>Sn</i> 68.76 X
5	1	Rear Bumper Side Retainer LH	\$	<i>DI</i> 68.76 ✓
6	1	Rear Bumper Reflectors RH	\$	<i>Sn</i> 119.74 X
7	1	Rear Bumper Reflectors LH	\$	<i>CM</i> 119.74 ✓
8	1	Rear Bumper Tow Hook Cover	\$	<i>Sn</i> 93.00 X
9	1	Rear End Panel Outer	\$	<i>Bu</i> 623.76 ✓
10	1	Rear End Panel Inner Trim	\$	<i>DI</i> 263.84 ✓
11	1	Rear Luggage Floor Panel	\$	<i>R</i> 973.00 X
12	1	Rear Luggage Floor Panel Insulator	\$	<i>Sn</i> 63.50 X
13	1	Rear Luggage Floor Panel Trim Board	\$	<i>Sn</i> 378.00 X
14	1	Bootlid	\$	<i>Bu</i> 973.00 ✓
15	1	Bootlid inner trim board	\$	<i>Sn</i> 400.00 X
16	1	Bootlid Weatherstrip	\$	<i>DI</i> 344.28 <i>508 Sn</i>
17	1	Bootlid Lock - Top	\$	<i>DI</i> 466.56 ✓
18	1	Bootlid 'CHEVROLET' Badge	\$	<i>DI</i> 120.62 ✓
19	1	Bootlid Logo	\$	<i>DI</i> 138.84 ✓
20	1	Bootlid 'EPICA LT' Badge	\$	<i>DI</i> 119.84 ✓
21	1	Bootlid Reflector Centre	\$	<i>Sn</i> 217.97 X
22	1	Bootlid Reflector RH	\$	<i>Sn</i> 128.40 X
23	1	Bootlid Reflector LH	\$	<i>CM</i> 128.40 ✓
24	1	Rear Tail Lamp RH	\$	<i>Sn</i> 479.30 X
25	1	Rear Tail Lamp LH	\$	<i>DI</i> 479.30 ✓
26	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	<i>R</i> 1,110.00 X
27	1	Rear Fender RH	\$	<i>R</i> 1,145.00 X
28	1	Rear Fender Inner Trim RH	\$	<i>Sn</i> 418.44 X
29	1	Rear Fender LH	\$	<i>R</i> 1,145.00 X

Trans-cab Auto Services Pte Ltd**AAD1804-164**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9426E

30	1	Rear Fender Inner Trim LH	\$	<i>Sn</i> 418.44	<i>X</i>
----	---	---------------------------	----	------------------	----------

TOTAL	\$	12,707.43
10%	\$	1,270.74
	\$	11,436.69

Specical Nett

1	1Set	Bootlid inner trim board Clip	\$	<i>nn</i> 40.00	<i>X</i>
2	1Set	Rear Bumper Parking Sensor	\$	<i>Sn</i> 300.00	<i>X</i>
3	1Set	Rear Bumper Fastener Clip	\$	<i>nn</i> 44.00	<i>✓</i>
4	1Set	Rear Fender Inner Trim Clip LH	\$	<i>nn</i> 30.00	<i>X</i>
5	1Set	Rear Bumper End Dust Cover Clip	\$	<i>nn</i> 30.00	<i>X</i>
6	1	Rear Boot Sticker 'Trans-cab'	\$	<i>nn</i> 30.00	<i>✓</i>
7	1	Rear Boot Sticker '6555-3333'	\$	<i>nn</i> 30.00	<i>✓</i>
8	1	Rear Exhaust Mounting	\$	<i>nn</i> 10.00	<i>X</i>
9	2	Rear Windscreen Sealant	\$	<i>nn</i> 80.00	<i>X</i>
10	1	Rear Windscreen Inner Sponge Seal	\$	<i>nn</i> 100.00	<i>X</i>
11	1	Spare Tyre	\$	<i>Sn</i> 180.00	<i>X</i>
12	1	Spare Wheel Rim	\$	<i>Sn</i> 126.74	<i>X</i>

TOTAL	\$	1,000.74
--------------	-----------	-----------------

TOTAL PARTS	\$	12,437.43
--------------------	-----------	------------------

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$	3,500.00	<i>700</i>
----	----------	------------

To Check Electrical Lighting Concerned.

\$	170.00	<i>200</i>
----	--------	------------

To Rust-Proofing Of The Affected Areas.

\$	170.00	<i>600</i>
----	--------	------------

Putty And Spray Painting Of The Affected
Portion.

\$	3,200.00	<i>800</i>
----	----------	------------

To reinstall rear bumper parking sensor.

\$	170.00	<i>600</i>
----	--------	------------

Trans-cab Auto Services Pte Ltd**AAD1804-164**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No: : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9426E

To transfer of end panel fittings and conduct
water seepage test. \$ 170.00 *601*

To transfer of boot fittings and conduct water
seepage test. \$ 170.00 *601*

To remove and refit interior fittings, trimings,
garnish, fittings and other, to enable repair. \$ *nn* 380.00 X

To check steering geometry and computer
wheel alignment \$ *nn* 220.00 X

\$ 8,150.00

TOTAL \$ 20,587.43

Repair Days

10 Days

5 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: