

ESTIMATE TO REPAIR

VEHICLE NO. : SKD 5900 T
MAKE : MERCEDES BENZ
MODEL : SL 350 A
YEAR : 2008
CHASSIS NO : WDB2304582F145459

SURVEYOR NAME	: Kenneth (LKK)
DATE OF SURVEY	: 14-05-2018
TIME OF SURVEY	:

DATE : 17-Apr-18
DATE OF ACCIDENT : 12-Apr-18
THIRD PARTY REF : SKU 4243 Z / AIG

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Front Bumper	Nett		<i>Per</i> \$ 1,830.00	
1 pc	O/S Front Bumper Bracket	Nett		\$ 90.00	
1 pc	Front Bumper Sensor	Nett		<i>my car</i> \$ 320.00	
1 pc	O/S Headlamp	Nett		\$ 4,750.00	
				\$ 6,990.00	
	Less 10%			\$ 699.00	
				\$ 6,291.00	
	To putty & spray painting.			<i>4201</i> \$ 500.00	
	To check front wiring and focus headlights.			<i>201</i> \$ 30.00	
	Labour Charges.			<i>3501</i> \$ 400.00	
	<i>Not Authorized L1 Day @ ? Resurvey After Paint 3 days</i>				
TG-RA/-	TOTAL				\$ 7,221.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel: 65-64520893 Fax: 65-64589127

Website : www.LTM.sg

Co.Reg No. 199307277D

GST Reg No. M2-0019086-0